MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address: 7204 Cedar Ave., Takoma Park Meeting Date: 2/21/2018

Resource: Outstanding Resource Report Date: 2/14/2018

(Takoma Park Historic District)

Public Notice: 2/7/2018

Applicant: Nancy Augustine and Adam Oppenheim

(Jackie Braitman, Architect)

Tax Credit: No

Staff: Michael Kyne

Case Number: 37/03-18J

Review:

PROPOSAL: Building addition

STAFF RECOMMENDATION:

HAWP

Staff recommends that the HPC approve with one (1) condition the HAWP application.

1. Window and door specifications will be submitted, with final review and approval delegated to staff.

ARCHITECTURAL DESCRIPTION:

SIGNIFICANCE: Outstanding Resource within the Takoma Park Historic District

STYLE: Classical Revival

DATE: c. 1913

BACKGROUND:

The applicants previously appeared before the Commission for a preliminary consultation at the January 23, 2018 HPC meeting.

PROPOSAL:

The applicant proposes a building addition and other alterations at the subject property.

APPLICABLE GUIDELINES

When reviewing alterations and new construction within the Takoma Park Historic District several documents are to be utilized as guidelines to assist the Commission in developing their decision. These documents include the historic preservation review guidelines in the approved and adopted amendment for the Takoma Park Historic District (Guidelines), Montgomery County Code Chapter 24A (Chapter 24A), and the Secretary of the Interior's Standards for Rehabilitation (Standards). The pertinent information in these documents is outlined below.

Takoma Park Historic District Guidelines

There are two very general, broad planning and design concepts which apply to all categories. These are:

- The design review emphasis will be restricted to changes that are all visible from the public rightof-way, irrespective of landscaping or vegetation (it is expected that the majority of new additions will be reviewed for their impact on the overall district), and,
- the importance of assuring that additions and other changes to existing structures act to reinforce and continue existing streetscape, landscape, and building patterns rather than to impair the character of the historic district.

Outstanding Resources - Residential

The Guidelines characterize Outstanding Resources as those

... which [are] of outstanding significance due to [their] architectural and/or historical features. An Outstanding Resource may date from any historical period and may be representative of any architectural style. However, it must have special features, architectural details and/or historical associations that make the resource especially representative of an architectural style, it must be especially important to the history of the district, and/or it must be especially unique within the context of the district.

These resources have the highest level of architectural and/or historical significance. While they will receive the most detailed level of design review, it is permissible to make sympathetic alterations, changes and additions to Outstanding Resources.

As a set of guiding principles for design review of Outstanding Resources, the Historic Preservation Commission will utilize the Secretary of the Interior's Standards for Rehabilitation.

The Guidelines that pertain to this project are as follows:

- Plans for all alterations should be compatible with the resource's original design; additions, specifically, should be sympathetic to existing architectural character, including massing, height, setbacks, and materials.
- Emphasize placement of major additions to the rear of existing structures so that they are less visible from the public right-of-way.
- While additions should be compatible, they are not required to be replicative of earlier architectural styles.
- Preservation of original and distinctive architectural features, such as porches, dormers, decorative details, shutters, etc. is encouraged.
- Preservation of original windows and doors, particularly those with specific architectural importance, and of original size and shape of openings is encouraged.
- Preservation of original building materials and the use of appropriate, compatible new materials is encouraged.

 All changes and additions should respect existing environmental settings, landscaping, and patterns of open space.

Montgomery County Code; Chapter 24A-8

- (a) The commission shall instruct the director to deny a permit if it finds, based on the evidence and information presented to or before the commission that the alteration for which the permit is sought would be inappropriate, inconsistent with or detrimental to the preservation, enhancement or ultimate protection of the historic site or historic resource within an historic district, and to the purposes of this chapter.
- (b) The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to insure conformity with the purposes and requirements of this chapter, if it finds that:
 - (1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or
 - (2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter; or
 - (3) The proposal would enhance or aid in the protection, preservation and public or private utilization of the historic site or historic resource located within an historic district in a manner compatible with the historical, archeological, architectural or cultural value of the historic site or historic district in which an historic resource is located; or
 - (4) The proposal is necessary in order that unsafe conditions or health hazards be remedied; or
 - (5) The proposal is necessary in order that the owner of the subject property not be deprived of reasonable use of the property or suffer undue hardship; or
 - (6) In balancing the interests of the public in preserving the historic site or historic resource located within an historic district, with the interests of the public from the use and benefit of the alternative proposal, the general public welfare is better served by granting the permit.
 - (c) It is not the intent of this chapter to limit new construction, alteration or repairs to any 1 period or architectural style.
 - (d) In the case of an application for work on an historic resource located within an historic district, the commission shall be lenient in its judgment of plans for structures of little historical or design significance or for plans involving new construction, unless such plans would seriously impair the historic or architectural value of surrounding historic resources or would impair the character of the historic district. (Ord. No. 9-4, § 1; Ord. No. 11-59.)

Secretary of the Interior's Standards for Rehabilitation:

The Secretary of the Interior defines rehabilitation as "the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features, which convey its historical, cultural, or architectural values." The Standards are as follows:

1. A property shall be used for its historic purpose or be placed in a new use that requires minimal change to the defining characteristics of the building and its site and environment.

- 2. The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.
- 3. Each property shall be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as adding conjectural features or architectural elements from other buildings, shall not be undertaken.
- 4. Most properties change over time; those changes that have acquired historic significance in their own right shall be retained and preserved.
- 5. Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a historic property shall be preserved.
- 6. Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary, physical, or pictorial evidence.
- 7. Chemical or physical treatments, such as sandblasting, that cause damage to historic materials shall not be used. The surface cleaning of structures, if appropriate, shall be undertaken using the gentlest means possible.
- 8. Significant archaeological resources affected by a project shall be protected and preserved. If such resources must be disturbed, mitigation measures shall be undertaken.
- 9. New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.
- 10. New additions and adjacent or related new construction shall be undertaken in such a manner that if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

STAFF DISCUSSION

The subject property is a 1 ½-story Classical Revival-style Outstanding Resource within the Takoma Park Historic District. Records indicate that the historic house was constructed in 1913, replacing a Queen Anne-style house that burned down that same year. The house is located on a corner lot, with its front facing Tulip Avenue and its right side facing Cedar Avenue. Because of the house's location, three of its elevations – the front, rear, and right side – are clearly visible from the public right-of-way. The applicant has indicated that the house experienced previous alterations, including the replacement of the original slate roof with asphalt and the replacement of the original clapboard siding on the dormers with asphalt shingles.

The applicants previously appeared before the Commission for a preliminary consultation at the January 23, 2018 HPC meeting. The Commission was supportive of the applicants' proposal, but expressed the following comments and concerns:

• The hyphen approach is appropriate, but some steps should be taken to make it read more as a

hyphen and/or distinct space. This could be accomplished by adding more fenestration, or perhaps by simply swapping the previously proposed right and left elevations of the hyphen.

- If possible, the hyphen should be shortened, while retaining the view of the dormers and other character-defining features on the rear of the historic house.
- The standing seam metal roof could be appropriate, if the correct details and finish (no ridge caps or vents, appropriate seam height, and a paintable matte finish) are proposed.
- The proposed curvilinear wheelchair ramp should be straight and moved adjacent to the building.
- The proposed poured concrete foundations and ramp should be parged to be more consistent with the historic house's foundation.
- There was no real support for the suggestion of three different roof types or for the suggestion of asphalt shingles on the addition and copper on the hyphen.
- There was concern from one Commissioner about the Palladian windows on the addition; however, the majority of Commissioners thought that you successfully referenced the details of the historic house.
- There was concern from one Commissioner about the paired window and shutters on the right side of the proposed hyphen; however, if the previous suggestions regarding fenestration changes are incorporated, these features will likely be removed from the proposal anyway.

The applicants have returned for a HAWP application, with the following revisions:

- More fenestration has been added to the proposed hyphen, with 12-lite doors and windows added to the left and right elevations.
- The length of the proposed hyphen has been reduced, going from 25'-11" to 20'.
- Asphalt shingle roofing is proposed for the hyphen and rear addition, differentiating the new structures from the historic house with slate roof.
- As revised, the wheelchair ramp is straight and directly adjacent to the proposed rear addition.
- The proposed wheelchair ramp will be parged to be consistent with the painted stone foundation of the historic house.
- The Palladian windows on the side elevations of the proposed rear addition have been simplified to take cues from but not but replicate the details of the historic house.

Staff finds that the applicants have successfully responded to the Commission's previous comments and concerns and recommends that the Commission approve the HAWP application, with the following condition: Window and door specifications will be submitted, with final review and approval delegated to staff.

After full and fair consideration of the applicant's submission staff finds the proposal, as modified by the conditions, as being consistent with the Criteria for Issuance in Chapter 24A-(b) 1 and 2, having found the

proposal is consistent with the Secretary of the Interior's Standards for Rehabilitation and Takoma Park Historic District Guidelines outlined above.

STAFF RECOMMENDATION:

Staff recommends that the Commission approve the HAWP application under the Criteria for Issuance in Chapter 24A-8(b), (1), (2) & (d) having found that the proposal is consistent with the *Takoma Park Historic District Guidelines*, and therefore will not substantially alter the exterior features of the historic resource and is compatible in character with the district and the purposes of Chapter 24A;

and with the Secretary of the Interior's Standards for Rehabilitation;

and with the general condition that the applicant shall present the 3 permit sets of drawings, if applicable, to Historic Preservation Commission (HPC) staff for review and stamping prior to submission for the Montgomery County Department of Permitting Services (DPS) building permits;

and with the general condition that final project design details, not specifically delineated by the Commission, shall be approved by HPC staff or brought back to the Commission as a revised HAWP application at staff's discretion;

and with the general condition that the applicant shall notify the Historic Preservation Staff if they propose to make any alterations to the approved plans. Once the work is completed the applicant will contact the staff person assigned to this application at 301-563-3400 or michael.kyne@montgomeryplanning.org to schedule a follow-up site visit.



RETURN TO DEPARTMENT OF PERMITTING SERVICES #55-ROSE VILLE FIRE PRINTED ON ROSE VILLE PERSONS #40-77-51-6

HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

| | | | | Contact Person: | Jackie Braitman | |
|--|--------------------|-----------------------------|--------------------------|---|--------------------------|----------------------|
| | | | | Daytime Phone No.: | 301-891-3800 |) |
| Tax Account No.: | 01057103 | | | | | |
| | | Augustine & Ad | am Oppenhei | M Daytime Phone No.: | | |
| Address: | 9029 F | airview Rd, Silv | er Spring, MD | 20910-4120 | | |
| Street Number City Braitman Design Studio Inc | | | | Steet | | |
| Contractor: Braitman Design Studio, Inc. Contractor Registration NMHIC# 125978 | | | | Phone No.: | 301-091-300 | 10 |
| | | Braitman | | 301-891-380 | ١٥ | |
| Agent for Owner: | | | Daytime Phone f | | . 301-091-3000 | |
| LOCATION OF BUI | LDING/PREMI | SE. | | · · · · · · · · · · · · · · · · · · · | | |
| House Number: | use Number: 7204 | | Street | Cedar Ave | | |
| Town/City: | Takoma I | Park | Nearest Cross Street: | Tulip Ave | | |
| Lot: P18 | Block: 6 | Subdivision | 0025 | | ···· | |
| Liber: | Folio: | Parcel | | | | |
| PART ONE: TYPE | AE BEBLAIT AT | TION AND LISE | | | | |
| | | TION AND USE | PUECK ALL | LORICADIT. | | |
| A. CHECK ALL APPLICABLE: CHECK ALL APPLICABLE: CHECK ALL APPLICABLE: CHECK ALL APPLICABLE: Porch Deck Shed | | | | | | |
| | | | E | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | | |
| ☐ Move | □ instali | ☐ Wreck/Raze | | Fireplace Woodba | • | Single Family |
| ☐ Revision | | □ Revocable © 250 000 | ☐ Fence/Wi | all (complete Section 4) | □ Other; | |
| | | \$350,000 | B 2. d | , , , , , , , , , , , , , , , , , , | | |
| IV. IT THIS IS A FEVISIO | n or a previously | approved active permit, r | ee remit # | | | |
| PART TWO: COM | PLETE FOR NE | W CONSTRUCTION AN | <u>ID EXTEND/ADDITIO</u> | NS | | |
| 2A. Type of sewege | e disposal: | 01 🗷 WSSC | 02 🔲 Septic | 03 🗆 Other: | | |
| 2B. Type of water s | nbbly: | 01 🛮 wssc | 02 🗆 Well | 03 🗍 Other: | · | |
| PART THREE- CO. | MPIETE NAIV | OR FENCE/RETAINING | WALL | | | |
| 3A. Height | | | | | | |
| | | rtaining wall is to be cons | meted on one of the fo | Bouden Incations | | |
| Cn party line | | - | end of owner | | | |
| On party and | в/ргарану иле | — Епину он и | no or owner | L3 Off pablic right of 4 | 789/00001781110 | |
| hereby certify that I | have the author | ity to make the foregoing | application, that the ap | plication is correct, and | that the construction wi | ll comply with plans |
| approved by all agen | icies listed and I | heraby acknowledge and | accept this to be a co | nordon for the Issuance | or this permit. | / |
| | V 6 | (| - | | 1/29/ | 18 |
| | Signature of tom | er or authorized agent | | _ | Det | |
| | | | | | | |
| Approved: | | | For Chairpe | vson, Historic Preservati | on Commission | |
| Disapproved: Signature: | | | | Date: | | |
| Application/Permit No.: | | | Date Filed: | | Date Issued: | |
| | | | _ | | _ | |

SEE REVERSE SIDE FOR INSTRUCTIONS

826332

Edit 6/21/99



Schedule 1a: Description of Existing Structures and environmental setting.

7204 is an Outstanding Resource in the Takoma Park historic district. The house is on the site of the BF Gilbert House from 1885 – 1913. BF Gilbert was the developer for Takoma Park. The original house on the site was a Queen Anne style home; it burned down in 1913. The rebuilt house – the existing house – is a "classical revival" style.

the size of the more typical lot in Takoma Park. A large 13ft by 44ft front porch has 6 large colonial columns. The house faces Tulip Ave even though the address is Cedar Ave. Continuing the "grand" style, The house sits at the northwest corner of Tulip and Cedar Avenues. The lot is 28,768 sf - almost 4 times the house is sits 115ft back from the sidewalk on Tulip. There is a terra cotta paver walkway on the property from the sidewalk gate to the front porch. These pavers possibly date from 1885. They match the terra cotta pavers on the public sidewalk adjacent to the house -- which are the only remaining original sidewalks in Takoma Park.

foundation appears to be older than the current early 1900's construction. We hypothesize that the stone home sits on a limestone foundation that extends partially (~30 inches) up the first floor walls. The stone foundation was from the original 1885 home. The Takoma Park Master Plan says this current home was The home is 1-1/2 stories with 2 front gable dormers, 3 back gable dormers, and partial basement. The built in 1913 while the Maryland real property database lists the construction date as 1918.

place" - delaying needed maintenance for the past 20-or-so years. In addition, many of the "repairs" made in the 1970's were ones that destroyed the original materials – such as replacing the slate roof with asphalt The current home has been owned by the Augustine family for 65 years. The Augustine parents "aged in and replacing the clapboard siding on the dormers with asphalt shingles.

The lot is landscaped with mature plantings and trees.

HAWP APPLICATION

Schedule 1a & 1b

AUGUSTINE-OPPENHEIM RESIDENCE 1204 Cedar Ave. Takona Park, MD 20912

01/30/18 1 of 20 Rev 04

Braitman Design Studio MHIC License #125978 120 Park Ave Takoma Park, MD 20912 Phone: 301-891-3000

www BraitmanDesign.Com braitman

Schedule 1b: General Description of Project & Effect on the Historic Resource. Setting and District.

property and is committed to restoring the historic character and materials. She is also planning to pursue a Maryland As mentioned, the house has been owned by one family for the past 65 years. The daugter has recently inherited the Historical Trust Easement further protecting the home and its setting

The objective of the work is to provide better living space while preserving and restoring the historic character of the home, including:

- with clapboard. They also plan to modernize or repair old mechanical systems. Historic exterior trim, windows, siding, home including: replacing the asphalt shingle roof with state and replacing the asphalt shingle siding on the dormers Repairs and Restoration of the original structure: The owners plan to restore historic materials removed from the and foundation walls will be restored and repaired.
- The historic Terra Colta Paver walkway on the site will be preserved and protected. The builder will also prepare a protection plan for the adjacent historic public sidewalk, coordinate that plan with the City of Takoma Park, and will execute that plan to fully protect that historic sidewalk.
- Proposed Addition: We propose to add an addition to the rear of the house that is subordinate to the original structure in both size and height. The proposed addition will also reflect the architectural style of the original home - same roof slope and window detail. The proposed addition will echo (but simplify) the original details including the 10-lite casement windows, tall 8 ft doors, and roof eaves detail.
- roof line than the original home or the addition. The addition is located and designed such that no historic details are Proposed Connector: We propose to connect the addition to the original home with a 1-story connector with a lower changed or obscured. The proposed connector will also provide a family entrance off the existing Cedar Avenue parking area. The entrance will not compete architecturally with the original front porch facing Tulip Ave.
- original structure, and restore clapboard siding to the dormer walls. We explored the idea of removing the paint from Original Architectural Elements will be Repaired or Restored: The original windows and doors will be repaired as will and exposing the original stone foundation. However, the structural engineer believes that the stone and mortar are the original shutters and porch columns. We will remove chain-link security coverings, restore a slate roof on the soft and could be damaged. So we will repaint instead
- to create a larger kitchen, better indoor/outdoor access, and safe stairs to the basement. As part of this interior change we propose to change a small section of roof over a back porch that was previously enclosed and incorporated into the Two Small Changes to the Original Home Will Not Be Visible: The project will also include an interior first floor remodel The new doors is not exactly in the same location as the window being removed. Again, these changes will be hidden roof extension will no longer be visible once the addition is built and we propose to change that one small section of kitchen. The current roof extends over that porch lowering the ceiling well below the 10ft ceilings in the home. This roof to a gable roof. We also proposed to remove one original window and install a new French door to a new deck. behind the new connector and addition.

ÁUGUSTINE-OPPENHEIM RESIDENCE
7204 Cedar Ave, Takoma Park, MD 20912

HAWP APPLICATION


2 of 20 Mills License #125978 Rev 04 Takene Park, MD 20912 01/30/18


License #125978
ark Ave
a Park, MD 20912
501-891-3800


www.BrailmanDesign.Com

BULD


9










(IZ)







(14)










www.BraitmanDesign.Com braitman - Mood Forch Columns and Porch Tum - Connete Porch - Mood Casement Mindous & Doors Braitman Design Studio MHIG License #125978 122 Park Ave Takoma Park, MD 20912 Phone: 301-891-3900 All Historic Elements Retained Roafilme & Gable Domers - Painted Clapboard Blans to New Bide Porch & Ramp 11 of 20 Rev 04 18% 01/30/18 HAWP APPLICATION Proposal - Elevations Historic Masoing Undhanged E1 - PROPOSED FRONT - TULIP ELEVATION 3/32 in = 1 ft RESTORE: - WOOD CLAPBOARD SIDING ON DORMERS - SLATS ROOF AUGUSTINE-OPPENHEIM RESIDENCE 7204 COCOLTANO, Takona Park, MD 20912 Stairs to Deck 4 3:0 F





(20)





www.BrailmanDesign.Com

braitman

01/30/18

HAWP APPLICATION

ÁUGUSTINE-OPPENHEIM RESIDENCE

FRONT FACADE

Braitman Design Studio MHIC Liconse #125978 120 Park Ave Taxoma Park, MD 20912 Phone. 301-891-3000

HAWP APPLICATION

A.UGUSTINE-OPPENHEIM RESIDENCE

17 of 20 Rev 04 01/30/18

Braiman Design Studio MHIC License #125978 120 Park Ave Takoma Park, MD 20912 Phone: 301-891-3800

braitman BUILD www.BratmanDesign.Com

HAWP APPLICATION


AUGUSTINE-OPPENHEIM RESIDENCE 7204 Cedar Ave, Takona Park, MD 20912

BACK FACADE

18 of 20 Rev 04 01/30/18

braitman Bull D www.BraitmanDesign.Com

CEDAR AVE FACADE



AUGUSTINE-OPPENHEIM RESIDENCE 72004 Cectar Avea, Takoma Park, MD 20972

19 of 20 Rev 04 01/30/18

Braitman Design Studio MHIC License #125978 120 Park Ave Takoma Park, MD 20912 Phone: 301-891-3800


braitman BUIL.D


AUGUSTINE-OPPENHEIM RESIDENCE 7204 Cedar Ave., Takona Park, MD 20912

NORTHWEST SIDE FACADE

HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFING [Owner, Owner's Agent, Adjacent and Confronting Property Owners] Owner's mailing address Owner's Agent's mailing address Nancy Augustine & Adam Oppenheim JACKIE BRAITMAN Braitman Design Studio, Inc. 9029 FAIRVIEW RD SILVER SPRING, MD 20910-4120 120 PARK AVE TAKOMA PARK, MD 20912-4311 Adjacent and confronting Property Owners mailing addresses BADT STEVEN M COLWELL JAMES C 7209 CEDAR AVE WEISS ALICE M TAKOMA PARK, MD 20912 7201 CEDAR AVE TAKOMA PARK, MD 20912 CARAFELLI JOSEPH JR & M A VAENA MARCOS J H 7203 CEDAR AVE VAENA KELLY TAKOMA PARK, MD 20912 7212 CEDAR AVE TAKOMA PARK, MD 20912 WELCH LAURA FLAMBERG GEMMA & 7118 CEDAR AVE DANIEL M LEVIN TAKOMA PARK, MD 20912 7205 CEDAR AVE TAKOMA PARK, MD 20912

PREVIOUS PROPOSAL






(g)

EXISTING - SECOND FLOOR - 1/16 in = 1 ft

١


FANTRY

LMING



EXISTING FIRST FLOOR - 1/16 in = 1 ft

(ii)




AUGÙSTINE-OPPENHEIM RESIDENCE 7204 Cedar Avo, Takoma Park, MD 20912


Preliminary HAWP

01/16/18 4 of 18 Rev 03

EXISTING BASEMENT - 1/16 in = 1 ft

Braitman Design Studio MHIC License #125978 120 Park Ave Takoma Park, MD 20912 Phone: 301-891-3800





Existing Structure - Elevations

AUGUSTINE-OPPENHEIM RESIDENCE 7204 Cedar Ave, Takoma Park, MD 20912

Preliminary HAWP

01/16/18 6 of 18 Rev 03

Braitman Design Studio MHIC License #125978 120 Park Ave Takoma Park, MD 20912 Phone: 301-891-3800

braitmandesign BUILD

E4 - EXISTING LEFT SIDE 3/32 in = 1 ft

Existing Structure - Elevations


AUGUSTINE-OPPENHEIM RESIDENCE 7204 Cedar Ave, Takoma Park, MD 20912

Preliminary HAWP

01/16/18 7 of 18 Rev 03

Braitman Design Studio MHIC License #125978 120 Park Ave Takoma Park, MD 20912 Phone: 301-891-3800

braitmandesign BUILD



Proposal - Floor Plans


ACCUSTINE-OPPENHEIM RESIDENCE 7204 Cedar Ave, Taxoma Park, MD 20912

Preliminary HAWP


01/16/18 8 of 18 Rev 03

Braitman Design Studio MHIC License #125978 120 Park Ave Takoma Park, MD 20912 Phone: 301-891-3800

braitmandesign Build



PROPOSED 2ND FLOOR PLAN - NO CHANGES 1/16 in = 1 ft



PROPOSED - BASEMENT PLAN 1/16 in = 1 ft

Proposal - Floor Plans

AUGUSTINE-OPPENHEIM RESIDENCE 7204 Cedar Ave, Takoma Park, MD 20912

Preliminary HAWP

9 of 18 Rev 03

01/16/18

Braitman Design Studio MHIC License #125978 120 Park Ave Takoma Park, MD 20912 Phone: 301-891-3800

braitmandesign BUILD

Wheelchair Ramp Blended Into Landscape Malls Mood Porch Columns and Porch Trim
 Concrete Porch - Mood Casement Mindows & Doors All Historic Elements Retained - Roof Lne & Gable Dormers Painted Clapboard Stairs to New Side Forch Historic Massing Unchanged

- WOOD CLAPBOARD SIDING ON DORMERS

. SLATE ROOF RESTORE:

E1 - PROPOSED FRONT - TULIP ELEVATION 3/32 in = 1 ft

Proposal - Elevations

AUGUSTINE-OPPENHEIM RESIDENCE 7204 Cedar Ave, Takoma Park, MD 20912


Preliminary HAWP

01/16/18 10 of 18 Rev 03

Braitman Design Studio MHIC License #125978 120 Park Ave Takoma Park, MD 20912 Phone: 301-891-3800

braitmandesign BUILD

www.BraltmanDesign.Com



www.BraitmanDesign.Com

E2 - PROPOSED BACK ELEVATION 3/32 in = 1 ft

Proposal - Elevations

AUGUSTINE-OPPENHEIM RESIDENCE 7204 Cedar Ave, Takoma Park, MD 20912


Preliminary HAWP

01/16/18 12 of 18 Rev 03

Braitman Design Studio MHIC License #125978 120 Park Ave Takoma Park, MD 20912 Phone: 301-891-3800

braitmandesign BUILD

www.BraitmanDesign.Com



Proposal - Elevations

AUGUSTINE-OPPENHEIM RESIDENCE 7204 Cedar Ave, Takoma Park, MD 20912

Preliminary HAWP

13 of 18 Rev 03 01/16/18

Braitman Design Studio MHIC License #125978 120 Park Ave Takoma Park, MD 20912 Phone: 301-891-3800

braitmandesign BUILD

www.BraitmanDesign.Com

| 1 | THE MARYLAND-NATIONAL CAPITAL PARK AND PLANNING COMMISSION |
|----|--|
| 2 | |
| 3 | |
| 4 | X |
| 5 | HISTORIC AREA WORK PERMIT - : 17 Hesketh Street : HPC Case No. 35/13-18C |
| 6 | : X |
| 7 | : PRELIMINARY CONSULTATION - : |
| 8 | 7204 Cedar Avenue : |
| 9 | X |
| 10 | A meeting in the above-entitled matter was held on |
| 11 | January 23, 2018, commencing at 7:34 p.m., in the MRO |
| 12 | Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland |
| 13 | 20910, before: |
| 14 | COMMITTEE MEMBERS |
| 15 | Bill Kirwan, Chair |
| 16 | Sandra Heiler Marsha Barnes |
| 17 | Kenneth Firestone |
| 18 | Richard Arkin Eliza Voigt |
| 19 | Robert Sutton |
| 20 | |
| 21 | |
| 22 | |
| 23 | |
| 24 | |
| 25 | |

Deposition Services, Inc.

12321 Middlebrook Road, Suite 210
Germantown, MD 20874
Tel: (301) 881-3344 Fax: (301) 881-3338
info@DepositionServices.com www.DepositionServices.com

| ALSO | PRESENT: | |
|-------|----------------------------|------|
| Phill | lip Estes | |
| Micha | ael Kyne | |
| Danie | el Bruechert | |
| | APPEARANCES | |
| STATI | PAGE | |
| Charl | 16 | |
| Jacki | 32 | |
| | | |
| | TABLE OF CONTENTS | |
| | | PAGE |
| I. | HISTORIC AREA WORK PERMITS | |
| | Case B | 4 |
| | Case C | 4 |
| | Case D | 4 |
| | Case F | 4 |
| | Case G | 4 |
| | Case E | 5 |
| II. | PRELIMINARY CONSULTATIONS | |
| | Case A | 23 |
| III. | MINUTES | 55 |
| IV. | OTHER BUSINESS | |
| | A. Commission Items | 55 |
| | B. Staff Items | 55 |

MR. KIRWAN: Any discussion? All in favor, please raise your right hand.

VOTE.

MR. KIRWAN: The motion passes unanimously. We want to thank you for coming out tonight, Ms. Wang, and wish you the best with your project as you go forward. Thank you.

The next item on our agenda this evening is a preliminary consultation for 7204 Cedar Avenue in Takoma Park. Do we have a Staff Report?

MR. KYNE: Yes, we do. Thank you. Again, 7204
Cedar Avenue, Takoma Park. This is an outstanding resource,
classical revival style, circa 1913. And the applicant is
here tonight with a proposal for a building addition and
other alterations. And I will start with a walk around the
property.

This is starting at the front. And this is actually from Tulip Avenue. And, as you can see, we have quite a large setback here. And this is, I'm angled sort of to the left front, and then just moving right around. This is across the street, again on Tulip Avenue, looking directly at the front at a right angle. And then across Cedar Avenue and moving up.

And then this is moving toward the rear. The rear yard. Back on the same side of the street as the house.

Looking across the rear yard at the rear neighbor. And then from the approximate rear right hand corner looking back at the house. And then, moving into the rear yard. This is looking straight on at the rear. Moving to the left, and when I say left and right in this instance, I'm referring to as viewed from the front. And this is the left side.

Toward the front of the house looking back along the left side into the rear. This is the right side. And then the front from the left corner.

And, this is the front dormer. And, as you may have noted, this is identical to the three dormers on the rear. Another view of the front dormers. This is just looking at the existing paver patio/driveway in the rear. And this is looking at an existing terracotta walkway that leads from the sidewalk to the house. This is on the right side of the house. And you may have also noted the terracotta sidewalk in the previous photos along Cedar Avenue on this side of the street.

This is an example of the chain link fence that is in the windows, all of the windows, currently, for security. On the front their actually installed on the inside. And then, on the sides and rear, they're installed on the outside. And just a quick view of some of the trees in the rear yard. I'm not sure if any of these are proposed to be impacted but, we want to make sure that we are taking this

2

3

4

5

7

8

9

1.0

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

into consideration.

And then the plans. The image on the screen in front of you is actually the existing site plan, which I inadvertently left out of the Staff Report. And the proposed site plan. Existing floor plans. Existing elevations. Then proposed floor plans and elevations.

The applicable guidelines in this case are the Takoma Park Historic District Guidelines, and the Secretary of Interior Standards for Rehabilitation. And, onto discussion. As you can see from the photographs, this is a one and a half story classic revival style outstanding And records indicate that the historic house was resource. constructed in 1913, replacing a Queen Anne style house that burned that same year. The house is located on a corner lot as noted, and as seen in the photographs, the front of the house faces Tulip Avenue, and the right side faces Cedar Avenue. And because of this, three of its elevations are clearly visible. That being the front, rear and right side. And the applicant has indicated that house experienced previous alterations including the replacement of the original slate roof with asphalt, and the replacement of the original clapboard siding on the dormers with asphalt shingles.

So, I'll just go into some detail for the proposed work. There is an extensive list of restoration work

including replacing the existing asphalt roof with slate.

Replacing the asphalt shingles on the dormers with wood clapboard siding to match the historic house. Repairing the exterior trim, siding and foundation walls as necessary.

Repairing the original windows and doors. Repairing the original shutters. Repairing the original porch columns.

Removing the chain link security coverings from the windows.

Regarding the additions, the proposal is to construct and one and a half story addition at the rear of the house which will be connected by a one-story hypen. And the proposed materials for the hypen and the addition include fiber cement siding, SDL wood windows, and standing seam metal roofing. Other work includes the construction of an attached deck at the left side of the proposed hypen and rear addition. The construction of a covered porch at the right side of the proposed hypen.

The construction of stone paver walkways at the right side of the property connecting to the proposed coverage porch. Construction of a stone wheelchair ramp at the right side of the property connecting to the proposed covered porch. The alteration of a small roof overhang at the rear/left side of the historic house. Changing the existing shed roof overhang to a gable roof overhang. And the conversion of an existing original window at the rear of the historic house to a French door.

2

3

5

7

8

10

11

12

13

14

15

16

17

18

19

20

21

22

24

25

Staff does fully support restoration and repair work finding that it will enhance the preservation of the But I do ask for your guidance regarding the resource. following, and for many of the things I'll list here, I did go in-depth in the Staff Report, so I won't repeat that verbatim here tonight, but hopefully, you've all had a chance to read that, and we can reference that if we need But, the questions that I, or the issues that I would seek your guidance on include the following: does the combined length of the proposed hypen and rear addition have the potential to detract from and/or overwhelm the historic house? Is the hypen approach appropriate at the subject property, or would a more traditional addition be more compatible with the surrounding district and streetscape? If the Commission finds that the hypen approach is appropriate in this case, should the materials and/or design be more clearly differentiated from the historic house, especially given the hypen's visibility from Cedar Avenue?

Would a more traditional addition be more appropriate, although it would require the alteration and/or removal of character defining features which are clearly visible from the right-of-way? I see any general guidance regarding the proposed materials, especially the standing seam metal roofing, and with regard to that, I would be looking for advice or more specifically, I'd be asking you

to give the applicant advice regarding the finish and the ridge details for the standing seam metal roof. Any guidance regarding the proposed conversion of the original window at the rear to a French door, noting the visibility from Cedar Avenue, and that the Guidelines for outstanding resources encourage the preservation of original windows and doors.

And, as I did state in the Staff Report, while the Guidelines do stress the importance of preserving the original windows and doors, if you find the hypen approach appropriate, and if you find the proposal appropriate, that window will not be visible from Cedar Avenue. Any guidance regarding the proposed alteration of the small roof overhang at the rear left side of the house. And Staff asks that the applicant provide any additional information regarding the existing overhang that may help the Commission in making their recommendations. Specifically regarding date and whether or not that is original.

And this was not in the Staff Report, but it has come to Staff's attention that this property may be in a sensitive area as the existing terracotta sidewalks along Cedar Avenue are the only remaining original sidewalks in the historic district. The City of Takoma Park is actively working with Historic Takoma to formulate a plan to protect these sidewalks. From the submitted site plan it is unclear

how the existing rear paver driveway is proposed to be altered, and whether these alterations have the potential to impact the adjacent sidewalks. Staff asks the applicant to clarify the proposal so that the Commission can ensure that the sidewalks will not be damaged. And, Staff also notes that there is an existing terracotta walkway. You saw that in the photos at the right side of the house. The walkway shares characteristics with the sidewalks along Cedar Avenue, but it's unclear if it is original and/or if it is proposed to be altered. Any information that can be provided regarding the walkway, and whether it is original, will help the Commission make informed recommendations.

And, so with that, I do recommend the applicant make any revisions based on the Historic Preservation

Commission's recommendations and return for a HAWP. And finally, I do want to show you some of the existing surrounding streetscape. This was just taken from Google street view. So this is basically from the subject property or the same side of the street as the subject property looking at the houses on the opposite side of the street of Cedar Avenue. So moving along. And then this is the existing property to the rear. and with that, I would be glad to take any questions you might have for me.

MR. KIRWAN: Michael, have we heard from Historic Takoma?

MR. KYNE: We haven't received any comments, no.

MR. KIRWAN: And we're kind of referring to this as a hypen, but it's not the typical hypen that we usually see and want to see, more of a connector. So, determining the use of that word versus just calling the whole thing an addition, I'm just curious. Is it just because it's physically in floor plan?

MR. KYNE: I think, in discussing with the applicant it was, in discussing with the applicants and determining why they were proposing this design, it was for the same reasons that we would often see a hypen proposed. It's to separate the addition from the historic house providing differentiation. As I noted in the Staff Report, this one has some major differences from what we usually see in a hypen. Hypens are usually very modest. They're not as long as the ones being proposed, and one of the main objectives in having a hypen at the rear is, of course, differentiation. But in making it more modest, it reduces the visibility from the oblique angles at the front.

Because you can see the rear clearly from Cedar Avenue, it may not be as appropriate in this case.

MR. KIRWAN: Okay. And the last question I had was, the side porch, deck, which is the side entrance into the house, it's rendered as if it, I mean, it kind of looks like it's brick. Have there been any indication of what the

material is for the side porch yet, or is that specified?

MR. KYNE: It hasn't been specified.

MR. KIRWAN: I mean, it has a lattice opening, so it almost look like it would be a light structure, like it would be a wood structure. We can ask the applicant.

MR. KYNE: Yes, let's ask the applicant because, as I noted, it hasn't been specified, so I'm not sure.

MR. KIRWAN: Okay. Any other questions?

MS. HEILER: You had mentioned the terracotta paving. Can you tell us again what would be the impact on the existing terracotta paving around the house?

MR. KYNE: Well again, one of my main reasons for mentioning that in the Staff Report tonight, I want the applicants to be aware that this information has come to light, and I want them to provide any information to you and to us as Staff, that might help us in making our future recommendations, because at this point it's unclear whether it will be impacted. I don't believe that it will, but I think it's just important that that's on the record, and that we can note that it will not be.

MS. VOIGT: Because, Michael, the existing walkway, there is an existing walkway that's adjacent to the terracotta, and the brick paving pad. None of this that connects to the terracotta is new? We can ask the applicant that too.

So -- yeah, let's ask the applicant. MR. KYNE: 1 But, if you look at the existing site plan, we can see the 2 terracotta walkway at the right side that I identified in 3 the photographs. And it looks to be in the same location in 4 the proposed, so I don't think that's being impacted. 5 it would be, I think, important for us to make that 6 determination tonight. 7 MR. KIRWAN: Any other questions? 8 Mr. Chairman, yes. Am I correct in MR. ARKIN: 9 assuming that the house is not occupied? 10 MR. KYNE: That is my understanding, yes. So, if 11 you want me to be a little more specific. Again, the 12 applicants can address this but, I believe the house is 13 currently unoccupied, but it's planned to be occupied by the 14 daughter of the present owners. 15 MR. ARKIN: And because it's been unoccupied was 16 the reason for installing the chain link? 17 MR. KYNE: That's my understanding, yes. 18 MR. ARKIN: Okay, thank you. 19 MR. KRIWAN: Any other questions for Staff? All 20 right, if not, we invite the applicant to please come 21 We can give you seven minutes for your testimony, 22 forward. and then we probably have some questions for you. 23 please state your name for the record before you speak. 24 MS. BRAITMAN: I'm Jackie Braitman. 25

2

3

4

5

6

7

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MR. KIRWAN: Is it on yet? Push the little square button and the light will come on. There you go.

MS. BRAITMAN: Jackie Braitman, Braitman Design I'm an agent for the owners. The answer to your question is that that chain link has been on for a very long The owners, current owner is the estate of the Augustines, and the heir is their daughter, who is my The Augustines have owned the house for 65 years, client. and Nancy, the daughter, the current owner, or to be owned, the heir, is very interested in restoring the house and preserving its character. The terracotta walkway is not being impacted. The existing terracotta walkway on the property, so the -- this is brick, and not historic. is terracotta and is the same terracotta as the sidewalk that is in the, on Cedar Avenue. There's no work that we would be proposing that would impact the terracotta.

We worked real hard to try to come up with a proposal that would meet the guidelines as we understood them. And so, because of the shape, if you could put the side view, the view from Cedar, because of the shape of the house and the shape of the roof, and the three back dormers, and the fact that it's on a corner and so visible, it was a challenge to come up with a program that would meet my client's needs as well as preserve that character. And it's, you know, in our view, a gable end addition would

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

19

20

21

22

23

25

destroy the character of the house viewed from Cedar, in particular.

So, I've always called it a connector rather than That connector is specifically meant to, so that from any view, you know, any oblique view or direct view from Cedar, you could always see the defining characteristics of the house. So that's one of the reasons for the length of that connector. You know, the reason I included the perspective view in addition to the elevations is because you can see that as you bring that addition closer to the house, we start to obscure the defining characteristics of the house. And, in addition, my client was very, I mean, from her perspective, she wants to preserve the interior character of the house too. And those upstairs rooms, what you don't appreciate from the pictures is that the house has 10 and 11 foot ceilings, including on the second floor. And the views from those dormers are quite dramatic, and we really don't want to block those So, that's one of the reasons for the long connector and for the way the addition is designed.

By my reading of the guidelines which talks about scale and character and form, it seems to me that we are in compliance with the guidelines, even though, if you look at the, you know, yes, the length along Cedar of the new construction is virtually identical to the historic massing.

They're both about 50 feet. But because of the way the connector and addition are developed, the scale, the massing is clearly subordinate to it. And I think that also the materials help define that difference. So the standing seam metal roof, which actually fairly typical in the neighborhood. One of the streets almost directly across, one of the houses almost directly across the street is a standing seam metal roof. I know that there is a house on Willow which was a standing seam metal roof, and you guys allowed them to remove that decaying roof a few years ago. But of that period, standing seam metal was typical in the construction there.

In addition, Cedar Avenue -- so, this is the site of the original Gilbert house. Gilbert is the gentleman who developed Takoma Park, and this was his house. The Queen Anne house that burned was his house. It was substantially more massive than the existing house. It was a Queen Anne, and the houses around it, the, absolutely, the pictures that Michael showed were directly across the street. But if you go one more block, there are some very large houses, and the lots on Cedar are larger than the average lots in Takoma Park. And most of those houses are larger. So, I don't think that the proposal is counter to the scale of that part of the neighborhood. Whereas, I'm on Park Avenue, a few blocks away, and it would be completely inappropriate on

Park. So, I think that's everything.

MR. KIRWAN: All right, great. Thank you for our testimony. I have a couple of questions. Coming back to the metal roof. The Commission has spent a long time looking at modern metal roofs compared to old historic metal roofs, and back in the day when you could still do painted tin, that was a great modern material to use --

MS. BRAITMAN: Right.

MR. KIRWAN: -- for a standing seam metal roof.
We've had concerns with the modern prefinished roof systems because they tend to have, because those joints are welded and seamed, they have heavy cap details, heavy venting details, heavy eave line details, so it'd be important as you begin to formalize exactly what material you want to use there to better understand, because we're making reference to historic metal roofs, but my guess is that's, you know, unless you're going to do a standing seam copper roof, which I'd be all in favor of, but that would be very expensive. You know, I think we'll struggle with prefinished metal roofs as we go forward.

MS. BRAITMAN: Okay.

MR. KIRWAN: And going back to a question I asked Staff, the side porch deck, is that --

MS. BRAITMAN: It's wood construction.

MR. KIRWAN: It's a wood deck, okay.

```
It is, it could be something
              MS. BRAITMAN:
1
   different, but it's currently proposed as wood.
2
             MR. KIRWAN: All right. Yes, Commissioner
3
4
   Firestone?
              MR. FIRESTONE: Okay, I'll try and kick this off,
5
   but one thing about the size of the lot and the proportions
6
   and size of this building, if I remember correctly, if you
7
   continue along Cedar towards Holly, the property adjacent to
8
    this one, doesn't it have basically have two houses on it?
9
              MS. BRAITMAN: As you continue along Tulip towards --
10
              MR. FIRESTONE: Tulip rather, yes, towards Holly.
11
              MS. BRAITMAN: You know, I'm, that's where
12
    Wolfgang lives and I'm not completely sure of where those
13
    property lines are.
14
              MR. FIRESTONE: But it's like one house is behind
15
    the other there?
16
              MS. BRAITMAN: Yes, that's right. Although, the
17
    house I think directly adjacent on Tulip has already entered
18
    into some kind of, I'm sure I'll use the term incorrectly,
19
    an historic preservation easement, so because of the size of
20
    the lot which guarantees that the lot is not subdivided.
2.1
    And my client intends to enter into the same type of
22
    agreement with this lot to further protect the house. But,
23
    you know, it is a huge lot.
              MR. FIRESTONE: Yeah, I mean, the point I was
25
```

trying to make is that, considering the size of the lot and considering the historic house that was there previously, I don't know that enlarging this house is unreasonable.

MS. BRAITMAN: Yeah, we're still at something like, you know, even with the addition, 15 percent lot coverage or something like that.

MR. FIRESTONE: The other question I had concerned the terracotta pavers. You said there shouldn't be any impact on them, but I think, I'm wondering is you are going to take some consideration for protecting or perhaps even removing and reinstalling them once construction starts?

MS. BRAITMAN: The plan was, is to, in the same way that we would do a tree protection plan, we would do a plan to protect those pavers on the lot, and also the pavers that we would be crossing as we bring construction equipment into the site. They actually are in pretty good, the sidewalk on the property is in quite good shape, and my worry would be that in uninstalling them, we would damage. them. And so, my current plan would be to protect them rather than to uninstall them and reinstall them.

MR. KIRWAN: Just to add onto that. I think it'll be important ultimately for us to see exactly where that existing walkway ends and how you're connecting into it. In the drawings it looks seamlessly, they all look like they're one material. So, at some point, we're going to want to see

the detail of --

MS. BRAITMAN: There's actually a step, right at the, right at where the current parking pad is, there's a, it's really a short, really tiny retaining wall, and it's a step, and that's where the brick starts and the pavers end.

MR. KIRWAN: Well, just make that very clear in the drawings. What material you're using compared to the new material will be important for us to see as you go forward. Commissioner Voigt, you had a question?

MS. VOIGT: Hi. Well, thank you very much for taking care of this house. I think it's a beautiful house.

MS. BRAITMAN: Isn't it a great house? Yeah.

MS. VOIGT: Yeah, I think so. It could be the lot too, it's really pretty. But, my question, so that the original house is one and a half stories, and the addition is one and a half stories, but because, you're saying because of this hypen or because of this separator, that you won't get the feeling. And I think the grade of the property --

MS. BRAITMAN: It's slight. The front grade is pretty steep, but in the back there's a little bit of grade there, but not a whole lot. But it does set it down a little bit. The addition is not actually one and a half stories. It's a vaulted ceiling, but the roofs line is the same as, the same slope as the historic roofline, and the

2

3

4

5

6

7

8

9

10

11

12

13

14

15

1.6

17

18

19

20

21

22

23

24

windows are the same. So it appears to be a one and a half story addition. It's really a one-story addition.

MS. VOIGT: Okay.

MR. KIRWAN: Any other questions?

MS. HEILER: Yes. I'm assuming that the foundation of the connector there is not ever visible because of the steps. Does the foundation of the addition, whatever part is visible, and the wall by the wheelchair ramp, does that match the foundation of the house?

This is one of the curious MS. BRAITMAN: No. It's a stone foundation. I mean it's, you'll love to walk into this basement. You know, the base of the stone foundation walls are about 30 inches wide, you know, and they taper up to, you know, 15 inches or so. What doesn't make sense is that that's not typical of construction for a house in 1913. So we believe that at least some of those stone walls were original foundation walls of the Gilbert house. However, one of the foundation, one of them is no longer, it's in the middle of the house and is no longer supporting. We suspect it was the original exterior wall of the Gilbert house, and then they matched that stone foundation in building a portion of the new house that goes That's supposition, because we can't find beyond that. plans on it. But, I don't, we couldn't match that. limestone, it's a pretty soft stone, which is one of the

25

reasons we're doing as little as possible to that stone 1 foundation. We were planning on doing poured concrete for 2 the foundation walls for the connector, and for the 3 addition. But they would not be visible, mostly because of 4 that, of the wheelchair ramp and the porch. 5 MS. BARNES: Several questions. I share my 6 colleagues views that it looks like a very, very wonderful 7 house and it's great to know that it's going to be rehabbed. 8 Really, a slate roof or a fake slate roof? 9 MS. BRAITMAN: No. My client is committed to this 10 house, and she wants to install a true fake, a true fake, a 11 12 true slate roof. Yeah. MS. BARNES: Which will make the issue of any 13 metal seam roof become even more important, I think, in 14 terms of how it corresponds. I wanted to ask about the 15 lights in the doorway in the connector. You have side 16 lights? At least it appears that. 17 MS. BREITMAN: Right. 18 MS. BARNES: And, I --19 MS. BRAITMAN: Because the original house has side 20 lights. 21 MS. BARNES: I see. 22 So if you look at the, well there's MS. BRAITMAN: 23

not a good picture of it in any of the material you've seen.

The front porch that faces Tulip has two glass doors with

21

22

23

24

25

side lights. So, that's the, you know, I actually had not 1 originally drawn it that way, but she wanted the skylights 2 to coordinate with the original. 3 MS. BARNES: Okay. And there seems to be a 4 pergola over the deck? 5 MS. BRAITMAN: Yeah. 6 Okay. 7 MS. BARNES: MS. BRAITMAN Which is not visible from any place, 8 9 but yes. MS. BARNES: And then, I wanted to ask you, given 10 the size of the lot and everything, if you had given 11 consideration to having the connector and the addition 12 slightly broader? It would appear that you have doorways 13 out onto the deck. 14 MS. BRAITMAN: Right. 15 MS. BARNES: And I just wondered if you had given 16 any thought to that all being a little broader. 17 suppose, comes back to the question of a more standard 18 addition rather than a connector with --19

MS. BRAITMAN: One of the, as is true with any house of this era, one of the drawbacks for today's lifestyle is no indoor/outdoor connection. And, except for the front porch, although the chain link kind of destroys that right at the moment. But, Mrs. Augustine, was a gardener, and while the garden beds haven't been maintained

2

3

4

5

6

7

8

9

10

11

13

14

15

16

17

18

19

20

21

well in the last 10 or 15 years, it's a wonderfully landscaped lot. And Nancy very much wants to restore the garden beds and improve them, and get an indoor/outdoor connection. And so one of the reasons we did design it the way we did, was so that while preserving completely the historic view, we could create good light and garden views from the kitchen, and from the new master bedroom. that's the reason we did it the way we did it, and if we brought it farther over, we would, it would make it harder to create that connection. MS. BARNES: And because you've mentioned the 12

garden beds and the lot, are there any trees that would be impacted by your design?

Thankfully, no. I'm not quite sure MS. BRAITMAN: why they didn't allow any mature trees to grow that close to the house in the back, but no.

MS. BARNES: Because they were wise.

Could be, but there are -- and MS. BRAITMAN: unfortunately, a lot, they've lost a lost of the mature oaks that were in that area. And we've already started planting more trees.

> Thank you. MS. BARNES:

MR. KIRWAN: Any other questions? Do you have question? Okay.

MR. ARKIN: I guess what I'm asking are questions.

22

23

24

25

1.6

1.8

But I'll begin by saying that I think the connector as you've described it is, really does succeed in drawing attention to the features of the main house, of the old historic house, and limiting, rather than obscuring them. I am concerned about two things that sort of jumped out at me, and I wonder if you could tell me why you plan on doing that. On the connector, looking at Circle 19, that elevation, the Cedar Avenue elevation, why do you have two windows with the shutters butting? You don't seem to have that anywhere else on the property, and I'm wondering why you chose those option if there is some other option that wouldn't stand out so much.

MS. BRAITMAN: May I ask whether the question is about the shutters or about the windows or both?

MR. ARKIN Well, both, really. You have on the original house the conventional, the conventional windows on the first floor seem to be shuttered, and you have the showier windows in the gable.

MR. KIRWAN: Commissioner Arkin, can I make a suggestion?

MR. ARKIN: Yeah.

MR. KIRWAN: That you simply state what you think is the appropriate thing to do in your comments during deliberation as opposed to asking a rhetorical, I mean not a rhetorical, but a sort of an open ended question that -- I

think you should state what your opinion is on those windows and your comments.

MR. ARKIN: I don't have an answer. That's why I'm posing it as a question.

MR. KIRWAWN: Then maybe if you don't have the answer --

MR. ARKIN: So, I don't have the answer. And so I'm asking.

MR. KIRWAN: Somebody else might pick it up, or it's maybe not a question to ask.

MR. ARKIN: And then my other question has to do with the standing seam roof. And it's quite a lot of roof you're adding to the historic house, and with the colors that you show on your renderings, it tends to, from that perspective it seems to overwhelm the roof, and I was, the slate roof, and I was wondering if there's some way you could perhaps, maybe, mute the color so it would not be so striking?

MS. BRAITMAN: Absolutely. And, you know, as I'm sitting here, one of the, you know, and thinking about the problems with trying to do anything with the metal that would not cause problems in terms of modernity, inclined to go to talk to my client about a copper roof on the connector, standing seam copper roof on the connector and a shingle roof, you know, an asphalt shingle roof on the

addition, which I think would probably solve the problem that you're raising as well as the issue of the materials.

MR. KIRWAN: Any other questions for the applicant?

MS. BRAITMAN: Can I ask a question?

MR. KIRWAN: Sure.

MS. BRAITMAN: One of the things that we've proposed in this is metal railings. And I haven't heard any concern about that. I wonder if there is any concern about that?

MR. KIRWAN: I, for one, don't. I think they're most appropriate when they're fully exposed to the weather like this. Wood and, you know, they're getting better and better with the synthetic wood railings, but they often still look a little fake, so I don't have a personal issue with metal railings when they're out and exposed like this. I think you're seeing heads nodding in agreement with that.

I'll just kick off with my comments. I do support the addition, an addition to this house, and I think the general configuration of what you've done, I find to be something that is an appropriate response to this resource for all the reasons you stated. I think it -- I do appreciate what you're doing with the hypen with regards to the interior views from the back of the house out into the garden. So I think that can be a good response.

2

3

5

6

7

8

10

11

12

13

14

15

16

17

1.8

19

20

21

22

23

24

25

I think my biggest issue that I kind of raised at the Staff report was, the hypen is not reading like a hypen. And I think it really should. It should. And I think more to the point with the introduction of a copper roof, that's going to differentiate it even more from the other two I think the hypen should read like some sort of volumes. enclosed glass gallery or something like that, so it really does read as a distinct thing separating these two pieces. And you have an opportunity, within the hypen you're actually showing us the back side of the hypen. side of the hypen is what's facing the garden, and I think, I would consider flipping that plan. That gives you the opportunity to have this very glassy long hallway that leads from the bedroom back to the rest of the house. And puts those -- I'm not going to take comments or questions. is our thoughts that you'll have to take back to Staff and consider.

So, that's my kind of view on this hypen, is it's right now looking too much like both the addition and the original resource, and it really needs to read as a distinct piece on its own. As you have already kind of alluded to, I think the roofs, and I don't think the roof of the hypen necessarily has to be copper. I think it could be an asphalt shingle roof if the roof of the addition is an asphalt shingle roof. They could all be slate. But I think

1.6

metal, I'm concerned about metal for the all the reasons I posed in my question. Standing seam copper would be great, and I think that would be an acceptable solution for the hypen, but again, it kind of leads to the hypen wanting to read more like a hypen.

With regards to the ramp, I do have concerns about the curvilinear shape of it. I totally agree the ramp is something completely appropriate to request, especially for long term residents in the house. But I think you actually ought to push the ramp up against the house and have the planting bed be what's facing the street, so that helps conceal the ramp and its exposure to the street view, and puts the planting bed that allows the plants to grow and conceal the railing that's coming down. I think the ramp's a little bit too much of a sculptural, calling too much attention to itself as some sort of sculptural thing that doesn't fit with the style of the house. I think it could be more rectilinear and concealed by the planters.

The railing details. You brought up the railings. The railing details will be important. Staff has lots of guidelines on things that we've approved before with regard to railings, so I would definitely get information from them on what you finally present to us. And with regard to the foundation, I'm a little, I was a little paused by the concrete foundation comment. I think actually wherever the

foundation is exposed, especially on the rear elevation, because there's no decks and things concealing it, it will be visible from public space. You might want to consider putting a parge coat over it that can be painted to match the stone foundation. Similarly, with the planting beds, I'm a little hesitant with stone on the ramp and the planting beds, so you may want to consider making a parged wall surface your sort of standard for the foundations of the addition to again, make those distinct from the stone foundation of the resource.

And lastly, Staff, I'm sure, will advise you, we're going to want to see a lot of information and specificity on the types of windows and doors you'll be using for the project, the muntin details, all that kind of stuff that they can sort of direct you to what we've find appropriate. You know, but I think a lot of the things I'm talking about are detail tweaks. I'm not talking about major changes to this project, and I think it's really just sort of tweaking it to get it there. But I think it's very close right now. It's generally headed in a great direction, and I appreciate your work with your client to do a sensitive addition to this resource.

MS. HEILER: I agree with the Chairman, that I think this is the right approach to putting an addition on this house. And with his suggestion that the better side of

the hypen faces the garden, and you might want to use that for the side that's most visible. I disagree with the whole idea of having three different roof materials, the slate on the house, and using wood on the or even asphalt shingle on the addition, and copper on the hypen. I think, you know, the state of the art right now with standing seam metal roofs that are prefinished has improved enormously in the last couple of years, and I think that you can come up with quite an appropriate standing seam metal roof that's what a matte finish that you could use on both the hypen and the addition. I would certainly not put an asphalt shingle roof on the addition with slate on the house. The addition does defer to the house, but not that much.

I fully understand what you're doing with this very long connector in preserving the view from the dormers on the house. I think though that the connector is disconcertingly long. If there is any way to reduce that size, and one way of doing it is as the Chairman suggested, making it glass. Otherwise, any way that you can reduce the length of it, I think improves the look of the total addition. Moving that at the addition closer to the house, I think benefits the entire structure. I think you've done a masterful job in repeating many of the elements of the house, the design elements in the addition and simplifying them somewhat. I think that's completely successful. And,

I agree with the notion of making the visible parts of the foundation, parging them or doing something to prevent that concrete from the contrast that it would provide with the house. And, in general, I don't like metal railings, but sometimes I think you have to do it. I hate to see a metal railing on a house that's this good but, you know, you're the architect.

MS. BARNES: I have to say that I appreciate the project you've brought to us. I do not share quite the concerns of other Commissioners about the length of the connector. I think that you could distinguish it a bit by removing the shutters on the windows and altering them slightly. And I find that the door with the lights, which is sympathetic to the main structure, perhaps is mimicking it too much and then not giving us the differentiation that we want. And I think there's always this tension between differentiation and sympathetic additions, and I appreciate what I think you've done in terms of being sympathetic.

I feel that the Chair's suggestion about the ramp is a very excellent one. And, I also support the suggestions about parging if you're using the concrete. I think that would work out better. And I am glad to hear that you will be taking steps to protect the terracotta walkways.

MR. FIRESTONE: I'm not going to add too much to

1.8

that I think that this is a very thoughtful and sensitive project that you're undertaking and your concerns about the original house, and doing, you know, keeping that as the primary focus of the area so that it will be visible and they'll be minimal alteration to is, and preserving it, is admirable and I'm looking forward to seeing some finished plans on this.

MR. SUTTON: Hi. I like the building a lot. I've been very interested in this type of Colonial revival, Greek revival, and I think it's preserving the front of the house is fantastic. I would like to see the connector reduced some. If you need more space, you might be able to put it in the rear addition. And so I agree that, I don't feel strongly one way or the other about the roof on the addition.

The one thing I would like to see that, is the Palladian window on the addition. Palladian windows, look like they match the ones on the historic side, and I would like to see a little bit of differentiation. And the reason I say that, the other windows on the addition are different than the windows on the historic house in design, and I'd like to see, I think, you know, the shutters and the windows themselves are a little bit different, and I'd like to see, personally, but I'm not going to fall on my sword over it,

3

5

6

7

8

9

1.0

11

12

13

14

15

16

17

18

19

20

21

22

23

24

maybe some modification of the Palladian windows.

MR. ARKIN: I don't have very much to add. I do think that the suggestion of shortening the connector is worth looking at. Even shortening it a little bit would If you decide not to reverse the make it stand out less. inside treatment of the connector, then I would suggest that you remove the shutters on the connector. I think they're They're not on the other side of the unnecessary. connector. And, be careful where you're using windows that I also think that the comment about the curvilinear ramp is an excellent comment. I think having a ramp like this is wonderful if the objective is to keep the house comfortable perhaps for aging, for the occupant to age in place. But the curvilinear treatment does stand out.

And similarly, I agree with the prior speaker that the Palladian window should repeat the suggestion or the sense of the window in the historic house, but not duplicate it exactly.

MS. VOIGT: Okay, well I'll just wrap it up. I think this is a great project. I really appreciate your restoration work on this house. I think it's a beautiful house. The size of the lot, I don't have a problem with the length of the connector. I actually think it works pretty well. I mean, when I looked through at a lot of different hypens, because I also thought that a hypen should be more

differentiated. But I went and looked at materials, and many of the hypens kind of do resemble the addition. So, I think this works really well. I think that the Commissioners had a lot of great details that I won't repeat, but I think they will really work well. So, it's all good. Thank you.

MR. FIRESTONE: Mr. Chairman, can I add one more comment?

MR. KIRWAN: Yes.

MR. FIRESTONE: I'm in favor of a longer hypen or connector, or whatever we want to call it, because I think, as you stated, one of the reasons for doing that is to preserve the views and appearance of the original house, and that if you make that shorter or larger, or bring the addition closer in, it will start to obscure the main house.

MR. KIRWAN: So I think overall you heard some pretty consistent comments. And again, I think it really is the details. I think the general approach seems to be very strong and we're very supportive of it. You should consult with Staff, but I think many of things are easily solvable, and we hope to see you when you come in for a historic area work permit.

MS. BRAITMAN: Thank you.

MR. KIRWAN: Thank you very much for coming in tonight. Okay. The next item on our agenda are the meeting

minutes. Do we have any that we should approve tonight, as a closing to the old way of doing? 2 MR. ESTES: Mr. Chairman, no, we have no meetings 3 to approve tonight. 4 MR. KIRWAN: Okay, very good. And I do not 5 believe we need a volunteer for tonight, so we'll move on to Commission items. None? Then we'll have a few Staff items 7 to discuss. 8 We looked at two Staff items in MR. KYNE: Yes. the worksession. One for 5912 Cedar Parkway, Chevy Chase, 10 and that was approved. And then we looked at a revision at 11 7400 Wisconsin Avenue, Bethesda, and that was not approved. 12 MR. KIRWAN: That's correct. We agree with those 13 conclusions. And with that, we're adjourned. 14 (Whereupon, at 8:59 p.m., the meeting was 15 adjourned.) 16 17 18 19 20 21 22 23 24 25