## $\frac{EXPEDITED}{MONTGOMERY\ COUNTY\ HISTORIC\ PRESERVATION\ COMMISSION}{STAFF\ REPORT}$

Address: 16501 Norwood Rd., Sandy Spring Meeting Date: 8/18/2021

**Resource:** Individually Listed Master Plan Site **Report Date:** 8/11/2021

Woodlawn


**Applicant:** Mongtomery Parks **Public Notice:** 8/4//2021

**Review:** HAWP **Tax Credit:** n/a

**Permit No.:** 959316 **Staff:** Dan Bruechert

**Proposal:** Partial Demolition

#### **STAFF RECOMMENDATION**



#### **ARCHITECTURAL DESCRIPTION**

SIGNIFICANCE: Individually Listed Master Plan Site (Woodlawn #28/14)

STYLE: Federal

DATE: 1800 w/ later additions



Figure 1: The designated Woodlawn site includes several outbuildings covering more than 20 acres.

From *Places from the Past*:

"One of the finest estates in the county dating from the early 1800s, Woodlawn includes a handsome brick mansion and a superb collection of outbuildings in a beautifully landscaped setting. The house was probably built either by Richard Thomas or his grandson, Samuel Jr., recipient of the property upon Richard's death in 1806. According to tradition, Samuel and Anna Thomas operated a Quaker boarding school at Woodlawn before 1819. Dr. Willima Palmer purchased the estate in 1825, moving to Montgomery County from Pennsylvania. Palmer was a founder of the Montgomery Mutual Fire Insurance Company.

The symmetrical front façade of the five-bay Federal style house features Flemish bond brick and a fanlight transom over the central entrance. William Plamer expanded the house with a kitchen wing. In 1881, his son, Benjamin Palmer, added the northwest wing. In 1832, master stonemason Issac Holland built an exception three-story stone bank barn with four large round arched openings on the basement level. The Property also includes a combination dairy and smokehouse of stone, a log house, and board and batten tenant house. Grounds include significant mature trees, including an Osage Orange with 11-foot trunk circumference, 100-foot high American Linden, and a 1999 County Champion Norway Spruce. The property, owned by the Maryland-National Capital Park and Planning Commission, is open to the public on special occasions."



Figure 2: The non-historic mudroom is covered by the red roof in the northeast corner of the house.

#### **PROPOSAL**

The applicant proposes to demolish a c.1980 mudroom in the northeast corner of the house. This non-historic portion of the house has suffered significant insect and water damage, and the walls have begun to shift on its concrete foundation and the room is not a safe space. The applicant proposes to remove the existing frame walls and, depending on the condition, may retain the shed roof.

#### **APPLICABLE GUIDELINES**

#### Policy On Use of Expedited Staff Reports for Simple HAWP Cases

IV. The Expedited Staff Report format may be used on the following type of cases:

- 2. Modifications to a property, which do not significantly alter its visual character.
- 4. Removal of accessory building that are not original to the site or otherwise historically significant.

#### Montgomery County Code; Chapter 24A-8

- (b) The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to ensure conformity with the purposes and requirements of this chapter, if it finds that:
  - (1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or
  - (2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter; or
  - (4) The proposal is necessary in order that unsafe conditions or health hazards be remedied;

#### Secretary of Interior's Standards for Rehabilitation

The Secretary of the Interior defines rehabilitation as "the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features, which convey its historical, cultural, or architectural values." The relevant *Standards* are as follows:

- 2. The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.
- 9. New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportions, and massing to protect the integrity of the property and its environment.
- 10. New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

#### STAFF RECOMMENDATION


Staff recommends that the Commission <u>approve</u> the HAWP application under the Criteria for Issuance in Chapter 24A-8(b)(1) and (2) having found that the proposal will not substantially alter the exterior features of the historic resource and is compatible in character with the district and the purposes of Chapter 24A;

and with the Secretary of the Interior's Standards for Rehabilitation #2, 9, and 10;

and with the general condition that the applicant will obtain all other applicable Montgomery County or local government agency permits. After the issuance of these permits, the applicant must contact this Historic Preservation Office if any changes to the approved plan are made;

and with the general condition that final project design details, not specifically delineated by the Commission, shall be approved by HPC staff or brought back to the Commission as a revised HAWP application at staff's discretion;

and with the general condition that the applicant shall notify the Historic Preservation Staff if they propose to make **any alterations** to the approved plans. Once the work is completed the applicant will contact the staff person assigned to this application at 301-563-3400 or <a href="mailto:dan.bruechert@montgomeryplanning.org">dan.bruechert@montgomeryplanning.org</a> to schedule a follow-up site visit. visit.





### DATE ASSIGNED\_\_ **APPLICATION FOR** HISTORIC AREA WORK PERMIT HISTORIC PRESERVATION COMMISSION 301.563.3400

#### **APPLICANT:**

Name:	E-mail: _	E-mail:			
Address:	City:	Zip:			
Daytime Phone:	Tax Acc	Tax Account No.:			
AGENT/CONTACT (if applica	ble):				
Name:	E-mail: _				
Address:	City:	Zip:			
Daytime Phone:	Contrac	ctor Registration No.:			
LOCATION OF BUILDING/PR	EMISE: MIHP # of Historic Propert	ty			
map of the easement, and do Are other Planning and/or He	cumentation from the Easement F aring Examiner Approvals /Review ecord Plat, etc.?) If YES, include info	vs Required as part of this Application?			
	Subdivision: l				
for proposed work are sub be accepted for review. Che New Construction Addition Demolition Grading/Excavation I hereby certify that I have th and accurate and that the co	mitted with this application. Indeed all that apply:  Deck/Porch Fence Hardscape/Landscape Roof e authority to make the foregoing a	overify that all supporting items complete Applications will not Shed/Garage/Accessory Structure Solar Tree removal/planting Window/Door Other: application, that the application is correct reviewed and approved by all necessary dition for the issuance of this permit.			

Description of Property: Please describe the building and surrounding environment. Include information on significant structures landscape features, or other significant features of the property:
Description of Work Proposed: Please give an overview of the work to be undertaken:

Work Item 1:	
Description of Current Condition:	Proposed Work:
Work Item 2:	
Description of Current Condition:	Proposed Work:
Work Item 3:	
Description of Current Condition:	Proposed Work:

#### Adjacent and Confronting Properties:

Silver Spring, MD 20905

211 Ednor Road

121 Ednor Road

16425 Snowdens Woods Lane

111 Ednor Road

109 Ednor Road

105 Ednor Road

1021 Norwood Road

16650 Norwood Road

16923 Norwood Road

16500 Alexander Manor Drive

# HISTORIC AREA WORK PERMIT CHECKLIST OF APPLICATION REQUIREMENTS

	Required Attachments						
Proposed Work	I. Written Description	2. Site Plan	3. Plans/ Elevations	4. Material Specifications	5. Photographs	6. Tree Survey	7. Property Owner Addresses
New Construction	*	*	*	*	*	*	*
Additions/ Alterations	*	*	*	*	*	*	*
Demolition	*	*	*		*		*
Deck/Porch	*	*	*	*	*	*	*
Fence/Wall	*	*	*	*	*	*	*
Driveway/ Parking Area	*	*		*	*	*	*
Grading/Exc avation/Land scaing	*	*		*	*	*	*
Tree Removal	*	*		*	*	*	*
Siding/ Roof Changes	*	*	*	*	*		*
Window/ Door Changes	*	*	*	*	*		*
Masonry Repair/ Repoint	*	*	*	*	*		*
Signs	*	*	*	*	*		*



#### DEPARTMENT OF PERMITTING SERVICES

Marc Elrich
County Executive

Mitra Pedoeem Director

#### HISTORIC AREA WORK PERMIT APPLICATION

Application Date: 7/9/2021

Application No: 959316

AP Type: HISTORIC Customer No: 1363287

#### **Comments**

Mudroom needs to be demolished ASAP due to suddenly collapsing walls. Decision about whether to rebuild will be made later.

#### Affidavit Acknowledgement

The Contractor is the Primary applicant authorized by the property owner This application does not violate any covenants and deed restrictions

#### **Primary Applicant Information**

Address 16501 NORWOOD RD SANDY SPRING, MD 20860

Othercontact Mueller (Primary)

#### **Historic Area Work Permit Details**

Work Type DEMO

Scope of Work Demolish non-historic walls of non-historic mudroom addition due to severely deteriorated condition.




Woodlawn, front (south) elevation. Mudroom is not visible from this elevation.



2011 photo of East elevation showing frame mudroom on the right.




Rear (north) elevation showing frame mudroom on the left.



Mudroom is the unnumbered frame space at the upper right-hand corner of the floor plan.



East elevation of mudroom. Note deterioration at sill. Wall is nearly detached. Also note door is no longer plumb. The good condition of the siding belies the deteriorated structural condition of the wall.



Interior of mudroom showing east wall (right) with separation of wall at foundation.



Bowing and separation of north wall under picture window.



Walls separating from ceiling. These are not just cracks in the paint.



Historic photo from HPO slide collection. Image is labeled "2/1989" but must be older as the trellis which runs in front of the mud room and which was built in 1986 is not shown in the photo. Photo appears to show rear porch being enclosed.