	STAFF REPORT		
Address:	4101 Manor Rd., Chevy Chase	Meeting Date:	10/11/2023
<b>Resource:</b>	Individually Listed Master Plan Site (Hayes Manor #35/10)	Report Date:	10/4/2023
Applicant:	Howard Hughes Medical Institute (HHMI) Susan Pommerer, Architect	Public Notice:	9/27/2023
<b>Review:</b>	HAWP	Staff:	Dan Bruechert
Permit No.:	1001591 REVISION	Tax Credit:	Partial
Proposal:	Revisions To Previously Approved HAWP for Grading Alterations and updates to limits of dis Investigations		•

#### MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION STAFF REPORT

# **STAFF RECOMMENDATION**

Staff recommends the HPC **approve** the revisions to the HAWP and reminds the application of its responsibilities under condition #4 from the original HAWP approval in addition to other conditions of approval that remain in force and are not extinguished by the approval of this revision:

4. After consulting with staff, the applicant may proceed with any additional proposed archaeological fieldwork, if necessary. Once the fieldwork is complete, and prior to approval of the building permit, the applicant shall complete a technical report that documents the archaeological findings and submit the report to Staff.

### **ARCHITECTURAL DESCRIPTION**

SIGNIFICANCE:	Individually Listed Master Plan Site #35/10 Hayes Manor
STYLE:	Georgian
DATE:	1767 w/ later alterations



Figure 1: The Master Plan Site is located in the southwest corner of the Howard Hughes Medical Institute Campus.

#### From *Places from the Past*:

"One of the earliest and best-preserved examples of Georgian style architecture in the region, Hayes Manor is characterized by refined detail and high-quality workmanship. The residence was built about 1767 for Reverend Alexander Williamson, rector of Prince George's Paris of the Anglican Church, one of the richest parishes in the Maryland colony. Williamson named the property Hayes after the home of William Pitt, Prime Minister of Britain. With the separation of church and state after the revolution, the Anglican Church was no longer Maryland's established church and Willamson's tax-supported salary ceased. He retreated to Hayes Manor until his death in 1792.

The brick residence has two front facades, customary for high-style Georgian houses. Both facades have expensive all-header bond brick. The south entrance opens into a front stair hall in a double pile plan. East and west wings were built in 1899 and 1908, designed by architect Walter Peter in a compatible style. Notable landscape features include a formal boxwood garden, evidence of a bowling green, and the Dunlop family cemetery. For 173 years, the Dunlop family owned Hayes Manor, beginning with Scottish immigrant James Dunlop who owned the estate from 1792."

### BACKGROUND

On December 7, 2022, the HPC approved a HAWP by consent for a comprehensive rehabilitation of the historic Hayes Manor that included alterations to the historic building and several non-historic additions, site work, and tree removals.<sup>1</sup>

The HPC approved a revision to the approved HAWP on August 16, 2023 that included a new roof

<sup>1</sup> The Staff Report for the 2022 HAWP is available here: <u>https://montgomeryplanning.org/wp-content/uploads/2022/11/II.F-4101-Manor-Road-Chevy-Chase-1001591.pdf</u>.

walkway and entrance, revisions to the garage, and other minor alterations.<sup>2</sup> The August revisions were approved by consent.

## PROPOSAL

The applicant proposes to revise the previously approved south drive, the site's stormwater management plan, and proposes to remove seven additional trees. The applicant has also provided updates on the required archaeological investigations at the site.

## APPLICABLE GUIDELINES

Proposed alterations to individual Master Plan Sites are reviewed under Montgomery County Code Chapter 24A (Chapter 24A) and the *Secretary of the Interior's Standards for Rehabilitation*. Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features, which convey its historical, cultural, or architectural values.

#### Montgomery County Code; Chapter 24A-8

- (a) The commission shall instruct the director to deny a permit if it finds, based on the evidence and information presented to or before the commission that the alteration for which the permit is sought would be inappropriate, inconsistent with or detrimental to the preservation, enhancement or ultimate protection of the historic site or historic resource within an historic district, and to the purposes of this chapter.
- (b) The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to ensure conformity with the purposes and requirements of this chapter, if it finds that:
  - (1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or
  - (2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter; or
  - (3) The proposal would enhance or aid in the protection, preservation and public or private utilization of the historic site or historic resource located within an historic district in a manner compatible with the historical, archeological, architectural or cultural value of the historic site or historic district in which an historic resource is located; or
  - (4) The proposal is necessary in order that unsafe conditions or health hazards be remedied; or
  - (5) The proposal is necessary in order that the owner of the subject property not be deprived of reasonable use of the property or suffer undue hardship; or

<sup>&</sup>lt;sup>2</sup> The Staff Report for the August 16, 2023 HAWP revisions are available here: <u>https://montgomeryplanning.org/wp-content/uploads/2023/08/I.J-4101-Manor-Road-Chevy-Chase-1001591-REVISION.pdf</u>.

(6) In balancing the interests of the public in preserving the historic site or historic resource located within an historic district, with the interests of the public from the use and benefit of the alternative proposal, the general public welfare is better served by granting the permit.

#### Secretary of the Interior's Standards for Rehabilitation

- 2. The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.
- 9. New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportions, and massing to protect the integrity of the property and its environment.
- 10. New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

#### STAFF DISCUSSION

The proposed rehabilitation of Hayes Manor will convert the vacant mansion into a residence for the president of the Howard Hughes Medical Institute (HHMI), but will also be used to host social and business functions. The proposed revisions include redesigning the south drive in front of the house, revising the stormwater management plan, and removing seven additional trees from the site that were not identified in the original HAWP. Staff finds the proposed revisions will not have a significant impact on the character of the site and recommends the HPC approve the plan with the condition that the applicant continues to consult with the HP Staff Archaeologist to satisfy the requirements of condition #4 from the original HAWP approval which states, "After consulting with staff, the applicant may proceed with any additional proposed archaeological fieldwork, if necessary. Once the fieldwork is complete, and prior to approval of the building permit, the applicant shall complete a technical report that documents the archaeological findings and submit the report to Staff.".

Much of the archaeological investigation on the site has been completed and a draft report has been submitted to Staff. Based on Staff's review of this document, Staff will require that the final report include a discussion of the likely domestic structure to the southwest of the manor house and the history of enslavement at Hayes Manor.

The abstract for the draft archaeological investigation report includes the following findings,

"In October 2022, Gray & Pape, Inc. conducted an archaeological survey of the limits of disturbance for the project. The results of this work led to additional investigations, specifically four areas where archaeologists believed there to be the potential for historic deposits related to the occupation and evolution of the property. These included the area adjacent to the southern porch, the southwestern portion of the limits of disturbance, the eastern portion of the limits of disturbance within the south yard, and an area in the north yard. Follow up investigations performed by Gray & Pape were conducted in December 2022 and consisted of the excavation of test units, additional shovel test pits, metal detection, and the sampling of two features. The four selected locations identified during the initial survey conducted in October 2022 were examined under this effort.

Of the four locations investigated as part of this work, the southwest yard provided the most information on the history of the property. A total of two features were identified in this area, one of which is being interpreted as a building pier. The artifact assemblage indicated this building served a domestic purpose and dates to the early nineteenth century. Due to the sensitivity of this area and the potential for additional discrete archaeological deposits not located during the archaeological testing, this area should be avoided during construction as well as being noted on property maps for potential future developments.

The remaining three locations failed to produce archaeological features related to the history of the property, due to twentieth-century modifications to the property or lack of additional data within the limits of disturbance. The northern location identified a 30 x 27-foot (9.1 x 8.2-meter) concrete drainage feature. While historic materials contemporaneous with the occupation for the property were recovered, all were from disturbed soils related to the construction of the drainage feature. No additional work is recommended for this area. The second location was along the eastern edge of the steps at the southern entrance. Excavations here revealed that extensive ground disturbance has taken place in the recent past for the installation of a waterproofing membrane and speed strip fasteners along the landing and the steps. No additional work is recommended for this area.

Lastly, the testing in the southeast yard consisted of the excavation of two test units to explore a potential concentration of nails found during metal detection efforts. While architectural debris and domestic artifacts were recovered from these two test units, no other evidence to support a building once stood in this location was recovered. Additionally, an intensive metal detector survey of the south yard recovered a high density of nails, indicating the yard was possibly used as workspace during renovations of the building. No additional work is recommended for this area.

In sum, while the property has been subjected to various levels of ground disturbance, there nonetheless remains the potential for additional deposits related to the occupation, use, and evolution of the property. These deposits and features could add significant data to our understanding of the early and evolved landscape of this property as well as those who lived and worked this land."

#### South Drive Revision and Archaeological Investigations

The approved site plan at Hayes Manor included expanding the existing gravel turnaround to the southwest of the house. Archaeological investigations, required as a condition to the HAWP's approval, in this area revealed evidence of a partial building foundation consistent with a building occupied by enslaved laborers. Staff provided two recommendations to the applicant, either conduct a full archaeological excavation of this area or modify the proposal to avoid any impacts in this area and preserve the archaeological feature in-place. The applicant chose to modify the proposed south drive and avoid any impacts, a treatment recommended in the draft archaeological investigation report.



Figure 2: Approved site plan showing the enlarged south drive (outlined in red).

The applicant proposes to revise the proposal by expanding the exposed aggregate concrete paving directly to the south of the house's south entrance (see below). The enlarged area will be large enough to accommodate a three-point turnaround and will be constructed in the same exposed aggregate concrete with a bluestone border that had been approved in the 2022 HAWP.




Figure 3: Revised site plan showing the new turnaround and bioretention area.

Staff finds the proposed revision will not have a substantial impact on the character of the site and will result in a net reduction in paving on site. Staff additionally finds that the proposed material is consistent

with the character of the site and the HPC's finding in the approved HAWP. Details regarding the archaeological feature will be incorporated into the final archaeological report and submitted to the historic preservation office. Staff recommends the HPC approve the HAWP under 24A-(b)(2) and Standards 2, 9, and 10.

#### **Stormwater Management Infrastructure**

The second revision proposed is a modification to a bioretention area that is part of the site's stormwater management plan. Currently, there is no stormwater management infrastructure on site. The original HAWP approval included a bioswale to the south of the approved turnaround (see *Fig. 2*). Because that feature is being removed from the scope of work, the applicant proposes to install a new bioswale to the south of the revised south drive, discussed above. The proposed bioswale will be located down the hill from the manor house.

As with the previous HAWP, Staff finds the proposed bioretention area is in keeping with the character of the site and will be constructed in an area of the site that has already been heavily disturbed. As with the previous HAWP, Staff recommends the HPC approve the revision under 24A-8(b)(6).

#### **Tree Removal**

When Staff reviewed the Natural Resource Inventory/Forest Stand Delineation (NRI/FSD), Historic Preservation Staff identified a number of tree removals that were not part of the original HAWP landscape/tree removal plan. Seven additional trees are identified for removal as part of this HAWP revision. The trees include:

- 1. An 8" (eight-inch) d.b.h. Redbud tree to the west of the sunroom, identified as in 'poor' condition in the tree survey;
- 2. A 5" (five-inch) d.b.h. Dogwood to the southeast of the garage;
- 3. A 42" (forty-two inch) d.b.h. American Beech southeast of the house near the intersection of the driveway to the house and the HHMI campus;
- 4. 44" (forty-four inch) d.b.h. Paulowian is also to the southeast of the house near the intersection of the driveway to the house and the HHMI campus
- 5. A multi-stem Honeysuckle located to the east of the garage;
- 6. An 18" (eighteen inch) d.b.h. Witchhazel, located immediately to the north of the house; and
- 7. A multi-trunk Yew located to the immediate north of the house.

The revision of the south drive, discussed above, will result in the retention of three trees previously approved for removal. Staff notes the applicant proposes planting approximately 43 (forty-three) trees not less than 4" (four inches) d.b.h. on site.

Staff finds the most significant of the trees (the Beech, Yew, and Witchhazel) are all in locations where substantial work has already been approved. In the case of the Witchhazel and Yew, the ADA access to the site is approved along the north side of the mansion, and requiring the retention of these trees would require a wholesale revision of the hardscaping plan. Additionally, the Beech tree is located immediately adjacent to the driveway that connects the Hayes Manor site to the HHMI campus and will be impacted by both the driveway and stormwater management construction.

Staff finds the other trees proposed for removal are either in poor health, are less than the 6" (six-inch) threshold the HPC requires for tree removals, or are identified as invasive (both the Paulowian and Honeysuckle). Staff finds the overall impact of these additional tree removals will not significantly alter the character of the site and the additional plantings are an appropriate mitigating measure. Staff recommends the HPC approve the revised tree plan under 24A-8(b)(2) and Standard 2.

## **STAFF RECOMMENDATION**

Staff recommends the HPC **approve the HAWP** revisions and reminds the applicant of its responsibilities under condition #4 from the original HAWP approval in addition to other conditions of approval that remain in force and are not extinguished by the approval of this revision;

4. After consulting with staff, the applicant may proceed with any additional proposed archaeological fieldwork, if necessary. Once the fieldwork is complete, and prior to approval of the building permit, the applicant shall complete a technical report that documents the archaeological findings and submit the report to Staff;

under the Criteria for Issuance in Chapter 24A-8(b)(2) and (6) having found that the proposal will not substantially alter the exterior features of the historic resource and is compatible with the purposes of Chapter 24A;

and with the Secretary of the Interior's Standards for Rehabilitation #2, 9, and 10;

and with the general condition that the applicant shall present an electronic set of drawings, if applicable, to Historic Preservation Commission (HPC) staff for review and stamping prior to submission for the Montgomery County Department of Permitting Services (DPS) building permits;


and with the general condition that final project design details, not specifically delineated by the Commission, shall be approved by HPC staff or brought back to the Commission as a revised HAWP application at staff's discretion;

and with the general condition that the applicant shall notify the Historic Preservation Staff if they propose to make **any alterations** to the approved plans. Once the work is completed the applicant will <u>contact the staff person</u> assigned to this application at 301-563-3400 or <u>dan.bruechert@montgomeryplanning.org</u> to schedule a follow-up site visit.

# HOWARD HUGHES MEDICAL INSTITUTE (HHMI) HAYES MANOR REHABILITATION

MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION REVISED HISTORIC AREA WORK PERMIT (HAWP) APPLICATION #1001591 REVISION 02

September 20, 2023



HISTORIC ARE	FOR STAFF ONLY: HAWP# TION FOR DATE ASSIGNED A WORK PERMIT	HAWP APPLICATION: MAILING [Owner, Owner's Agent, Adjacent a
301.56	53.3400	<b>Owner's Mailing Address:</b> Howard Hughes Medical Institute
C UN S		c/o Mr. Robert "OB" Obrist
APPLICANT:		4000 Jones Bridge Road
Name: C/o Robert "OB" Obrist	E-mail: obristr@hhmi.org	Chevy Chase, MD 20815
Address: 4000 Jones Bridge Road	City: Chevy Chase, MD Zip: 20815	Adjacent and Confronting Property Owners Mailing
		Allen M. Hutter
Daytime Phone: (301) 215-8608	Tax Account No.: 00425422	3905 Jones Bridge Rd.
	a starte reaction of the second se	Chevy Chase, MD 20815
AGENT/CONTACT (if applicable):		Tax Acct. No. 07-00671492 Lot 5 Block 1
SmithGroup		
Name: 0/0 Susan Pommerer, AIA - Principal	E-mail: _susan.pommerer@smithgroup.com	Jana L. Mason, Trustee
1700 New York Avenue NW Suite 100	Washington DO 20006	The Jana L. Mason Trust
Address: 1700 New York Avenue NW, Suite 100	City: Washington, DG Zip: 20006	P. O. Box 15126
1000 001 0017		Chevy Chase, MD 20825
Daytime Phone: (202) 974-0847	Contractor Registration No.: TBD	Tax Acct. No. 07-02850862 Lot 8 Block 1
A second second and the second second second		Nancy C. Wong
LOCATION OF BUILDING/PREMISE: MIHP # of	Historic Property35/10	8800 Connecticut Ave.
Is the Property Located within an Historic Distric	t?Yes/District Name	Chevy Chase, MD 20815
	X No/Individual Site Name Hayes Manor	Tax Acct. No. 07-02645803 Lot P15 Block 1
map of the easement, and documentation from 2016 Final Forest Conservation Plan and 1999 & 200	vironmental Easement on the Property? If YES, include a the Easement Holder supporting this application. 2 Easement Agreements with Columbia Country Club provals / Reviews Required as part of this Application? YES, include information on these reviews as	8800 Spring Valley Rd. Chevy Chase, MD 20815 Tax Acct. No. 07-00671561 Lot 1 Block 7 Chevy Chase Land Co. 5471 WISCONSIN AVE # 320
	and Marcon M	Chevy Chase, MD 20815
Building Number: 35/10 Street	4101 Manor Road	Tax Acct. No. 07-00466785 Lot 7-12 Block 22
Chevy Chase MD	Connecticut Avenue	Kitty C. Barry Revocable Trust
Town/City: Chevy Chase, MD Neare	est Cross Street: Connecticut Avenue	4004 Manor Rd.
Lot: _? Block: _26 Subdi	vision: Manor Parcel: B Plat No. 23792	Chevy Chase, MD 20815 Tax Acct. No. 07-00467255 Lot 5 Block 24
for proposed work are submitted with this a         be accepted for review. Check all that apply:         New Construction       Deck/Pord         Addition       Fence         Demolition       X         Hardscape       Grading/Excavation	/Landscape X Window/Door Other:	JORGE F. CHAMOT ALLISON ARIAS 3904 Manor Rd. Chevy Chase, MD 20815 Tax Acct. No. 07-00467290 Lot 9 Block 25 Joan N. Pickett Tr. 3719 Village Park Dr. Chowy Chase, MD, 20815
and accurate and that the construction will con	e the foregoing application, that the application is correct oply with plans reviewed and approved by all necessary	Chevy Chase, MD 20815 Tax Acct. No. 07-03028066 Lot 10 Block A Steven I. & W.E. Silver LIVING TRUST
<u>_</u>	this to be a condition for the issuance of this permit.	3713 Village Park Dr.
Susan Pommerer.	September 20, 2023	Chevy Chase, MD 20815
AND A REAL PROPERTY AND A REAL PROPERTY.	Data	Tax Acct. No. 07-03028033 Lot 7 Block A
Signature of owner or authorized age	nt Date	Tax Acct. No. 07-05028055 Lot 7 Block A

ADDRESSES FOR NOTIFYING and Confronting Property Owners]
Owner's Agent Mailing Address:
SmithGroup
c/o Susan Pommerer 1700 New York Avenue NW, Suite 100
Washington, DC 20006
Addresses:
SUNA SEO
TIMOTHY Y SEO
3909 Jones Bridge Rd.
Chevy Chase, MD 20815 Tax Acct. No. 07-00671388 Lot 7 Block 1
IAN I FE
AMANDA LEE
8801 Spring Valley Rd.
Chevy Chase, MD 20815
Tax Acct. No. 07-00670910 Lot 9 Block 1
MICHAEL LEO FLANAGAN
JACQUELINE LANEZ FLANAGAN
8801 Kensington Pkwy
Chevy Chase, MD 20815
Tax Acct. No. 07-00526446 Lot P3, Pt Lt 4 Block 1 Chevy Chase Land Co.
5471 WISCONSIN AVE # 320
Chevy Chase, MD 20815
Tax Acct. No. 07-00466741 Lot 1-6 Block 22
MARY ELLEN MURPHY
8514 Lynwood Pl.
Chevy Chase, MD 20815
Tax Acct. No. 07-00466923 Lot 13 Block 24
JULIAN E GILLESPIE
HEATHER A GILLESPIE
8519 Longfellow Place Chevy Chase, MD 20815
Tax Acct. No. 07-00467142 Lots P3 & 4 Block 24
VINCENZO SALINA AMORINI BOLOGNINI 8515 Lynwood
PI.
Chevy Chase, MD 20815
Tax Acct. No. 07-00466706 Lots P7 & 8 Block 25
Danial C. Caldharg & Marian K. Caldharr
Daniel S. Goldberg & Marion K. Goldberg
8616 Village Park Pl. Chevy Chase, MD 20815
Tax Acct. No. 07-03028077 Lot 11 Block A
Robert H. & A.N. Thompson
3715 Village Park Dr.
Chevy Chase, MD 20815
Tax Acct. No. 07-03028044 Lot 8 Block A

JOHN J KEELING	ALEXANDER V ILYASOV
PATRICIA MONTILLA-KEELING	
3717 Village Park Dr.	3709 Village Park. Dr.
Chevy Chase, MD 20815	Chevy Chase, MD 20815
Tax Acct. No. 07-03028055 Lot 9 Block A	Tax Acct. No. 07-03028000 Lot 5 Block A
lacqueline R. Knepshield	CHARLES J FASELIS
REVOCABLE TRUST	DOMINIQUE HOWARD
3711 Village Park Dr.	8617 Village Park Pl.
Chevy Chase, MD 20815	Chevy Chase, MD 20815
Tax Acct. No. 07-03028011 Lot 6 Block A	Tax Acct. No. 07-03028215 Lot 1 Block B
Sukhjit S. Sidhu & Jagdisk K Sidhu	NANCY A RYAN REVOC TR
3803 Village Park Dr.	3805 Village Park Dr.
Chevy Chase, MD 20815	Chevy Chase, MD 20815
ax Acct. No. 07-03028226 Lot 2 Block B	Tax Acct. No. 07-03028237 Lot 3 Block B
Aida T. Jarkas	Chevy Chase Park Community Association
3804 Village Park Dr.	c/o Management Group Associates
Chevy Chase, MD 20815	20440 Century Blvd., Suite 100 Germantown, MD 20874
Fax Acct. No. 07-03028294 Lot 13 Block C	Tax Acct. No. 07-03028022 Parcel C Block C
Chevy Chase Park Community Association	Chevy Chase Park Community Association c/o
c/o Management Group Associates	Management Group Associates
20440 Century Blvd., Suite 100	20440 Century Blvd., Suite 100
Germantown, MD 20874	Germantown, MD 20874
ax Acct. No. 07-03028088 Parcel E Block C	Tax Acct. No. 07-03028306 Part of Parcel G Block C
Dennis W. Schraf, Sr. & H.M. Schraf	David F. Hodge, Jr. & P.J. Hodge
3812 Platt Ridge Rd.	8810 Platt Ridge Rd.
Chevy Chase, MD 20815	Chevy Chase, MD 20815
ax Acct. No. 07-02829488 Lot 1	Tax Acct. No. 07-02829490 Lot 2
CHEVY CHASE HOUSE TR	Jerome K. & A.R. Blask
3806 Platt Ridge Rd.	8804 Platt Ridge Rd.
Chevy Chase, MD 20815	Chevy Chase, MD 20815
Fax Acct. No. 07-02829513 Lot 4	Tax Acct. No. 07-02829524 Lot 5
Mojdeh & Nazir A. Waroich	Columbia County Club
3808 Platt Ridge Rd.	7900 Connecticut Ave.
Chevy Chase, MD 20815	Chevy Chase, MD 20815
ax Acct. No. 07-02829502 Lot P3	Tax Acct. No. 07-03580358 N355, Parcel B
HOWARD HUGHES MEDICAL INSTITUTE	Sara G. & M. H. Dent
1000 Jones Bridge Rd.	30 7th St E., Suite 2000
Chevy Chase, MD 20815	Saint Paul, MN 55101
ax Acct. No. 07-03851725 Parcel N976, Lot 6	Tax Acct. No. 07-00425661 Parcel P319
Maryland-National Capital Park & Planning Comm.	VINCENT HORVILLE
425 Reedie Drive	4021 JONES BRIDGE ROAD
Vheaton, MD 20902	Chevy Chase, MD 20815
ax Acct. No. 07-00428607 Parcel P806	Tax Acct. No. 07-00419272 Parcel P912
GREGORY BAYTLER	BENJAMIN D CLARK
ATYANA BAYTLER	SOSHANA L CLARK ET AL
.5837 CRABBS BRANCH WAY #A	4003 Jones Bridge Rd.
ROCKVILLE, MD 20855	Chevy Chase, MD 20815
ax Acct. No. 07-00419283 Parcel P913	Tax Acct. No. 07-00426756 Parcel P928
BA B2 RESIDENTIAL LLC	CHEVY CHASE B2 REATIL LLC
5406 IVY LANE SUITE 700	6406 IVY LANE SUITE 700
GREENBELT, MD 20770	GREENBELT, MD 20770
Tax Acct. No. 07-03824436 UNIT B2 RES	Tax Acct. No. 07-03824447 PUNIT B2 RETAIL

## **Description of Property:**

Please describe the building and surrounding environment. Include information on significant structures, landscape features, or other significant features of the property:

The Hayes Manor was built ca. 1767 in the Georgian style, consisting of two and a half stories above grade with a below grade basement in a four square configuration. The east wing, consisting of two stories plus a basement, was added in 1899 and the west wing (sun porch addition) and garage were constructed in 1908. A greenhouse connecting the garage to the east wing is thought to have been built in the 1960's. Exterior walls are of solid brick construction and floors are primarily wood-framed. The property is located on the grounds of the Howard Hughes Medical Institute (HHMI) Campus at 4000 Jones Bridge Rd in Chevy Chase, Maryland. The historic structure is approximately 9,000 SF and was documented by the Historic American Building Survey (HABS) in 1962.

In 1984 Hayes Manor was included in the Montgomery County Master Plan for Historic Preservation and was deemed significant under Criteria 1.a, 1.d, and 2.a of the Montgomery County Preservation Ordinance as having significant cultural characteristics of the county/ state/nation, exemplifying historic heritage of the community and representing architectural and design significance of a particular period. HHMI purchased the property in 2002 from the Columbia Foundation and the building has for the most part remained vacant since that time.

Hayes Manor is located on approximately 9.44 acres, a small portion of an original tract of land purchased by Alexander Williamson in 1762. The area north of the residence includes landscape gardens, pea gravel pathways, and a guest house. A loop road through the HHMI headquarters campus provides access to campus facilities. Access to Hayes Manor is provided by way of a driveway connecting to the southern end of the loop road. The driveway is asphalt but transitions to gravel near the residence.

Hayes Manor is surrounded by stately, mature walnut, hickory, and oak trees, boxwood garden, and a bowling green. Research has been completed to understand the developmental history of the house and surrounding landscape.

### **Description of Work Proposed:**

Please give an overview of the work to be undertaken:

In early 2021 SmithGroup was hired by HHMI to provide an updated Master Plan for the HHMI Campus that included an evaluation of the future use of Hayes Manor. As part of that process, it was determined that Hayes Manor could be utilized as a residence for the HHMI President and could also support events and receptions while retaining the historic character of the structure. In addition to meeting the functional programmatic needs, the rehabilitation scope will include improvements to accessibility, life-safety, building infrastructure, and deferred maintenance necessary to make this a serviceable and code-compliant structure.

The proposed plan repurposes the house with meeting and entertainment spaces on the first floor with the President's residence on the second floor. The first floor of the main house and the west sunroom will be converted to flexible reception space. The east wing of the first floor will include a meeting/dining room and a residential kitchen which will be served and supported by the main kitchen in the headquarters building. New accessible entrances will be provided into the house and onto a rehabilitated east patio located between the House and the Garage.

The second floor of the House will become the President's private residence. The plan will feature two bedrooms with ensuite bathrooms, a large living and dining room, a modern eat-in kitchen, two offices, and a laundry/ guest bathroom. The second floor is approximately 3,000 gross square feet offering modern living in a historic structure.

In addition to the building renovations, the Owner intends to make improvements to the on-campus circulation system directly related to access to the Hayes Manor to improve accessibility and stormwater management per county regulations. The scope of the renovation extends to patios, gardens, and landscape areas around the residence. New retaining walls are proposed to extend the outdoor lawn area and address the grade change between the area north of the residence and the loop road.

The project scope includes providing an ADA accessible route from existing HHMI headquarters campus buildings to Hayes Manor; both to the interior of the residence as well as exterior amenity areas. The ADA route begins from an exterior plaza on the east side of the loop road. The elevation of this plaza is lower than the loop roadway so a series of ramps with handrails and landings are proposed. After crossing the loop road, the ADA route will continue west to connect to the new east patio and the residence. The material of the ADA route will be concrete. All ramps will be designed to meet Americans with Disabilities Act (ADA) requirements and are not-to-exceed 12:1 slope. All areas with slopes exceeding 5% shall have metal handrails.

Stormwater management (SWM) for the development area must be provided in accordance with State and County requirements. SWM requirements for development within the County are defined by Chapter 19 of the Montgomery County code. Environmental Site Design (ESD) practices will be used to treat runoff from the proposed development. The Code defines ESD as using small scale SWM practices, nonstructural techniques, and better site planning to mimic natural hydrologic runoff characteristics to minimize the impact of land development on water resources.

The design of the site and landscape surrounding Hayes Manor seeks to create a landscape that complements the historic character of the building and grounds as well as the Institute's contemporary campus. The landscape shall address several important missions at once: to provide a useful and relaxing residential environment for the President and family; a direct and accessible pedestrian connection between the headquarters building and the residence typified by intuitive and comfortable wayfinding; and a welcoming environment for invited visitors that can support private, catered events. Open spaces will be designed and assessed for their fit into, and enhancement of, the historic landscape quality and the overall campus landscape framework.

Site plantings will include deciduous shade trees, evergreen trees, flowering understory trees, mixed shrubs, ornamental grasses, perennials and annuals, ground covers and lawn. Exposed areas within plant beds are to be mulched, and all planted areas will be irrigated. Large deciduous shade trees will typically be specified at 5" caliper, depending on species and availability. All plantings will be specified for American Nursery Stock Standards.

Pedestrian walkways will typically be cast-in-place concrete with finishes and coloring consistent with sidewalks elsewhere on the campus. Vehicular areas will typically be asphalt or seeded aggregate concrete closer to the historic entries. Select areas will have enhanced paving materials: bluestone pavers, mortar set, for all patio spaces around the house and garage, and

select walkways as noted in the plan. At the driveway entry court, bluestone pavers with be set on a concrete base and seeded cast-in-place concrete for select walkways and the driveway sections closest to the house. Driveway edges and bands are to be stone cobbles (aka Belgian block) and mortar set.

Site retaining walls shall be constructed to be seamless continuations of the existing walls and be constructed of matching stone. Stairs shall match the materials and general design of existing site stairs on campus, with bluestone treads and fieldstone risers.

# **Organization of Revised Application:**

This revision to the previously approved Historic Area Work Permit (HAWP) is organized in parts align with the original application.

REVISIONS TO SITE IMPROVEMENTS Work Item #1: South Drive Work Item #7: Stormwater Management Infrastructure Work Item #9: Tree Conservation Plan

# SITE IMPROVEMENTS OVERALL SITE PLAN



Howard Hughes Medical Institute (HHMI) Hayes Manor Rehabilitation

PLANT SCHE	DULE				
SHADE TREES	CODE	QTY	BOTANICAL / COMMON NAME	SIZE	MITIGATION INCHES
$\odot$	Ar	9	ACER RUBRUM / RED MAPLE	4" CAL.	36"
	Co2	15	CELTIS OCCIDENTALIS / COMMON HACKBERRY	4" CAL.	60*
	Ls	10	LIQUIDAMBAR STYRACIFLUA / SWEET GUM	4" CAL.	40"
$\odot$	Ns	4	NYSSA SYLVATICA / TUPELO	4" CAL.	16"
	Qa	5	QUERCUS ALBA / WHITE OAK	4" CAL.	20*

TOTAL: 43 trees

172"

#### LEGEND



TREE TO BE REMOVED (INCLUDED IN ORIGINAL HAWP APPLICATION)



TREE TO BE REMOVED WITH INTENT TO SAVE

TREE TO BE REMOVED (INCLUDED AS PART OF HAWP REV 02)



PROPOSED TREE (PER PLANT SCHEDULE ABOVE)



REVISED SOUTH DRIVE WITH PAVED AREA FOR VEHICULAR TURN-AROUND

REVISED BIORETENTION LOCATION

REVISED LIMITS OF DISTURBANCE

# SITE IMPROVEMENTS

# WORK ITEM #1:

# SOUTH DRIVE

Description of Current Condition: An existing gravel drive is located along the south facade of Hayes Manor leading to a gravel turnaround located southwest of the Sunroom.

**Revision to Proposed Work:** The existing gravel drive will be replaced by a seeded aggregate concrete drive with mortar set bluestone cobble edge. To avoid impacts to previously documented archaeological resources and further removal of existing trees, the design for the vehicular turn around at the west end of the new south drive is being revised. To allow vehicles to turn around in front of the Manor House, the paved area adjacent to the proposed South Porch is enlarged to accommodate 3-point turning. The larger paved area will be finished as originally design bluestone paving with a cobble edge.

# WORK ITEM #7:

# STORMWATER MANAGEMENT INFRASTRUCTURE

Description of Current Condition: There is no stormwater management infrastructure present at the site immediately surrounding Hayes Manor. The HHMI Headquarters campus includes the required infrastructure related to the headquarters building(s) located elsewhere on site, but it is not serving this area.

**Revision to Proposed Work:** To avoid impacts to previously documented archaeological resources the redesign includes relocation of the proposed bioretention area located southwest of the Manor House. A similar bioretention area has been located south of the proposed South Drive.

# WORK ITEM #9:

# TREE CONSERVATION PLAN

Description of Current Condition: The proposed site improvements discussed in this application will impact trees on the site. The trees which will be removed and others which will be impacted are identified in the map to the right and listed in the inventory below.

Revision to Proposed Work: The proposed site improvements will result in the loss of trees. The sum total of the diameter at breast height (d.b.h.) of the trees removed that require mitigation by the county equals 648.50 inches. The County mitigation requirement to address this loss in trees includes a total of 168.125 inches of tree d.b.h. replacement by planting new trees throughout the site. The replacement trees will be not less than 4" d.b.h. and of the species listed on the next page. This will result in approximately forty-three (43) new trees planted on the site.

The inventory of trees to be removed, or otherwise impacted, has been revised. The inventory includes notes identifying trees which will be maintained as a result of the redesign of the South Drive. In addition, the inventory is accompanied by the site plan locating additional trees to be removed. This work has been coordinated with the Forest Conservation Plans. Please see the Inventory of Planned Tree Removals and Impacts on following pages.

WORK ITEM #9: ADDITIONAL TREE REMOVAL, TYP. WORK ITEM #1: REDESIGNED SOUTH DRIVE WORK ITEM #7: **RELOCATED BIORETENTION AREA REVISED LIMITS OF DISTURBANCE** 

HAYES MA

CURRENT LIMITS OF DISTURBAN

BIORETENTION FACILITY

EVISED SOUTH DRIVE WITH PAVED AREA FO EHICULAR TURN-AROUNE

OPOSED TREE

TREE TO BE REMOVED

ICLUDED AS PART OF HAWP REV 02 TREE TO BE REMOVED WITH INTENT TO SAV

TREE TO BE RMEOVED JDED IN ORIGINAL HAWP APPLICATION

Historic Area Work Permit (HAWP) Application 14 evision 02 September 20,2023

# WORK ITEM #9: TREE CONSERVATION PLAN (CONTINUED)

# INVENTORY OF PLANNED TREE REMOVAL AND IMPACTS

TREE ID#	DBH	SPECIES	GRANDFATHERE	D IMPACT/REMOV	E NOTES	% PROPOSED IMPACT	% APPROVED IMPACT PER #120020960	CONDITION	MITIGATION	TREE ID#	DBH	SPECIES	GRANDFATHERED IMPACT/REMOVE	NOTES	% PROPOSED IMPACT	% APPROVED IMPACT PER #120020960	CONDITION	MITIGATION
87	49	Black walnut		None	Included in original HAWP	0%		Good	0	872	8,14,18	American Holly	Impact	Included in list for HAWP Rev 02	12%		Fair Good	0
553	3	White Fringetree	x	Remove with intent to s	save Included in original HAWP as "impact"; changed to "REMOVE" for HAWP Rev 02	100%	100%	Fair	0	873 875	14	American Holly Pecan	None None		0% 0%		Good Good	0
										881	50	Shagbark Hickory	Impact	Included in list for HAWP Rev 02	17%	0.01%	Good	0
554	69	Silver Maple	Х	Impact	Included in original HAWP	23%	75%	Good	0	883 884	4 3	Flowering Dogwood	None None		0% 0%		Fair Good	0
555 558	4,9	Flowering Dogwood Red Maple	x	None Impact	Included in original HAWP	0% 43%	100%	Fair Good	0	892	18	Flowering Dogwood Golden Raintree	None		0%		Good	0
559	8	Eastern Redbud		None	Included in original HAWP as "impact";	0%	100%	Good	0	893	33	Red Oak	Impact	Included in list for HAWP Rev 02	4%		Good	0
					changed to "NONE" for HAWP Rev 02					894 895	5	Flowering Dogwood Eastern Redbud	None Remove	Additional tree removal included in	0% 2%		Fair Poor - fall hazard	0
560	14	Sugar Maple	X	Impact	Included in original HAWP	17%	62%	Good	0	000	Ŭ			list for HAWP Rev 02	2,0			Ŭ
561	13	Willow Oak	x	Remove	Included in original HAWP and listed	100%	100%	Good	5	896	10	Black Cherry	None		0%		Good	0
					on "grandfathered" removal list					897 901	14.5	White Oak Black Cherry	None None		0% 0%		Good Fair	0
562	3	Flowering Dogwood		None		0%		Good	0	902	39	Northern Red Oak	None	Included in list for HAWP Rev 02	0%		Good	0
563	9	Willow Oak	X	Remove	Included in original HAWP and listed	100%	100%	Good	3.5	903	42	Red Oak	Impact	Included in list for HAWP Rev 02	20%		Good	0
					on "grandfathered" removal list					904 905	<u>34</u> 8	White Oak Southern Redcedar	Impact None	Included in list for HAWP Rev 02	0.20%		Good Poor	0
564	7	Red Maple	x	Impact	Included in original HAWP as	30%	100%	Good	0	907	25	White Ash	None		0%		Good	0
					"REMOVE"; changed to "IMPACT" for					909	34	Black Walnut	None		0%		Good	0
565	<u> </u>	Eloworing Dogwood	v	Impact	HAWP Rev 02 Included in original HAWP	32%	100%	Fair	0	910 915	14 28	Norway Spruce Chestnut Oak	None None		0% 0%		Good Good	0
566	7	Flowering Dogwood Sugar Maple	X	Impact Impact	Included in original HAWP	23%	80%	Good	0	916	31	Tulip Poplar	None		0%		Good	0
567	8	Red Maple	Х	Impact	Included in original HAWP	30%	100%	Good	0	918	26	Kentucky Coffeetree	None		0%		Good	0
568 572	7 6	Red Maple Red Maple		None None		0%	100%	Good Good	0	919 962	16 35	Kentucky Coffeetree Mossycup Oak	None	Included in list for HAWP Rev 02	0% 0%		Good	0
574	1,3,2,2,1,3,3	Star Magnolia		None		0%	100%	Good	0	964	5	Bush Honeysuckle	None		0%		Poor	0
575	11	American Beech		None		0%	100%	Good	0	965	32	American Linden	None	Included in list for HAWP Rev 02	0%		Good	0
576 747	3,4,2,2,1 36	Serviceberry Black Walnut	×	None Impact	Included in original HAWP	0%	100% 37%	Good Good	0	979	6,3,2,3,1,4,1,1,4	Bush Honeysuckle	None	Removed from "REMOVE" list for HAWP Rev 02	0%		Poor	0
747	12	Norway Spruce	^	None	Included in original HAWP	0%	37%	Good	0	980	7	Flowering Dogwood	None	Removed from "REMOVE" list for HAWP	0%		Fair - leans	0
749	37, 27	Sweet Cherry	X	Impact	Included in original HAWP	38%	62%	Good	0					Rev 02				
760	3,4	Flowering Dogwood	×	None	Included in existing LIAN/D	0%	10%	Fair	0	981	9	Black Cherry	None	Removed from "REMOVE" list for HAWP Rev 02	0%		Fair - 981, 982, 983, 984 are one tree	0
763	28	White Pine White Pine	× ×	Impact Impact	Included in original HAWP Included in original HAWP	5% 21%	10%	Fair Good	0									
778	11	Japanese Cedar		None		0%		Good	0	982	10	Black Cherry	None	Removed from "REMOVE" list for HAWP	0%		Fair - 981, 982, 983,	0
786	5,4,6,6,5,4	Crape Myrtle		Impact	Included in original HAWP	7%		Good	0					Rev 02			984 are one tree	
794 795	7	Flowering Dogwood Norway Spruce		None Impact	Included in original HAWP	0% 41%	32%	Good Good	0	983	11	Black Cherry	None	Removed from "REMOVE" list for HAWP	0%		Fair - 981, 982, 983,	0
799	5,5,5,5,5,3,3	Crape Myrtle	X	Impact	Included in original HAWP	12%	50%	Good	0			-		Rev 02			984 are one tree	
800 801	3,3,3,2,2,2,2,2	Crape Myrtle	×	None		0%	50%	Good	0	984	11	Black Cherry	None	Removed from "REMOVE" list for HAWP	0%		Fair - 981, 982, 983,	0
801	29	Crape Myrtle Norway Spruce	X	Impact Impact	Included in original HAWP Included in original HAWP	15% 32%	50% 42%	Good Good	0	364		Black cherry	None	Rev 02	0%		984 are one tree	0
806	21	Norway Spruce	X	Impact	Included in list for HAWP Rev 02	23%	36%	Good	0									
807	26	Black walnut	x	Impact	Included in list for HAWP Rev 02	17%	19%	Good	0	985	15	Black Cherry	None	Removed from "REMOVE" list for HAWP Rev 02	0%		Good	0
808 816	28 3,5	Red Oak Canadian Hemlock		Remove with intent to s None	ave Included in original HAWP	27% 0%		Good Fair	28 0	987	37	White Oak	Impact	Removed from "REMOVE" list for HAWP	38%		Good	0
817	10	Japanese Cedar		None		0%	9%	Good	0					Rev 02				
818	11	Sugar Maple		None		0%	86%	Good	0	988	50	Mossycup Oak	Impact	Included in list for HAWP Rev 02	10%		Good	0
819 820	3	Virginia Pine Virginia Pine	x	None Impact	Included in list for HAWP Rev 02	0%	32%	Poor Poor	0	1027 1030	8,6,4,2 9,13	Crape Myrtle Flowering Cherry	Remove	Included in list for HAWP Rev 02 Included in original HAWP	12% 100%		Good Poor	22
821	12	Japanese Cedar	X	Impact	Included in list for HAWP Rev 02	24%	90%	Good	0	1031	2,3	Flowering Dogwood	None		0%		Poor	0
822	12	Sugar Maple	x	Remove	Included in original HAWP and listed	100%	100%	Good	5	1032	34 18	Pecan White Pine	Impact None	Included in list for HAWP Rev 02	37% 0%		Good Good	0
					on "grandfathered" removal list					1034	10	Weeping Cherry	None		0%		Good	0
823	5	Flowering Dogwood		Remove	Included in original HAWP	100%		Good	5	1035	7,25	American Holly	Impact	Included in list for HAWP Rev 02	5%		Poor	0
825	10	Red Maple	x	Remove	Included in original HAWP and listed on "grandfathered" removal list	100%	100%	Good	3.5	1036	5	Flowering Dogwood	Remove with intent to save	Additional tree removal included in list for HAWP Rev 02	37%		Good - Potential transplant if needed and feasible	5
826 827	<u>58</u> 5	Tulip Poplar Flowering Dogwood		Remove Remove	Included in original HAWP Included in original HAWP	100% 100%	30%	Good Good	58 5	1037	26.5	Shagbark Hickory	Remove	Included in original HAWP	100%		Good	26.5
828	10	Black Cherry		Remove	Included in original HAWP	37%	11%	Good	10	1041	43	Pecan	Impact	Included in list for HAWP Rev 02	26%		Good	0
831	40	Tulip Poplar		Impact	Included in original HAWP as	39%	30%	Good	0	1052	<u>33</u> 46	White Oak Willow Oak	Impact Impact Impact	Included in list for HAWP Rev 02 Included in list for HAWP Rev 02	3% 26%		Good Good	0
					"REMOVE"; Included in list for HAWP Rev 02 as "impact"					1061	20	Tupelo	Impact	Included in list for HAWP Rev 02	33%		Good	0
832	31	Chinese Chestnut		Impact	Included in list for HAWP Rev 02	41%		Good	0	1064	4,4	Flowering Dogwood	Remove	Included in original HAWP	100%		Dead	0
833	5	Flowering Dogwood		None	Included in original HAWD as	0%		Good	0	1065 1067	27 35	White Oak Slippery Elm	Impact Impact	Included in list for HAWP Rev 02 Included in list for HAWP Rev 02	33% 25%		Good Good	0
834	21	White Oak		Impact	Included in original HAWP as "REMOVE"; Included in list for HAWP	37%		Good	0			3,3,4 Bush Honeysuckle	Impact           Remove	Additional tree removal included in	100%	11%	Fair	42
					Rev 02 as "impact"									list for HAWP Rev 02		0.000	0	
835 836	<u>33</u> 3,9,11,8	White Oak American Holly		Remove with intent to s None	ave Included in original HAWP	33% 0%		Good Poor	<u>33</u> 0	1080 1081	30 4	White Oak Flowering Dogwood	Impact None	Included in list for HAWP Rev 02	8% 0%	0.01%	Good Poor	0
836	2,2,3,3,5,5,5,5,3,4	Kousa Dogwood	x	Impact	Included in list for HAWP Rev 02	1%	6%	Good	0	1083	30	White Oak	Impact	Included in list for HAWP Rev 02	1%		Good	0
839	9	Flowering Dogwood	X	Impact	Included in list for HAWP Rev 02	7%	10%	Fair	0	1091	33	Black Walnut	None		0%		Good	0
840 841	18 27	Black Walnut		Remove	Included in original HAWP Included in list for HAWP Rev 02	<u>100%</u> 4%		Good Good	18 0	1094 1098	20	Northern Red oak White Oak	None		0% 0%		Good Good	0
842	6	Sweet Gum Black Locust		Impact None	Included in list for HAWP Rev 02	0%		Good	0					L				
843	6	Black Locust		None		0%		Good	0									
844 845	<u>7</u> 9	Sugar Maple Eastern Redbud		Remove Remove	Included in original HAWP	35% 47%	24% 32%	Good Fair	7 9									
845	6	Eastern Redbud		Remove Remove	Included in original HAWP Included in original HAWP	47%	32%	Good	6									
847	4,3,4,2	Serviceberry		Remove	Included in original HAWP	100%	33%	Fair	13									
848	4,3,2,2,1 3	Serviceberry		Remove None	Included in original HAWP	100%	54%	Good	12					LEGE	ND			
849 853	10	Dead tree Black Locust		None Impact	Included in list for HAWP Rev 02	0% 5%		Dead Fair	0									
859	14	Norway Spruce		Impact	Included in list for HAWP Rev 02	20%		Good	0						_			
860	16	Wild Cherry		Remove	Included in original HAWP	100%		Good	16						TREES TO	BE REMOVE	D	
861 862	15 6	Norway Spruce Black Locust		Impact None	Included in list for HAWP Rev 02	27% 0%		Good Fair	0									
863	3	Crape Myrtle		Remove	Included in original HAWP	100%		Poor	3						_			
864	15	Black Locust		Remove	Included in original HAWP	100%		Fair	15						TREES W	HICH WILL BE	E IMPACTED	
867 868	29 18	Black Locust Witchhazel		Remove Remove	Included in original HAWP Additional tree removal included in	100% 100%		Poor Poor - measured a	29 t 18						-			
					list for HAWP Rev 02			base										
870	19,15,9	Yew		Remove	Additional tree removal included in	100%		Good	43									
					list for HAWP Rev 02													

# WORK ITEM #9: TREE CONSERVATION PLAN (CONTINUED)

# **INVENTORY OF PLANNED TREE REMOVAL AND IMPACTS (CONTINUED)**

	DBH	SPECIES	GRANDFATHERED	IMPACT/REMOVE	NOTES	% PROPOSED IMPACT	% APPROVED IMPACT PER #120020960	CONDITION	MITIGATION	TREE ID#	DBH	SPECIES	GRANDFATHERED	IMPACT/REMOVE	NOTES	% PROPOSED IMPACT	% APPROVED IMPACT PER #120020960	CONDITION	MITIGATION
1105	3,3,5	Flowering Dogwood	Nor	ne		0%	100%	Good	0	2424	6,4,1	Black Locust		Remove	Included in original HAWP	100%		Good	11
1109	5	Eastern Redbud	Nor	ne		0%		Fair	0	2425	5	Black Locust	1	Remove	Included in original HAWP	100%		Good	5
1110	6	Eastern Redbud	Nor	ne		0%		Fair	0	2426	4	Southern Redcedar	1	lone		0%		Good	0
1111	5	Eastern Redbud	Nor	ne		0%		Fair	0	2427	2	Flowering Dogwood	1	lone		0%		Good	0
1112	6	American Beech	Nor	ne		0%		Good	0	2428	37	White Oak	1	lone	Included in original HAWP as				
1116	24	White Oak	Nor	ne		0%		Good	0						"REMOVE"; Included in list for HAWP				
1117	34	Black Walnut	Imp	pact	Included in list for HAWP Rev 02	30%		Good	0						Rev 02 "NONE"				
1118	30	Black Walnut	X Imp	pact	Included in list for HAWP Rev 02	8%	35%	Good	0	2429	33	White Oak		lone	Included in list for HAWP Rev 02	0%		Good	0
1122	42	American Beech	Rer	move with intent to save	Additional tree removal included in	100%		Good	42	2430	4	Slippery Elm		lone		0%		Good	0
					list for HAWP Rev 02					2431	10	Black Locust		mpact	Included in list for HAWP Rev 02	10%	82%	Good	0
1123	11	Virginia Pine		nove	Included in original HAWP	100%		Good	11	2432	4	Slippery Elm		lone		0%		Poor	0
1124	17	Tupelo	Imp	pact	Included in list for HAWP Rev 02	10%		Good	0	2433	8	American Sycamore		lone		0%		Good	0
1125	9	Virginia Pine	Nor			0%		Good	0	2434	14,16	Norway Spruce	X	mpact	Included in list for HAWP Rev 02	10%	40%	Good	0
1148	4	Hemlock	Nor	ne	Included in original HAWP as	0%		Good	0	2435	35	White Oak	1	mpact	Included in list for HAWP Rev 02	32%		Good	0
					"REMOVE"; Included in list for HAWP					2436	2,4	Boxelder		lone		0%		Good	0
					Rev 02 "NONE"					2437	4	White Mulberry		lone		0%		Good	0
1149	8	Hemlock	Nor			0%		Good	0	2438	6	Flowering Dogwood		mpact	Included in list for HAWP Rev 02	7%		Good	0
1201	6	American Hornbeam	Nor			0%		Good	0	2439	6	Flowering Dogwood		lone		0%		Good	0
1224	15	American Hornbeam	Nor			0%		Fair	0	2440	6	Northern Red Oak		lone		0%		Good	0
1225	7	Sweetgum	Nor			0%		Good	0	2441	24	Black Walnut		lone		0%		Good	0
1226	13	Boxelder	Nor			0%		Good	0	2442	12	Weeping Cherry		lone		0%		Fair	0
1227	5	Sweetgum	Nor			0%		Good	0	2443	4	Black Locust		Remove	Included in original HAWP	100%		Good	4
1228	13,15	Boxelder	Nor			0%		Good	0	2444	6	Black Locust		lemove	Included in original HAWP	100%		Good	6
1230	32	Black Walnut	Nor			0%		Good	0	2445	4	Black Cherry		lemove	Included in original HAWP	100%		Good	4
1232	7	Red Maple	Nor			0%		Good	0	2446	5	Black Cherry		Remove	Included in original HAWP	100%		Good	5
1233	8	Sweetgum	Nor	ne		0%		Good	0	2447	10	American Beech		lone		0%		Fair	0
2156	37	Red Oak	Rer	nove	Included in original HAWP	100%		Fair - leans,	37	2448	2,3	Black Cherry		lone		0%		Good	0
								deadwood		2449	8	Virginia Pine		mpact	Included in list for HAWP Rev 02	11%		Fair	0
2176	44	Paulownia	Rer	nove	Additional tree removal included in	45%		Fair - leans,	44	2450	28	Red Oak		lone		0%		Good - slight lean	0
					list for HAWP Rev 02			deadwood, wound		2451	45	American Beech		lone		0%		Good	0
								closure, decay,		2452	35	Tulip Poplar		mpact	Included in list for HAWP Rev 02	3%		Good	0
								highly invasive; also		2453	33	Black Walnut		lone				Good	0
																0%			
								has supplemental aluminum tag #190		2454	33	White Oak		lone		0%		Fair - deadwood, cavities	0
								has supplemental aluminum tag #190		2454 2455		White Oak Red Oak							0
	13	Elm	Nor			0%		has supplemental aluminum tag #190 Poor	0	2455	33 24	Red Oak	1	lone		0%		cavities Fair/Good - swollen at base, deadwood	0
2260	4	Japanese Maple	Imp	pact	Included in list for HAWP Rev 02	19%		has supplemental aluminum tag #190 Poor Good	0		33		1	lone		0%		cavities Fair/Good - swollen at base, deadwood Fair/good -	
2260 2409	4 4,5,5,4,5,3	Japanese Maple Black Cherry	Imp Nor	pact ne		19% 0%		has supplemental aluminum tag #190 Poor Good Poor	0 0	2455	33 24	Red Oak	1	lone		0%		cavities Fair/Good - swollen at base, deadwood Fair/good - sapsucker holes,	0
2260	4	Japanese Maple	Imp Nor	pact	Included in list for HAWP Rev 02 Included in list for HAWP Rev 02	19%		has supplemental aluminum tag #190 Poor Good Poor Poor - 2" dead trunk	0	2455	33 24 24	Red Oak Sugar Maple		lone lone lone		0%		cavities Fair/Good - swollen at base, deadwood Fair/good - sapsucker holes, ohw, deadwood	0
2260 2409	4 4,5,5,4,5,3	Japanese Maple Black Cherry	Imp Nor	pact ne		19% 0%		has supplemental aluminum tag #190 Poor Good Poor	0 0	2455 2456 2457	33 24 24 24 24	Red Oak Sugar Maple Slippery Elm		ione ione ione Remove	Included in original HAWP	0% 0% 0% 100%	32%	cavities Fair/Good - swollen at base, deadwood Fair/good - sapsucker holes, ohw, deadwood Good	0
	4 4,5,5,4,5,3 2,8	Japanese Maple Black Cherry Smoketree	Imp Nor Imp	pact ne pact		19% 0% 5%		has supplemental aluminum tag #190 Poor Good Poor Poor - 2" dead trunk to be removed	0 0 0	2455 2456 2457 2458	33 24 24 24 2 2	Red Oak Sugar Maple Slippery Elm Slippery Elm		lone lone lone Remove Remove	Included in original HAWP	0% 0% 0% 100%	32% 100%	cavities Fair/Good - swollen at base, deadwood Fair/good - sapsucker holes, ohw, deadwood Good Good	0 0 2 0
2260 2409 2410 2411	4 4,5,5,4,5,3 2,8 6	Japanese Maple Black Cherry Smoketree Tree of Heaven	Imp Nor Imp Nor	pact ne pact ne		19% 0% 5% 0%		has supplemental aluminum tag #190 Poor Good Poor - 2" dead trunk to be removed Good	0 0 0	2455 2456 2457 2458 2458 2459	33 24 24 24 24 2 2 2	Red Oak Sugar Maple Slippery Elm Slippery Elm Slippery Elm		kone kone kone kemove ternove ternove	<u>_</u>	0% 0% 0% 100% 100%	32% 100% 21%	cavities Fair/Good - swollen at base, deadwood Fair/good - sapsucker holes, ohw, deadwood Good Good Good	0 0 2 0 2
2260 2409 2410 2411 2412	4 4,5,5,4,5,3 2,8 6 6	Japanese Maple Black Cherry Smoketree Tree of Heaven Tree of Heaven	Imp Nor Imp Nor Imp Nor Nor	pact ne pact ne ne	Included in list for HAWP Rev 02	19% 0% 5% 0%		has supplemental aluminum tag #190 Poor Poor - 2" dead trunk to be removed Good Good	0 0 0 0	2455 2456 2457 2458 2459 2460	33 24 24 24 2 2 2 2 2 2 4	Red Oak Sugar Maple Slippery Elm Slippery Elm White Mulberry		lone ione Remove Remove Remove Ione	Included in original HAWP	0% 0% 0% 100% 100% 0%	32% 100%	cavities Fair/Good - swollen at base, deadwood Fair/good - sapsucker holes, ohw, deadwood Good Good Good Good	0 0 2 0 2 0
2260 2409 2410 2411 2412 2413	4 4,5,5,4,5,3 2,8 6 6 14	Japanese Maple Black Cherry Smoketree Tree of Heaven Tree of Heaven Black Locust	Nor	pact pact ne ne nove	Included in list for HAWP Rev 02	19% 0% 5% 0% 0% 100%	100%	has supplemental aluminum tag #190 Poor Poor - 2° dead trunk to be removed Good Good Good	0 0 0 0 0	2455 2456 2456 2458 2459 2460 2460	33 24 24 24 24 2 2 2 2 2 4 2 2	Red Oak Sugar Maple Slippery Elm Slippery Elm Slippery Elm White Mulberry Flowering Dogwood		ione ione ione Remove Remove Remove Ione ione	Included in original HAWP	0% 0% 0% 100% 100% 0% 0%	32% 100% 21%	cavities Fair/Good - swollen at base, deadwood Fair/good - sapsucker holes, ohw, deadwood Good Good Good Good Good	0 0 0 0 0
2260 2409 2410 2411 2412 2413 2414 2414 2414 2414 2414	4 4,5,5,4,5,3 2,8 6 6 14 10	Japanese Maple Black Cherry Smoketree Tree of Heaven Tree of Heaven Black Locust Black Locust	Imp Nor Nor Nor Nor Nor X Rer X Rer	pact pact ne ne nove move	Included in list for HAWP Rev 02	19% 0% 5% 0% 0% 100%		has supplemental aluminum tag #190 Poor Poor - 2° dead trunk to be removed Good Good Good Fair	0 0 0 0 0 0 0	2455 2456 2457 2458 2459 2460 2460 2461 2462	33 24 24 2 2 2 2 2 2 2 2 4 2 2 4,4	Red Oak Sugar Maple Slippery Elm Slippery Elm White Mulberry Flowering Dogwood Flowering Dogwood		kone kone temove temove temove kone kone kone	Included in original HAWP	0% 0% 0% 100% 100% 0% 0%	32% 100% 21%	cavities Fair/Good - swollen at base, deadwood Fair/good - sapsucker holes, ohw, deadwood Good Good Good Good Good Good Good	0 0 2 0 2 0 0 0 0 0
2260 2409 2410 2411 2412 2413 2413 2414 2415	4 4,5,5,4,5,3 2,8 6 6 6 14 10 7	Japanese Maple Black Cherry Smoketree Tree of Heaven Tree of Heaven Black Locust Black Locust Black Locust	Nor Imp Nor Imp Nor Nor X Rer X Rer X Rer Nor	pact ne ne ne nove nove ne	Included in list for HAWP Rev 02 Included in original HAWP Included in original HAWP	19% 0% 5% 0% 0% 100% 0%	100% 100%	has supplemental aluminum tag #190 Poor Poor - 2" dead trunk to be removed Good Good Fair Good	0 0 0 0 0 0 0 0	2455 2456 2457 2458 2459 2460 2460 2461 2462 2463	33 24 24 2 2 2 2 4 2 2 4 2 2 4 8	Red Oak Sugar Maple Slippery Elm Slippery Elm White Mulberry Flowering Dogwood Flowering Dogwood Black Locust		lone Vone Vone Remove Remove Vone Vone Vone Vone Vone Vone Vone Von	Included in original HAWP Included in original HAWP	0% 0% 0% 100% 100% 0% 0% 0% 0%	32% 100% 21% 24%	cavities Fair/Good - swollen at base, deadwood Fair/good - sapsucker holes, ohw, deadwood Good Good Good Good Good Good Good	0 0 2 0 0 0 0 0 0 0 0
2260 2409 2410 2411 2412 2413 2413 2414 2415 2415 2416	4 4.5.5.4.5.3 2,8 6 6 6 14 10 7 7 1	Japanese Maple Black Cherry Smoketree Tree of Heaven Tree of Heaven Black Locust Black Locust Black Locust Slipery Elm	Nor Nor Nor X Rer X Rer Nor X Rer Nor X Rer	pact ne ne ne ne move nove nove nove nove	Included in list for HAWP Rev 02 Included in original HAWP Included in original HAWP Included in original HAWP	19% 0% 5% 0% 0% 100% 0% 100%	100% 100% 100%	has supplemental aluminum tag #190 Poor Good Poor - 2° dead trunk to be removed Good Good Fair Good Good	0 0 0 0 0 0 0 0 0 0	2455 2456 2456 2458 2459 2460 2461 2461 2462 2463 2463 2464	33 24 24 2 2 2 2 2 4 2 2 4 4 2 2 4,4 8 9	Red Oak       Sugar Maple       Slippery Elm       Slippery Elm       White Mulberry       Flowering Dogwood       Flowering Dogwood       Black Locust       Black Locust		kone kone kone kemove kemove kemove kemove kemove kone kone kone kone kone kone kone kon	Included in original HAWP	0% 0% 0% 100% 100% 0% 0% 0% 0% 0% 0% 1%	32% 100% 21% 24% 7%	cavities Fair/Good - swollen at base, deadwood Fair/good - sapsucker holes, ohw, deadwood Good Good Good Good Good Good Good	0 0 2 0 0 0 0 0 0 0 0 0 0
2260 2409 2410 2412 2412 2412 2413 2414 2415 2416 2416 2417 2417	4 4,5,5,4,5,3 2,8 6 6 14 10 7 7 1 1	Japanese Maple Black Cherry Smoketree Tree of Heaven Black Locust Black Locust Black Locust Slippery Elm Slippery Elm	Nor Nor Nor Nor Nor Nor Nor X Rer X Rer X Rer X Rer X Rer	pact ne ne ne nove nove ne nove nove nove no	Included in list for HAWP Rev 02 Included in original HAWP Included in original HAWP Included in original HAWP Included in original HAWP	19% 0% 5% 0% 0% 100% 100% 100%	100% 100% 100%	has supplemental aluminum tag #190 Poor Poor - 2" dead trunk to be removed Good Good Fair Good Good	0 0 0 0 0 0 0 0 0 0 0 0 0 0	2455 2456 2457 2458 2459 2460 2460 2461 2462 2463	33 24 24 2 2 2 2 4 2 2 4 2 2 4 8	Red Oak Sugar Maple Slippery Elm Slippery Elm White Mulberry Flowering Dogwood Flowering Dogwood Black Locust		lone Vone Vone Remove Remove Vone Vone Vone Vone Vone Vone Vone Von	Included in original HAWP Included in original HAWP	0% 0% 0% 100% 100% 0% 0% 0% 0%	32% 100% 21% 24% 7%	cavities Fair/Good - swollen at base, deadwood Fair/good - sapsucker holes, ohw, deadwood Good Good Good Good Good Good Good	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
2260 2409 2410 2411 2411 2412 2413 2413 2415 2415 2415 2415 2416 2417 2418 2418 2418	4 4,5,5,4,5,3 2,8 6 6 6 14 10 7 1 1 1 1	Japanese Maple Black Cherry Smoketree Tree of Heaven Tree of Heaven Black Locust Black Locust Black Locust Slippery Elm Slippery Elm Slippery Elm	Nor Nor X Rer X Rer X Rer X Rer X Rer X Rer X Rer X Rer	pact pact pact ne ne move nove move move move move move	Included in list for HAWP Rev 02 Included in original HAWP	19% 0% 5% 0% 100% 100% 100% 100%	100% 100% 100% 100%	has supplemental aluminum tag #190 Poor Poor - 2° dead trunk to be removed Good Good Fair Good Good Good Good	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2455 2456 2456 2458 2458 2459 2460 2461 2462 2462 2463 2463 2465	33 24 24 24 2 2 2 2 4 4 2 2 4 4 2 4 4 5 9 9 9	Red Oak       Sugar Maple       Slippery Elm       Slippery Elm       White Mulberry       Flowering Dogwood       Flowering Dogwood       Black Locust       Black Locust       Green Ash		ione ione ione ione temove temove temove temove tone ione ione tone tone tone tone tone tone tone t	Included in original HAWP Included in original HAWP	0% 0% 0% 100% 100% 0% 0% 0% 0% 0%	32% 100% 21% 24% 7%	cavities Fair/Good - swollen at base, deadwood at base, deadwood Fair/good - sapsucker holes, ohw, deadwood Good Good Good Good Good Good Good	0 0 2 0 0 0 0 0 0 0 0 0 0 0
2260         2409           2410         2411           2411         2412           2412         2413           2414         2415           2415         2416           2417         2417           2418         2418	4 4,5,5,4,5,3 2,8 6 6 14 10 7 7 1 1	Japanese Maple Black Cherry Smoketree Tree of Heaven Black Locust Black Locust Black Locust Slippery Elm Slippery Elm	Nor Nor X Rer X Rer X Rer X Rer X Rer X Rer X Rer	pact ne ne ne nove nove ne nove nove nove no	Included in list for HAWP Rev 02 Included in original HAWP Included in original HAWP Included in original HAWP Included in original HAWP	19% 0% 5% 0% 0% 100% 100% 100%	100% 100% 100%	has supplemental aluminum tag #190 Poor Poor - 2" dead trunk to be removed Good Good Fair Good Good	0 0 0 0 0 0 0 0 0 0 0 0 0 0	2455 2456 2457 2458 2459 2460 2460 2461 2462 2463 2464 2465 2466	33 24 24 2 2 2 2 2 4 2 2 4 4 2 2 4,4 8 9	Red Oak       Sugar Maple       Slippery Elm       Slippery Elm       White Mulberry       Flowering Dogwood       Flowering Dogwood       Black Locust       Black Locust		kone kone kone kemove kemove kemove kemove kemove kone kone kone kone kone kone kone kon	Included in original HAWP Included in original HAWP	0% 0% 0% 100% 100% 0% 0% 0% 0% 0% 0% 1%	32% 100% 21% 24% 7%	cavities Fair/Good - swollen at base, deadwood Fair/good - sapsucker holes, ohw, deadwood Good Good Good Good Good Good Good	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
2260 2409 2410 2411 2412 2412 2413 2414 2415 2415 2416	4 4,5,5,4,5,3 2,8 6 6 6 14 10 7 1 1 1 1	Japanese Maple Black Cherry Smoketree Tree of Heaven Tree of Heaven Black Locust Black Locust Black Locust Slippery Elm Slippery Elm Slippery Elm	Nor Nor X Rer X Rer X Rer X Rer X Rer X Rer X Rer X Rer	pact pact pact ne ne move nove move move move move move	Included in list for HAWP Rev 02 Included in original HAWP	19% 0% 5% 0% 100% 100% 100% 100%	100% 100% 100% 100%	has supplemental aluminum tag #190 Poor Poor - 2° dead trunk to be removed Good Good Fair Good Good Good Good	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2455 2456 2456 2458 2458 2459 2460 2461 2462 2462 2463 2463 2465	33 24 24 24 2 2 2 2 4 4 2 2 4 4 2 4 4 5 9 9 9	Red Oak       Sugar Maple       Slippery Elm       Slippery Elm       White Mulberry       Flowering Dogwood       Flowering Dogwood       Black Locust       Black Locust       Green Ash		ione ione ione ione temove temove temove temove tone ione ione tone tone tone tone tone tone tone t	Included in original HAWP Included in original HAWP	0% 0% 0% 100% 100% 0% 0% 0% 0% 0%	32% 100% 21% 24% 7%	cavities Fair/Good - swollen at base, deadwood at base, deadwood Fair/good - sapsucker holes, ohw, deadwood Good Good Good Good Good Good Good	0 0 2 0 0 0 0 0 0 0 0 0 0 0
2260 2409 2410 2411 2411 2412 2413 2413 2415 2415 2415 2415 2416 2417 2418 2418 2418	4 4,5,5,4,5,3 2,8 6 6 6 14 10 7 1 1 1 1	Japanese Maple Black Cherry Smoketree Tree of Heaven Tree of Heaven Black Locust Black Locust Black Locust Slippery Elm Slippery Elm Slippery Elm	Nor Nor X Rer X Rer X Rer X Rer X Rer X Rer X Rer X Rer	pact pact pact ne ne move nove move move move move move	Included in list for HAWP Rev 02 Included in original HAWP	19% 0% 5% 0% 100% 100% 100% 100%	100% 100% 100% 100%	has supplemental aluminum tag #190 Poor Poor - 2° dead trunk to be removed Good Good Fair Good Good Good Good	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2455 2456 2457 2458 2459 2460 2460 2461 2462 2463 2464 2465 2466	33 24 24 2 2 2 2 2 2 4 4 2 2 4,4 8 9 9 9 9 5	Red Oak Red Oak Sugar Maple Slippery Elm Slippery Elm White Mulberry Flowering Dogwood Black Locust Black Locust Green Ash White Mulberry		kone kone kone kone kemove kemove kemove kemove kemove kone kone kone kone kone kone kone kon	Included in original HAWP Included in original HAWP	0% 0% 0% 100% 100% 0% 0% 0% 0% 0%	32% 100% 21% 24% 7%	cavities Fair/Good - swollen at base, deadwood Fair/good - sapsucker holes, ohw, deadwood Good Good Good Good Good Good Good	0 0 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0

# LEGEND

TREES TO BE REMOVED

TREES WHICH WILL BE IMPACTED