Address:	7500 Maple Ave., Takoma Park	Meeting Date:	6/25/2025
Resource:	Multiple Resources Takoma Park Historic District	Report Date:	6/18/2025
Project Contact	: City of Takoma Park	Public Notice:	6/11/2025
Review:	HAWP	Tax Credit:	No
Case Number:	1119049	Staff:	Dan Bruechert
Proposal:	Right-of-way alterations associated with the Map	le Ave. Connectivity	Project

MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION STAFF REPORT

RECOMMENDATION

Staff recommends that the Historic Preservation Commission **approve** the HAWP application.

PROPERTY DESCRIPTION

SIGNIFICANCE:Outstanding and Contributing Resources to the Takoma Park Historic DistrictSTYLE:Right-of-WayDATE:Platted 1883



Figure 1: The project is on Maple Ave. from Philadelphia Ave. to the Takoma Park/DC line.

PROPOSAL

The applicant proposes to install traffic calming measures along Maple Ave. within the Takoma Park Historic District.

APPLICABLE GUIDELINES

The Historic Preservation Office and Historic Preservation Commission (HPC) consult several documents when reviewing alterations and new construction within the Takoma Park Historic District. These documents include the historic preservation review guidelines in the approved and adopted amendment for the *Takoma Park Historic District (Guidelines), Montgomery County Code Chapter 24A (Chapter 24A),* and the *Secretary of the Interior's Standards for Rehabilitation (Standards).* Ordinarily, projects occurring in the section of the historic district known as "Takoma Old Town" also utilize Ordinance No. 2592, which provide additional guidance within this commercial area. The ordinance does not include any guidance for work in the public right-of-way or infrastructure improvements. The pertinent information in these four documents is outlined below.

Takoma Park Historic District Guidelines

There are two broad planning and design concepts which apply to all categories. These are:

- The design review emphasis will be restricted to changes that are all visible from the public rightof-way, irrespective of landscaping or vegetation (it is expected that the majority of new additions will be reviewed for their impact on the overall district), and
- The importance of assuring that additions and other changes to existing structures act to reinforce and continue existing streetscape, landscape, and building patterns rather than to impair the character of the historic district.

Public Improvements

Although much of Takoma Park's architectural and historical significance is derived directly from the built environment, there are overall community features which contribute greatly – and are in fact integral – to the historic ambiance of this "garden suburb." These features should be recognized and preserved as part of the setting for this historic district.

... Another feature which is closely related to the sense of open space in the district is the existence of a large number of mature trees and extensive landscaping throughout the community. All public improvements in Takoma Park should strive to create the minimal disturbance possible to these types of natural features...

... Finally, the roads which pass through Takoma Park have a major impact on the character of this historic community. The Montgomery County Department of Transportation and the Maryland State Highway Administration should be sensitive to the importance of Takoma Park as a historic district and should assure that road and sidewalk improvements are done in such a way as to enhance, rather than detract, from the historic ambiance of Takoma Park. In particular, any changes to Philadelphia Avenue (MD 410), Piney Branch Road (MD 320), and Carroll Avenue (MD 195) should be carefully considered and designed to be in keeping with Takoma Park's historic character.

Montgomery County Code, Chapter 24A-8

The following guidance which pertains to this project are as follows:

- (b) The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to ensure conformity with the purposes and requirements of this chapter, if it finds that:
 - (1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or
 - (2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter;
 - (3) The proposal would enhance or aid in the protection, preservation and public or private utilization of the historic site or historic resource located within an historic district in a manner compatible with the historical, archeological, architectural or cultural value of the historic site or historic district in which an historic resource is located; or
 - (4) The proposal is necessary in order that unsafe conditions or health hazards be remedied;
- (d) In the case of an application for work on an historic resource located within an historic district, the commission shall be lenient in its judgment of plans for structures of little historical or design significance or for plans involving new construction, unless such plans would seriously impair the historic or architectural value of surrounding historic resources or would impair the character of the historic district. (Ord. No. 9-4, § 1; Ord. No. 11-59.)

Secretary of the Interior's Standards for Rehabilitation

The Secretary of the Interior defines rehabilitation as "the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features, which convey its historical, cultural, or architectural values." The applicable *Standards* are as follows:

- 2. The historic character of a property will be retained and preserved. The removal of distinctive materials or alteration of features, spaces and spatial relationships that characterize a property will be avoided.
- 5. Distinctive materials, features, finishes and construction techniques or examples of craftsmanship that characterize a property will be preserved.
- 6. Deteriorated historic features will be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature will match the old in design, color, texture, and, where possible, materials. Replacement of missing features will be substantiated by documentary and physical evidence.
- 9. New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.
- 10. New additions and adjacent or related new construction shall be undertaken in such a manner that if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

STAFF DISCUSSION

The proposed project is intended to install several traffic calming measures along Maple Ave. in the Takoma Park Historic District. The proposed work involves removing several existing speed humps/bumps, installing chicanes and curb extensions, raising an intersection, constructing a median, and installing several signs and selective painting.¹ Staff finds the overall impact to the historic district will be minimal and recommends the HPC approve the alterations. Staff additionally notes that all of this work can be removed at a future date and the roadway can be returned to its existing condition as required by *Standard #10*. Only one tree will be removed as part of this infrastructure project, a 3" d.b.h. (three-inch diameter at breast height) Red Maple. Removing this tree does not require a HAWP.




Figure 2: Maple Ave. (highlighted) was platted in B.F. Gilbert's 1883 Plat for Takoma Park.

Maple Avenue was originally platted as a 40' (forty foot wide) right-of-way in the 1883 plat for Takoma

¹ The Mandatory Referral submission was considered at the May 29, 2025 Planning Board Meeting. The Staff Report for that hearing is available here: <u>https://montgomeryplanningboard.org/wp-content/uploads/2025/05/Maple-</u>Avenue-Connectivity-Project-Mandatory-Referral-MR2025001.pdf.

Park (see *Fig. 2*, above). The street is only 22' (twenty-two feet) wide from the Washington DC line to Tulip Ave. From Tulip Ave. to Philadelphia Ave., Maple Avenue is 28' (twenty-eight feet) wide.

First, the applicant proposes to remove the existing 7 (seven) speed humps along Maple Ave. While the installation date of these features is unknown, speed bumps are not characteristic of historic districts. Staff finds the historic ambiance or 'garden suburb' will not be negatively impacted by removing the speed bumps and Staff recommends the HPC approve their removal under the *Design Guidelines* and 24A-8(b)(2) and (d), and *Standard #2*.

Second, the applicant proposes to install 13 (thirteen) curb extensions/chicanes along Maple Ave. These are concrete traffic calming features that project approximately 8' (eight feet) into the roadway (see *Figure 3*, below). The chicanes will be detached from the existing curb to maintain existing gutter flow and are located so as not to interrupt access to any of the existing driveways. The drawings submitted with the mandatory referral review note the chicane curbs will be 6'' (six inches tall) and notated the chicanes as 'planted/grass area(s).' One chicane, located at a Ride-On bus stop, will be concrete. The intended effect of the chicanes is to narrow the roadway so that cars need to slow down so that only one car may pass through an area at a time.



Figure 3: A typical chicane on a residential street.

Staff finds the introduction of the chicanes will not disrupt the character of the roadway and finds the planted area of the chicanes will enhance the garden suburb character of the historic district rather than detract from it (per the *Design Guidelines*) and further finds it is consistent with 24A-8(b)(2) and (d), and Standard 2.

Third, the applicant proposes to extend the curb at two intersections the southeast corner of Maple Ave. and Tulip Ave. and the northwest corner of Maple Ave. and Old Philadelphia Ave. These curb extensions will extend into the existing roadway and will be constructed using painted concrete. These new curbs will create a narrower turning radius, requiring drivers to take these turns at a slower speed. Staff finds the visual effect of these curb expansions will be minimal on the historic district and reinforce the materials and character of the district as required under the *Design Guidelines*, 24A-8(b)(2) and (d), and *Standard #2*.

Fourth, the applicant proposes to rebuild the intersection of Maple Ave. and Tulip Ave. to raise the

intersection. The effect of this construction will be to create a speed hump at the existing four-way stop. Staff finds raising the intersection by several inches will not have a significant impact on the visual or historic character along Maple Ave., particularly as the material will not be changed. Staff recommends the HPC approve the raised intersection at Maple and Tulip Ave. under the *Design Guidelines*, 24A-8(b)(2) and (d), and *Standard #2*.

Fifth, the applicant proposes to construct a 6' (six foot) wide median just to the south of the intersection of Philadelphia Ave. and Maple Ave. The median will have a planted area in the middle, and it is colocated with a crosswalk across Maple Ave. The median will force cars to slow down, thereby improving the pedestrian safety of the crosswalk. Staff finds this type of median is common traffic-calming feature found in urban and suburban context, and it will not appear out of place in this location. Staff further finds the planted median will help to reinforce the garden suburb ambiance identified in the *Design Guidelines*. Staff recommends the HPC approve the median under 24A-8(b)(2) and (d), the *Design Guidelines*, and *Standard 2*.

Finally, the applicant proposes to install several signs and paint the pavement. Several signs identifying the location of Ride-On bus stops are identified on the plans. Staff is unsure if these signs will replace existing signs or are new features. However, Staff finds WMATA and Ride-On signs are found throughout the historic district and are essential for public transportation and should be approved as a matter of course under the 24A-8(d). The applicant also proposes to paint the paving to identify crosswalks and shared lane markings directing motorists to yield to bicycles. Staff finds painting the roadway is commonly found throughout the historic district and are intended to improve roadway safety. Staff finds the painting should be approved as a matter of course under the *Design Guidelines;* 24A-8(b)(2), (4), and (d); and *Standard* 2.

STAFF RECOMMENDATION

Staff recommends that the Commission **approve** the HAWP application; under the Criteria for Issuance in Chapter 24A-8(b)(2), (4), and (d), having found that the proposal will not substantially alter the exterior features of the historic resource and is compatible in character with the district and the purposes of Chapter 24A;

and with the Secretary of the Interior's Standards for Rehabilitation #2 and #10;

and with the general condition that the applicant shall present an electronic set of drawings, if applicable, to Historic Preservation Commission (HPC) staff for review and stamping prior to submission for the Montgomery County Department of Permitting Services (DPS) building permits;

and with the general condition that final project design details, not specifically delineated by the Commission, shall be approved by HPC staff or brought back to the Commission as a revised HAWP application at staff's discretion;

and with the general condition that the applicant shall notify the Historic Preservation Staff if they propose to make **any alterations** to the approved plans. Once the work is completed the applicant will <u>contact the staff person</u> assigned to this application at 301-563-3400 or <u>dan.bruechert@montgomeryplanning.org</u> to schedule a follow-up site visit.

GOMERY CO	For Staff only: HAWP#
APPLICATION HISTORIC AREA WO HISTORIC PRESERVATION 301.563.340	
APPLICANT:	
Name: Rosalind Grigsby (H&CDD)	E-mail:rosalindg@takomaparkmd.gov
Address: 7500 Maple Ave	_{E-mail:} <u>rosalindg@takomaparkmd.gov</u> _{City:} <u>Takoma Park</u> _{Zip:} 20912
Daytime Phone: (301) 891-7119	Tax Account No.: N/A
AGENT/CONTACT (if applicable):	
_{Name:} Rosalind Grigsby	E-mail:rosalindg@takomaparkmd.gov
Address: 7500 Maple Ave	_{City:} Takoma Park _{Zip:} 20912
Daytime Phone: (301) 891-7119	Contractor Registration No.: <u>N/A</u>
LOCATION OF BUILDING/PREMISE: MIHP # of Histori	_{c Property} M:37-3
Is the Property Located within an Historic District? \underline{X}	Takoma Park Historic District
Is there an Historic Preservation/Land Trust/Environme map of the easement, and documentation from the Eas	ental Easement on the Property? If YES, include a
Are other Planning and/or Hearing Examiner Approvals (Conditional Use, Variance, Record Plat, etc.?) If YES, in supplemental information.	
Building Number: Street:	
Town/City: Nearest Cros	s Street:
Lot: Block: Subdivision:	Parcel:
TYPE OF WORK PROPOSED: See the checklist on Pa for proposed work are submitted with this applica	tion. Incomplete Applications will not
be accepted for review. Check all that apply: New Construction Deck/Porch	Shed/Garage/Accessory Structure
Addition Fence	Tree removal/planting
Demolition V Hardscape/Lands	
Grading/Excavation Roof	Other:
I hereby certify that I have the authority to make the for and accurate and that the construction will comply wit	
agencies and hereby acknowledge and accept this to b Resalind Grigsby	be a condition for the issuance of this permit.

7

HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFING [Owner, Owner's Agent, Adjacent and Confronting Property Owners]								
Owner's mailing address Rosalind Grigsby Housing & Community Development Dept 7500 Maple Ave Takoma Park, MD 20912 Adjacent and confronting	Owner's Agent's mailing address Rosalind Grigsby Housing & Community Development Dept 7500 Maple Ave Takoma Park, MD 20912 Property Owners mailing addresses							
Potomac Electric Power Co. Ms. Belinda Reid, Customer Contacts Manager 701 9th St NW Rm 7412 Washington, DC 20001-4572	City of Takoma Park Daryl Braithwaite, Public Works Director 31 Oswego Ave Takoma Park, MD 20912							
Takoma Business Center LLC 6930 Carroll Avenue Takoma Park, MD 20912	Dance Exchange 7117 Maple Ave Takoma Park, MD 20912							
James B. Garner 7421 Maple Avenue Takoma Park, MD 20912	See attached page for remaining address							

7100 Maple Avenue Takoma Park, MD 20912

7102-4 Maple Avenue Takoma Park, MD 20912

7106-8 Maple Avenue Takoma Park, MD 20912

7123 Maple Avenue Takoma Park, MD 20912

7110 Maple Avenue Takoma Park, MD 20912

7112 Maple Avenue Takoma Park, MD 20912

7116 Maple Avenue Takoma Park, MD 20912

7118 Maple Avenue Takoma Park, MD 20912

7120 Maple Avenue Takoma Park, MD 20912

7122 Maple Avenue Takoma Park, MD 20912

7124 Maple Avenue Takoma Park, MD 20912

7200 Maple Avenue Takoma Park, MD 20912

7202 Maple Avenue Takoma Park, MD 20912

7204 Maple Avenue Takoma Park, MD 20912

7206 Maple Avenue Takoma Park, MD 20912 7208 Maple Avenue Takoma Park, MD 20912

7210 Maple Avenue Takoma Park, MD 20912

7212 Maple Avenue Takoma Park, MD 20912

7214 Maple Avenue Takoma Park, MD 20912

7216 Maple Avenue Takoma Park, MD 20912

7218 Maple Avenue Takoma Park, MD 20912

7300 Maple Avenue Takoma Park, MD 20912

7302 Maple Avenue Takoma Park, MD 20912

7304 Maple Avenue Takoma Park, MD 20912

7306 Maple Avenue Takoma Park, MD 20912

7310 Maple Avenue Takoma Park, MD 20912

7312 Maple Avenue Takoma Park, MD 20912

7314 Maple Avenue Takoma Park, MD 20912

7316 Maple Avenue Takoma Park, MD 20912

7400 Maple Avenue Takoma Park, MD 20912 7402 Maple Avenue Takoma Park, MD 20912

7404 Maple Avenue Takoma Park, MD 20912

7406 Maple Avenue Takoma Park, MD 20912

7408 Maple Avenue Takoma Park, MD 20912

7410 Maple Avenue Takoma Park, MD 20912

7412 Maple Avenue Takoma Park, MD 20912

7414 Maple Avenue Takoma Park, MD 20912

7416 Maple Avenue Takoma Park, MD 20912

7418 Maple Avenue Takoma Park, MD 20912

7420 Maple Avenue Takoma Park, MD 20912

7125 Maple Avenue Takoma Park, MD 20912

7127 Maple Avenue Takoma Park, MD 20912

7129 Maple Avenue Takoma Park, MD 20912

7131 Maple Avenue Takoma Park, MD 20912

7133 Maple Avenue Takoma Park, MD 20912

7135 Maple Avenue Takoma Park, MD 20912

7137 Maple Avenue Takoma Park, MD 20912

7207 Maple Avenue Takoma Park, MD 20912

7209 Maple Avenue Takoma Park, MD 20912

7211 Maple Avenue Takoma Park, MD 20912

7213 Maple Avenue Takoma Park, MD 20912

7215 Maple Avenue Takoma Park, MD 20912

7217 Maple Avenue Takoma Park, MD 20912

7219 Maple Avenue Takoma Park, MD 20912

7301 Maple Avenue Takoma Park, MD 20912

7305 Maple Avenue Takoma Park, MD 20912

7307 Maple Avenue Takoma Park, MD 20912

7309 Maple Avenue Takoma Park, MD 20912

7311 Maple Avenue Takoma Park, MD 20912

7313 Maple Avenue Takoma Park, MD 20912 7315 Maple Avenue Takoma Park, MD 20912

7401 Maple Avenue Takoma Park, MD 20912

7403 Maple Avenue Takoma Park, MD 20912

7405 Maple Avenue Takoma Park, MD 20912

7407 Maple Avenue Takoma Park, MD 20912

7409 Maple Avenue Takoma Park, MD 20912

7411 Maple Avenue Takoma Park, MD 20912

7413 Maple Avenue Takoma Park, MD 20912

1 Valley View Ave Takoma Park, MD 20912

7417 Maple Avenue Takoma Park, MD 20912

7419 Maple Avenue Takoma Park, MD 20912 Description of Property: Please describe the building and surrounding environment. Include information on significant structures, landscape features, or other significant features of the property:

The area of work will occur along Maple Avenue from the DC/Montgomery County line north of Carroll Avenue to Philadelphia Avenue. This section of Maple Avenue is narrower than other sections and is typically 26 feet wide from curb to curb. The posted speed limit in the neighborhood is 25 MPH, the road additionally has traffic calming measures, including speed humps and a raised intersection. The road also features on-street parking, multiple bus stops, and continuous sidewalks with a green buffer on the northbound side.

The buildings along this stretch of Maple Avenue include single-family residences, with architectural styles consisting of bungalows, Craftsman, Colonial Revival, Cape Cod, and minimal traditional houses. Takoma Park Historic District is important for its botanical environment as a large number of scientists and horticulturists working for the Department of Agriculture established the neighborhood in the early twentieth century. The neighborhood was founded in 1884 when the members sought to include ideas of picturesque landscaping and planning (Stowell 1973).

Description of Work Proposed: Please give an overview of the work to be undertaken:

The proposed work includes supplementing and enhancing/improving the traffic calming measures. The current concept plans propose landscaped intermittent curb extensions along Maple Avenue. The curb extensions will not be wider than the width of a car and all access to driveways will be retained. The purpose of this is to force drivers to maintain slower speeds along the street, even when cars are not parked on the street. The curb extensions will be free standing/detached from the sidewalk and extant curb, allowing water to flow to the gutter without any changes. Shared lane marking will be applied to the street to alert drivers of bicyclist and pedestrians. These lane markings will adhere to the MdMUTCD standards. Crosswalk improvements consisting of raising the crosswalks and better striping will be included in the work. Transit waiting areas will be improved where possible.

Description of Current Condition:	Proposed Work:
Narrow roadway with continuous on-street parking on both sides except for at residential driveways.	The concept plans propose intermittent landscaped curb extensions along Maple Avenue. These will be no wider than the width of a parked car and placed to maintain access to all residential driveways. These elements will mimic a parked car and reinforce the yield street condition. The proposed curb extensions are detached to maintain existing gutter flow. No drainage structures on this section will be impacted by the proposed improvements.
	•
Work Item 2: Crosswalk Upgrades	•
Work Item 2: Crosswalk Upgrades	Proposed Work:


Work Item 3: Shared Lane Markings	
Description of Current Condition:	Proposed Work:
Currently there are no shared lane markings to alert cars to watch out for bikers. Current traffic calming measures include speed humps and a raised intersection.	Shared lane markings shall be placed in accordance with the MdMUTCD.

HISTORIC AREA WORK PERMIT CHECKLIST OF APPLICATION REQUIREMENTS

	Required Attachments						
Proposed Work	I. Written Description	2. Site Plan	3. Plans/ Elevations	4. Material Specifications	5. Photographs	6. Tree Survey	7. Property Owner Addresses
New Construction	*	*	*	*	*	*	*
Additions/ Alterations	*	*	*	*	*	*	*
Demolition	*	*	*		*		*
Deck/Porch	*	*	*	*	*	*	*
Fence/Wall	*	*	*	*	*	*	*
Driveway/ Parking Area	*	*		*	*	*	*
Grading/Exc avation/Land scaing	*	*		*	*	*	*
Tree Removal	*	*		*	*	*	*
Siding/ Roof Changes	*	*	*	*	*		*
Window/ Door Changes	*	*	*	*	*		*
Masonry Repair/ Repoint	*	*	*	*	*		*
Signs	*	*	*	*	*		*



Photograph 1: View of Maple Avenue from 7421 Maple Avenue, near Philadelphia Avenue, looking southwest (RK&K June 2023). Project plans indicate a curb extension at this location.




Photograph 2: View of Maple Avenue from 7122 Maple Avenue, looking northeast (RK&K June 2023). According to project plans a curb extension will be added near the stop sign, just prior to the intersection.



Photograph 3: View of the intersection of Tulip and Maple Avenues, looking northwest (RK&K June 2023). According to project plans a curb extension will be added near the stop sign, just prior to the intersection.



Photograph 4: View of the intersection of Tulip and Maple Avenues, looking southwest (RK&K June 2023). According to project plans a curb extension will be added in front of the mailbox, just after the intersection.



Photograph 5: View of Maple Avenue from 7131 Maple Avenue, looking southwest towards Carroll Avenue (RK&K June 2023). According to project plans curb extensions will be added on each side of the crosswalk stripes.



TYPICAL SECTION 1 CITY LINE TO PHILADELPHIA AVENUE

← WEST

EAST →



TYPICAL SECTION 1A EAST ->

WEST

Tree ID T1	Scientific Name	Species	DBH	Condition	MAPLE AVENUE TREE INVENTORY TABLE Comments	Remov
		Red maple	20		Broken branches, included bark, exposed roots, trunk wound, overhanging sidewalk and curb	
2		Red maple	20			
			-		Girdling roots, overhanging sidewalk and curb, broken branches	
3	Quercus bicolor	Swamp white oak	2		Some branch damage, tree cage needs to be removed	
4	Quercus bicolor	Swamp white oak	2		Some branch damage, tree cage needs to be removed	
5	Quercus bicolor	Swamp white oak	2	Good	Some branch damage, tree cage needs to be removed	
6	Quercus bicolor	Swamp white oak	2	Good/Fair	Some branch damage, tree cage needs to be removed, improper trunk flair, some watersprouts	
7		Sugar maple	5		Trunk wound, some broken branches	
, 8			17		Exposed roots, pushing against sidewalk, pruning damage, under power line, some dead broken branches	
		Sugar maple				
		Sugar maple	7		Some larger dead branches, girdled roots	
10	Platanus occidentalis	American sycamore	13	Good/Fair	Some exposed roots, some dead branches	
11	Acer rubrum	Red maple	12	Good/Fair	Exposed, girdling roots, some pruning damage	
12		Red maple	9		Exposed, girdling roots, some pruning damage	
			2			
13	Quercus bicolor	Swamp white oak	2	<u> </u>	Some tip dieback, weak trunk flair	
14		Eastern red cedar	14	Good/Fair	Overhanging sidewalk, pruning on trunk, some dieback in lower canopy, some dead branches	
15	Juniperus virginiana	Eastern red cedar	17	Good	Twin of 11" and 17", interfering with powerlines, some dead branches	
16		Little-leaf linden	2	Good		
17		American sycamore		Good		
		Sugar maple	17		Some trunk damage and exposed roots, lean, some broken branches	
		American sycamore	5	Fair	Some broken branches and exposed roots, water sprouts, poor growth form	
20	Platanus occidentalis	American sycamore	10	Good/Fair	Exposed roots, lean, some broken branches	
21		American sycamore			Some poorly pruned branches on trunk, partially dead leader, trunk wound	
22	Tilia cordata	Little-leaf linden				
			2		Some pruning damage and dead branches	
23		American sycamore			Exposed roots, some pruned branches	
24	Acer saccharum	Sugar maple	22	Good/Fair	Some pruned branches, some girdled exposed roots, slight lean	
25		Sugar maple	19		Some pruned branches, some girdled exposed roots, slight lean	
		Eastern white pine	22		Overhangs, some dead and broken branches	
27		Eastern white pine	21		Overhangs, some dead branches	
		Sugar maple	5		Some pruned branches	
29	Acer saccharum	Sugar maple	5	Good	Exposed fine roots	
		Pin oak	22		Minor exposed roots	
31	Acer saccharum	Sugar maple	4		Poor root flair, broken branches	
			1			
		Sugar maple	4		Poor root flair, broken branches	
33	Tilia americana	American linden	13		Overhanging	
34	Acer saccharum	Sugar maple	5	Good/Fair	Sap sucker holes, poor root flair	
		Deodar cedar	26		Some dead branches, overhanging	
36	Tilia americana	American linden	13		Overhanging	
		Sugar maple	5	Good	Healed over trunk wound, poorly pruned branches	
38	Acer saccharum	Sugar maple	2	Good		
39	Cedrus deodara	Deodar cedar	23	Good/Fair	Sap sucker holes, pruned and dead branches	
		Bradford pear	21	<u> </u>	Overhanging, some dead branches, lean	
			21			
41	Acer saccharum	Sugar maple	4		Some pruning damage, some exposed roots	
42	Acer saccharum	Sugar maple	22		Some pruning damage, some broken branches	
43*	Acer saccharum	Sugar maple	26	Good/Fair	Some exposed roots, healed over trunk wounds, some dead branches	
44*	Acer saccharum	Sugar maple	25	Good/Fair	Exposed roots, lean, dead and broken branches	
	Acer saccharum	Sugar maple	21		Exposed girdled roots, dead and broken branches	
			3		Exposed gir dred roots, dead and broken branches	x
		Red maple	3	Good		×
		Crepe myrtle	4	Good	Multi-stemmed, two 2", 3", 4" trunks	
48	Quercus alba	White oak	15	Good		
	l a manatra amia an				Multi stammad tuva / 2 tuva 2 trumka	
49	Lagerstroemia sp.	Crepe myrtle	4	Good	Mulli-slemmed two 4 , 3 , two 2 - trunks	
	· ·	, ,	4 4		Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed two 4", three 3", 2" trunks	
50	Lagerstroemia sp.	Crepe myrtle	4	Good	Multi-stemmed two 4", three 3", 2" trunks	
50 51	Lagerstroemia sp. Lagerstroemia sp.	Crepe myrtle Crepe myrtle	4 4 4	Good Good	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks	
50 51 52	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp.	Crepe myrtle Crepe myrtle Crepe myrtle	4 4 4 4	Good Good Good	Multi-stemmed two 4", three 3", 2" trunks	
50 51 52	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum	Crepe myrtle Crepe myrtle Crepe myrtle Red maple	4 4 4 4 8	Good Good	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks	
50 51 52 53	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum	Crepe myrtle Crepe myrtle Crepe myrtle Red maple	4 4 4 4 8 4	Good Good Good Good	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks	
50 51 52 53 54	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp.	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle	4	Good Good Good Good Good	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks	
50 51 52 53 54 55*	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple	4 27	Good Good Good Good Good Good/Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk	
50 51 52 53 54 55* 56**	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak	4 27 32	Good Good Good Good Good/Fair Good/Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches	
50 51 52 53 54 55* 56** 56**	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa	4 27 32 28	Good Good Good Good Good/Fair Good/Fair Good/Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches	
50 51 52 53 54 55* 56** 56**	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak	4 27 32	Good Good Good Good Good/Fair Good/Fair Good/Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches	
50 51 52 53 54 55* 56** 57* 57* 58*	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak	4 27 32 28 24	Good Good Good Good Good/Fair Good/Fair Good Good/Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches	
50 51 52 53 54 55* 56** 56** 57* 58* 58* 59**	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus rubra	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak	4 27 32 28 24 32	Good Good Good Good/Fair Good/Fair Good/Fair Good/Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Exposed roots, abutting sidewalk, dead broken branches	
50 51 52 53 54 55* 55* 55* 57* 58* 59** 60*	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus rubra Picea abies	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak	4 27 32 28 24 32 27	Good Good Good Good Good/Fair Good/Fair Good Good/Fair Fair Good	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 61**	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus rubra Picea abies Quercus alba	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin cak Northern catalpa White oak Northern red oak Northern red oak Norway spruce White oak	4 27 32 28 24 32 27	Good Good Good Good Good/Fair Good/Fair Good/Fair Fair Good Good/Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Overhanging into road, some dead branches Some dead branches	
50 51 52 53 54 55* 55* 55* 55* 55* 55* 55* 55* 55*	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp.	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin cak Northern catalpa White oak Northern red oak Northern red oak Norway spruce White oak Crepe myrtle	4 27 32 28 24 32 27 32 32 3	Good Good Good Good Good/Fair Good/Fair Fair Good Good/Fair Good Good/Fair Good/Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead broken branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Some dead branches Multi-stemmed, branch damage	
50 51 52 53 54 55* 55* 55* 55* 55* 55* 55* 55* 55*	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp.	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin cak Northern catalpa White oak Northern red oak Northern red oak Norway spruce White oak	4 27 32 28 24 32 27	Good Good Good Good Good/Fair Good/Fair Fair Good Good/Fair Good Good/Fair Good/Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Overhanging into road, some dead branches Some dead branches	
50 51 52 53 54 55* 56** 57* 59** 60* 61** 62 63	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud	4 27 32 28 24 32 27 32 32 3 10	Good Good Good Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead broken branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 61** 61** 62 63 64	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak Northern red oak Crepe myrtle Eastern red bud Pin oak	4 27 32 28 24 32 27 32 3 10 15	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Watersprouting, dead branches, exposed roots, interfering with powerlines	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 60* 60* 60* 61** 62 63 64 65	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak Northern red oak Crepe myrtle Eastern red bud Pin oak Pin oak	4 27 32 28 24 32 27 32 27 32 3 10 15 18	Good Good Good Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Overhanging into road, some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Watersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form	
50 51 52 53 554 55* 55* 57* 58* 59** 60* 61** 60* 61** 62 63 64 65 66	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Watersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form	
50 51 52 53 554 55* 55* 55* 55* 55* 55* 55* 60* 61** 60* 61** 62 63 64 65 66 66 67	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Watersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form	
50 51 52 53 554 55* 55* 55* 55* 55* 55* 55* 60* 61** 60* 61** 62 63 64 65 66 66 67	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Watersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form	
50 51 52 53 554 55* 55* 55* 55* 55* 55* 55* 55* 55*	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris Quercus palustris Quercus palustris Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Watersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form	
50 51 52 53 554 55* 55* 55* 55* 55* 55* 55* 55* 55*	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris Quercus palustris Quercus palustris Quercus palustris Quercus palustris Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak Pin oak Pin oak Pin oak	4 27 32 28 24 32 27 32 37 32 3 10 15 18 18 18 20 15 14	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead broken branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Overhanging into road, some dead branches Some dead branches Some dead branches Some dead branches Some pruning damage, some dead and broken branches, interfering with powerlines Watersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form	
50 51 52 53 54 55* 55* 55* 55* 55* 55* 55* 55* 55*	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak Pin oak Pin oak Pin oak Pin oak	4 27 32 28 24 32 27 32 27 32 3 10 15 18 18 18 18 20 15 14 12	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead broken branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Some dead branches Some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Watersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form	
50 51 52 53 54 55* 56** 55* 56** 55* 56** 57* 58* 59** 50* 50* 50* 50* 50* 50* 50* 5	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak Pin oak Pin oak Pin oak Pin oak Pin oak Pin oak Pin oak	4 27 32 28 24 32 27 32 27 32 3 10 15 18 18 18 20 15 14 12 5	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Watersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines	
50 51 52 53 54 55* 55* 55* 55* 55* 55* 55* 55* 55*	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak	4 27 32 28 24 32 27 32 27 32 3 10 15 18 18 18 18 20 15 14 12	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging into road, some dead branches Overhanging into road, some dead branches Some dead branches Some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Watersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines	
50 51 52 53 54 55* 55* 55* 55* 55* 55* 55* 55* 55*	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak Pin oak Pin oak Pin oak Pin oak Pin oak Pin oak Pin oak	4 27 32 28 24 32 27 32 27 32 3 10 15 18 18 18 20 15 14 12 5	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging into road, some dead branches Overhanging into road, some dead branches Some dead branches Some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Watersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines	
50 51 52 53 54 55* 56** 57* 58* 59** 50* 50* 50* 50* 50* 50* 50* 5	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak Northern red oak Northern red oak Northern red bud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Overhanging into road, some dead broken branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Watersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water spr	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 60* 60* 60* 60* 60* 60* 6	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak Northern red oak Northern red bud Vhite oak Crepe myrtle Eastern red bud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead broken branches Some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Watersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form. Dead broken branches, exposed roots, water sprouting, poor growth form. Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerl	
50 51 52 53 54 55* 56** 57* 58* 59** 50* 50* 50* 50* 50* 50* 50* 5	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8	Good Good Good Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Overhanging into road, some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 60* 60* 60* 60* 60* 60* 6	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris Cercis canadensis	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak Eastern redbud Pin oak Eastern redbud	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8 8 13 7 4 4	Good Good Good Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging into road, some dead branches Overhanging into road, some dead broken branches Overhanging into road, some dead broken branches Some dead branches Some dead branches Some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Watersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor gr	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 60* 60* 60* 60* 60* 60* 6	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak Eastern redbud Pin oak Eastern redbud Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8	Good Good Good Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Overhanging into road, some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with	
50 51 52 53 554 55* 55* 55* 55* 55* 55* 55* 55* 60* 60* 60* 60* 60* 60* 60* 60* 60* 60	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak Eastern redbud Pin oak Eastern redbud Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8 8 13 7 4 4	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead broken branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Matersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 61** 60* 61** 62 63 64 65 66 67 66 67 68 67 70 71 72 73 74 75 76 77 78	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak Eastern redbud Pin oak Eastern redbud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 15 18 18 20 15 14 12 5 8 8 13 7 4 4 16 9	Good Good Good Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead broken branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form. Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering	
50 51 52 53 54 55* 56** 55* 56** 57* 58* 59** 60* 61** 662 663 664 665 666 67 668 667 70 71 72 73 74 75 76 77 78 79	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8 8 13 7 4 4 4 16 9 9 13	Good Good Good Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging into road, some dead broken branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead broken branches Some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerli	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 61** 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 80	Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus alba Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 15 18 18 20 15 14 12 5 8 8 13 7 4 4 16 9	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Dead broken branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Broken branches, water sprouting, interfering with powerlines Broken branches, water sprouting, interfering with powerlines Broken	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 61** 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 80	Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus alba Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8 8 13 7 4 4 4 16 9 9 13	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging into road, some dead broken branches Exposed roots, abutting sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead broken branches Some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerli	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 61** 62 63 64 65 66 67 70 71 72 73 74 75 76 77 78 80 81	Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak Eastern redbud Pin oak Eastern redbud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8 8 13 7 4 4 4 16 9 9	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, dead broken branches Exposed roots, abutting sidewalk, dead broken branches Some dead branches Some dead branches Multi-stemmed, branch damage Some dead branches Multi-stemmed, branch damage Some dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form. Dead broken branches, exposed roots, water sprouting, poor growth form. Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, w	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 61** 62 63 64 65 66 67 68 66 67 68 66 67 70 71 72 73 74 75 76 77 78 80 81 82	Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Acer rubrum Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8 8 13 7 4 4 4 16 9 9 13 9 11 17	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed M Multi-stemmed M Multi-stemmed two 4", 3" trunks Some exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging into road, some dead broken branches Some dead branches Some dead branches Some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Matersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Exposed roots, broken branches, water sprouting, interfering with powerlines Exposed roots, broken branches, water sprouting, interfering w	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 61** 60* 61** 62 63 64 65 66 67 66 67 68 66 70 71 72 73 74 75 76 77 78 79 80 81 82 83*	Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus alba Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 18 20 15 14 12 5 8 8 13 7 4 4 16 9 9 11 17 25	Good Good Good Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging into road, some dead branches Overhanging into road, some dead branches Overhanging into road, some dead branches Some pruning damage, some dead and broken branches, interfering with powerlines Watersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Exposed roots, broken branches, water sprouting, inte	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 61** 60* 61** 60* 63 64 65 66 66 67 70 71 72 73 74 75 76 77 78 79 80 81 82 83*	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8 13 7 4 4 4 16 9 11 17 25 34	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Exposed roots, abutting sidewalk, some dead branches Exposed roots, abutting sidewalk, some dead branches Overhanging into road, some dead branches Overhanging into road, some dead branches Some dead branches Multi-stemmed, branch damage Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Matersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form. Dead broken branches, exposed roots, water sprouting, poor growth form. Dead broken branches, exposed roots, water sprouting, poor growth form. Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Exposed roots, broken branches, water sprouting, interf	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 61** 60* 61** 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83* 84**	Lagerstroemia sp. Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8 13 7 4 4 16 9 11 17 25 34 11	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, voerhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead broken branches Overhanging into road, some dead broken branches Overhanging into road, some dead broken branches Overhanging into road, some dead broken branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Matersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Exposed roots, broken branches, water sprouting, interfering with powerlines Exposed roots, broken bran	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 60* 60* 60* 60* 60* 60* 6	Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Lagerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8 13 7 4 4 4 16 9 11 17 25 34	Good Good Good Good/Fair Good/Fair Good/Fair Fair Good/Fair Good/Fair Good/Fair Fair Fair Fair Fair Fair Fair Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Exposed roots, abutting sidewalk, some dead branches Exposed roots, abutting sidewalk, some dead branches Overhanging into road, some dead branches Overhanging into road, some dead branches Some dead branches Multi-stemmed, branch damage Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Matersprouting, dead branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form. Dead broken branches, exposed roots, water sprouting, poor growth form. Dead broken branches, exposed roots, water sprouting, poor growth form. Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Exposed roots, broken branches, water sprouting, interf	
50 51 52 53 54 554 554 554 554 554 554	Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Agerstroemia sp. Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus alba Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak Eastern redbud Pin oak Eastern redbud Pin oak Eastern redbud Pin oak Eastern redbud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8 13 7 4 4 4 16 9 13 7 11 17 25 34 11 12	GoodGoodGoodGoodGood/FairGood/FairGood/FairGood/FairGood/Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead broken branches Overhanging into road, some dead broken branches Overhanging into road, some dead broken branches Overhanging into road, some dead broken branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Dead broken branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Exposed roots, broken branches, water sprouting, interfering with powerlines Expose	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 61** 60* 61** 60* 61** 62 63 64 65 66 66 67 70 71 72 73 74 75 76 77 78 79 80 81 82 83* 85 84** 85 86 87	Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak Eastern redbud Pin oak Eastern redbud Pin oak Eastern redbud Pin oak Eastern redbud Pin oak Pin oak Eastern redbud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8 8 13 7 4 4 16 9 13 7 4 11 17 25 34 11 12 14	GoodGoodGoodGoodGood/FairGood/FairGood/FairGood/Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed two 4", 3" trunks Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging into road, some dead broken branches Exposed roots, abutting sidewalk, dead broken branches Overhanging into road, some dead branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Bead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, exposed roots, water sprouting, poor growth form. Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, noor growth form, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Exposed roots, broken branches, water sprouting, interfering with powerlines Exposed roots, broken branches, water sprouting, interfering with powerlines Exposed ro	
50 51 52 53 54 55* 56** 57* 58* 59** 60* 61** 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 80 81 82 83* 84** 85 86 87	Lagerstroemia sp. Lagerstroemia sp. Acer rubrum Acer rubrum Quercus palustris Catalpa speciosa Quercus alba Quercus alba Quercus alba Quercus rubra Picea abies Quercus alba Lagerstroemia sp. Cercis canadensis Quercus palustris Quercus palustris	Crepe myrtle Crepe myrtle Red maple Crepe myrtle Red maple Pin oak Northern catalpa White oak Northern red oak Northern red oak Norway spruce White oak Crepe myrtle Eastern red bud Pin oak Pin oak Eastern redbud Pin oak Eastern redbud Pin oak Eastern redbud Pin oak Eastern redbud Pin oak Pin oak	4 27 32 28 24 32 27 32 3 10 15 18 18 18 20 15 14 12 5 8 13 7 4 4 4 16 9 13 7 11 17 25 34 11 12	GoodGoodGoodGoodGood/FairGood/FairGood/FairGood/Fair	Multi-stemmed two 4", three 3", 2" trunks Multi-stemmed two 4", 3", two 2" trunks Multi-stemmed Multi-stemmed two 4", 3" trunks Some girdled and exposed roots, overhang, abutting sidewalk Some exposed roots, overhang, minor dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead branches Overhanging, abuts sidewalk, some dead broken branches Overhanging into road, some dead broken branches Overhanging into road, some dead broken branches Overhanging into road, some dead broken branches Some dead branches Multi-stemmed, branch damage Some pruning damage, some dead and broken branches, interfering with powerlines Dead broken branches, exposed roots, interfering with powerlines Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, poor growth form, interfering with powerlines Dead broken branches, water sprouting, interfering with powerlines Exposed roots, broken branches, water sprouting, interfering with powerlines Expose	

RKK

 \rightarrow

-

m

P: 410.728.2900 700 E. Pratt Street, Suite 500 | Baltimore, MD 21202 Engineers | Construction Managers | Planners | Scientists www.rkk.com

Responsive People | Creative Solutions

Wittin Limin 02-06-2025

Maryland DNR Qualified Professional Name: Christina Simini Address: 700 East Pratt St., Suite 500 Baltimore, MD 21202 Phone: 410-462-9386 csimini@rkk.com

Date

PLOTTED: 2/6/2025 FILE: \\ad.rkk.com\fs\Cloud\Projects\2023\23149_MapleAve\CADD\plans\Existing Conditions\pES - EC\pEC-0012_MapleAve_TreeTable.dgn

F91	Pinus strobus	Eastern white pine	22	Good/Fair	Pruned for powerlines, interfering trunk
		Sugar maple	5		Dead broken branches, major trunk wounds
		River birch	12		Multi-stemmed 12", 7" and 10" trunks, heavily pruned for powerlines, watersprouting, overhanging into road
	2	Sugar maple	4		Exposed roots, lean
		Sugar maple	4		Exposed roots, lean
		Sugar maple	6		Interfering trunks, healed over trunk wound
		Sugar maple	5		Minor pruning damage
		Sugar maple	4		Minor pruning damage
		Silver maple	8		Minor pruning damage
	/	Pin oak	28		Dead and broken branches, interfering with powerlines
		Sugar maple	3		Some dead branches
		Sugar maple	3	Good	
		Sugar maple	3		Minor trunk wounds, some minor trunk wounds
104	Acer saccharinum	Silver maple	6	Good/Fair	Exposed roots, interfering with powerline, broken branches
105	Acer saccharinum	Silver maple	4		Exposed roots, interfering with powerline, broken branches
106	Acer saccharinum	Silver maple	4	Good/Fair	Exposed roots, interfering with powerline, broken branches
107	Acer saccharinum	Silver maple	4	Good/Fair	Exposed roots, interfering with powerline, broken branches
108	Acer saccharinum	Silver maple	5	Good/Fair	Exposed roots, interfering with powerline, broken branches
		Silver maple	3	Good	
		Silver maple	4	Good	
		Silver maple	4	Good	
		Silver maple	4	Good	
		Silver maple	3		Some dead branches, looks sick
				Fair	
		Silver maple	3	Good	
		Silver maple	4	Good	
		Silver maple	3	Good	
		Silver maple	4	Good	Minor exposed roots
		Silver maple	2	Good	
119		Silver maple	2	Good	Nearly dead.
		Magnolia species	14		Minor exposed roots, adjacent to sidewalk
		Silver maple	2	Good	
		Silver maple	3	Good	
		Silver maple	3	Good	
		Silver maple	4		Minor trunk wound and exposed roots
					Dead and broken branches. Slight lean
		American sycamore			
		American sycamore		, i	Dead and broken branches. Lean
	5 5	Black walnut	23		Some dead and broken branches
		Silver maple	5		Minor exposed roots
		Silver maple	6	Good/Fair	Exposed roots, some pruning damage
130	Acer saccharinum	Silver maple	5	Good	
131	Acer saccharinum	Silver maple	6	Good	Minor exposed roots and pruning damage
132	Acer saccharinum	Silver maple	10		Exposed roots, dead broken branches and pruning damage
		Ornamental cherry	17	· · ·	Major dead branches, lean exposed roots
	,	Silver maple	7		Pruning damage, interfering with powerlines, exposed roots
		Silver maple	6		Pruning damage, interfering with powerlines, exposed roots
				· · · · · · · · · · · · · · · · · · ·	
		Silver maple	6		Pruning damage, interfering with powerlines, exposed roots
		Silver maple	1		Pruning damage, interfering with powerlines, exposed roots
		Deodar cedar	18		Some dead branches, overhanging
		Ornamental cherry	14		Exposed roots, trunk wounds, watersprouting at base, vines on trunk, broken and dead branches
	Prunus sp.	Ornamental cherry	1 7	Fair	Exposed roots, trunk wounds, watersprouting at base, vines on trunk, broken and dead branches
141	Prunus sp.	Ornamental cherry	16	Fair	Exposed roots, trunk wounds, watersprouting at base, vines on trunk, broken and dead branches
142	Quercus palustris	Pin oak	8	Good	
143**	Quercus rubra	Northern red oak	35	Good/Fair	Canopy is pruned
144**	Quercus alba	White oak	35	Good	
		Southern red oak	35	Good	
		Southern red oak	38		Bulging roots, chopped at top, poor growth form
		Red maple	13		Interfering with powerlines, pruned
	Liriodendron tulipifera		28		Major dead secondary leaders, bulging root base, thin crown
		White oak	26		Dead and broken branches, overhanging
			11		
	,	American holly		Good Cood/Foir	Interfering with newerlines and other tree
		Red maple	20		Interfering with powerlines and other tree
		White oak			Dead branches, interfering with powerlines
		White oak	32		Some dead branches, interfering with powerlines
		Northern red oak	15		Some dead branches and slight lean
		American sycamore	7		Interfering with powerlines
	Quercus alba	White oak	20		Interfering with powerlines
157**	Quercus rubra	Northern red oak	35	Fair	Major dead secondary leader, one sided, interfering with powerlines
158**	Quercus alba	White oak	32		Some broken dead branches
		Southern red oak	38	· ·	Slightly poor growth form, slight lean, dead branches
		Southern red oak	27		Some dead branches
		American beech			Some broken dead branches, bulging exposed roots
		Red maple	32	· · · · · · · · · · · · · · · · · · ·	Some major dead branches, one sided
	Quercus alba	White oak	24		Some dead and broken branches, interfering with powerlines, vines on trunk
			15	Fair	Some dead branches, interfering with powerlines, poor growth form
		Pignut hickory			Some dead branches, merrering with powertines, poor growth form
		Northern red oak	11	Good	
		Northern red oak	9		Interfering with powerlines
1/7**		Southern red oak	32	· · · · · · · · · · · · · · · · · · ·	Water sprouting, some dead and broken branches
	,	Chinese elm	16	Good	
168		Chinese elm	15	Good	
168	Ulmus parvifolia		15	Good	
168 169		Chinese elm	10	0000	
168 169 170	Ulmus parvifolia				
7168 7169 7170 7171	Ulmus parvifolia Ulmus parvifolia	Chinese elm	1 7	Good	Some pruned branches and water sprouting exposed roots on steen slope
168 169 170 171 171	Ulmus parvifolia Ulmus parvifolia Ulmus americana	Chinese elm American elm	1 7 16	Good Good/Fair	Some pruned branches and water sprouting, exposed roots, on steep slope
F168 F169 F170 F171 F172 F173*	Ulmus parvifolia Ulmus parvifolia Ulmus americana Ulmus americana	Chinese elm	1 7	Good Good/Fair Fair	Some pruned branches and water sprouting, exposed roots, on steep slope Some pruned branches and water sprouting, exposed roots, on steep slope Nearly dead.


	NO.	REVISION	DATE	BY	
DESIGN SECTION 240-777-7221					Chief, Division of Transportation Engineering
ENGINEERING 240-777-7220					·
DIVISION OF TRANSPORTATION					APPROVED
<u>CONTACT:</u>				-	Chief, Transportation Planning and Design Section
CATTIERSBORG, MARTEAND					4
100 EDISON PARK DRIVE Gaithersburg, maryland					RECOMMENDED FOR APPROVAL
DEPARTMENT OF TRANSPORTATION					ROCKVILLE, M
MONTGOMERY COUNTY					DEPARTMENT OF TR
<u>OWNER/ADDRESS:</u>					MONTGOMERY


		CITY OF TAKOMA PARK MAPLE AVENUE CONNECTIVITY PROJECT FROM CARROLL AVENUE TO HILLTOP ROAD / SLIGO CREEK PARKWA PLAN NO. 42025100E BASE MAP # 208NW01, 209NW01, 209NE01 TAX MAP # JN341, JN342, JN562 ELECTION DISTRICT # 13					
Y COUNTY RANSPORT	TATION	TREE INVENTORY					
MARYLAND		SCALE <u>N/A</u> DATE <u>FEBRUARY 2025</u> CONTRACT NO. <u>T.B.D.</u>	\neg				
ion	Date	DESIGNED BY CAS COUNTY MONTGOMERY DRAWN BY CO LOGMILE CHECKED BY MH MDE/PRD	_				
		DRAWING OF SHEET No. 13 OF 16					

-

 $- \oplus -$

2. ROOT PRUNE AS DIRECTED BY CITY ARBORIST AND MD LTE IF ROOTS ENCOUNTERED WITHIN LOD.





LEGEND

TPF	TREE PROTECTION FENCE
	SOIL BOUNDARY
	CONTOURS
	PROPERTY BOUNDARIES
-	DIRECTION OF TRAFFIC
LOD	LIMIT OF DISTURBANCE
	100 YEAR FLOODPLAIN
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	EXISTING TREE CANOPY LINE
$\odot$	INDIMIDUAL TREES
$(\overline{O})$	INDMDUAL TREE W/CRZ

RKK

 $\smallsetminus$ 

P: 410.728.2900 700 E. Pratt Street, Suite 500 | Baltimore, MD 21202 Engineers | Construction Managers | Planners | Scientists www.rkk.com Responsive People | Creative Solutions


PLOTTED: 2/6/2025 FILE: \\ad.rkk.com\fs\Cloud\Projects\2023\23149_MapleAve\CADD\plans\Existing Conditions\pES - EC\pES-P001_MapleAve - EC.dgn

	NO.	REVISION	DATE	BY	
DESIGN SECTION 240-777-7221					Chief, Division of Transportation Engineering
DIVISION OF TRANSPORTATION ENGINEERING 240-777-7220					Chief, Transportation Planning and Design Section APPROVED
CONTACT:					
100 EDISON PARK DRIVE Gaithersburg, maryland	L		_		RECOMMENDED FOR APPROVAL
DEPARTMENT OF TRANSPORTATION					ROCKVILLE, M
<u>owner/address:</u> Montgomery county					MONTGOMERY DEPARTMENT OF TR

-


-

2. ROOT PRUNE AS DIRECTED BY CITY ARBORIST AND MD LTE IF ROOTS ENCOUNTERED WITHIN LOD.






LEGEND



	NO.	REVISION	DATE	BY	
DESIGN SECTION 240-777-7221					Chief, Division of Transportation Engineering
<u>Contact:</u> Division of transportation Engineering 240-777-7220					Chief, Transportation Planning and Design Section APPROV <b>E</b> D
GAITHERSBURG, MARYLAND					RECOMMENDED FOR APPROVAL
<u>OWNER/ADDRESS:</u> MONTGOMERY COUNTY DEPARTMENT OF TRANSPORTATION 100 EDISON PARK DRIVE					MONTGOMERY DEPARTMENT OF TR ROCKVILLE, M

-

2. ROOT PRUNE AS DIRECTED BY CITY ARBORIST AND MD LTE IF ROOTS ENCOUNTERED WITHIN LOD.



# LEGEND

	TREE PROTECTION FENCE
	SOIL BOUNDARY
	CONTOURS
	PROPERTY BOUNDARIES
-	DIRECTION OF TRAFFIC
— LOD ——	LIMIT OF DISTURBANCE
	100 YEAR FLOODPLAIN
$\sim$	EXISTING TREE CANOPY LINE
$\odot$	INDMDUAL TREES
$(\bigcirc)$	INDMDUAL TREE W/CRZ

RKK

P: 410.728.2900 700 E. Pratt Street, Suite 500 | Baltimore, MD 21202 Engineers | Construction Managers | Planners | Scientists www.rkk.com Responsive People | Creative Solutions


 $- \oplus -$ 

PLOTTED: 2/6/2025 FILE: \\ad.rkk.com\tas\Cloud\Projects\2023\23149_MapleAve\CADD\plans\Existing Conditions\pES - EC\pES-P003_MapleAve - EC.dgn

	NO.	REVISION	DATE	BY	
240-777-7220 DESIGN SECTION 240-777-7221					Chief, Division of Transportation Engineering
<u>CONTACT:</u> DIVISION OF TRANSPORTATION ENGINEERING					Chief, Transportation Planning and Design Section APPROVED
GAITHERSBURG, MARYLAND					RECOMMENDED FOR APPROVAL
<u>OWNER/ADDRESS:</u> MONTGOMERY COUNTY DEPARTMENT OF TRANSPORTATION 100 EDISON PARK DRIVE					MONTGOMER DEPARTMENT OF T ROCKVILLE,

-

2. ROOT PRUNE AS DIRECTED BY CITY ARBORIST AND MD LTE IF ROOTS ENCOUNTERED WITHIN LOD.



<u>LEGEND</u>

	TREE PROTECTION FENCE
	SOIL BOUNDARY
	CONTOURS
	PROPERTY BOUNDARIES
-	DIRECTION OF TRAFFIC
LOD	LIMIT OF DISTURBANCE
	100 YEAR FLOODPLAIN
$\sim\sim\sim\sim$	EXISTING TREE CANOPY LINE
$\odot$	INDMDUAL TREES
$(\bigcirc)$	INDMDUAL TREE W/CRZ



P: 410.728.2900 700 E. Pratt Street, Suite 500 | Baltimore, MD 21202 Engineers | Construction Managers | Planners | Scientists www.rkk.com Responsive People | Creative Solutions

 $- \oplus$ 

PLOTTED: 2/6/2025 FILE: \lad.rkk.com/ts\Cloud\Projects\2023\23149_MapleAve\CADD\plans\Existing Conditions\pES - EC\pES-P004_MapleAve - EC.dgn


	NO	PEVISION	DATE	BY	
DESIGN SECTION 240-777-7221					and, show of hansportation Engineering
240-777-7220					Chief, Division of Transportation Engineering
					1
DIVISION OF TRANSPORTATION					APPROVED
CONTACT:					Chief, Transportation Planning and Design Section
00117407					·
GAITHERSBURG, MARYLAND					RECOMMENDED FOR APPROVAL
100 EDISON PARK DRIVE					
DEPARTMENT OF TRANSPORTATION	<u> </u>				ROCKVILLE, MA
MONTGOMERY COUNTY					DEPARTMENT OF TR
<u>OWNER/ADDRESS:</u>					MONTGOMERY

23

-

2. ROOT PRUNE AS DIRECTED BY CITY ARBORIST AND MD LTE IF ROOTS ENCOUNTERED WITHIN LOD.

> 25.00 + 27 STA LINE MATCH



# **LEGEND**

	TREE PROTECTION FENCE
	SOIL BOUNDARY
	CONTOURS
	PROPERTY BOUNDARIES
→	DIRECTION OF TRAFFIC
- LOD	LIMIT OF DISTURBANCE
	100 YEAR FLOODPLAIN
$\sim$	EXISTING TREE CANOPY LINE
$\odot$	INDMDUAL TREES
$(\bigcirc)$	INDMIDUAL TREE W/CRZ

RKK

P: 410.728.2900 700 E. Pratt Street, Suite 500 | Baltimore, MD 21202 Engineers | Construction Managers | Planners | Scientists www.rkk.com Responsive People | Creative Solutions


 $- \bigoplus$ 

PLOTTED: 2/6/2025 FILE: \\ad.rkk.com\fs\Cloud\Projects\2023\23149_MapleAve\CADD\plans\Existing Conditions\pES - EC\pES-P005_MapleAve - EC.dgn

	NO	REVISION	DATE	BY	
DESIGN SECTION 240-777-7221					Chief, Division of Transportation Engineering
<u>Contact:</u> Division of transportation Engineering 240-777-7220					Chief, Transportation Planning and Design Section APPROV <b>E</b> D
GAITHERSBURG, MARYLAND					RECOMMENDED FOR APPROVAL
<u>OWNER/ADDRESS:</u> MONTGOMERY COUNTY DEPARTMENT OF TRANSPORTATION 100 EDISON PARK DRIVE					MONTGOMERY DEPARTMENT OF TR ROCKVILLE, M

-

2. ROOT PRUNE AS DIRECTED BY CITY ARBORIST AND MD LTE IF ROOTS ENCOUNTERED WITHIN LOD.



<u>LEGEND</u>

TPF	TREE PROTECTION FENCE
	SOIL BOUNDARY
	CONTOURS
	PROPERTY BOUNDARIES
→	DIRECTION OF TRAFFIC
- LOD -	LIMIT OF DISTURBANCE
	100 YEAR FLOODPLAIN
$\sim \sim \sim \sim$	EXISTING TREE CANOPY LINE
$\bigcirc$	INDIVIDUAL TREES
$(\overline{O})$	INDIVIDUAL TREE W/CRZ

RKK

 $\smallsetminus$ 

P: 410.728.2900 700 E. Pratt Street, Suite 500 | Baltimore, MD 21202 Engineers | Construction Managers | Planners | Scientists www.rkk.com Responsive People | Creative Solutions

 $- \oplus -$ 

	NO.	REVISION	DATE	BY	
240-777-7221					
DESIGN SECTION					Chief, Division of Transportation Engineering
240-777-7220					]
DIVISION OF TRANSPORTATION ENGINEERING					APPROV <b>E</b> D
CONTACT:					Chief, Transportation Planning and Design Section
GAITHERSBURG, MARYLAND					RECOMMENDED FOR APPROVAL
100 EDISON PARK DRIVE					
MONTGOMERY COUNTY DEPARTMENT OF TRANSPORTATION	<u> </u>				ROCKVILLE, M
OWNER/ADDRESS:					MONTGOMERY DEPARTMENT OF TR