# <u>EXPEDITED</u> MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address: 31 Oxford St., Chevy Chase Meeting Date: 10/10/2018

**Resource:** Contributing Resource **Report Date:** 10/3/2018

(Chevy Chase Village Historic District)

**Public Notice:** 9/26/2018

**Applicant:** Dan Morgan and Mary Elaine Shannon

**Tax Credit:** Yes

Review: HAWP Staff: Michael Kyne

**Case Number:** 35/13-18AA

**PROPOSAL:** Siding alteration, roof replacement, and shutter replacement

### **STAFF RECOMMENDATION:**

Approve

Approve with conditions

### **ARCHITECTURAL DESCRIPTION**

SIGNIFICANCE: Contributing Resource within the Chevy Chase Village Historic District

STYLE: Craftsman DATE: c. 1916-27

### **PROPOSAL:**

The applicants are proposing rehabilitation work at the subject property, with the following specifications:

- Removal of the non-historic aluminum siding.
- Repairs and painting of the original cedar siding.
- In-kind replacement of the three-tab asphalt roofing shingles.
- Replacement of the non-historic aluminum louvered shutters (11 pairs total) with wooden louvered shutters (operable) of the same dimensions.
- Other repairs, including re-caulking of the historic windows.

### **APPLICABLE GUIDELINES:**

### Policy On Use of Expedited Staff Reports for Simple HAWP Cases

IV. The Expedited Staff Report format may be used on the following type of cases:

2. Modifications to a property, which do not significantly alter its visual character.

### Montgomery County Code; Chapter 24A-8

- (b) The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to insure conformity with the purposes and requirements of this chapter, if it finds that:
  - (1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or
  - (2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter; or
  - (3) The proposal would enhance or aid in the protection, preservation and public or private utilization of the historic site or historic resource located within an historic district in a manner compatible with the historical, archeological, architectural or cultural value of the historic site or historic district in which an historic resource is located; or
  - (4) The proposal is necessary in order that unsafe conditions or health hazards be remedied; or
  - (5) The proposal is necessary in order that the owner of the subject property not be deprived of reasonable use of the property or suffer undue hardship; or
  - (6) In balancing the interests of the public in preserving the historic site or historic resource located within an historic district, with the interests of the public from the use and benefit of the alternative proposal, the general public welfare is better served by granting the permit.
  - (c) It is not the intent of this chapter to limit new construction, alteration or repairs to any 1 period or architectural style.

(Ord. No. 9-4, § 1; Ord. No. 11-59.)

### **STAFF RECOMMENDATION:**

Staff recommends that the Commission <u>approve</u> the HAWP application under the Criteria for Issuance in Chapter 24A-8(b), (1) & (2) and having found that the proposal will not substantially alter the exterior features of the historic resource and is compatible in character with the district and the purposes of Chapter 24A;

and with the Secretary of the Interior's Standard for Rehabilitation #2 and 9;

and with the general condition that the applicant shall present the **3 permit sets of drawings**, **if applicable**, **to Historic Preservation Commission (HPC) staff for review and stamping** prior to submission for the Montgomery County Department of Permitting Services (DPS) building permits;

and with the general condition that final project design details, not specifically delineated by the Commission, shall be approved by HPC staff or brought back to the Commission as a revised HAWP application at staff's discretion;

and with the general condition that the applicant shall notify the Historic Preservation Staff if they propose to make **any alterations** to the approved plans. Once the work is completed the applicant will contact the staff person assigned to this application at 301-563-3400 or michael.kyne@montgomeryplanning.org to schedule a follow-up site visit.



Edit 6/21/99

# HISTORIC PRESERVATION COMMISSION 301/563-3400

# APPLICATION FOR HISTORIC AREA WORK PERMIT

eshannon0609@gmail.com	Cont	act Person:	Elaine Shannon
ontact Email:	Dayt	ime Phone No.:	202-664-9232
District - 07 Account Number - 00454652			
ame of Property Owner: Dan Morgan and Mary Elaine S	Shannon Days	ime Phone No.:	202-664-9232
ddress: 31 Oxford Street, Chevy Chase, Md. 20815			
Street Number City		Steet	Zip Code
ontractorn:		Phone No.:	
ontractor Registration No.:			
gent for Owner:	Day	ime Phone No.:	
OCATION OF BUILDING PREMISE			
louse Number: 31	Street Or	xford	
own/City: Chevy Chase Nearest C		onnecticut Aven	nue
ot: PT LTS 18 & 19 Block: 57 Subdivision:		Village	
CHASE SEC 2 Folio: Parcat:			
iber: Folio: Parce:			
Martin a martinasan amarin Martin Martin			
and the second of the second of the	CHECK ALL APPLIC	ABLE:	
Check All APPRICABLE: ROO RESULTANT AS THE NEW VIEW			Idition Porch Deck Shed
Property and the second			ning Stove Single Family
☐ Move ☐ Install ☐ Wreck/Raze			
	Fence/Wall (con	rplete Section 4)	Other:
1B. Construction cost estimate: \$ 50,000			
1C. If this is a revision of a previously approved active permit, see Permi	t #		
	naraaaniana		
PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTE	NU/AUUIIIUNS	- II - I	WA
2A. Type of sewage disposal: 01 🗆 WSSC 02 🗀			
2B. Type of water supply: 01 ☐ WSSC 02 ☐	Well	03 🗆 Other:	
PARTATRIAS & COMMUNICATION VIOLENCE AND ANNING WATE			
3A. Height feet inches			110
3B. Indicate whether the fence or retaining wall is to be constructed or	n one of the followin	a locations:	CA
	and the same of th	On public right of w	av/assamant
☐ On party line/property line ☐ Entirely on land of ow	nios 🔾	Oil public Ingili or in	· // • — • · · · · · · · · · · · · · · · · ·
I hereby curry that I have the authority to make the foregoing applicati	ion, that the applicat	ion is correct, and t	het the construction will comply with plans
approved by all agencies listed and I hereby acknowledge and accept	this to be a condition	n for the issuance o	I this permit.
			12/00/8
		<	35p1 - 1210
Signature of disperior authorized egent			/Date
Approved:	For Chairperson,	Historic Preservatio	n Commission
Disapproved: Signature:			
			Data Issued:
· +p			

950785

# THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION.

	See attached
eneral descrip	stion of project and its effect on the historic resource(s), the environmental setting, and, where applicable, the historic district:
	attached
See	attachod

#### 2. SITE PLAN

Site and environmental setting, drawn to scale. You may use your plat. Your site plan must include:

a. the scale, north arrow, and date;

1. WRITTEN DESCRIPTION OF PROJECT

- b. dimensions of all existing and proposed structures; and
- c. site features such as walkways, driveways, fences, ponds, streams, trash dumpsters, mechanical equipment, and landscaping.

#### 3. PLANS AND ELEVATIONS

You must submit 2 copies of plans and elevations in a format no larger than \$1" x 17". Plans on 8 1/2" x 11" paper are preferred.

- Schematic construction plans, with marked dimensions, indicating location, size and general type of walls, window and door openings, and other fixed features of both the existing resource(s) and the proposed work.
- b. Elevations (facades), with marked dimensions, clearly indicating proposed work in relation to existing construction and, when appropriate, context. All materials and fixtures proposed for the exterior must be noted on the elevations drawings. An existing and a proposed elevation drawing of each facade affected by the proposed work is required.

### 4. MATERIALS SPECIFICATIONS

General description of materials and manufactured items proposed for incorporation in the work of the project. This information may be included on your design drawings.

### 5. PHOTOGRAPHS

- a. Clearly labeled photographic prints of each facade of existing resource, including details of the affected portions. All labels should be placed on the front of photographs.
- Clearly label photographic prints of the resource as viewed from the public right-of-way and of the adjoining properties. All labels should be placed on the front of photographs.

#### 6. TREE SURVEY

If you are proposing construction adjacent to or within the dripline of any tree 5" or larger in diameter (at approximately 4 feet above the ground), you must file an accurate tree survey identifying the size, location, and species of each tree of at least that dimension.

### 7. ADDRESSES OF ADJACENT AND CONFRONTING PROPERTY OWNERS

For ALL projects, provide an accurate list of adjacent and confronting property owners (not tenants), including names, addresses, and zip codes. This list should include the owners of all lots or parcels which adjoin the parcel in question, as well as the owner(s) of lot(s) or parcel(s) which lie directly across the street/highway from the parcel in question.

# Application for Historic Area Work Permit

To: Montgomery County Historic Preservation Commission Department of Permitting Services (DPS) 255 Rockville Pike, Rockville, Md. 20850 240.777.0311.

From Dan Morgan and Mary Elaine Shannon 31 Oxford Street Chevy Chase, Md. 20815

### 1. Written description of project

a. Description of existing structure and environmental setting, including historical features and significance:

The Chevy Chase Village Historic District was created in 1995, with 11 buildings initially, and expanded in 1998 to include 326 structures, mostly residences, between the Chevy Chase Club and Bradley Lane on the north and Western Avenue on the south.



The house at 31 Oxford Street, built between 1906 and 1908, shares that history and exemplifies the graceful architectural styles of the historic community.

According to a document available on the Montgomery Planning Department website, quoting Places from the Past: The Tradition in Gardez Bien in Montgomery County, Maryland by Clare Lise Cavicchi:

Architecturally, Chevy Chase Village contains the county's highest concentration of outstanding architect-designed and builder vernacular suburban houses rendered in post-Victorian styles of the period 1890-1930. Together, the surviving plan and architecture of Chevy Chase Village represents one of the most intact and important examples of suburban planning and architectural expression built in the region before World War II.

The three-story crafstman-style house at 31 Oxford Street is typical of the large, graceful houses constructed in Chevy Chase Village soon after the neighborhood was established in 1890. A cornerstone found on the property is inscribed 1906. Montgomery County property records give the date of construction as 1908. It appears to be the oldest structure on Oxford Street. A capped well in the back yard suggests that a farm once sat on or near the site.

The house is a white wood frame house, sided with cedar shingles seen throughout Chevy Chase Village. It has a graceful wrap-around veranda with cylindrical columns and original architectural details inside and out. Doors, windows, mahogany bannisters and other features are original. The rooms have high ceilings and moulding. The floors are of red pine no longer available. The windows are large and well-placed to bring light into the house.

Over the years, we have changed nothing about the appearance of the house from the street. Very few changes have been made in the rear. The floor plan has never changed. Our efforts have focused on restoring, rehabilitating and preserving the house as its builder originally conceived it.

We acquired the house in 1985 and found it in need of extensive repairs and rehabilitation. The front porch had large holes in the floor. The columns that hold up the roof over the porch were sagging. The foundation was crumbling. The heating system was decades old. Joists had been severed, causing the whole structure to sink inward. The previous owners attempted to remedy this critical problem by jerry-rigging a two-story jack that reached from the cement basement floor to the top of the kitchen. The jack supported an I-beam that extended across the kitchen ceiling to support the second and third floors.

We replaced the rotted front porch floor with tropical mahogany, which has a long life and can withstand Washington's weather extremes. We installed a new roof, with asphalt shingles, the same material as we found when we moved in.

The floor plan of the house is as it was originally constructed, with one exception: a flat-roofed familly room apparently added to the rear in the 1960s. We found this room partly finished, with subflooring but no flooring, rudimentary space heating and a rudimentary powder room. We finished it in 1989, with a maple floor and central heating and air conditioning. We added glass sliding doors to the garden. We re-roofed the flat family room roof.

Also in 1989, we updated the kitchen and restored the original hardwood flooring, hidden under layers of vinyl tile. The kitchen features wood cabinets and tile. It has the look of a farmhouse kitchen, in keeping with the priod of the house. In 1989, we undertook extensive work to reinforce the original foundation. We updated the second-floor bathroom, replacing plastic tile tiled with high quality ceramic tiles. We repaired and painted ceilings and walls damaged by leaks from the second and third bathrooms.

In 2005, we added an air conditioning system to the second and third floors, using a Unico ductless system designed specifically for retrofitting historic stuctures. This system did not require alteration of the interior to accommodate ducts.

In 2012, we updated the third floor bathroom. In 2014, we replaced the sewage outflow pipe, which had crumbled over the years and was undermining the foundation.

The previous owners covered the entire house's cedar siding with aluminum siding. When we rehabilitated the kitchen in 1989, we removed the aluminum siding on the exterior walls of the kitchen. We hope to remove the rest of the aluminum siding this year.

In 2016, we repainted and restored the plaster walls of the living room, dining room and entrance hall, which are the oldest part of the house. We used historic colors found in the homes of George Washington and Thomas Jefferson. We finished the 1960s-era powder room, replacing a plywood-and-plastic vanity with an heirloom-quality tiger maple vanity and mirror and adding a hardwood floor.

When we moved into the house in 1985, the side yard and much of the back yard were paved with asphalt. The previous owners had used the yard as a parking lot for their several vehicles. We had the asphalt dug out by hand. Over the years we added soil and plants. In 2014, we had the garden designed by Alida Morgan, an artist and professional landscape designer. We made broader perennial beds and added tables and benches.

Today, 31 Oxford Street looks much as it did when it was built. Like all houses, and for that matter, all people, it takes work to stay the same.

b. General description of project and its effect on the historic resource, the environmental setting and the historic district


We propose to continue our work to restore the house to its original beauty and maintaining it good condition. Our current project is straightfoward: cleaning, repairing and repainting. We contemplate no changes to the structure. We plan to:

- Clean and paint peeling and mildewed all painted surfaces.
- Remove aluminum siding applied by a previous owner.
- Caulk and repaint the original cedar siding, with repairs as needed.
- Replace fake aluminum shutters with real wooden shutters that match original wooden shutters.
- Replace aging roof with missing shingles with new roof, with asphalt shingles, the same as before. Windows will be recaulked and preserved.

Once the repairs and repainting are accomplished, the house will look the same as it always had, but fresher.

# HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFING [Owner, Owner's Agent, Adjacent and Confronting Property Owners] Owner's mailing address Owner's Agent's mailing address Dan Morgan and Mary Elaine Shannon, 31 Oxford Street, Chevy Chase, Md. 20815 eshannon0609@gmail.com 202-664-9232 or 301-654-3158 Adjacent and confronting Property Owners mailing addresses Hashim, Jeff & Maryam Salass Talbott, Scott & Leanne 25 Oxford Street 33 Oxford Street Phone: (301) 907-0123 Phone: (301) 229-5816 Email: jjhashim@gmail.com Email: stalbott@electran.org Minshall, Werner E. & Joan M. Rayder, J.W. & Helene 12 Oxford Street 14 Oxford Street Phone: (301) 654-8258 Phone: (301) 656-6436 Email: wem@msscompany.com Email: jwrayder@aol.com

Leggett, Matthew & Melissa 16 Oxford Street Phone: (301) 652-8546 Email: matthew.h.leggett@gmail.com



# OXFORD STREET



NO TITLE REPORT FURNISHED

LOCATION SURVEY OF

# 3/ OXFORP STREET

MONTGOMERY COUNTY, MP

SUBDIVISION

CHEVY CHAS

LOT PARTS OF 18& 19

PLAT BOOK: 2

DATE: 3-06-85

CASE NO: 13634

BLOCK: 57

PLAT NO: \_\_ 106

SCALE: /"= ZO"

FILE NO: \_RC 85027

CERTIFICATION:

HEREBY CERTIFY THAT THE POSITION OF ALL THE EXISTING IMPROVEMENTS ON THE ABOVE DESCRIBED PROJECTLY HAS BEEN GAREFULLY ESTABLISHED BY A TRANSIT TAPE SURVEY AND THAT UNLESS OTHERWISE SHOWN THERE ARE

**Existing Property Conditions Photographs** 



Detail: Photo# 1 4/25/18 Front (south) elevation



Detail Photo# 2 4/25/18 Front (south) elevation Shows mildew, peeling paint, aluminum siding to be removed



Detail Photo# 3 8/20/18 Front (south) elevation Shows view from adjacent neighbors at 33 Oxford Street



Detail Photo# 4 8/20/18 Side (east) elevation Shows view from adjacent neighbors (33 Oxford Street)



Detail Photo# 5 8/20/18 Front (south) elevation

View from confronting neighbors and adjacent neighbors (29 Oxford Street)



Detail Photo# 6 4/25/18 Front (south) elevation Shows mildew, peeling paint under eaves aluminum siding to be removed



Detail Photo# 7 4/25/18 Front (south) elevation
Shows mildew, peeling paint under eaves aluminum siding to be removed



Detail Photo# 8 4/25/18 Front (south) elevation Shows mildew, peeling paint under eaves aluminum siding to be removed



Detail Photo# 9 4/25/18 Front (south) elevation Front (south) elevation detail of covered front porch Shows peeling paint, mildew



Detail Photo# 10 4/25/18 Front (south) elevation Front (south) elevation detail of eaves with peeling paint, mildew



Detail Photo#11 4/25/18 Front (south) elevation Front (south) elevation detail of front steps and railing Shows peeling paint, mildew



Detail Photo#12 4/25/18 Front (south) elevation Front (south) elevation and side (east) elevation detail of front porch railing



Detail Photo#13 4/25/18 Front (south) elevation side (east) elevation detail of front porch railing showing peeling paint, mildew



Detail Photo#14 4/25/18 Front (south) elevation
Front (south) elevation and side (east) elevation, detail of front porch railing showing peeling paint, mildew

**Existing Property Conditions Photographs** 



Detail Photo#15 4/25/18 Front (south) elevation Front (south) elevation, detail of front porch showing aluminum siding to be removed



Detail Photo#16 4/25/18 Front (south) elevation Front (south) elevation, detail of front porch showing aluminum siding to be removed

**Existing Property Conditions Photographs** 



Detail Photo#17 4/25/18 Front (south) elevation
Front (south) elevation, detail of 2<sup>nd</sup> and 3<sup>rd</sup> floor eaves shot from front yard



Detail Photo#18 4/25/18 side (east) elevation

Side of front porch and bginning of east elevation, showing aluminum siding to be removed.

**Existing Property Conditions Photographs** 



Detail Photo#19 4/25/18 Front (south) elevation Front (south) elevation, detail of eaves showing peeling paint and mildew



Detail Photo#20 4/25/18 Rear (north) elevation showing 3-story oldest part of house and ca. 1960 1-story family room



Detail Photo#21 4/25/18 Rear (north) elevation showing 3-story oldest part of house with original cedar shingles needing paint, plus vee-shaped kitchen bay



Detail Photo#22 4/25/18 Rear (north) elevation showing  $1^{st}$ -floor ca. 1960 family room needing siding repairs, paint

**Existing Property Conditions Photographs** 



Detail Photo#23 4/25/18 Rear (north) elevation showing 3-story oldest part of house with original cedar shingles and adjoining 1-story ca. 1960 family room



Detail Photo#24 4/25/18 Rear (north) elevation showing 3-story oldest part of house with original cedar shingles needing paint, plus top vee-shaped kitchen bay



Detail Photo#25 4/25/18 Rear (north) elevation showing  $1^{st}$ -floor ca. 1960 family room needing siding repairs, paint, plus part of  $2^{nd}$  floor side (west0 elevation



Detail Photo#26 4/25/18 Side (east) elevation showing 1st-floor side door aluminum siding to be removed



Detail Photo#27 4/25/18 Side (east) elevation showing 1st-floor side door aluminum siding to be removed



Detail Photo#28 4/25/18 Side (east) elevation showing aluminum siding to be removed, eaves needing painting

**Existing Property Conditions Photographs** 



Detail Photo#29 4/25/18 Side (east) elevation showing 3rd-floor window aluminum siding to be removed, eaves needing painting



Detail 1 rolo 30 4/23/18 Side (east) elevation showing 1st-floor side kitchen door and side kitchen window, original cedar siding and eaves needing painting



Detail Photo#31 4/25/18 Side (east) elevation showing  $2^{nd}$  floor windows, original cedar siding, woodwork and eaves needing painting



Detail Photo#3 $\mathfrak{P}$  4/25/18 Side (east) elevation showing  $2^{nd}$  floor windows, original cedar siding, woodwork and eaves needing painting



Detail Photo#33 4/25/18 Side (west) elevation showing rear side of wraparound porch, aluminum siding to be removed, woodwork needing painting



Detail Photo#34 4/25/18 Side (west) elevation showing rear side of wraparound porch, aluminum siding to be removed, woodwork needing painting

**Existing Property Conditions Photographs** 



Detail Photo#35 4/25/18 Side (west) elevation showing exterior of family room, aluminum siding to be removed, woodwork needing painting



Detail Photo#36 4/25/18 Side (west) elevation showing exterior of family room, aluminum siding to be removed, woodwork needing painting



Detail Photo #37 4/25/18 Side (west) elevation showing exterior of family room and edge of wraparound front porch, showing aluminum siding to be removed, woodwork needing painting




Detail Photo#38 4/25/18 rear (north) elevation and side (west) elevation showing  $2^{nd}$  floor exterior and family room roof, aluminum siding to be removed, eaves and woodwork needing painting



Detail Photo#39 4/25/18 rear (north) elevation and side (west) elevation showing  $2^{nd}$  floor exterior and family room roof, aluminum siding to be removed, eaves and woodwork needing painting



Detail Photo#3 4/25/18 rear (north) elevation and side (west) elevation showing 2<sup>nd</sup> floor exterior and family room roof, aluminum siding to be removed, eaves and woodwork needing painting



Detail Photo##6 4/25/18 rear (north) elevation and side (west) elevation showing 2<sup>nd</sup> floor exterior and family room roof, aluminum siding to be removed, eaves and woodwork needing painting



Detail Photo#4 $\mathfrak{H}$  4/25/18 rear (north) elevation and side (west) elevation showing 2<sup>nd</sup> floor exterior and family room roof, aluminum siding to be removed, eaves and woodwork needing painting



Detail Photo#42 rear (north) elevation roof showing missing and irregular shingles



Detail Photo#4 4/25/18 rear (north) elevation roof showing missing and irregular shingles

Applicant: Dan Morgan and Mary Elaine Shannon, 31 Oxford St, Chevy Chase, Md. 20815



Detail Photo#45 8/22/18 side (east) elevation showing detail of aluminum siding to be removed and original cedar siding underneath



Detail Photo#46 8/22/18 side (east) elevation showing original cedar siding, removed years ago and repainted



# **Sloped Roof Replacement**

Scheduled Date:	Completion Da	ate:			
Name: Elaine Shannon	Date: 5/14/18	Representative: John			
Address: 31 Oxford St Chevy Chase MD 20815					
Phone:	E-	-mail:			

Scope of	Work and 1	Installation S	Specifications

202-664-9232

**Protection** protect house and grounds from falling debris / set up work area to protect ground while working

**Removal** remove existing *main house* down to the wood decking and haul away daily

Decking inspect all wood decking for rot or damage and replace 1 sheet at an additional rate of \$65 per sheet for ½"

CDX plywood

**Ventilation** furnish and install Smart Ridge II shingle-over ridge ventilation on all peaks from end to end

Ice & Water Guard furnish and install rubberized ice & water shield to the gutterline

**Underlayment** furnish and install #15 underlayment over entire exposed roof deck

**Drip Edge** furnish and install aluminum drip edge along all gutter lines

**General Flashing** furnish and install aluminum flashing at all walls, chimneys and skylights

**Pipe Flashing** furnish and install neoprene pipe collars at all vent pipes

Shingles furnish and install Owens Corning 25yr Supreme Color TBD

**Clean Up** clean all gutters, ground and haul away all debris

Guarantee LIFETIME Labor Guarantee

**Notes** 

**Total Investment:** \$ 17,250 Initial: Shingle Color: TBD

Options and Upgrades				
Extreme Storm:	furnish and install rubberized ice & water shield over entire roof deck	\$	Initial:	
Algae Protection:	furnish and install Zinc strips along all ridges and hips	\$	Initial:	
		\$	Initial:	
		\$	Initial:	

Total Cost: \$17,250 Deposit: \$5,750 Balance Upon Completion: \$11,500 Payment Type: ☐ Check ☐ CC ☐ Bill Me

Cancellation: You may cancel this agreement within 3 business days by calling the office, stating that you do not want the services, and receiving a cancellation code. If you cancel, any deposits will be returned.

Please sign below to authorize the above service

Signature on file 5/1/18 date

Please initial below that you received, read and approve the: Terms & Conditions  $\underline{EB}$  Workmanship Guarantee  $\underline{EB}$  initial initial