# 2<sup>nd</sup> Preliminary Consultation MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address: 8940 Jones Mill Rd., Chevy Chase Meeting Date: 4/10/2019

**Resource:** Master Plan Site #35/12 **Report Date:** 4/3/2019

(Woodend)

**Public Notice:** 3/27/2019

**Applicant:** Audubon Naturalist Society

(Amy Ritsko-Warren, Agent)

Tax Credit: N/A

**Review:** 2<sup>nd</sup> Preliminary Consultation

**Staff:** Michael Kyne

**Case Number:** N/A

**PROPOSAL:** Hardscape alterations

#### STAFF RECOMMENDATION:

Staff recommends that the applicants make any revisions based on the HPC's recommendations and return for a HAWP application.

#### ARCHITECTURAL DESCRIPTION

SIGNIFICANCE: Master Plan Site STYLE: Georgian Revival

DATE: 1927

#### **Except from Places from the Past:**

In 1927, John Russell Pope, accomplished architect of Eclectic Classicism, designed Woodend for Chester Wells, a naval officer, and Marion Dixon Wells, an Australian heiress. Pope's best-known works include the National Gallery of Art (1941) and the Jefferson Memorial (1943). The spacious H-shaped mansion has Flemish-bond brick walls and quoins, molded water table, stone belt course, and denticulated cornice. The front (east) elevation has a semicircular portico with Ionic columns. A central door on the south elevation, opening into a terrace, has Corinthian pilasters supporting an egg and dart molded cornice, with scrolled broken-pediment. On the north, an oversize Palladian window, lighting a staircase, surmounts a doorway with heavy cornice and oversize Doric columns. A stone balustrade above the two-story brick walls conceals a low hip roof sheathed in copper.

On the interior, a large central hall has a grand, sweeping staircase with heavy newel posts at each landing. The library, or Bird Room, a richly paneled space with natural wood finish, is a reproduction of a room in Abergelde, Marion Wells' childhood home in Australia. While marble hearths and brick firebacks unite fireplaces throughout the house, each has differently detailed mantel pieces. The third level, sheltered beneath the hip roof over the main block, contained a caretaker's apartment. Sited on a hillside, the house is accessed by a long drive through beautifully landscaped grounds. The 40-acre property includes a brick gatehouse garage and numerous mature trees. Marion Wells, an ardent bird watcher, bequeathed the property to the Audubon Naturalist Society. The organization manages Woodend

as a nature preserve and education center.




Fig. 1: Subject property.

#### **BACKGROUND:**

The applicants previously appeared before the Commission for a preliminary consultation at the January 23, 2019 HPC meeting. At that time, the applicants proposed the installation of new walkways and other alterations. The Commission expressed concerns regarding the compatibility of the proposed new walkway materials (brick) and design, the replacement/relocation of the existing gazebo, and the installation of fences/gates on the terrace at the south side of the mansion.

#### **PROPOSAL:**

The applicants have returned with a revised hardscape plan. Specifically, the applicants are proposing the following work items:

- Replacement and extension of existing walkways.
- Replacement/redesign of existing parking areas.
- Other hardscape alterations.

In response to the Commission's previous concerns, the gazebo replacement/relocation and the fence/gate installation have been removed from the proposal.

Link to January 23, 2019 HPC meeting recording:

http://mncppc.granicus.com/MediaPlayer.php?publish\_id=9057cad6-201c-11e9-b021-0050569183fa

 $<sup>^{1}</sup> Link \ to \ previous \ staff \ report: \ \underline{https://montgomeryplanning.org/wp-content/uploads/2019/01/II.C-8940-Jones-Mill-Road-Chevy-Chase.pdf}$ 

#### **APPLICABLE GUIDELINES**

In accordance with section 1.5 of the Historic Preservation Commission Rules, Guidelines, and Procedures (Regulation No. 27-97) ("Regulations"), in developing its decision when reviewing a Historic Area Work Permit application for an undertaking at a Master Plan site the Commission uses section 24A-8 of the Montgomery County Code ("Chapter 24A"), the *Secretary of the Interior's Standards and Guidelines for Rehabilitation* ("Standards"), and pertinent guidance in applicable master plans. [Note: where guidance in an applicable master plan is inconsistent with the Standards, the master plan guidance shall take precedence (section 1.5(b) of the Regulations).] The pertinent information in these documents, incorporated in their entirety by reference herein, is outline below.

#### Sec. 24A-8. Same-Criteria for issuance.

- (a) The commission shall instruct the director to deny a permit if it finds, based on the evidence and information presented to or before the commission that the alteration for which the permit is sought would be inappropriate, inconsistent with or detrimental to the preservation, enhancement or ultimate protection of the historic site or historic resource within an historic district, and to the purposes of this chapter.
- (b) The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to insure conformity with the purposes and requirements of this chapter, if it finds that:
- (1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or
- (2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter; or
- (3) The proposal would enhance or aid in the protection, preservation and public or private utilization of the historic site or historic resource located within an historic district in a manner compatible with the historical, archeological, architectural or cultural value of the historic site or historic district in which an historic resource is located; or
- (4) The proposal is necessary in order that unsafe conditions or health hazards be remedied; or
- (5) The proposal is necessary in order that the owner of the subject property not be deprived of reasonable use of the property or suffer undue hardship; [emphasis added] or
- (6) In balancing the interests of the public in preserving the historic site or historic resource located within an historic district, with the interests of the public from the use and benefit of the alternative proposal, the general public welfare is better served by granting the permit.
- (c) It is not the intent of this chapter to limit new construction, alteration or repairs to any 1 period or architectural style.
- (d) In the case of an application for work on an historic resource located within an historic district, the commission shall be lenient in its judgment of plans for structures of little historical or design significance or for plans involving new construction, unless such plans would seriously impair the historic


or architectural value of surrounding historic resources or would impair the character of the historic district. (*Ord. No. 9-4*, § 1; *Ord. No. 11-59.*)

#### Secretary of Interior's Standards for Rehabilitation

The Secretary of the Interior defines rehabilitation as "the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features, which convey its historical, cultural, or architectural values." Because the property is a Master Plan Site, the Commission's focus in reviewing the proposal should be the *Secretary of the Interior's Standards for Rehabilitation*. The *Standards* are as follows:

- #2: The historic character of a property will be retained and preserved. The removal of distinctive materials or alterations of features, spaces, and spatial relationships that characterize a property will be avoided.
- #9: New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportion, and massing to protect the integrity of the property and its environment.
- #10: New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

#### **STAFF DISCUSSION:**






Fig. 2: Existing site plan (top), previous proposal (bottom left), and current proposal (bottom right).

#### North Entrance Walkway

The applicants propose to replace the existing concrete walkway with a flagstone on gravel walkway. The new walkway will follow the edge of the existing driveway and will be extended to connect to an existing crosswalk from the north parking area. The existing non-historic gazebo near the walkway is proposed to be removed, and the existing light posts along the walkway will be replaced with new light posts, which were previously approved by the HPC.

#### Audubon Naturalist Shop Parking Area

The existing asphalt parking area at the Audubon Naturalist Shop (north side of the mansion) s proposed to be replaced with permeable pavers. A section of asphalt adjacent to the mansion will be replaced with a flagstone pedestrian walkway. The walkway will match/connect with the proposed new north entrance walkway to the east and with an existing gravel path through the Blair Native Plant Garden to the west. The existing gravel path through the Blair Native Plant Garden will be widened and replaced with bonded gravel to make it accessible.

#### West Parking Area

The existing asphalt parking area at the west side of the mansion will be redesigned, with five parking spots directly in front of the mansion removed, and the asphalt replaced with permeable pavers. Garden beds will be added in front of the mansion where the parking spots will be removed, and a flagstone walkway will continue in a north-south direction.

#### South Side Walkways

The non-historic curvilinear walkways at the south side of the mansion will be replaced with new rectilinear walkways. The existing walkways are constructed from concrete pavers, whereas the proposed walkways will be constructed from bonded gravel. Bonded gravel will make the walkways accessible, while clearly differentiating them from the more formal flagstone walkways at the north and west parking areas/entrances.

#### East Portico

The non-historic curvilinear landing at the base of the portico on the east side of the mansion will be replaced and expanded. The proposed new material will be flagstone to be consistent with the proposed walkways, as well as with an existing walkway at the east side of the mansion.

Staff is supportive of the applicants' proposal, finding that the proposed alterations are consistent with the *Standards* and are unlikely to detract from the historic character-defining features of the resource. The applicants have followed the advice of the Commission and have researched the landscape design at other buildings designed by John Russell Pope. The applicants' revisions are based largely on the results of that research, which revealed the prevalent the use of flagstone, pavers, and gravel, with a rectilinear design.

Staff asks the Commission to provide any guidance that might make the proposal more compatible with the subject property and the criteria for approval.

#### STAFF RECOMMENDATION:

Staff recommends that the applicants make any revisions based on the HPC's recommendations and return for a HAWP application.





uigi	UNIC	AREA	MOKK PEKWII
0.	10		Committee Amy Ritsto-War
Contact Basil: anu	1. warming	eanshane o	
Tax Account No.: 530			Doyama Pinna No.: 301.652.9/88 X
Hand Property And	whom Ahr	implied Sovie	ty Depline Phone No.: 301, 652, 9188
8940 Tolor	= mill D	d Classes	Chase, MD 20815
Contraction: 2/1/17	r Land	Sapina	Proceed No.: 301.428.8810
Contractor Registration No.:	34280		
Agent for Owner:	A		Daytime Place No.:
Dealer Dealer to the second			
House Number 894	0	Street	Jones Mill Road
Formities Cheur C	base	Names Cress Street	Woodhillow Drive
Lot	Subdivi	The second second second second second	
Liber: Folie:	P	WES	101 398 CLEAN
Water and a service	VETTON AND USE		
IA CHECKALL APPLICABLE			APPLICABLE
Construct DE Extend			Stats Room Addition Perch Deck Shed
O Move 25 Install			☐ Fireplace ☐ Weedburning Stove ☐ Single Family
Revision D Repair			Ahil (complete Section 4) Other;
1B. Construction cost againmete: 1	-	Mary and Company of the Company	
IC if this is a revaion of a provious	sh editaring stone bear	rst, sae Permit #	
Math. 400 state 1	₹ I+ 1, 11 (m)	L'. Dur. Chen	
ZA. Type of sewage disposest.	OI WSSC	02 🗔 Septec	63 (3 Other:
2B. Type of water mapphy:	OI) WSSC	02 🗆 Well	03 🖸 Other:
Paris appet darde t	le la ·/ act	A STATE	
IA. Horgizfoot(	Control of the Contro		
18. Indicate whether the fence or	the state of the s	assistanted on one of the b	down bridge
13 On party line/property line			On public right of every/renoment
harnly carely that I have the putte	rity to make the forego	ing application, that the a	ophication is correct, and that the construction well comply with plans andition for the issuance of this permit.
.0 ~	, and any accommoda	man ecretis par to pa e c	minimum for the criminics of this paried.
My DE	· Mu	_	1/2/19
Sepreture W ou	मा स साविकाताची स्ट्रांसा		Date
	************		
aproved.			rson, Historic Preservation Convolusion
Suppreved:	Signature		Chinc
pplication/Pennit No.:		Duta Fili	ad:Dotts bround:
de 6/21/99	SEE REV	ERSE SIDE FOR	INSTRUCTIONS

#### Written Description of Project

a. Description of existing structure(s) and environmental setting, including their historical features and significance.

#### Woodend Sanctuary, Headquarters of the Audubon Naturalist Society

Woodend Nature Sanctuary in Chevy Chase, Maryland has been the headquarters of the Audubon Naturalist Society (ANS) for the past 50 years. Founded in 1897, ANS's mission is to "inspire residents of the Washington, DC region to appreciate, understand and protect their natural environment through outdoor experiences, education and advocacy."

#### **Historic Significance**

The Audubon Naturalist Society headquarters at Woodend Nature Sanctuary is an historically significant site listed on the National Historic Register, and on Montgomery County's Master Plan for Historic Preservation.

The Woodend estate was designed by John Russell Pope as a residence for owners Captain and Mrs. Chester Wells. Pope's classically inspired works include the Jefferson Memorial, the West Wing of the National Gallery of Art and Constitution Hall in Washington, DC. Built in 1927, the Woodend mansion is an admired example of Georgian Revival architecture, known for symmetry and geometric proportions.

The Wells family called Woodend their home from 1927 until Mrs. Wells passed away in 1967. In her will, Mrs. Wells donated Woodend to ANS, "...for the purposes of maintaining a headquarters and a bird sanctuary. In 1969, the organization moved its headquarters to Woodend and the primary function of the land and its buildings transitioned from private residence to a nature sanctuary that is free and open to the public 365 days a year.

In 1980, Woodend's building and grounds were accepted by the US Department of the Interior as an historically designated site.

#### **Looking Forward**

ANS has launched a Nature for All project to improve the visitor experience and guide the stewardship and restoration of Woodend Nature Sanctuary. Nature for All envisions "Historic Woodend Sanctuary is Washington's oasis of sustainable, healthy natural habitats – welcoming and inspiring all people to enjoy, learn about and protect our shared environment." Our Nature for All project puts the Woodend buildings and grounds front and center, as cultural features to be interpreted to visitors as integral parts of our education and conservation mission.

Audubon Naturalist Society aims to improve the visitor experience and increase the opportunities for people of all ages and abilities in Montgomery County and the region to enjoy, learn about, and conserve nature. Essential to achieving this goal is guiding and directing unaccompanied visitors to special places within Woodend Nature Sanctuary.

- b. General description of project and its effect on the historic resource(s), the environmental setting, and, where applicable, the historic district.
  - 1. Replace and extend existing north walkway to improve safety and accessibility
  - 2. Replace existing shop asphalt parking area with permeable pavers and flagstone walkway, and widen and bond gravel path to improve safety and drainage
  - 3. Replace existing western asphalt parking area with garden areas, permeable pavers, and an accessible walkway to improve safety, accessibility and drainage
  - 4. Replace, realign and extend existing walkways on southern (garden) façade
  - 5. Replace and expand existing landing around portico

#### 1. Replace and Extend Existing North Walkway

<u>Overview:</u> A good walkway makes it easier and safer for visitors to walk through a landscape. It provides more reliable access in all weather and makes it possible for differently-abled visitors to access site features more easily. Well-located walkways serve as bread crumb trails that tell visitors where to go.

The replacement and extension of the existing walkway will make the accessible entrance visible from the parking area, keep visitors separate from cars and trucks by giving them a dedicated walkway, and protect the historic lawn from foot traffic.

Existing Conditions: Today, there is no walkway that leads visitors from the main, north parking lot to the mansion. To get to the accessible entrance, visitors must walk on the drive toward the shop. Only when visitors are in front of the shop can the accessible entrance and its path be seen. The existing pathway extends from the mansion's north entrance then curves to the shop parking area near the building.






Existing Concrete Walkway Begins in Shop Parking Lot




Existing Concrete Walkway Ends at Accessible Entrance

#### **Existing North Walkway - concrete**



#### **Proposed North Walkway - flagstone**



<u>Site Plan:</u> Replace the existing north entrance walkway with new materials and extend it to a crosswalk where visitors will cross from the north parking area. The existing gazebo will be removed, and existing light posts will be removed and replaced with new light posts (previously approved by HPC) to illuminate the new walkway. The newly extended path will follow the drive edge, collect visitors pulling them to the mansion and off the driveway. Foliage around the north entrance will be trimmed or removed to open up the view of the mansion. The new pathway alignment allows more space for garden plantings to screen a hose bib at the mansion corner.

<u>Materials</u>: The walkway will be constructed of Pennsylvania cut flagstone in a pattern of squares and rectangles as in the photo from "The Waves" below. The stone will be set in a gravel base with quarter-inch joints filled with crushed stone. Flagstone is currently used on the property in the original walkway from the portico to the mansion and is a common material used for walkways in other John Russell Pope residential buildings.



Flagstone walkway at John Russell Pope Home "The Waves" From "Mastering Tradition: The Residential Architecture of John Russell Pope" by James B. Garrison



Existing Flagstone Walkway at Woodend

## 2. Replace existing shop asphalt parking area with permeable pavers and flagstone walkway, and widen and bond gravel path.

<u>Overview:</u> Replacing a portion of the existing asphalt parking area with a cohesively designed, accessible path will lead visitors from the north and shop parking areas to the west facing front of the mansion. Replacing the existing asphalt surface in the shop parking lot with permeable pavers will allow ANS to improve drainage around the mansion foundation and treat more of the stormwater that flows off the property into neighboring properties. Widening and bonding the gravel through the Blair Garden will improve accessibility from the north to the west side of the mansion.

<u>Existing Conditions</u>: Woodend's shop parking area is paved in asphalt with no marked pedestrian crossing or entrance. There is an existing gravel path through the Blair Native Plant Garden that leads visitors from one asphalt parking area to the other. The gravel path is suitable for walking, however it is impossible to traverse if using a walker, wheelchair, or stroller.







**Existing Loose Gravel Garden Path** 

Drainage and stormwater treatment is a significant challenge at Woodend. The mansion was built at the top of a hill and yet the basement continues to flood during large storm events. All of the stormwater from the mansion roof and the property's paved areas negatively impacts the mansion and our neighbors, in addition to contributing to the pollution entering the county stormwater system and Rock Creek itself. As a conservation organization, ANS would like to replace the asphalt parking area to protect the mansion and model best stormwater management practices available today.

<u>Site Plan:</u> Replace portions of existing asphalt shop parking surface with permeable pavers to improve drainage. Replace asphalt closest to the mansion with flagstone pedestrian walkway to improve safety. Widen existing gravel path through Blair Native Plant Garden and bond the gravel to make it accessible.

## **Existing Shop Parking and Walkway Proposed Shop Parking and Walkway** NORTH ENTRANCE WEST ENTRANCE 9 WEST ENTRANCE SOUTH TERRRACE SOUTH TERRINCE Asphalt Flagstone Loose Gravel Permeable pavers **Bonded Gravel**

<u>Materials</u>: Flagstone to match north walkway for walkway; permeable pavers for parking area using small squares to fit with Pope design; bonded pea gravel for garden path. Pea gravel or crushed stone is a common material used for walkways in other John Russell Pope residential buildings. Several of Pope's residential houses include pavers entry courtyards.



**Permeable Concrete Pavers** 



Paver entrance at Meridian House, 1920
From "Mastering Tradition: The Residential Architecture of John
Russell Pope" by James B. Garrison



**Bonded gravel** 



Gravel walkway at Mills Residence, 1915
From "Mastering Tradition: The Residential Architecture of John
Russell Pope" by James B. Garrison

### 3. Replace existing western asphalt parking area with gardens, accessible walkway, and permeable pavers.


<u>Overview</u>: With a reconfiguration of the western parking area, the formal front (western) façade of Woodend will be visibly accessible to all visitors instead of obscured by parked cars as it is today. A dedicated pedestrian walkway will keep pedestrians safe and separate from vehicles. The view of the formal front entrance of the mansion will be enhanced with the extension of the existing garden beds in front of the mansion, and the addition of garden beds on the western edge of the pedestrian walkway.



Western Façade of Woodend - Formal Entrance

<u>Existing Conditions</u>: The cars parked in front of the west entrance obscure the formal front door to the mansion and detract from the overall view of the building. From all parking areas, pedestrians must walk behind and between parked cars to access the west (front) entrance to the mansion. The parking area goes directly up to the garden beds with no pedestrian walkway. The permeable pavers will improve drainage and treat stormwater run-off from our roof and parking area.

<u>Site Plan:</u> Redesign west parking lot to improve view of mansion and pedestrian access to the west entrance. Remove 5 parking spots directly in front of building to open up view of mansion. Replace an asphalt parking section with garden beds flanking an accessible walkway. Replace remaining portions of existing asphalt parking surface with permeable pavers and retain existing parking spots on the west side of the lot.



<u>Materials</u>: Flagstone to match other walkways described, Permeable pavers as described for Shop lot

#### 4. Replace, realign and extend existing walkways on southern (garden) façade


<u>Overview:</u> A realignment, extension and replacement of existing walkways around the garden façade of the mansion will enhance and reflect the geometric grandeur of the building while providing accessible pedestrian access from the western parking area to the eastern façade portico. The pathways will help preserve the landscaping and lawn that are deteriorating due to extensive foot traffic.




<u>Existing Conditions</u>: Current walkways are constructed of non-historic concrete pavers that are inconsistent with the character of the building. The existing walkways on this façade follow a scalloped shape and terminate off-center of the terrace. There is currently no connection from the center stair landing to any walkway. Due to growing tree roots and moisture, the existing pathway is no longer level. Because pedestrians have no clear and contiguous path around the lawn side of the mansion, foot traffic has deeply deteriorated the lawn and landscaping.

<u>Site Plan:</u> Realign walkways to reflect the geometric shape and symmetry of John Russell Pope's design of the mansion. Replace concrete paver materials with bonded gravel. Extend the walkway so it meets with the stair landing and continues to meet the connection to the eastern (portico) façade walkway.

#### **Existing South Walkways**



#### **Proposed South Walkways**




Concrete pavers

WEST ENTRANCE


Bonded gravel

Material: Bonded gravel.

0



From "Mastering Tradition: The Residential Architecture of John Russell Pope" by James B. Garrison




#### 5. Replace and expand existing landing around portico

<u>Overview:</u> Replacing the existing concrete pavers around the portico with flagstone will cohesively connect the building to the historic flagstone pathway to the grove.




<u>Existing Conditions:</u> The existing concrete pavers are inconsistent with the materials used on the portico, with its marble floor and poured concrete stairs, and the adjoining flagstone path. Because of the grading under the pavers, the two steps off the portico have dramatically different rises, resulting in an unsafe and awkward decent from the portico to the landing. The existing pavers are heaving from growing tree roots and moisture.

<u>Site Plan:</u> Replace the existing concrete pavers with flagstone. Expand the width of the landing. Regrade the landing so the rise of the second step from the portico matches the rise of the first step.




Materials: Flagstone set in gravel as described for north walkway

#### **Existing Full Site Plan**



#### **Proposed Site Plan**




#### **Existing (Non-historic) Materials:**

Asphalt



Poured concrete



**Concrete Pavers** 



Loose Gravel



**Proposed Materials:** 

Permeable pavers



Flagstone



**Bonded Gravel** 



**Material Examples from John Russell Pope Designs** 

**Pavers** 




Flagstone




Gravel




#### **Examples of Residential Site Plans Designed by John Russell Pope**




Plans of House and Garden House of George Hewitt Myers, Esq., Washington, D. C.





House of Philip Gossler, Wheatley Hills, Long Island office of John Russell Pope, architect ellen shipman, landscape architect



SITE AND FLOOR PLANS

#### **Tree Survey**

Three multi-stemmed trees (overall diameter of each between 12 - 15 inches) will be removed along the North Entrance Pathway in order to open up the view of the door and palladian window of the mansion's north facade. Two trees of approximately 10 inches in diameter will be removed to allow for the reconfiguration of pathways off the south terrace of the mansion.

#### **Working with the Community**

In 2017, the Audubon Naturalist Society formed a Community Liaison Council to help keep our neighbors apprised of plans for Woodend and to hear and incorporate their feedback on the Woodend plans. To date, we have held six Community Liaison Meetings (March 29, April 18, and September 14, 2017, February 22 and September 18, 2018, and February 21, 2019). We have reported to our neighbors about the Nature for All Project, including proposed upgrades to the walkways around the mansion. Audubon Naturalist Society looks forward to better serving the residents of Montgomery County with our Nature for All project.

### **Adjacent and Confronting Property Owners**

NAME	ADDRESS	LOT/BLOCK
1. Malcom & Alina Brenner	9101 Brierly Rd. Bethesda, MD 20815	Lot !/Block I
2. Bl)'an & Mal)' Jacobik	9103 Brierly Rd. Chevy Chase, MD 208!5	Lot 2/Biock I
3. Joseph Cupo & Kathleen Teixeira	9.05 Brierly Rd. Chevy Chase, MD 20815	Lot 3/Biock I
4. Stacy Berman & Edward Rosen	9107 Brierly Rd. Chevy Chase, MD 20815	Lot 4/Block 1
5. Mildeen Worrell	9109 Brierly Rd. Chevy Chase, MD 20815	Lot 5/Biock I
6. Neil & Rachel Hyman	911 I Brierly Rd. Chevy Chase, MD 20815	Lot 6/Biock I
7. Steven Schwartz & Elana Cohen	9113 Brierly Rd. Chevy Chase, MD 20815	Lot 7/Biock I
8. William & R A Panton	3213 Woodhollow Dr. Chevy Chase, MD 20815	Lot 9/Biock 1
9. Nathan Abraham	3214 Woodhollow Dr. Chevy Chase, MD 20815	Lot 6/Block 4
I0. Bruce & Iresha Fletcher	9002 Levelle Dr. Chevy Chase, MD 20851	Lot SA/Block 4
II. Daniel & D M Bailey	9000 Levelle Dr. Chevy Chase, MD 20815	Lot 7A/Block 4
12. Janet Rutsch Revoc Trust	900 I Levelle Dr. Chevy Chase, MD 20815	Lot 15A/Biock 6
!3. Neil Stormer & lain Habboo	9000 Jones Mill Rd. Che <u>vy</u> Chase, MD 20815	Lot 14A/Block 6
14. Ruth Gillilland Grove	900 I Jones Mill Rd. Chevy Chase, MD 20815	
15. Mark Smith & Maxine Harris	9005 Jones Mill Rd. Chevy Chase, MD 20815	Lot 7
16. Maryland National Capital Park & Planning Commission	8787 Georgia Ave. Silver Spring, MD 20910	

17. Maryland National Capital Park & Planning Commission	8787 Georgia Ave. Silver Spring, MD 20910	
18. Maryland National Capital Park & Planning Commission	8787 Georgia Ave. Silver Spring, MD 20910	Par B/Biock A
19. Robyn Allen	3101 Black Chestnut Ln. Chevy Chase, MD 20815	Lot23/Block A
20. Michael August & Bonnie Weaver	3103 Black Chestnut Ln. Chevy Chase, MD 20815	Lot24/Block A
21. Charles & S D Alston	3105 Black Chestnut Ln. Chevy Chase, MD 20815	Lot 25/Block A
22. Sherif & Norma Ettefa	3107 Black Chestnut Ln. Chevy Chase, MD 20815	Lot 26/Block A
23. Andrew & P E Shoyer	3108 Black Chestnut Ln. Chevy Chase, MD 20815	Lot 18/Biock A
24. Ezra Reese & Azad Nilofer	8811 Jones Mill Rd. Chevy Chase, MD 20815	Lot 15/Block A
25.Joanna Nunan & Thomas Nunan 3'd	8809 Jones Mill Rd. Chevy Chase, MD 20815	Lot 14/Block A
26.Gonzalo C Pastor & Judith Gold	8807 Jones Mill Rd. Chevy Chase, MD 20815	Lot 16/Biock A
27.John Bristol & Caroline Quijada	320 I Flushing Meadow Ter. Chevy Chase, MD 20815	Lot 23/Block 2
28. Thomas & K M Gilday	3211 Flushing Meadow Ter. Chevy Chase, MD 20815	Lot 18/Biock 2
29. Peter Mathers & Bonnie Beavers	3213 Flushing Meadow Ter. Chevy Chase, MD 20815	Lot 17/Biock 2
30. Mohamadi Ali & Sara Depew	3212 Flushing MeadowTer. Chevy Chase, rviD 20815	Lot 16/Block 2
31. Jose Demarais Jr & ER L Demarais	8819 Altimont Ln. Ch vy Chase, MD 20815	Lot 9/Block 2
32. Howard & K R Rosenberg	8816 Altimont Ln. Chevy Chase, MD 20815	Lot 9/Block I
33. North Chevy Chase Swimming	3 Campbell Ct. Kensington, MD 20895	

34. John & Julie Fox	3500 Dundee Dr.	Lot 6/Biock H
54.30m & June 10A	Chevy Chase, MD 20815	Lot 0/Block 11
35. Douglas & Marianna Lanzo	8824 Brierly Rd. Chevy Chase, MD 20815	Lot 3/Biock F
36. Thomas & B G Corbin	8826 Brierly Rd. Chevy Chase, MD 20815	Lot 2/Biock F
37. May & LA Breslow	8828 Brierly Rd. Chevy Chase, MD 20815	Lot 1/Biock F
38. Gary Sinise Foundation	21700 Oxnard St. #580 Woodland Hills, CA 91367	Lot 7/Biock E
39. John & Subadra Molyneaux	8908 Brierly Rd. Chevy Chase, MD 20815	Lot 6/Block E
40. Delfin & M A Go	8912 Brierly Rd. Chevy Chase, MD 20815	Lot 5/Biock E
41. Anthony J. Froelich Jr & M A Froelich	8918 Brierly Rd. Che_vy_Chase, MD 20815	Lot 4/Biock E
42. John McKeon et al Tr	8922 Brierly Rd. Chevy Chase, MD 20815	Lot 2/Block E
43. Robert Kreimeyer Jr et al.	9002 Brierly Rd. Chevy Chase, MD 20815	Lot 17/Biock D
44. Helen Kelly et al Tr	9006 Brierly Rd. Chevy Chase, MD 20815	Lot 18/Biock D
45. Andrew & A Goldfarb	9010 Brierly Rd. Chevy Chase, MD 20815	Lot 19/Biock D
46. Stephen & J K N Drake	9012 Brierly Rd. Chevy Chase, MD 20815	Lot P20/Biock D
47. Bret & AM Kelly	9018 Brierly Rd. Chevy Chase, MD 20815	Lot P20/Block D
48. Bret & A M Kelly	9018 Brierly Rd. Chevy Chase, MD 20815	Lot 9/Biock A