

*Preliminary Consultation*  
**MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION**  
**STAFF REPORT**

<b>Address:</b>	7314 Maple Avenue, Takoma Park	<b>Meeting Date:</b>	9/3/2025
<b>Resource:</b>	Contributing Resource Takoma Park Historic District	<b>Report Date:</b>	8/27/2025
<b>Applicant:</b>	Eric Maier and Krisztina Petz (Eric Hurtt, Architect)	<b>Public Notice:</b>	8/20/2025
<b>Review:</b>	Preliminary Consultation	<b>Tax Credit:</b>	No
<b>Permit No.:</b>	1129183	<b>Staff:</b>	Laura DiPasquale
<b>Proposal:</b>	Construction of new addition and retroactive tree removal		


---

**RECOMMENDATION**

Staff recommends that the applicant make any changes recommended by the HPC and return for a HAWP.

**PROPERTY DESCRIPTION**

**SIGNIFICANCE:** Contributing Resource to the Takoma Park Historic District  
**STYLE:** Arts & Crafts Four Square  
**DATE:** 1921



*Figure 1: The rear of the subject property abuts the northern boundary line of the Takoma Park Historic District.*





*Figure 2: Front and partial north side elevations of the subject property from Maple Avenue.*




*Figure 3: Front and south side elevations of the subject property from Maple Avenue.*

## **PROPOSAL**

The applicant proposes to construct a one-story 390 square foot gable-roofed addition off the north rear corner of the house. The L-shaped addition would extend 6 feet into the side yard along the northeastern side of the property and extend approximately 26 feet towards the rear before turning to run 18-feet 2-inches along the rear elevation of the existing house. The addition would be clad in 7-inch exposure smooth Hardie Plank fiber cement siding with painted wood corner and trim boards and feature Marvin Ultimate aluminum-exterior casement windows, Marvin Ultimate wood double-hung windows and French doors, and new composite decks, stairs, and railings.

The applicants also seek retroactive approval for the removal of a 47.8-inch diameter Southern Red Oak removed from the back right corner of the house that was removed in 2025 without a Historic Area Work Permit.



**Figure 4: Proposed front and rear elevations.**

## **APPLICABLE GUIDELINES**

The Historic Preservation Office and Historic Preservation Commission (HPC) consult several documents when reviewing alterations and new construction within the Takoma Park Historic District. These documents include the historic preservation review guidelines in the approved and adopted amendment for the *Takoma Park Historic District (Guidelines)*, *Montgomery County Code Chapter 24A (Chapter 24A)*, and the *Secretary of the Interior's Standards for Rehabilitation (Standards)*. The pertinent information in these four documents is outlined below.

### ***Takoma Park Historic District Guidelines***

There are two broad planning and design concepts which apply to all categories. These are:

- The design review emphasis will be restricted to changes that are all visible from the public right-of-way, irrespective of landscaping or vegetation (it is expected that the majority of new additions will be reviewed for their impact on the overall district), and
- The importance of assuring that additions and other changes to existing structures act to reinforce and continue existing streetscape, landscape, and building patterns rather than to impair the character of the historic district.



A majority of the buildings in the Takoma Park Historic District have been assessed as being “Contributing Resources.” While these buildings may not have the same level of architectural or historical significance as Outstanding Resources or may have lost some degree of integrity, collectively, they are the basic building blocks of the Takoma Park district. They are important to the overall character of the district and the streetscape due to their size, scale, and architectural qualities, rather than for their particular architectural features.

Contributing Resources should receive a more lenient level of design review than those structures that have been classified as Outstanding. This design review should emphasize the importance of the resource to the overall streetscape and its compatibility with existing patterns rather than focusing on a close scrutiny of architectural detailing. In general, however, changes to Contributing Resources should respect the predominant architectural style of the resource.

#### *Residential Areas*

In Takoma Park, there are a number of elements which define the streetscape and building patterns.

- Use of decorative stone retaining walls (where required by topographic changes) and occasionally fences to define a sidewalk line and separate yards from street.
- Sidewalks and planting strips along the street.
- Orientation of driveways and parking areas to the rear and side of buildings.
- Extensive landscaping, including mature trees and flowering plants (e.g. azaleas).

The following guidance which pertains to this project are as follows:

- All exterior alterations, including those to architectural features and details, should be generally consistent with the predominant architectural style and period of the resource and should preserve the predominant architectural features of the resource; exact replication of existing details and features is, however, not required.
- Minor alterations to areas that do not directly front on a public right-of-way – such as vents, metal stovepipes, air conditioners, fences, skylights, etc. – should be allowed as a matter of course;
- Major additions should, where feasible, be placed to the rear of existing structures so that they are less visible from the public right-of-way; additions and alterations to the first floor at the front of a structure are discouraged but not automatically prohibited;
- While additions should be compatible, they are not required to be replicative of earlier architectural styles;
- Second story additions or expansions should be generally consistent with the predominant architectural style and period of the resource (although structures that have been historically single story can be expanded) and should be appropriate to the surrounding streetscape in terms of scale and massing;
- Alterations to areas that do not directly front on a public right-of-way which involve the replacement of or damage to original ornamental or architectural features are discouraged but may be considered and approved on a case-by-case basis.
- Original size and shape of window and door openings should be maintained, where feasible.
- Alterations to features that are not visible at all from the public right-of-way should be allowed as a matter of course.
- All changes and additions should respect existing environmental settings, landscaping, and patterns of open space.

#### ***Montgomery County Code, Chapter 24A-8***

The following guidance which pertains to this project are as follows:



- (b) The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to ensure conformity with the purposes and requirements of this chapter, if it finds that:
  - (1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or
  - (2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter;
- (d) In the case of an application for work on an historic resource located within an historic district, the commission shall be lenient in its judgment of plans for structures of little historical or design significance or for plans involving new construction, unless such plans would seriously impair the historic or architectural value of surrounding historic resources or would impair the character of the historic district. (Ord. No. 9-4, § 1; Ord. No. 11-59.)

### ***Secretary of the Interior's Standards for Rehabilitation***

The Secretary of the Interior defines rehabilitation as “the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features, which convey its historical, cultural, or architectural values.” The applicable *Standards* are as follows:

- 2. The historic character of a property will be retained and preserved. The removal of distinctive materials or alteration of features, spaces and spatial relationships that characterize a property will be avoided.
- 9. New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.
- 10. New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

### ***Historic Preservation Commission Policy No. 24-01: Policy for the Appropriateness of Substitute Materials for Porch and Deck Flooring***

- 4. **Contributing Resources – These are significant for their contribution to the district as a whole and prioritize retaining the architectural style, overall volume, and size. Porch floors on ‘Contributing’ resources may be a compatible substitute material (discussed below), provided the material matches the building’s historic character and construction methods. Historic rear porches for ‘Contributing’ resources may be constructed using a compatible substitute material. Non-historic porches and decks on ‘Contributing’ resources that are not visible from the public right-of-way may be constructed using substitute materials.**
- 5. **Non-Contributing Resources/Secondary/Spatial – These were constructed after the district’s period of significance or have been so heavily modified that they no longer contribute to the historic district’s character. These resources do not need to use traditional materials. New porch flooring/decking materials for these resources need to satisfy the criteria for compatible substitute material.**
- 6. **Compatible substitute materials for replacement porch flooring/decking – On buildings where a substitute material is acceptable under this policy, the material must satisfy the following criteria:**
  - It must match the dimensions and installation method (i.e.) of the existing material or a historically appropriate porch flooring, (e.g., boards must run perpendicular to the house for porches);
  - It must be millable;








Figure 6: Existing/demolition plan and proposed first-floor plan.



Figure 7: Existing conditions photographs provided by the applicant.



8



NEW EXTERIOR ADDITIONS TO HISTORIC BUILDINGS AND RELATED NEW CONSTRUCTION	
RECOMMENDED	NOT RECOMMENDED
<b>New Additions</b>	
Placing functions and services required for a new use (including elevators and stairways) in secondary or non-character-defining interior spaces of the historic building rather than constructing a new addition.	Expanding the size of the historic building by constructing a new addition when requirements for the new use could be met by altering non-character-defining interior spaces.
Constructing a new addition on a secondary or non-character-defining elevation and limiting its size and scale in relationship to the historic building.	Constructing a new addition on or adjacent to a primary elevation of the building which negatively impacts the building's historic character.
Constructing a new addition that results in the least possible loss of historic materials so that character-defining features are not obscured, damaged, or destroyed.	Attaching a new addition in a manner that obscures, damages, or destroys character-defining features of the historic building.
Designing a new addition that is compatible with the historic building.	Designing a new addition that is significantly different and, thus, incompatible with the historic building.
Ensuring that the addition is subordinate and secondary to the historic building and is compatible in massing, scale, materials, relationship of solids to voids, and color.	Constructing a new addition that is as large as or larger than the historic building, which visually overwhelms it (i.e., results in the diminution or loss of its historic character).
NEW EXTERIOR ADDITIONS TO HISTORIC BUILDINGS AND RELATED NEW CONSTRUCTION	
RECOMMENDED	NOT RECOMMENDED
Using the same forms, materials, and color range of the historic building in a manner that does not duplicate it, but distinguishes the addition from the original building.	Duplicating the exact form, material, style, and detailing of the historic building in a new addition so that the new work appears to be historic.
Basing the alignment, rhythm, and size of the window and door openings of the new addition on those of the historic building.	
Incorporating a simple, recessed, small-scale hyphen, or connection, to physically and visually separate the addition from the historic building.	
Distinguishing the addition from the original building by setting it back from the wall plane of the historic building.	


**Figure 10: Excerpt from the Secretary of the Interior's Guidelines for Rehabilitating Historic Buildings, Guidelines for New Exterior Additions to Historic Buildings and Related New Construction.**

Staff finds that the proposed addition meets most but not all of the recommendations for appropriate additions laid out in the *Rehabilitation Guidelines*. The proposed addition would be located on a secondary elevation and at one-story, would be limited in size and scale in relationship to the historic building. Attaching primarily to the non-historic rear addition constructed in 2015, the proposed addition results in the least possible loss of historic materials, and only obscures a small portion of the side wall of the historic main block. Generally, staff finds that the design of the proposed addition is compatible with the historic building in terms of height, scale, massing, materials, fenestration alignment and rhythm, and relationships of solids to voids. Staff finds that the proposed 7-inch exposure Hardie plank siding, simulated-divided-light clad-wood Marvin windows, and asphalt shingle roof are compatible with the historic structure and surrounding streetscape, as well as the HPC's 2015 approval for siding installation on the main block and new addition, and are consistent with the Guidelines and Chapter 24A-8(b)(2). Staff notes that the proposed composite deck, stair, and railing material is not specified, but should comply with *Policy 24-01*.

Staff does find, however, that the proposed eave overhang is out of scale with the proposed addition and should be reduced. Staff finds that the addition should read as secondary to the main block and not try to

replicate the overhanging eave depth of the main block, which has a different pitch and massing, and should be differentiated from the old, per *Standard 9*.


The larger question for the HPC is regarding the appropriateness of the addition projecting beyond the wall plane of the historic house and eliminating the recess of the 2015 addition at the first-floor. Staff finds that on the one hand, whereas a two-story addition projecting into the side yard would likely read as overwhelming to the historic building, the smaller scale of the one-story projection still reads as subordinate to the historic building. On the other hand, the proposed addition eliminates the small 6-inch recess between the main block and 2015 addition at the first-floor and the purposeful change in wall planes between the old and new. The *Rehabilitation Guidelines* recommend that additions incorporate simple, recessed, small-scale hyphens or connections to physically and visually separate the addition from the historic building, and to distinguish the addition from the original building by setting it back from the wall plane of the historic building. Staff finds that, should the HPC determine that the projection of the one-story addition beyond the side wall plane is appropriate, the addition be shifted back behind the return of the historic main block so that it does not intersect with the side wall plane of the historic house and the full height of the existing trim board between the historic main block and addition remains visible.



**Figure 11: Proposed front elevation.** Staff notes this view does not show the entire elevation of the proposed addition.



Staff finds that the construction of a one-story projecting side addition is not completely aberrant to the HPC's previous approvals, having found evidence of at least two previous HPC approval for construction of side additions on Contributing resources in the Takoma Park Historic District. In 1999, the HPC approved a small 6-foot wide by 16-foot long mudroom addition at 7221 Cedar, which was not ultimately constructed.<sup>2</sup> The HPC also approved a side addition at 7221 Spruce Avenue, a Contributing resource with significant site constraints, in 1996.<sup>3</sup>



**Figure 12: Approved (but not constructed) mudroom addition at 7221 Cedar Avenue, Takoma Park, 1999.**

### *Tree Removal*

The application also includes photographs of a large oak tree with a note that the tree was removed under permit W012765-032425, which is a City of Takoma Park permit number. Staff has determined that this tree was removed without a Historic Area Work Permit, and that the applicants must receive retroactive approval for the removal. Staff notes that the City of Takoma Park permit identifies the tree as a 47.8-inch diameter at breast height (d.b.h) Southern Red Oak, and that the applicants opted to pay a fee in lieu of replacement planting. The fee-in-lieu payment indicates that the tree was not dead or hazardous, since the City of Takoma Park's website notes that if a tree is determined dead or hazardous, the permit will be approved immediately after the Urban Forest Manager's inspection, and nothing more will be required after the permit is issued.

Staff notes that, although the tree was shown on the 2015 site plan for construction of the rear addition (Figure 5), it appears to actually have been much closer to the approved construction, just off of the eaveline of the rear, north corner (Figure 13). Per the *Guidelines*, Takoma Park's residential area is characterized by generous lawns shaded by large mature trees. Staff finds that, while the large oak contributed to that overall tree canopy, presently there remains sufficient tree canopy provided by the large tree in the front yard, and other large mature trees on adjacent properties. However, staff notes that it takes decades for trees to reach their full, mature height, and that the continued removal of large trees in Takoma Park will eventually degrade the character of the district. As such, staff recommends that at least one new oak tree be planted in the rear yard of the property. The new tree should be planted at an appropriate distance from the house and existing trees.

<sup>2</sup> Staff report and application materials for additions to 7221 Cedar Avenue, approved by the HPC in 1999: [https://mcatlas.org/files/06\\_HistoricPreservation\\_PhotoArchives/Padlock/HAR60640002/Box006/37-3-99N\\_Takoma%20Park%20Historic%20District\\_7221%20Cedar%20Avenue\\_06-23-1999.pdf](https://mcatlas.org/files/06_HistoricPreservation_PhotoArchives/Padlock/HAR60640002/Box006/37-3-99N_Takoma%20Park%20Historic%20District_7221%20Cedar%20Avenue_06-23-1999.pdf)

<sup>3</sup> Staff report and application materials for additions to 7221 Spruce Avenue, approved by the HPC in 1999: [https://mcatlas.org/files/06\\_HistoricPreservation\\_PhotoArchives/Padlock/HAR60640002/Box003/37-3-96I\\_Takoma%20Park%20Historic%20District\\_7221%20Spruce%20Avenue\\_04-10-1996.pdf](https://mcatlas.org/files/06_HistoricPreservation_PhotoArchives/Padlock/HAR60640002/Box003/37-3-96I_Takoma%20Park%20Historic%20District_7221%20Spruce%20Avenue_04-10-1996.pdf)



**Figure 13:** Photographs of the 2015 rear addition and the 47.8 d.b.h Red Oak tree that was removed in 2025.



**Figure 14:** Aerial view of the property in March 2025 prior to the tree removal. A red arrow points to the tree that was removed.





*Figure 15: The subject property in 2022, prior to tree removal (Google Streetview) and in July 2025, after tree removal (Historic Preservation Office). A red arrow points to the tree that was removed.*

### **STAFF RECOMMENDATION**

Staff recommends that the applicant make any revisions based upon the HPC's comments and return for a HAWP.

#### ***Staff Requested HPC Feedback***

- The appropriateness of the location, scale, and massing of the proposed addition;
- The appropriateness of the proposed addition design;
- The appropriateness of the proposed addition materials; and,
- Any other comments.

#### ***Staff-recommended materials to be submitted for a future submission:***

- Existing conditions elevation drawings;
- A full elevation detail of the proposed addition unobscured by the existing building chimney;
- Complete materials specifications, including of the proposed composite porch decking, stair and railings.
- A tree survey showing the location of existing trees on the property and in proximity to the property line, plus the location of a new oak tree to be planted to replace the tree removed without a HAWP.





APPLICATION FOR  
HISTORIC AREA WORK PERMIT  
HISTORIC PRESERVATION COMMISSION  
301.563.3400

FOR STAFF ONLY:

HAWP# 1129183

DATE ASSIGNED

APPLICANT:

Name: Eric Maier & Krisztina Petz  
Address: 7314 Maple Avenue  
Daytime Phone: (517) 388-1390

E-mail: ericjmaier@gmail.com, krisztina.petz@gmail.com  
City: Takoma Park Zip: 20912  
Tax Account No.:

AGENT/CONTACT (if applicable):

Name: Eric Hurtt for Hill & Hurtt Architects  
Address: 3335 Connecticut Ave NW Suite 101  
Daytime Phone: (202) 681-1495

E-mail: eric@hillandhurtt.com  
City: Washington, DC Zip: 20008  
Contractor Registration No.:

LOCATION OF BUILDING/PREMISE: MIHP # of Historic Property

Is the Property Located within an Historic District? ☒ Yes/District Name Takoma Park Historic District  
☐ No/Individual Site Name

Is there an Historic Preservation/Land Trust/Environmental Easement on the Property? If YES, include a map of the easement, and documentation from the Easement Holder supporting this application.

Are other Planning and/or Hearing Examiner Approvals /Reviews Required as part of this Application? (Conditional Use, Variance, Record Plat, etc.?) If YES, include information on these reviews as supplemental information.

Building Number: 7314 Street: Maple Avenue  
Town/City: Takoma Park Nearest Cross Street: Philadelphia Avenue  
Lot: P17 Block: 5 Subdivision: Gilberts Parcel:

TYPE OF WORK PROPOSED: See the checklist on Page 4 to verify that all supporting items for proposed work are submitted with this application. Incomplete Applications will not be accepted for review. Check all that apply:

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> New Construction | <input checked="" type="checkbox"/> Deck/Porch | <input type="checkbox"/> Shed/Garage/Accessory Structure |
| <input checked="" type="checkbox"/> Addition         | <input type="checkbox"/> Fence                 | <input type="checkbox"/> Solar                           |
| <input type="checkbox"/> Demolition                  | <input type="checkbox"/> Hardscape/Landscape   | <input type="checkbox"/> Tree removal/planting           |
| <input type="checkbox"/> Grading/Excavation          | <input type="checkbox"/> Roof                  | <input checked="" type="checkbox"/> Window/Door          |
|  |  | <input type="checkbox"/> Other:                          |

I hereby certify that I have the authority to make the foregoing application, that the application is correct and accurate and that the construction will comply with plans reviewed and approved by all necessary agencies and hereby acknowledge and accept this to be a condition for the issuance of this permit.

Signature of owner or authorized agent

Date

**HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFYING**  
[Owner, Owner's Agent, Adjacent and Confronting Property Owners]

**Owner's mailing address**  
Eric Maier & Krisztina Petz  
7314 Maple Avenue  
Takoma Park, MD 20912

**Owner's Agent's mailing address**  
Eric Hurtt  
Hill & Hurtt Architects  
3335 Connecticut Avenue NW  
Suite 101  
Washington, DC 20008

**Adjacent and confronting Property Owners mailing addresses**

Thomas Herman & Angela Ellis  
7312 Maple Avenue  
Takoma Park, MD 20912

David Rogers & Rebekah Zanditon  
7316 Maple Avenue  
Takoma Park, MD 20912

Samer Sadek & Maria Said  
7315 Maple Avenue  
Takoma Park, MD 20912

John La Rue & Rachel Ort  
7315 Cedar Avenue  
Takoma Park, MD 20912



**Description of Property:** Please describe the building and surrounding environment. Include information on significant structures, landscape features, or other significant features of the property:

Two-story plus basement foursquare home, originally built early 20th century with circa 2015 two-story over crawl space addition at rear of home. First floor exterior 7" exposure Hardie-Plank cement fiber siding, second floor exterior 4" exposure Hardie-Plank cement fiber siding. Hipped, asphalt shingle roof with front and rear dormers and extended eaves. Covered front porch with front facing gable and cement floor. Cobble stone and gravel driveway along NE side of property. Non-original shed on concrete slab behind house. Home is a Category Two contributing resource in the Takoma Park Historic District.

**Description of Work Proposed:** Please give an overview of the work to be undertaken:

Single-story over crawl space addition off of North corner of house to include sunroom plus driveway side entry and mudroom. Addition footprint increases overall footprint of home by 390 square feet, resulting in a total lot coverage of 17% (currently 13%). Proposed addition includes new deck and stair at driveway and new deck and stair to rear yard. Exterior finish materials to include 7" exposure Hardi-Plank cement fiber siding with painted wood corner and trim boards to match the current finishes, with panel detailing below the sunroom windows. 3:12 pitched roof with asphalt shingles and rear facing gable with extended eaves. Ridge height approximately 17' above grade.




Work Item 1: <u>Single-story addition at North corner of home</u>	
Description of Current Condition: North corner of home includes an inset porch over crawl space at the first floor facing the rear yard. West first floor corner consists of a bay of windows facing the rear yard. Although the driveway serving the property is along the northeast side of the home, there is no entry to the house from the drive.	Proposed Work: First floor addition occupies the inset porch area and extends to the Northeast and Northwest. Addition preserves the West first floor windows and all second floor windows. A stair and stoop provide access from the driveway to a small entry and mudroom, the front facing wall of which aligns with the original back corner of the house. The NE wall of the addition is inside of the side yard setback.
Work Item 2: _____	
Description of Current Condition:	Proposed Work:
Work Item 3: _____	
Description of Current Condition:	Proposed Work:

# HISTORIC AREA WORK PERMIT CHECKLIST OF APPLICATION REQUIREMENTS

	Required Attachments						
Proposed Work	1. Written Description	2. Site Plan	3. Plans/Elevations	4. Material Specifications	5. Photographs	6. Tree Survey	7. Property Owner Addresses
New Construction	*	*	*	*	*	*	*
Additions/Alterations	*	*	*	*	*	*	*
Demolition	*	*	*		*		*
Deck/Porch	*	*	*	*	*	*	*
Fence/Wall	*	*	*	*	*	*	*
Driveway/Parking Area	*	*		*	*	*	*
Grading/Excavation/Landscaping	*	*		*	*	*	*
Tree Removal	*	*		*	*	*	*
Siding/ Roof Changes	*	*	*	*	*		*
Window/Door Changes	*	*	*	*	*		*
Masonry Repair/Repoint	*	*	*	*	*		*
Signs	*	*	*	*	*		*

VICINITY MAP



ZONING MAP



ZONING SUMMARY

LEGAL DESCRIPTION:	PLAT BLOCK 5 LOT P17		
LOT AREA:	9,800 SF		
ZONE:	R-60		
ZONING REQUIREMENTS:	ALLOWED/REQUIRED:	EXISTING:	PROPOSED:
LOT OCCUPANCY:	35%	13%	17%
BUILDING HEIGHT:	35' MAX.	27'	NO CHANGE
FRONT YARD SETBACK:	25' MIN.	33.5'	NO CHANGE
SIDE YARD SETBACK:	7' MIN.	13.5'	7.6'
REAR YARD SETBACK:	20' MIN.	119'	102'
SQUARE FOOTAGE:		3302 SF	3692 SF
BASEMENT:		700 SF	NO CHANGE
FIRST FLOOR:		1117 SF	1507 SF
SECOND FLOOR:		975 SF	NO CHANGE
ATTIC:		510 SF	NO CHANGE

KEY TO MATERIALS AND SYMBOLS

	WOOD FRAMING-CONTINUOUS		WOOD FRAMED WALL		CONCRETE MASONRY UNIT		RIGID INSULATION		ELEVATION
	WOOD BLOCKING		METAL		BATT INSULATION		WINDOW TYPE		REVISION NUMBER
	FINISH WOOD		GRAVEL		SPRAY FOAM INSULATION		DOOR TYPE		ENLARGED DETAIL
	BRICK		CONCRETE		STONE		PLUMBING		WALL SECTION
	PLYWOOD		GYPSUM WALL BOARD				INTERIOR FIXTURE TYPE		BUILDING SECTION
							SMOKE DETECTOR		

PROJECT NARATIVE

ADDITION OF EXISTING 2-STORY HOME TO INCLUDE NEW SUNROOM AND MUDROOM AT FIRST FLOOR. NO NEW WORK AT BASEMENT OR SECOND FLOOR.

PROJECT INFORMATION

ADDRESS: 7314 MAPLE AVE  
TAKOMA PARK, MD 20912

OWNERS: ERIC MAIER  
KRISZTINA PETZ

OWNERS' ADDRESS: 7314 MAPLE AVE  
TAKOMA PARK, MD 20912

DESIGN CRITERIA

RESIDENTIAL CONSTRUCTION DESIGN PARAMETERS:


GROUND SNOW LOAD	30 PSF
WIND SPEED	115 MPH
SEISMIC DESIGN CATEGORY	B
SUBJECT TO DAMAGE FROM:	
WEATHERING	SEVERE
TERMITE	MODERATE TO HEAVY
DECAY	SLIGHT TO MODERATE
FROST LINE DEPTH	30"
WINTER DESIGN TEMP.	13 DEGREE F.
ICE SHIELD UNDERLAYMENT	REQUIRED
AIR FREEZING INDEX	300
MEAN ANNUAL TEMP.	55 DEGREE F.

GENERAL NOTES


- The following notes shall apply to all drawings made as part of the Contract for construction for this project, including those drawings listed in the INDEX of this sheet:
- Contractor must not scale drawings for dimensions. Any questions regarding dimensions must be directed to the architect.
  - Contractor must verify all dimensions in the field prior to the start of construction and contact architect with any questions or discrepancies.
  - Dimensions shown are to face of structure (i.e. face of stud, masonry, or existing construction) unless noted otherwise on drawings.
  - The details in the drawings and specifications cover the installation of all materials and work as called for on the drawings and specifications. It is the responsibility of the contractor to check the documents prior to the start of work. Any discrepancies shall be brought to the architect's attention with a notification for clarification. Any work installed in conflict with the architectural drawings and specifications shall be corrected by the contractor at their own expense. Items to be furnished by owner are noted and agreed to in the contract between owner and contractor.
  - Questions due to any apparent conflicts within the documents should be brought to the architect's attention in time to be clarified by addendum. If the contractor's responsibility for the work that is in question cannot be clarified by reference to the contract, then a mutually agreeable good faith option shall be adopted.
  - All construction resulting from execution of this work shall conform to the International Residential Code (IRC) and International Energy Conservation Code (IECC), 2021 edition, as amended by Montgomery County Executive Regulation no. 13-24.
  - Throughout the plans there are abbreviations which are in common use. The list of abbreviations is not intended to be complete, and any questions about abbreviations should be addressed with the architect.
  - The residence will be occupied for the duration of the project. Care should be taken to keep the premises clean and safe for the occupants at the close of each day's work. Interruptions in the utility services shall be kept at a minimum. All utilities shall be operable for the Owner's continued use during the times of continued residence. Coordinate with Owner any breaks in service well in advance of anticipated break.
  - The construction work described in these drawings is applicable only to the this project. The Architect accepts no liability whatsoever for any construction work performed on the basis of these drawings if such work is not executed under a general Contract.
  - Contractor shall comply with current requirements for random mitigation.

LIST OF ABBREVIATIONS

Abbreviation	Item		
@	At	JST.	Joist
A.F.F.	Above Finish Floor	JT.	Joint
ABV.	Above	M., MAS.	Masonry
A.H.U.	Air Handling Unit	MDO	Medium Density Overlay
APPROX.	Approximate	MDF	Medium Density Fiberboard
BD.	Board	MEM.	Membrane
Bldg.	Building	M.O.	Masonry Opening
BLKG.	Blocking	MECH.	Mechanical
C.	Concrete	Mil.	1/1000 inch
CL	Center Line	MIN.	Minimum
CLG.	Ceiling	O.C.	On Center
C.J.	Ceiling Joist	O.W.T.	Open Web Truss
CMU	Concrete Masonry Unit	PLY., PLYWD	Plywood
COL.	Column	P.T.	Pressure Treated
CONC.	Concrete	P.T.D.	Painted
CONT.	Continuous	R.	Riser(s)
CPR.	Copper	R.O.	Rough Opening
DWG.	Drawing	REINF.	Reinforcing
EQ.	Equal	SHTG.	Sheathing
EX.	Existing	SIM.	Similar
EXT.	Exterior	STD.	Standard
F.D.	Floor Drain	STL.	Steel
FIN.	Finish	ST. STL.	Stainless Steel
FLASH'G	Flashing	STOR.	Storage
FLR.	Floor	STRUC.	Structure
F.O.	Face of	SW.	Switch
F.O.S.	Face of Stud	T	Tread(s)
F.O.M.	Face of Masonry	T&G	Tongue and Groove
FRMG.	Framing	TJI	Truss Joists
FT.	Foot	T.O.	Top of
FTG.	Footing	T.O. ARCH	Top of Arch
GALV.	Galvanized	T.O.W.	Top of Wall
GWB.	Gypsum Wall Board	U.N.O.	Unless Noted Otherwise
HB	Hose Bib	W/	With
HT.	Height/Heat	WD.	Wood
H.W.	Hot Water	WIN., WDW.	Window
IN.	Inch	WPFG	Waterproofing



"Professional Certification. I certify that these documents were prepared or approved by me, and that I am a duly licensed architect under the laws of the State of Maryland  
License Number: 0018022  
Expiration Date: 3.30.2027"



HILL & HURTT ARCHITECTS  
3335 CONNECTICUT AVE NW  
SUITE 101  
WASHINGTON, DC 20008  
202.204.0424

ADDITION AND RENOVATION OF THE  
MAIER-PETZ RESIDENCE  
7314 MAPLE AVE  
TAKOMA PARK, MD 20912

HISTORIC REVIEW  
SET  
13 August 2025

COVER SHEET



G001



DOOR SCHEDULE						
STORY	MARK	LOCATION	SIZE	STYLE	HARDWARE SET	NOTES
First Floor						
	101A	FAMILY ROOM	3'-6"x6'-8"	CASED OPENING	NONE	
	101B	MUDROOM	2'-6"x6'-8"	PANEL DOOR	PASSAGE	
	102A	FAMILY ROOM	9'-0"x7'-10"	CASED OPENING	NONE	
	EXT 1	SUNROOM	3'-0"x6'-8"	FRENCH DOOR	ENTRY	TRANSOM (MARVIN UIDTR 3016)
	EXT 2	MUDROOM	3'-0"x6'-8"	FRENCH DOOR	ENTRY	SIDELITE (OX L)

1

A101

DOOR SCHEDULE

WINDOW SCHEDULE					
MARK	MODEL	TYPE	FRAME SIZE	LITE PATTERN	NOTES
W-01	MARVIN ULTIMATE WOOD DOUBLE HUNG UWDH2426	DOUBLE HUNG	2'-5 1/2"x5'-1"	3x2 / SOLID	MATCH EX. WINDOW @ FAMILY ROOM
W-02	MARVIN ULTIMATE CASEMENT UCA3292	CASEMENT	2'-9"x7'-7"	3x5	TEMPERED

2

A101

WINDOW SCHEDULE

ADDITIONAL NOTES:  
Contractor to field verify all dimensions.  
All sizing and designations based on manufacturer sizing.  
Insulated Glass LoE-272 glazing with Argon, typical to all units. Max U-value .35 Max SHGC .40  
DOUBLE HUNG: U-VALUE= 0.29 SHGC= 0.29  
CASEMENT: U-VALUE= 0.29 SHGC= 0.24  
FRENCH DOORS: U-VALUE= 0.30 SHGC= 0.24  
Provide tempered glass per code.  
All units have clad aluminum exterior, color to be selected from manufacturer's standard and optional colors, interior to be primed wood.  
Window hardware color as selected by owner; door hardware color to be owner selected, use adjustable hinges.  
7/8" Putty Glaze SDL with space bar.  
Operable windows to have full screen with aluminum surround; charcoal fiberglass screen mesh.

DEMOLITION NOTES	
SYMBOL	NOTE
1	REMOVE EXTERIOR WALLS AS REQ. TO ACCOMMODATE NEW WORK. PROVIDE BRACING/SHORING AS REQ.
2	REMOVE INTERIOR WALLS AS REQ. TO ACCOMMODATE NEW WORK. PROVIDE BRACING/SHORING AS REQ.
3	REMOVE DOOR, JAMB, CASING, & ACCESSORIES. SAVE & PROTECT FOR POSSIBLE RE-USE AND/OR DONATION
4	REMOVE WINDOW, CASING, & ACCESSORIES
5	REMOVE DECKING, STAIR & RAIL

NOTES:  
1. DASHED LINES INDICATE ITEMS TO BE REMOVED OR NEW WORK, TYPICAL. GC TO COORDINATE AND VERIFY PRECISE DIMENSIONS OF WORK TO BE REMOVED WITH PROPOSED PLANS.  
2. CONSULT WITH OWNER/ARCHITECT TO VERIFY ITEMS TO BE SALVAGED AND/OR FOR RE-USE.  
3. COORDINATE DEMOLITION PLAN WITH ALL PROPOSED DRAWINGS TO VERIFY WORK TO BE REMOVED.  
4. PROTECT ALL ADJACENT SURFACES, LANDSCAPE ELEMENTS, AND ITEMS TO REMAIN DURING CONSTRUCTION.  
5. ALL MEP WORK EXPOSED IN DEMOLITION SHALL BE TEMPORARILY SECURED AND CAPPED AS REQ'D. EXISTING MEP WORK THAT DOES NOT COMPLY WITH THE NEW WORK SHALL BE REMOVED.  
6. GC SHALL REMOVE DEBRIS FROM SITE ON A REGULAR BASIS AND SHALL NOT STOCKPILE DEBRIS IN THE STRUCTURE.

	EXISTING TO REMAIN
	TO BE REMOVED
	AREA OF NO WORK

3

A101

DEMOLITION NOTES

## WOOD DOUBLE HUNG

GLASS DESCRIPTION	DIVIDER	U FACTOR	SHGC	VT	CR	ENERGY STAR	CANADA ENERGY STAR
11/16" IG Low E2 Arg		0.29	0.29	0.51	57	NC	
	SDL S < 1"	0.29	0.26	0.45	57	NC	
	SDL N < 1"	0.29	0.26	0.45	57	NC	

## WOOD CASEMENT PUSH OUT

GLASS DESCRIPTION	DIVIDER	U FACTOR	SHGC	VT	CR	ENERGY STAR	CANADA ENERGY STAR
3/4" IG Low E2 Arg		0.29	0.28	0.48	60	NC	
	SDL S < 1"	0.29	0.26	0.43	60	NC	
	SDL N < 1"	0.29	0.26	0.43	60	NC	

## INSWING FRENCH DOOR

GLASS DESCRIPTION	DIVIDER	U FACTOR	SHGC	VT	CR	ENERGY STAR	CANADA ENERGY STAR
3/4" IG Low E2 Arg		0.30	0.24	0.40	61	N, NC, SC, S	
	SDL S < 1"	0.30	0.21	0.34	61	N, NC, SC, S	
	SDL N < 1"	0.30	0.21	0.34	61	N, NC, SC, S	

## INSWING FRENCH DOOR TRANSOM



GLASS DESCRIPTION	DIVIDER	U FACTOR	SHGC	VT	CR	ENERGY STAR	CANADA ENERGY STAR
3/4" IG Low E2 Arg		0.30	0.27	0.46	61	NC	
	SDL S < 1"	0.30	0.24	0.41	61	NC, SC, S	
	SDL N < 1"	0.30	0.24	0.41	61	NC, SC, S	

4

A101

FIRST FLOOR DEMOLITION PLAN

SCALE: 1/4" = 1'-0"





5

A101

FIRST FLOOR PLAN - PROPOSED

SCALE: 1/4" = 1'-0"



"Professional Certification. I certify that these documents were prepared or approved by me, and that I am a duly licensed architect under the laws of the State of Maryland  
License Number: 0018022  
Expiration Date: 3.30.2027."



HILL & HURTT ARCHITECTS  
3335 CONNECTICUT AVE NW  
SUITE 101  
WASHINGTON, DC 20008  
202.204.0424

ADDITION AND RENOVATION OF THE  
MAIER-PETZ RESIDENCE  
7314 MAPLE AVE  
TAKOMA PARK, MD 20912


HISTORIC REVIEW  
SET  
13 August 2025

PROPOSED FLOOR PLANS



A101

"Professional Certification. I certify that these documents were prepared or approved by me, and that I am a duly licensed architect under the laws of the State of Maryland  
License Number: 0018022  
Expiration Date: 3.30.2027."



HILL & HURTT ARCHITECTS  
3335 CONNECTICUT AVE NW  
SUITE 101  
WASHINGTON, DC 20008  
202.204.0424


ADDITION AND RENOVATION OF THE  
MAIER-PETZ RESIDENCE  
7314 MAPLE AVE  
TAKOMA PARK, MD 20912

HISTORIC REVIEW  
SET  
13 August 2025



EXTERIOR ELEVATIONS




A201



1  
A201  
PROPOSED REAR ELEVATION  
SCALE: 1/4" = 1'-0"





2  
A201  
PROPOSED NORTH ELEVATION  
SCALE: 1/4" = 1'-0"





MAIER-PETZ RESIDENCE  
7314 MAPLE AVE  
TAKOMA PARK, MD 20912

## EXTERIOR ELEVATIONS







1  
A301 EX. FRONT FACADE



2  
A301 EX. NORTHEAST FACADE



3  
A301 VIEW OF EX. N-NE CORNER & DRIVEWAY



4  
A301 EX. REAR FACADE



5  
A301 EX. WEST CORNER

TREE REMOVED UNDER REMOVAL  
PERMIT W012765-032425

"Professional Certification. I certify that  
these documents were prepared or  
approved by me, and that I am a duly  
licensed architect under the laws of the  
State of Maryland  
License Number: 0018022  
Expiration Date: 3.30.2027"



HILL & HURTT ARCHITECTS  
3335 CONNECTICUT AVE NW  
SUITE 101  
WASHINGTON, DC 20008  
202.204.0424

ADDITION AND RENOVATION OF THE  
MAIER-PETZ RESIDENCE  
7314 MAPLE AVE  
TAKOMA PARK, MD 20912

HISTORIC REVIEW  
SET  
13 August 2025

EXISTING CONDITIONS



A301







1  
A302  
EX. SOUTHWEST FACADE



3  
A302  
VIEW FROM MAPLE AVE



2  
A302  
FIRST FLOOR SIDING EXPOSURE  
NOT TO SCALE



4  
A302  
VIEW OF BACKYARD FROM EXISTING REAR DECK

"Professional Certification. I certify that these documents were prepared or approved by me, and that I am a duly licensed architect under the laws of the State of Maryland  
License Number: 0018022  
Expiration Date: 3.30.2027"



HILL & HURTT ARCHITECTS  
3335 CONNECTICUT AVE NW  
SUITE 101  
WASHINGTON, DC 20008  
202.204.0424

ADDITION AND RENOVATION OF THE  
MAIER-PETZ RESIDENCE  
7314 MAPLE AVE  
TAKOMA PARK, MD 20912

HISTORIC REVIEW  
SET  
13 August 2025

EXISTING CONDITIONS



A302



# Hardie® Plank Lap Siding

## Submittal Form

**01**
**Submitted to:** .....

**Project Name:** .....

**Submitted by:** .....

**Date:** .....

☐ **HZ5® Product Zone**    ☐ **HZ10® Product Zone**
**Product Width:**    ☐ 5-1/4in    ☐ 6-1/4in    ☒ 7-1/4in    ☐ 8in    ☐ 8-1/4in    ☐ 9-1/4in    ☐ 12in

**Product Finish:**    ☒ **Primed**    ☐ **ColorPlus® Technology**
**Product Texture:**    ☒ **Smooth**    ☐ **Select Cedarmill®**    ☐ **Colonial Roughsawn®**  
☐ **Colonial Smooth®**    ☐ **Rustic Cedar**

# Hardie® Plank Lap Siding

## Specification Sheet

**01**
**DIVISION: 07 00 00 THERMAL AND MOISTURE PROTECTION**
**SECTION: 07 46 46 FIBER CEMENT SIDING**

### HARDIE® PLANK LAP SIDING

#### Manufacturer

*James Hardie Building Products, Inc.*

The products are manufactured at the following locations, with quality control inspections by ICC-ES:

- Cleburne, Texas
- Plant City, Florida
- Reno, Nevada
- Waxahachie, Texas
- Prattville, Alabama
- Peru, Illinois
- Pulaski, Virginia
- Tacoma, Washington
- Fontana, California
- Summerville, South Carolina

#### Compliance with the following codes

- 2006 thru 2021 International Building Code (IBC)
- 2006 thru 2021 International Residential Code (IRC)

For more information about other compliances and applicable uses, refer to ICC-ES ESR-2290

#### Features

- Noncombustible
- Dimensionally Stable
- Resists damage from pests
- Weather Resistant-Engineered for Climate®
- Impact resistant
- Sustainable

#### Use

Hardie® fiber-cement lap siding is used as exterior wall covering. The product complies with IBC Section 1403.9 and IRC Section R703.10. The product may be used on exterior walls of buildings of Type I, II, III and IV construction (IBC)

#### Description

Hardie® Plank lap siding is a single-faced, cellulose fiber-reinforced cement (fiber-cement) product. Hardie® Plank lap siding complies with ASTM C1186, as Grade II, Type A; has a flame-spread index of 0 and a smoke-developed index of 5 when tested in accordance with ASTM E84; and is classified as noncombustible when tested in accordance with ASTM E136.

#### Available Sizes

Product	Width (in)	Length	Thickness (in)
Hardie® Plank lap siding*	5-1/4, 6-1/4, 7-1/4, 8, 8-1/4, 9-1/4, 12	12 feet	5/16

\* HZ5: 9-1/4, 12 only available primed    HZ10: 5-1/4, 9-1/4, 12 only available primed.

Weight 2.31 lbs. per square foot

#### Texture & Finish

Hardie® Plank lap siding comes in a variety of textures and finishes. The product is available in smooth or wood grain texture. Additional textures are available on a regional basis. Finish options are primed for field paint, or factory finished with ColorPlus® Technology. Color availability varies by region.

#### Engineered for Climate®

Hardie® Plank lap siding is engineered for performance to specific weather conditions by climate zones as identified by the following map.



Performance Properties

	General Property	Test Method	Unit or Characteristic	Requirement	Result
PHYSICAL ATTRIBUTES	Dimensional Tolerances	ASTM C1185	Length	± 0.5% or ± 1/4 in	Pass
			Width	± 0.5% or ± 1/4 in	
			Thickness	± 0.04 in	
			Squareness	Δ in diagonals ≤ 1/32 in/ft of sheet length. Opposite sheet sides shall not vary in length by more than 1/32 in/ft	
			Edge Straightness	≤ 1/32 in/ft of length	
	Density, lb/ft³	ASTM C1185		As reported	83
	Water Absorption, % by mass	ASTM C1185		As reported	36
THERMAL	Water Tightness	ASTM C1185	Physical Observations	No drop formation	Pass
	Flexural Strength	ASTM C1185	Wet conditioned, psi	>1015 psi	Pass
			Equilibrium conditioned, psi	>1450 psi	
THERMAL	Thermal Conductivity	ASTM C177	(BTU/(hr·ft²·F))/inch	As reported	2.07
	Actual Thermal Conductivity		(K <sub>eff</sub> )		6.62
	Thermal Resistance		R=1/ K <sub>eff</sub>		0.48
	Actual Thermal Resistance		(R)		0.15
DURABILITY	Warm Water Resistance	ASTM C1185	Physical Observations	No visible cracks or structural alteration	Pass
	Heat/Rain Resistance	ASTM C1185	Physical Observations	No visible cracks or structural alteration	Pass
	Freeze/Thaw Resistance	ASTM C1185	Physical Observations	No visible cracks or structural alteration	Pass
			Mass Loss, %	≤ 3.0%	
FIRE CHARACTERISTICS			Freeze/Thaw, % strength retention	≥ 80%	
	UV Accelerated Weathering Test	ASTM G23	Physical Observations	No cracking, checking, or crazing	Pass
	Surface Burning Characteristics	ASTM E84	Flame Spread Index (FSI)		0
			Smoke Developed Index (SDI)		≤ 5
			Fuel Contributed		0
			NFPA Class		A
			Uniform Building Code Class	As reported	1
	Noncombustibility	ASTM E136	Noncombustible	Pass/fail	Pass
	Fire Resistance Rated Construction	ASTM E119	Fire Resistance Rating	1-hour	Note 1

Note 1: listed on Warnock Hersey and ESR 2290

Installation

Install Hardie® Plank lap siding in accordance with:

- Hardie® Plank lap siding installation instructions
- ICC-ES ESR 2290
- Requirements of authorities having jurisdiction

Warranty

Hardie® Plank lap siding: 30-year, Non-Prorated, Limited Warranty  
ColorPlus® Technology: 15-year Limited Finish Warranty

Sustainable Design Contribution

- Regionally sourced content- varies by project location
- Avoidance of certain chemicals or Red List Compliance

Detailed product information for LEED projects, or other state or regional sustainability programs is available through James Hardie Technical Services.

Storage and Handling

Store flat and keep dry and covered prior to installation.

Technical Services

Contact James Hardie Technical Services online at JamesHardie.com, or by phone at (800)426-4051


**IMPORTANT:** Failure to install and finish this product in accordance with applicable building codes and James Hardie written application instructions may affect system performance, violate local building codes, void the product-only warranty and lead to personal injury. **DESIGN ADVICE:** Any information or assistance provided by James Hardie in relation to specific projects must be approved by the relevant specialists engaged for the project eg. builder, architect or engineer. James Hardie will not be responsible in connection with any such information or assistance.




**Section Details: Operating/Stationary/Picture - 3/4" (19) IG**

Scale: 3" = 1' 0"

**Operating**




**Head Jamb and Sill**




**Jambs**









































**Stationary/Picture**



**Head Jamb and Sill**




**Jambs**

MO (mm)	1 - 4 1/2 (419)	1 - 6 1/2 (469)	1 - 8 1/2 (520)	2 - 1/2 (622)	2 - 2 1/2 (673)	2 - 4 1/2 (723)	2 - 6 1/2 (774)	2 - 8 1/2 (825)	3 - 1/2 (927)	3 - 4 1/2 (1028)
RO (mm)	1 - 5 (431)	1 - 7 (482)	1 - 9 (533)	2 - 1 (635)	2 - 3 (685)	2 - 5 (736)	2 - 7 (787)	2 - 9 (838)	3 - 1 (939)	3 - 5 (1041)
FS (mm)	1 - 4 (406)	1 - 6 (457)	1 - 8 (508)	2 - 0 (609)	2 - 2 (660)	2 - 4 (711)	2 - 6 (762)	2 - 8 (812)	3 - 0 (914)	3 - 4 (1016)
DLO (mm)	0 - 10 13/64 (259)	1 - 0 13/64 (310)	1 - 2 13/64 (361)	1 - 6 13/64 (462)	1 - 8 13/64 (513)	1 - 10 13/64 (564)	2 - 0 13/64 (615)	2 - 2 13/64 (666)	2 - 6 13/64 (767)	2 - 10 13/64 (869)
6 - 5 3/8 (1965) 6 - 5 5/8 (1971) 6 - 5 1/8 (1958) 5 - 11 21/64 (1812)										
	UCA1678 T UCAPO1678 T	UCA1878 T UCAPO1878 T	UCA2078 T UCAPO2078 T	UCA2478 T UCAPO2478 T	UCA2678 T UCAPO2678 T	UCA2878 ET UCAPO2878 ET	UCA3078 ET UCAPO3078 ET	UCA3278 ET UCAPO3278 ET	UCA3678 ET UCAPO3678 ET	UCA4078 ET UCAPO4078 ET
6 - 11 3/8 (2117) 6 - 11 5/8 (2124) 6 - 11 1/8 (2111) 6 - 5 21/64 (1964)										
	UCA1684 T UCAPO1684 T	UCA1884 T UCAPO1884 T	UCA2084 T UCAPO2084 T	UCA2484 UCAPO2484	UCA2684 T UCAPO2684 T	UCA2884 ET UCAPO2884 ET	UCA3084 ET UCAPO3084 ET	UCA3284 ET UCAPO3284 ET	UCA3684 ET UCAPO3684 ET	UCA4084 ET UCAPO4084 ET
7 - 7 3/8 (2320) 7 - 7 5/8 (2327) 7 - 7 1/8 (2314) 7 - 1 21/64 (2167)										
	UCA1692 T UCAPO1692 T	UCA1892 T UCAPO1892 T	UCA2092 T UCAPO2092 T	UCA2492 T UCAPO2492 T	UCA2692 T UCAPO2692 T	UCA2892 ET UCAPO2892 ET	UCA3092 ET UCAPO3092 ET	UCA3292 ET UCAPO3292 ET	UCA3692 ET UCAPO3692 ET	UCA4092 ET UCAPO4092 ET
7 - 11 3/8 (2422) 7 - 11 5/8 (2428) 7 - 11 1/8 (2416) 7 - 5 21/64 (2269)										
	UCA1696 T UCAPO1696 T	UCA1896 T UCAPO1896 T	UCA2096 T UCAPO2096 T	UCA2496 T UCAPO2496 T	UCA2696 T UCAPO2696 T	UCA2896 ET UCAPO2896 ET	UCA3096 ET UCAPO3096 ET	UCA3296 ET UCAPO3296 ET	UCA3696 ET UCAPO3696 ET	

Construction Details

Casements available as an operator or stationary.

L or R handing determined from exterior.




CASEMENT STANDARD OPERATION AS VIEWED FROM THE OUTSIDE



**Section Details: Operating**


Scale: 3" = 1' 0"

**Double Hung**





**Lower Sash**

**Upper Sash**

























**Single Hung**





WOOD DOUBLE HUNG

MO (mm)	2-0 1/2 (622)	2-4 1/2 (724)	2-8 1/2 (826)	2-10 1/2 (876)	3-0 1/2 (927)	3-2 1/2 (978)	3-4 1/2 (1029)	3-8 1/2 (1130)	4-0 1/2 (1232)
RO (mm)	1-10 3/8 (568)	2-2 3/8 (670)	2-6 3/8 (772)	2-8 3/8 (822)	2-10 3/8 (873)	3-0 3/8 (924)	3-2 3/8 (975)	3-6 3/8 (1076)	3-10 3/8 (1178)
FS (mm)	1-9 3/8 (543)	2-1 3/8 (645)	2-5 3/8 (746)	2-7 3/8 (797)	2-9 3/8 (848)	2-11 3/8 (899)	3-1 3/8 (949)	3-5 3/8 (1051)	3-9 3/8 (1153)
DLO (mm)	1-2 15/16 (379)	1-6 15/16 (481)	1-10 15/16 (583)	2-0 15/16 (633)	2-2 15/16 (684)	2-4 15/16 (735)	2-6 15/16 (786)	2-10 15/16 (887)	3-2 15/16 (989)
2-10 9/16 (878) 2-9 1/2 (851) 2-9 1/2 (953)w 3-1 (840) 3-1 (838) 1-0 15/16 (329)	 UWDH1612	 UWDH2012	 UWDH2412	 UWDH2612	 UWDH2812	 UWDH3012	 UWDH3212	 UWDH3612	 UWDH4012
3-2 9/16 (980) 3-1 1/2 (953)w 3-1 (840) 1-0 15/16 (329)	 UWDH1614	 UWDH2014	 UWDH2414	 UWDH2614	 UWDH2814	 UWDH3014	 UWDH3214	 UWDH3614	 UWDH4014
3-6 9/16 (1081) 3-5 1/2 (1054) 3-5 (1041) 1-2 15/16 (379)	 UWDH1616	 UWDH2016	 UWDH2416	 UWDH2616	 UWDH2816	 UWDH3016	 UWDH3216	 UWDH3616	 UWDH4016
3-10 9/16 (1183) 3-9 1/2 (1156) 3-9 (1143) 1-4 15/16 (430)	 UWDH1618	 UWDH2018	 UWDH2418	 UWDH2618	 UWDH2818	 UWDH3018	 UWDH3218	 UWDH3618	 UWDH4018
4-2 9/16 (1284) 4-1 1/2 (1257) 4-1 (1245) 1-6 15/16 (481)	 UWDH1620	 UWDH2020	 UWDH2420	 UWDH2620	 UWDH2820	 UWDH3020	 UWDH3220	 UWDH3620	 UWDH4020
4-6 9/16 (1386) 4-5 1/2 (1359) 4-5 (1346) 1-8 15/16 (632)	 UWDH1622	 UWDH2022	 UWDH2422	 UWDH2622	 UWDH2822	 UWDH3022	 UWDH3222	 UWDH3622	 UWDH4022
4-10 9/16 (1488) 4-9 1/2 (1461) 4-9 (1448) 1-10 15/16 (583)	 UWDH1624	 UWDH2024	 UWDH2424	 UWDH2624	 UWDH2824	 UWDH3024	 UWDH3224	 UWDH3624	 UWDH4024
5-6 9/16 (1589) 5-1 1/2 (1562) 5-1 (1549) 2-0 15/16 (633)	 UWDH1626	 UWDH2026	 UWDH2426	 UWDH2626	 UWDH2826	 UWDH3026	 UWDH3226	 UWDH3626 E	 UWDH4026 E
5-6 9/16 (1691) 5-5 1/2 (1664) 5-5 (1651) 2-2 15/16 (684)	 UWDH1628	 UWDH2028	 UWDH2428	 UWDH2628	 UWDH2828	 UWDH3028 E	 UWDH3228 E	 UWDH3628 E	 UWDH4028 E




MULTIPLE ASSEMBLY CONVERSIONS

ROUGH OPENING		MASONRY OPENING WITH BMC	
Width	Height	Width	Height
Add all frame sizes plus 1" (25)	Add frame sizes plus 1/2" (13)	Add all frame sizes plus 3 1/8" (79)	Add frame sizes plus 1 9/16" (39)

Ultimate Wood Double Hung: UWDH


Details and Elevations not to scale.  
E These windows meet national Egress codes for fire evacuation. Local codes may differ.  
\* For more Cottage Style sizes than the sample shown, please contact your Marvin representative. Ultimate Double Hung cottage call number formula is figured in fifths. Top sash is 2/5 and bottom is 3/5.  
1. Standard call number; 2024  
2. Add the two glass heights; 24" + 24" = 48"  
3. Divide 48" by 2/5; 19-13/64"  
4. Round to the nearest standard glass height; 20"  
5. Subtract from total glass height; 48" - 20" = 28" The call number for the above example is: 2020/28. The top sash will be a 2020 and the bottom sash will be a 2028

**Inswing Section Details: Standard Sliding and Standard Swinging Screens**




## Inswing Section Details: Operating


Scale: 3" = 1' 0"




6 9/16" Head Jamb and Sill



XX R - Meeting Stiles



6 9/16" Sill with Sill Cover




6 9/16" X R Jamb




**Inswing/Outswing Section Details: Direct Glaze Transom**


Scale: 3" = 1' 0"




Head Jamb and Sill




4 9/16" Head Jamb



Rectangular Ultimate Direct Glaze Transom  
over Ultimate Inswing French Door  
w/ 6 9/16" Jamb




4 9/16" Side Jamb




Ultimate Direct Glaze Transom Jamb


**Standard Insulating Glass Divided Lite Options**




Insulating Glass




Aluminum 23/32"  
Contour GBG




5/8" SDL




5/8" SDL  
W/Spacer




5/8" Putty  
SDL




5/8" Putty SDL  
W/Spacer




7/8" SDL




7/8" SDL  
W/Spacer Bar




7/8" Putty SDL




7/8" Putty SDL  
W/Spacer Bar




1 1/8" SDL




1 1/8" SDL  
W/Spacer Bar



1 1/8" Putty SDL



1 1/8" Putty SDL  
W/Spacer Bar



1 11/16" IG ADL

**NOTE:** Due to the inherent qualities of tempered glass, daylight gaps may be seen when using simulated divided lite bars. Daylight gaps could be visible between the internal spacer bar and surface applied bars when viewing from an acute angle to the glass on the following applications:

- Tempered glass over 72" high while using 5/8" SDL bars
- Tempered glass over 91" high while using 7/8" SDL bars.

# W012765-032425 - Tree Removal Request

## Message History (6)

 On 5/13/2025 at 2:02 AM, "Dorinda D. Jones" <dorinda.jones@cityoftakoma.org> wrote:

**Subject:** Tree Removal Request :: W012765-032425

**Body:**

05/13/2025

APPLICATION NUMBER

Eric Maier  
7314 Maple Ave.  
Takoma Park, MD 20912

Re: Tree Removal Application at:  
7314 Maple Ave  
Takoma Park MD 20912

Dear Eric Maier:

Permit Number: W012765-032425

This is your permit to remove the following tree from your property.

Tree Type: **SOUTHERN RED OAK**

Trunk Diameter: **47.8 inches**

Tree Location Relative to House: **BACK RIGHT**

### Replacement Planting Requirement

You have opted to pay the fee-in-lieu to satisfy the entirety of your replacement planting requirement and your obligation has been fulfilled. No further action is required.

TREE WORK DONE FOR HIRE IN THE CITY OF TAKOMA PARK MUST BE CARRIED OUT BY A MARYLAND STATE LICENSED TREE EXPERT (LTE). HIRING SOMEONE WHO IS NOT LICENSED IS A VIOLATION OF CITY AND STATE LAW. MAKE SURE YOUR CONTRACTOR HAS AN LTE NUMBER BEFORE YOU HIRE THEM.

If you have any questions, please contact the Urban Forest Manager by replying to this email.