

MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION
STAFF REPORT

Address:	12 Hesketh St., Chevy Chase	Meeting Date:	1/11/2017
Resource:	Contributing Resource Chevy Chase Village Historic District	Report Date:	1/4/2017
Applicant:	Neil Cullen (Jason Gagen, Architect)	Public Notice:	12/28/2016
Review:	HAWP	Tax Credit:	N/A
Case Number:	35/13-17A	Staff:	Michael Kyne
PROPOSAL:	Rear addition and window replacement		

STAFF RECOMMENDATION:

Staff recommends that HPC **approve with conditions** the HAWP application.

1. **The proposed replacement roofing materials will be architectural asphalt shingles, with final review and approval delegated to staff**
2. **The proposed front door replacement is not approved.**
3. **Window and door details will be submitted, with final review and approval delegated to staff.**

ARCHITECTURAL DESCRIPTION

SIGNIFICANCE: Contributing Resource within the Chevy Chase Village Historic District
STYLE: Dutch Colonial
DATE: c. 1916-1927

BACKGROUND

The applicant previously appeared before the Commission at the December 7, 2016 HPC meeting for a preliminary consultation. At that time, the Commission expressed the following concerns regarding the applicant's proposal:

- The proposed stone chimney was incompatible with the historic house, and a brick chimney would be more appropriate.
- Replacing the original windows on the front elevation has the potential to detract from the streetscape of the historic district. The Commission was less concerned about replacing the original windows on the side elevations.
- A spread mull is needed at all proposed paired and ganged windows.
- The ridgeline of the proposed rear addition was too high.

There was also some concern about the general incompatibility of the proposed rear addition with the

historic house, and the Commission encouraged the applicant to explore alternatives that may be more compatible; however, the Commission did indicate that, due to a lack of visibility, the proposed rear addition would be reluctantly approved.

The Commission also encouraged the applicant to create a tree protection plan to ensure that two elm trees (one at 10 Hesketh Street and one on the property line between 10 Hesketh Street and the subject property) would not be impacted by the proposal.

The applicant has revised their proposal consistent with the Commission's comments and returned with a HAWP application.

PROPOSAL:

- Remove an existing two-story rear addition
- Construct a new two-story rear addition
- Replace the historic windows with new windows
- Restore/extend the existing driveway to the existing rear garage
- Remove one 7" dbh sycamore tree
- Replace the existing asphalt shingle roofing on the historic house with synthetic slate roofing
- Replace the existing front door within the existing opening

APPLICABLE GUIDELINES:

In accordance with section 1.5 of the Historic Preservation Commission Rules, Guidelines, and Procedures (Regulation No. 27-97) ("Regulations"), in developing its decision when reviewing a Historic Area Work Permit application for an undertaking at a Master Plan site the Commission uses section 24A-8 of the Montgomery County Code ("Chapter 24A"), the *Secretary of the Interior's Standards and Guidelines for Rehabilitation* ("Standards"), and pertinent guidance in applicable master plans. [Note: where guidance in an applicable master plan is inconsistent with the Standards, the master plan guidance shall take precedence (section 1.5(b) of the Regulations).] The pertinent information in these documents, incorporated in their entirety by reference herein, is outlined below.

Sec. 24A-8. Same-Criteria for issuance.

(a) The commission shall instruct the director to deny a permit if it finds, based on the evidence and information presented to or before the commission that the alteration for which the permit is sought would be inappropriate, inconsistent with or detrimental to the preservation, enhancement or ultimate protection of the historic site or historic resource within an historic district, and to the purposes of this chapter.

(b) The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to insure conformity with the purposes and requirements of this chapter, if it finds that:

(1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or

(2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter; or

(3) The proposal would enhance or aid in the protection, preservation and public or private utilization of the historic site or historic resource located within an historic district in a manner

compatible with the historical, archeological, architectural or cultural value of the historic site or historic district in which an historic resource is located; or

(4) The proposal is necessary in order that unsafe conditions or health hazards be remedied; or

(5) The proposal is necessary in order that the owner of the subject property not be deprived of reasonable use of the property or suffer undue hardship; [emphasis added] or

(6) In balancing the interests of the public in preserving the historic site or historic resource located within an historic district, with the interests of the public from the use and benefit of the alternative proposal, the general public welfare is better served by granting the permit.

(c) It is not the intent of this chapter to limit new construction, alteration or repairs to any 1 period or architectural style.

(d) In the case of an application for work on an historic resource located within an historic district, the commission shall be lenient in its judgment of plans for structures of little historical or design significance or for plans involving new construction, unless such plans would seriously impair the historic or architectural value of surrounding historic resources or would impair the character of the historic district. (*Ord. No. 9-4, § 1; Ord. No. 11-59*)

Chevy Chase Historic District Guidelines

The guidelines break down specific projects into three levels of review – Lenient, Moderate and Strict Scrutiny.

“Lenient Scrutiny” means that the emphasis of the review should be on issues of general massing and scale, and compatibility with the surrounding streetscape, and should allow for a very liberal interpretation of preservation rules. Most changes should be permitted unless there are major problems with massing, scale and compatibility.

“Moderate Scrutiny” involves a higher standard of review than “lenient scrutiny.” Besides issues of massing, scale and compatibility, preserving the integrity of the resource is taken into account. Alterations should be designed so that the altered structure still contributes to the district. Use of compatible new materials, rather than the original building materials, should be permitted. Planned changes should be compatible with the structure’s existing design, but should not be required to replicate its architectural style.

“Strict Scrutiny” means that the planned changes should be reviewed to insure that the integrity of the significant exterior architectural or landscaping features and details is not compromised. However, strict scrutiny should not be “strict in theory but fatal in fact” i.e. it does not mean that there can be no changes but simply that the proposed changes should be reviewed with extra care.

The Guidelines state three basic policies that should be adhered to, including:

Preserving the integrity of the contributing structures in the district. Alterations to contributing structures should be designed in such a way that the altered structure still contributes to the district.

Design review emphasis should be restricted to changes that will be visible from the front or side public right-of-way, or that would be visible in the absence of vegetation or landscaping.

Alterations to the portion of a property that are not visible from the public right-of-way should be subject to very lenient review. Most changes to rear of the properties should be approved as a matter of course.

The Guidelines that pertain to this project are as follows:

Doors should be subject to moderate scrutiny if they are visible from the public right-of-way, lenient scrutiny if they are not. For outstanding resources, they should be subject to strict scrutiny if they are visible from the public right-of-way. Addition of compatible storm doors should be encouraged.

Driveways should be subject to strict scrutiny only with regard to their impact on landscaping, particularly mature trees. In all other respects, driveways should be subject to lenient scrutiny. Parking pads and other paving in front yards should be discouraged.

Lot coverage should be subject to strict scrutiny in view of the critical importance of preserving the Village's open park-like character.

Major additions should, where feasible, be placed to the rear of the existing structure so that they are less visible from the public right-of-way. Major additions which substantially alter or obscure the front of the structure should be discouraged but not automatically prohibited. For example, where lot size does not permit placement to the rear, and the proposed addition is compatible with the street scape, it should be subject to moderate scrutiny for contributing resources, but strict scrutiny for outstanding resources.

Porches should be subject to moderate scrutiny if they are visible from the public right-of-way, lenient scrutiny if they are not.

Roofing materials should be subject to moderate scrutiny if they are visible from the public right-of-way, lenient scrutiny if they are not. In general, materials differing from the original should be approved for contributing resources.

Tree removal should be subject to strict scrutiny and consistent with the Chevy Chase Village Urban Forest Ordinance.

Windows (including window replacement) should be subject to moderate scrutiny if they are visible from the public right-of-way, lenient scrutiny if they are not. For outstanding resources, they should be subject to strict scrutiny. Addition of compatible exterior storm windows should be encouraged, whether visible from the public right-of-way or not. Vinyl and aluminum windows (other than storm windows) should be discouraged. Addition of security bars should be subject to lenient scrutiny, whether visible from the public right-of-way or not.

Secretary of Interior's Standards for Rehabilitation

The Secretary of the Interior defines rehabilitation as "the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features, which convey its historical, cultural, or architectural values." The *Standards* are as follows:

1. A property shall be used for its historic purpose or be placed in a new use that requires minimal change to the defining characteristics of the building and its site and environment.
2. The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.
3. Each property shall be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as adding conjectural features or architectural elements from other buildings, shall not be undertaken.

4. Most properties change over time; those changes that have acquired historic significance in their own right shall be retained and preserved.
5. Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a historic property shall be preserved.
6. Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary, physical, or pictorial evidence.
7. Chemical or physical treatments, such as sandblasting, that cause damage to historic materials shall not be used. The surface cleaning of structures, if appropriate, shall be undertaken using the gentlest means possible.
8. Significant archaeological resources affected by a project shall be protected and preserved. If such resources must be disturbed, mitigation measures shall be undertaken.
9. New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.
10. New additions and adjacent or related new construction shall be undertaken in such a manner that if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

STAFF DISCUSSION

The applicant previously appeared before the Commission at the December 7, 2016 HPC meeting for a preliminary consultation. At that time, the Commission expressed the following concerns regarding the applicant's proposal:

- The proposed stone chimney was incompatible with the historic house, and a brick chimney would be more appropriate.
- Replacing the original windows on the front elevation has the potential to detract from the streetscape of the historic district. The Commission was less concerned about replacing the original windows on the side elevations.
- A spread mull is needed at all proposed paired and ganged windows.
- The ridgeline of the proposed rear addition was too high.

There was also some concern about the general incompatibility of the proposed rear addition with the historic house, and the Commission encouraged the applicant to explore alternatives that may be more compatible; however, the Commission did indicate that, due to a lack of visibility, the proposed rear addition would be reluctantly approved.

The Commission also encouraged the applicant to create a tree protection plan to ensure that two elm trees (one at 10 Hesketh Street and one on the property line between 10 Hesketh Street and the subject property) would not be impacted by the proposal.

The applicant has revised their proposal consistent with the Commission's comments and returned with a

HAWP application. Specifically, the applicant has made the following revisions:

- The currently proposed chimney is brick.
- The original windows on the front elevation will be retained.
- The ridgeline of the proposed rear addition has been lowered by 4”, making it a total of 8” below the ridgeline of the historic house.
- A 6” spread mull has been added at the paired and ganged windows, which have been limited to the rear elevation.
- The applicant proposes an alternative design for the addition, with a gambrel roof form that takes cues from the historic house.
- A tree protection plan is proposed to ensure that the elm tree at 10 Hesketh Street and the elm tree on the property line between 10 Hesketh Street and the subject property are not impacted.

New aspects of the applicant’s proposal include replacing the existing asphalt shingle roofing on the historic house with synthetic slate and replacing the existing front door within the existing opening.

The *Guidelines* state that “[r]oofing materials should be subject to moderate scrutiny if they are visible from the public right-of-way, lenient scrutiny if they are not. In general, materials differing from the original should be approved for contributing resources.” The Commission generally discourages the use of synthetic slate, and, in this case, staff suggests that architectural asphalt shingles may be more appropriate, with less potential to detract from the subject property and surrounding historic district. The applicant has indicated that they would be amenable to using architectural asphalt shingles in place of synthetic slate. Staff recommends a condition of approval, stipulating that the proposed replacement roofing materials will be architectural asphalt shingles, with final review and approval delegated to staff.

The *Guidelines* state that “[d]oors should be subject to moderate scrutiny if they are visible from the public right-of-way, lenient scrutiny if they are not.” The applicant has provided photographs of the existing front door, which suggests that it is likely historic. No documentation has been provided to indicate that the existing front door is severely deteriorated and in need of replacement, and staff recommends that the proposed front door replacement not be approved.

The applicant has indicated that the proposed new windows (including the replacement windows on the side elevations) will be wood clad SDL windows, but has not provided any additional information. In accordance with the Commission’s typical requirement, the proposed SDL windows should have permanently-affixed 7/8” profile muntins with spacer bars. Staff recommends a condition of approval, stipulating that window details be submitted, with final review and approval delegated to staff. Details should also be submitted for any doors on the proposed rear addition, with final review and approval delegated to staff.

After full and fair consideration of the applicant’s submission staff finds the proposal as being consistent with the Criteria for Issuance in Chapter 24A-(b) 1 and 2, having found the proposal is consistent with the *Secretary of the Interior’s Standards for Rehabilitation* and *Chevy Chase Village Historic District Guidelines* outlined above.

STAFF RECOMMENDATION

Staff recommends that the Commission **approve with the conditions specified on Circle 1** the HAWP application under the Criteria for Issuance in Chapter 24A-8(b), having found that the proposal is consistent with the Chevy Chase Village Historic District Guidelines identified above, and therefore will not substantially alter the exterior features of the historic resource and is compatible in character with the district

and the purposes of Chapter 24A;

and with the Secretary of the Interior's Standards for Rehabilitation;

and with the general condition that the applicant shall present the **3 permit sets of drawings, if applicable to Historic Preservation Commission (HPC) staff for review and stamping** prior to submission for the Montgomery County Department of Permitting Services (DPS) building permits;

and with the general condition that final project design details, not specifically delineated by the Commission, shall be approved by HPC staff or brought back to the Commission as a revised HAWP application at staff's discretion;

and with the general condition that the applicant shall notify the Historic Preservation Staff if they propose to make **any alterations** to the approved plans. Once the work is completed the applicant will contact the staff person assigned to this application at 301-563-3400 or michael.kyne@montgomeryplanning.org to schedule a follow-up site visit.



HISTORIC PRESERVATION COMMISSION
301/563-3400

APPLICATION FOR
HISTORIC AREA WORK PERMIT

Contact Email: jjagen@flanaganaarchitects.com Contact Person: TOM FLANAGAN
JASON GAGEN
Daytime Phone No.: 301-652-4811

Tax Account No.: _____
Name of Property Owner: NEIL CULLEN Daytime Phone No.: 240-418-7708
Address: 12 HESKETH ST. CHEVY CHASE MD 20815
Street Number City State Zip Code
Contractor: NORTHCLIFF BUILDERS, INC. Phone No.: 301-908-8140
Contractor Registration No.: 120960
Agent for Owner: WILLIAM MALONEY Daytime Phone No.: _____

LOCATION OF BUILDING/PREMISE

House Number: 12 Street: HESKETH STREET
Town/City: CHEVY CHASE Nearest Cross Street: MAGNOLIA PKWY.
Lot: P8+17 Block: 24+25 Subdivision: CHEVY CHASE-SECTION 2
Liber: _____ Folio: _____ Parcel: _____

PART ONE: TYPE OF PERMIT ACTION AND USE

1A. CHECK ALL APPLICABLE: Construct Extend Alter/Renovate A/C Slab Room Addition Porch Deck Shed
 Move Install Wreck/Raze Solar Fireplace Woodburning Stove Single Family
 Revision Repair Revoicable Fence/Wall (complete Section 4) Other: _____
1B. Construction cost estimate: \$ 250,000
1C. If this is a revision of a previously approved active permit, see Permit # No

PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND/ADDITIONS

2A. Type of sewage disposal: 01 WSSC 02 Septic 03 Other: _____
2B. Type of water supply: 01 WSSC 02 Well 03 Other: _____

PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WALL

3A. Height _____ feet _____ inches
3B. Indicate whether the fence or retaining wall is to be constructed on one of the following locations:
 On party line/property line Entirely on land of owner On public right of way/easement

I hereby certify that I have the authority to make the foregoing application, that the application is correct, and that the construction will comply with plans approved by all agencies listed and I hereby acknowledge and accept this to be a condition for the issuance of this permit.

[Signature] 11.14.10
Signature of owner or authorized agent - TOM FLANAGAN Date

Approved: _____ For Chairperson, Historic Preservation Commission
Disapproved: _____ Signature: _____ Date: _____
Application/Permit No.: _____ Date Filed: _____ Date Issued: _____

**THE FOLLOWING ITEMS MUST BE COMPLETED AND THE
REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION.**

1. WRITTEN DESCRIPTION OF PROJECT

- a. Description of existing structure(s) and environmental setting, including their historical features and significance:

THE EXISTING HOUSE IS A TWO-STORY WOOD FRAME HOUSE W/ A
BASEMENT. IT HAS WOOD SIDING, SINGLE-PANE WINDOWS AND
ASPHALT SHINGLE ROOFING ON A MANSARD ROOF. IT IS CONSIDERED
A CONTRIBUTING ASSET TO THE HISTORIC DISTRICT, BUT DOES
NOT APPEAR TO HAVE ANY SIGNIFICANT HISTORICAL
FEATURES OF VALUE TO THE NEIGHBORHOOD.

REVISED

- b. General description of project and its effect on the historic resource(s), the environmental setting, and, where applicable, the historic district:

THE PROPOSED ADDITION IS TWO STORIES AT THE REAR
OF THE ORIGINAL HOUSE AND INSET ON BOTH SIDES TO
MINIMIZE IT VISUALLY FROM THE STREET. NEW SIMULATED
DIVIDED LITE WINDOWS TO REPLACE EXISTING SINGLE PANE
WINDOWS. EXTERIOR MATERIALS TO COMPLEMENT ORIGINAL HOUSE AND/
OR TO BE IN KEEPING W/ THE SURROUNDING NEIGHBORHOOD.

2. **SITE PLAN** DNE STORY PORCH ADDITION TO MATCH EXISTING SCREEN PORCH.

Site and environmental setting, drawn to scale. You may use your plat. Your site plan must include:

- ✓ a. the scale, north arrow, and date;
- ✓ b. dimensions of all existing and proposed structures; and
- ✓ c. site features such as walkways, driveways, fences, ponds, streams, trash dumpsters, mechanical equipment, and landscaping.

3. PLANS AND ELEVATIONS

You must submit 2 copies of plans and elevations in a format no larger than 11" x 17". Plans on 8 1/2" x 11" paper are preferred.

- ✓ a. *Schematic construction plans*, with marked dimensions, indicating location, size and general type of walls, window and door openings, and other fixed features of both the existing resource(s) and the proposed work.
- ✓ b. Elevations (facades), with marked dimensions; clearly indicating proposed work in relation to existing construction and, when appropriate, context. All materials and fixtures proposed for the exterior must be noted on the elevations drawings. An existing and a proposed elevation drawing of each facade affected by the proposed work is required.

✓ **4. MATERIALS SPECIFICATIONS**

General description of materials and manufactured items proposed for incorporation in the work of the project. This information may be included on your design drawings.

5. PHOTOGRAPHS

- ✓ a. Clearly labeled photographic prints of each facade of existing resource, including details of the affected portions. All labels should be placed on the front of photographs.
- ✓ b. Clearly label photographic prints of the resource as viewed from the public right-of-way end of the adjoining properties. All labels should be placed on the front of photographs.

6. TREE SURVEY

If you are proposing construction adjacent to or within the dripline of any tree 6" or larger in diameter (at approximately 4 feet above the ground), you must file an accurate tree survey identifying the size, location, and species of each tree of at least that dimension. - SEE SP-1

7. ADDRESSES OF ADJACENT AND CONFRONTING PROPERTY OWNERS


For ALL projects, provide an accurate list of adjacent and confronting property owners (not tenants), including names, addresses, and zip codes. This list should include the owners of all lots or parcels which adjoin the parcel in question, as well as the owner(s) of lot(s) or parcel(s) which lie directly across the street/highway from the parcel in question.

PLEASE PRINT (IN BLUE OR BLACK INK) OR TYPE THIS INFORMATION ON THE FOLLOWING PAGE.
PLEASE STAY WITHIN THE GUIDES OF THE TEMPLATE, AS THIS WILL BE PHOTOCOPIED DIRECTLY ONTO MAILING LABELS.

Montgomery County Zoning (last amended: November 8, 2016 H-113, H-114, H-116)

Address/Place Name Searching

12 HESKETH ST




Handwritten initials or mark.



Job Name:
CULLEN RESIDENCE
 12 HESKETH ST
 CHEVY CHASE, MD

Sheet Description:
SITE PLAN

Project #:	184400
Scale:	AS NOTED
Drawn by:	CAS
Checked by:	
Date:	08 APR 78




PROJECT NO. 100-100-100
 DATE: 10/10/10
 DRAWN BY: J. SMITH
 CHECKED BY: M. JONES
 SCALE: AS SHOWN


CULLEN RESIDENCE

PROJECT NO. 100-100-100
 DATE: 10/10/10
 DRAWN BY: J. SMITH
 CHECKED BY: M. JONES
 SCALE: AS SHOWN

- KEYNOTES**
1. SEE PLAN FOR WINDOW SCHEDULE
 2. SEE PLAN FOR DOOR SCHEDULE
 3. SEE PLAN FOR ROOF SCHEDULE
 4. SEE PLAN FOR FLOOR SCHEDULE
 5. SEE PLAN FOR WALL SCHEDULE
 6. SEE PLAN FOR CEILING SCHEDULE
 7. SEE PLAN FOR FINISH SCHEDULE
 8. SEE PLAN FOR LIGHTING SCHEDULE
 9. SEE PLAN FOR MECHANICAL SCHEDULE
 10. SEE PLAN FOR ELECTRICAL SCHEDULE
 11. SEE PLAN FOR PAINT SCHEDULE
 12. SEE PLAN FOR GLASS SCHEDULE
 13. SEE PLAN FOR METAL SCHEDULE
 14. SEE PLAN FOR WOOD SCHEDULE
 15. SEE PLAN FOR STONE SCHEDULE
 16. SEE PLAN FOR TILE SCHEDULE
 17. SEE PLAN FOR CARPET SCHEDULE
 18. SEE PLAN FOR RUG SCHEDULE
 19. SEE PLAN FOR CURTAIN SCHEDULE
 20. SEE PLAN FOR BLIND SCHEDULE
 21. SEE PLAN FOR SHUTTER SCHEDULE
 22. SEE PLAN FOR LAMINATE SCHEDULE
 23. SEE PLAN FOR GRANITE SCHEDULE
 24. SEE PLAN FOR MARBLE SCHEDULE
 25. SEE PLAN FOR QUARTZ SCHEDULE
 26. SEE PLAN FOR SOLID SURFACE SCHEDULE
 27. SEE PLAN FOR COUNTER SCHEDULE
 28. SEE PLAN FOR SINK SCHEDULE
 29. SEE PLAN FOR STOVE SCHEDULE
 30. SEE PLAN FOR REFRIG SCHEDULE
 31. SEE PLAN FOR DISHWASHER SCHEDULE
 32. SEE PLAN FOR RANGE SCHEDULE
 33. SEE PLAN FOR MICROWAVE SCHEDULE
 34. SEE PLAN FOR TOASTER SCHEDULE
 35. SEE PLAN FOR BLENDER SCHEDULE
 36. SEE PLAN FOR KITCHEN AID SCHEDULE
 37. SEE PLAN FOR TOASTER OVEN SCHEDULE
 38. SEE PLAN FOR COFFEE MAKER SCHEDULE
 39. SEE PLAN FOR JUICER SCHEDULE
 40. SEE PLAN FOR WINE COOLER SCHEDULE
 41. SEE PLAN FOR REFRIG SCHEDULE
 42. SEE PLAN FOR FREEZER SCHEDULE
 43. SEE PLAN FOR ICE MAKER SCHEDULE
 44. SEE PLAN FOR WATER DISPENSER SCHEDULE
 45. SEE PLAN FOR SINK SCHEDULE
 46. SEE PLAN FOR STOVE SCHEDULE
 47. SEE PLAN FOR REFRIG SCHEDULE
 48. SEE PLAN FOR FREEZER SCHEDULE
 49. SEE PLAN FOR ICE MAKER SCHEDULE
 50. SEE PLAN FOR WATER DISPENSER SCHEDULE



- EXTERIOR FINISH MATERIALS**
1. SEE PLAN FOR WINDOW SCHEDULE
 2. SEE PLAN FOR DOOR SCHEDULE
 3. SEE PLAN FOR ROOF SCHEDULE
 4. SEE PLAN FOR FLOOR SCHEDULE
 5. SEE PLAN FOR WALL SCHEDULE
 6. SEE PLAN FOR CEILING SCHEDULE
 7. SEE PLAN FOR FINISH SCHEDULE
 8. SEE PLAN FOR LIGHTING SCHEDULE
 9. SEE PLAN FOR MECHANICAL SCHEDULE
 10. SEE PLAN FOR ELECTRICAL SCHEDULE
 11. SEE PLAN FOR PAINT SCHEDULE
 12. SEE PLAN FOR GLASS SCHEDULE
 13. SEE PLAN FOR METAL SCHEDULE
 14. SEE PLAN FOR WOOD SCHEDULE
 15. SEE PLAN FOR STONE SCHEDULE
 16. SEE PLAN FOR TILE SCHEDULE
 17. SEE PLAN FOR CARPET SCHEDULE
 18. SEE PLAN FOR RUG SCHEDULE
 19. SEE PLAN FOR CURTAIN SCHEDULE
 20. SEE PLAN FOR BLIND SCHEDULE
 21. SEE PLAN FOR SHUTTER SCHEDULE
 22. SEE PLAN FOR LAMINATE SCHEDULE
 23. SEE PLAN FOR GRANITE SCHEDULE
 24. SEE PLAN FOR MARBLE SCHEDULE
 25. SEE PLAN FOR QUARTZ SCHEDULE
 26. SEE PLAN FOR SOLID SURFACE SCHEDULE
 27. SEE PLAN FOR COUNTER SCHEDULE
 28. SEE PLAN FOR SINK SCHEDULE
 29. SEE PLAN FOR STOVE SCHEDULE
 30. SEE PLAN FOR REFRIG SCHEDULE
 31. SEE PLAN FOR DISHWASHER SCHEDULE
 32. SEE PLAN FOR RANGE SCHEDULE
 33. SEE PLAN FOR MICROWAVE SCHEDULE
 34. SEE PLAN FOR TOASTER SCHEDULE
 35. SEE PLAN FOR BLENDER SCHEDULE
 36. SEE PLAN FOR KITCHEN AID SCHEDULE
 37. SEE PLAN FOR TOASTER OVEN SCHEDULE
 38. SEE PLAN FOR COFFEE MAKER SCHEDULE
 39. SEE PLAN FOR JUICER SCHEDULE
 40. SEE PLAN FOR WINE COOLER SCHEDULE
 41. SEE PLAN FOR REFRIG SCHEDULE
 42. SEE PLAN FOR FREEZER SCHEDULE
 43. SEE PLAN FOR ICE MAKER SCHEDULE
 44. SEE PLAN FOR WATER DISPENSER SCHEDULE
 45. SEE PLAN FOR SINK SCHEDULE
 46. SEE PLAN FOR STOVE SCHEDULE
 47. SEE PLAN FOR REFRIG SCHEDULE
 48. SEE PLAN FOR FREEZER SCHEDULE
 49. SEE PLAN FOR ICE MAKER SCHEDULE
 50. SEE PLAN FOR WATER DISPENSER SCHEDULE






EXISTING FRONT DOOR



7228 — BUNGALOW (TDL)




SERIES: Bungalow Series®
TYPE: Exterior Decorative
APPLICATIONS: Can be used for a swing door, with barn track hardware, with pivot hardware, in a patio swing door or slider system and many other applications for the home's exterior.

Construction Type:
 Engineered All-Wood Stiles and Rails with Dowel Pinned Stile/Rail Joinery

Panels: 1-7/16" Innerbond® Double Hip-Raised Panel, Beaded V-Groove
Profile: Ovolo Sticking
Glass: 3/4" Insulated Glazing (shown with optional beveled glass)


DETAILED DRAWING




STANDARD FEATURES

-  Any Wood Species
-  Virtually Any Size
-  Glass Options
-  UltraBlock® Technology
-  Privacy Rating: 1

DETAILS





HESKETH ST.

12 10 8 6 4 2

PROPOSED ADDITION.

R-60

GOOGLE MAPS PROP. IDENTIFIED.

BA-1790

Google Maps 7 Hesketh St
10 HESKETH.




Image capture: May 2014 © 2016 Google

Chevy Chase Village, Maryland
Street View - May 2014

12 HESKETH.

BUILDING HGT EXHIBIT ①

<https://www.google.com/maps/place/12+Hesketh+St,+Chevy+Chase,+MD+20815/@38.9685203,-77.0801722,3a,75.4y,179.1...> 11/21/2016


Google Maps 12 Hesketh St



Imagery ©2016 Google, Map data ©2016 Google 20 ft

12 HESKETH.

REAR YARD EXHIBIT ③



LIMITS OF DISTURBANCE
COINCIDES WITH THIS
PROPERTY LINE
LIMITS OF DISTURBANCE
(LOD): 7,000 S.F. ±

PROP. AREA OF
EX. HOUSE TO BE
REMOVED. # EJECTOR PUMP REQUIRED
FOR LOWER LEVEL SEWER.
PLUMBER TO CONFIRM.

EX. DRAINAGE
AREA TO SITE
= 1.6 ACRES ±

S OF DISTURBANCE
COINCIDES WITH THIS
PROPERTY LINE

UTILITY LOCATIONS ARE
SUBJECT TO FIELD
MODIFICATION, PROVIDED

① PROVIDE TREE PROTECTION AT REAR ELM TREES
AT 10 HESKETH - PER NEIGHBOR'S REQUEST.

HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFYING
 [Owner, Owner's Agent, Adjacent and Confronting Property Owners]

<p>Owner's mailing address</p> <p>NEIL CULLEN 12 HESKETH STREET CHEVY CHASE, MD 20815</p>	<p>Owner's Agent's mailing address</p> <p>FLANAGAN ARCHITECTS, AIA % JASON GAGEN 8120 WOODMONT AVE #107 BETHESDA, MD 20814</p>
<p align="center">Adjacent and confronting Property Owners mailing addresses</p>	
<p>JERRY GUDIS 5 HESKETH STREET CHEVY CHASE, MD 20815</p>	<p>DAVID BLAKE BATH JAMES MEISEL 7 HESKETH STREET CHEVY CHASE, MD 20815</p>
<p>NANCY WATTERS STEPHEN SAYRE 10 HESKETH STREET CHEVY CHASE, MD 20815</p>	<p>JULIE CHAPMAN DAVID CUSHING 14 HESKETH STREET CHEVY CHASE, MD 20815</p>
<p>CHARLES TRAIN GEORGIA SANGER 11 GRAPTON STREET CHEVY CHASE, MD 20815</p>	<p>ROBERT LEVIN 13 GRAPTON STREET CHEVY CHASE, MD 20815</p>

CULLEN RESIDENCE

12 HESKETH STREET CHEVY CHASE, MD 20815



CULLEN RESIDENCE
12 HESKETH STREET
CHEVY CHASE, MD 20815

INDEX OF DRAWINGS

OWNER'S REQUIREMENTS

GENERAL NOTES

ABBREVIATIONS

SYMBOLS & MATERIALS

RESPONSIBILITY SCHEDULE

NO.	DESCRIPTION	DATE	BY
1	PRELIMINARY DESIGN	10/15/01	FLN
2	SCHEMATIC DESIGN	10/22/01	FLN
3	CONCEPTUAL DESIGN	11/05/01	FLN
4	PRELIMINARY CONTRACT DOCUMENTS	11/12/01	FLN
5	SCHEMATIC CONTRACT DOCUMENTS	11/19/01	FLN
6	CONCEPTUAL CONTRACT DOCUMENTS	12/06/01	FLN
7	PRELIMINARY PERMITS	12/13/01	FLN
8	SCHEMATIC PERMITS	12/20/01	FLN
9	CONCEPTUAL PERMITS	1/06/02	FLN
10	PRELIMINARY BIDDING	1/13/02	FLN
11	SCHEMATIC BIDDING	1/20/02	FLN
12	CONCEPTUAL BIDDING	2/06/02	FLN
13	PRELIMINARY CONSTRUCTION	2/13/02	FLN
14	SCHEMATIC CONSTRUCTION	2/20/02	FLN
15	CONCEPTUAL CONSTRUCTION	3/06/02	FLN
16	PRELIMINARY CLOSEOUT	3/13/02	FLN
17	SCHEMATIC CLOSEOUT	3/20/02	FLN
18	CONCEPTUAL CLOSEOUT	4/06/02	FLN

PROFESSIONAL DATA

PROJECT NO. 01-001
DATE: 10/15/01
DRAWN BY: FLN
CHECKED BY: FLN
SCALE: AS SHOWN
SHEET NO. 1 OF 1

INDEX OF DRAWINGS

NO.	DESCRIPTION	DATE
1	GENERAL NOTES	10/15/01
2	FOUNDATION	10/22/01
3	FLOOR PLAN	11/05/01
4	ELEVATIONS	11/12/01
5	SECTION	11/19/01
6	DETAILS	12/06/01
7	PERMITS	12/13/01
8	BIDDING	12/20/01
9	CONSTRUCTION	1/06/02
10	CLOSEOUT	1/13/02

OWNER'S REQUIREMENTS

1. THE OWNER DESIRES A SINGLE-FAMILY RESIDENCE WITH THE FOLLOWING FEATURES:

- 1.1. A 2 1/2 STORY HOUSE WITH A FINISHED ATTIC.
- 1.2. A 2 CAR GARAGE WITH A FINISHED INTERIOR.
- 1.3. A HARDWOOD FLOOR THROUGHOUT THE MAIN FLOOR.
- 1.4. A GRANITE COUNTERTOP IN THE KITCHEN.
- 1.5. A STAINLESS STEEL APPLIANCE PACKAGE.
- 1.6. A WALK-IN PANTRY.
- 1.7. A BREAKFAST ROOM WITH A VIEW OF THE GARDEN.
- 1.8. A BATH WITH A WALK-IN CLOSET.
- 1.9. A MASTER BEDROOM WITH A WALK-IN CLOSET.
- 1.10. A FRONT PORCH WITH A VIEW OF THE GARDEN.
- 1.11. A REAR PORCH WITH A VIEW OF THE GARDEN.
- 1.12. A LANDSCAPED YARD WITH A VIEW OF THE GARDEN.

GENERAL NOTES

1. ALL WORK SHALL BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE BUILDING CODES AND REGULATIONS OF THE DISTRICT OF COLUMBIA.

2. THE CONTRACTOR SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY PERMITS AND INSURANCE.

3. THE CONTRACTOR SHALL MAINTAIN ACCESS TO ALL ADJACENT PROPERTIES AT ALL TIMES.

4. THE CONTRACTOR SHALL PROTECT ALL EXISTING UTILITIES AND STRUCTURES.

5. THE CONTRACTOR SHALL MAINTAIN THE SITE AT ALL TIMES.

6. THE CONTRACTOR SHALL BE RESPONSIBLE FOR THE PROTECTION OF ALL ADJACENT PROPERTIES.

7. THE CONTRACTOR SHALL MAINTAIN THE SITE AT ALL TIMES.

8. THE CONTRACTOR SHALL BE RESPONSIBLE FOR THE PROTECTION OF ALL ADJACENT PROPERTIES.

9. THE CONTRACTOR SHALL MAINTAIN THE SITE AT ALL TIMES.

10. THE CONTRACTOR SHALL BE RESPONSIBLE FOR THE PROTECTION OF ALL ADJACENT PROPERTIES.

ABBREVIATIONS

SYMBOL	DESCRIPTION
1/4" = 1'-0"	SCALE
1/8" = 1'-0"	SCALE
1/16" = 1'-0"	SCALE
1/32" = 1'-0"	SCALE
1/64" = 1'-0"	SCALE
1/128" = 1'-0"	SCALE
1/256" = 1'-0"	SCALE
1/512" = 1'-0"	SCALE
1/1024" = 1'-0"	SCALE
1/2048" = 1'-0"	SCALE
1/4096" = 1'-0"	SCALE
1/8192" = 1'-0"	SCALE
1/16384" = 1'-0"	SCALE
1/32768" = 1'-0"	SCALE
1/65536" = 1'-0"	SCALE
1/131072" = 1'-0"	SCALE
1/262144" = 1'-0"	SCALE
1/524288" = 1'-0"	SCALE
1/1048576" = 1'-0"	SCALE
1/2097152" = 1'-0"	SCALE
1/4194304" = 1'-0"	SCALE
1/8388608" = 1'-0"	SCALE
1/16777216" = 1'-0"	SCALE
1/33554432" = 1'-0"	SCALE
1/67108864" = 1'-0"	SCALE
1/134217728" = 1'-0"	SCALE
1/268435456" = 1'-0"	SCALE
1/536870912" = 1'-0"	SCALE
1/1073741824" = 1'-0"	SCALE
1/2147483648" = 1'-0"	SCALE
1/4294967296" = 1'-0"	SCALE
1/8589934592" = 1'-0"	SCALE
1/17179869184" = 1'-0"	SCALE
1/34359738368" = 1'-0"	SCALE
1/68719476736" = 1'-0"	SCALE
1/137438953472" = 1'-0"	SCALE
1/274877906944" = 1'-0"	SCALE
1/549755813888" = 1'-0"	SCALE
1/1099511627776" = 1'-0"	SCALE
1/2199023255552" = 1'-0"	SCALE
1/4398046511104" = 1'-0"	SCALE
1/8796093022208" = 1'-0"	SCALE
1/17592186044416" = 1'-0"	SCALE
1/35184372088832" = 1'-0"	SCALE
1/70368744177664" = 1'-0"	SCALE
1/140737488355328" = 1'-0"	SCALE
1/281474976710656" = 1'-0"	SCALE
1/562949953421312" = 1'-0"	SCALE
1/1125899906842624" = 1'-0"	SCALE
1/2251799813685248" = 1'-0"	SCALE
1/4503599627370496" = 1'-0"	SCALE
1/9007199254740992" = 1'-0"	SCALE
1/18014398509481984" = 1'-0"	SCALE
1/36028797018963968" = 1'-0"	SCALE
1/72057594037927936" = 1'-0"	SCALE
1/144115188075855872" = 1'-0"	SCALE
1/288230376151711744" = 1'-0"	SCALE
1/576460752303423488" = 1'-0"	SCALE
1/1152921504606846976" = 1'-0"	SCALE
1/2305843009213693952" = 1'-0"	SCALE
1/4611686018427387904" = 1'-0"	SCALE
1/9223372036854775808" = 1'-0"	SCALE
1/18446744073709551616" = 1'-0"	SCALE
1/36893488147419103232" = 1'-0"	SCALE
1/73786976294838206464" = 1'-0"	SCALE
1/147573952593676412928" = 1'-0"	SCALE
1/295147905187352825856" = 1'-0"	SCALE
1/590295810374705651712" = 1'-0"	SCALE
1/1180591620749411303424" = 1'-0"	SCALE
1/2361183241498822606848" = 1'-0"	SCALE
1/4722366482997645213696" = 1'-0"	SCALE
1/9444732965995290427392" = 1'-0"	SCALE
1/18889465931990580854784" = 1'-0"	SCALE
1/37778931863981161709568" = 1'-0"	SCALE
1/75557863727962323419136" = 1'-0"	SCALE
1/151115727455924646838272" = 1'-0"	SCALE
1/302231454911849293676544" = 1'-0"	SCALE
1/604462909823698587353088" = 1'-0"	SCALE
1/1208925819647397174706176" = 1'-0"	SCALE
1/2417851639294794349412352" = 1'-0"	SCALE
1/4835703278589588698824704" = 1'-0"	SCALE
1/9671406557179177397649408" = 1'-0"	SCALE
1/19342813114358354795298816" = 1'-0"	SCALE
1/38685626228716709590597632" = 1'-0"	SCALE
1/77371252457433419181195264" = 1'-0"	SCALE
1/154742504914866837362390528" = 1'-0"	SCALE
1/309485009829733674724781152" = 1'-0"	SCALE
1/618970019659467349449562304" = 1'-0"	SCALE
1/1237940039318934988991244608" = 1'-0"	SCALE
1/2475880078637869977982489216" = 1'-0"	SCALE
1/4951760157275739955964978432" = 1'-0"	SCALE
1/9903520314551479911932956864" = 1'-0"	SCALE
1/1980704062910315823865913728" = 1'-0"	SCALE
1/3961408125820631647731827456" = 1'-0"	SCALE
1/7922816251641263295463654912" = 1'-0"	SCALE
1/1584563250328252590912708928" = 1'-0"	SCALE
1/3169126500656505181825417856" = 1'-0"	SCALE
1/6338253001313010363650835712" = 1'-0"	SCALE
1/12676506002626020727301671424" = 1'-0"	SCALE
1/25353012005252041454603342848" = 1'-0"	SCALE
1/50706024010504082913206685696" = 1'-0"	SCALE
1/101412048021008158226413371392" = 1'-0"	SCALE
1/202824096042016316452826742784" = 1'-0"	SCALE
1/40564819208403263284565348576" = 1'-0"	SCALE
1/81129638416806526569130697152" = 1'-0"	SCALE
1/16225927683361305313826138304" = 1'-0"	SCALE
1/32451855366722610627652266608" = 1'-0"	SCALE
1/64903710733445221255304533216" = 1'-0"	SCALE
1/129807421468894425111060666432" = 1'-0"	SCALE
1/259614842937788850222121332864" = 1'-0"	SCALE
1/519229685875577700444242665728" = 1'-0"	SCALE
1/1038459371711155400888485331456" = 1'-0"	SCALE
1/2076918743422310801776970662712" = 1'-0"	SCALE
1/4153837486844621603553941325424" = 1'-0"	SCALE
1/8307674973689243207107822650848" = 1'-0"	SCALE
1/1661534994737848641421564530176" = 1'-0"	SCALE
1/3323069989475697282843129060352" = 1'-0"	SCALE
1/6646139978951394565686258120704" = 1'-0"	SCALE
1/13292279957902789113772516244128" = 1'-0"	SCALE
1/26584559915805578227545032488256" = 1'-0"	SCALE
1/53169119831611156455090064976512" = 1'-0"	SCALE
1/106338239663222312910180129953024" = 1'-0"	SCALE
1/212676479326444625820360259906048" = 1'-0"	SCALE
1/425352958652889251640720519812096" = 1'-0"	SCALE
1/850705917305778503281441039624192" = 1'-0"	SCALE
1/170141183461155700656288207248384" = 1'-0"	SCALE
1/34028236692231140131257641449676768" = 1'-0"	SCALE
1/680564733844622802625152829953536" = 1'-0"	SCALE
1/1361129467689245645251055599107104" = 1'-0"	SCALE
1/27222589533784912905021111982142208" = 1'-0"	SCALE
1/5444517906756982581004222396424416" = 1'-0"	SCALE
1/1088903581351396516200844479284832" = 1'-0"	SCALE
1/2177807162702793032401688958569664" = 1'-0"	SCALE
1/4355614325405586064803377917139328" = 1'-0"	SCALE
1/8711228650811172129606755834278656" = 1'-0"	SCALE
1/17422457101623542519213511668557312" = 1'-0"	SCALE
1/34844914203247085038427023337114624" = 1'-0"	SCALE
1/6968982840649417007685404667422848" = 1'-0"	SCALE
1/1393796568129824015377080933485696" = 1'-0"	SCALE
1/2787593136259648030754161866971392" = 1'-0"	SCALE
1/5575186272519296061510833733942784" = 1'-0"	SCALE
1/1115037254503859212302166676677568" = 1'-0"	SCALE
1/2230074509007718424604333533355136" = 1'-0"	SCALE
1/446014901801543684920866706671072" = 1'-0"	SCALE
1/892029803603087369841733413342144" = 1'-0"	SCALE
1/178405960720617473968346682668288" = 1'-0"	SCALE
1/356811921441234947937693653336576" = 1'-0"	SCALE
1/713623842882469895875387306673152" = 1'-0"	SCALE
1/142724768576493979175077461346304" = 1'-0"	SCALE
1/285449537152987958350154922692608" = 1'-0"	SCALE
1/570899074305975916700309845385216" = 1'-0"	SCALE
1/1141798148611911834000619687704432" = 1'-0"	SCALE
1/2283596297223823668001239361408864" = 1'-0"	SCALE
1/456719259444764733600247872281728" = 1'-0"	SCALE
1/913438518889529467200495744563456" = 1'-0"	SCALE
1/1826877137779058934400991489126912" = 1'-0"	SCALE
1/3653754275558117868801982978253824" = 1'-0"	SCALE
1/7307508551116235737603965956507648" = 1'-0"	SCALE
1/1461501710223247147520793191301536" = 1'-0"	SCALE
1/2923003420446494295041586382603072" = 1'-0"	SCALE
1/5846006840892988590083172765206144" = 1'-0"	SCALE
1/1169201368178597718016354552412288" = 1'-0"	SCALE
1/233840273635719543603270910482576" = 1'-0"	SCALE
1/467680547271439087206541820965152" = 1'-0"	SCALE
1/935361094542878174413108401930304" = 1'-0"	SCALE
1/187072218908575634826221603860608" = 1'-0"	SCALE
1/374144437817151269652442717321216" = 1'-0"	SCALE
1/748288875634302539304885434642432" = 1'-0"	SCALE
1/149657775126860507860977089284864" = 1'-0"	SCALE
1/299315550253721015721154178569728" = 1'-0"	SCALE
1/598631100507442031442308357139456" = 1'-0"	SCALE
1/119726220101488402288461714278912" = 1'-0"	SCALE
1/239452440202976804576923428557824" = 1'-0"	SCALE
1/478904880405953609153846857115648" = 1'-0"	SCALE
1/95780976081190721830769371431296" = 1'-0"	SCALE
1/191561951623781437601538542862592" = 1'-0"	SCALE
1/383123903247562875203077085725184" = 1'-0"	SCALE
1/76624780649512575040615417145136" = 1'-0"	SCALE
1/153249561290251500801268342892704" = 1'-0"	SCALE
1/306499122580503001602536685785408" = 1'-0"	SCALE
1/612998245161006003205073371570816" = 1'-0"	SCALE
1/12259964903220120064010146434416" = 1'-0"	SCALE
1/24519929806440240128020292868832" = 1'-0"	SCALE
1/49039859612880480256040585737664" = 1'-0"	SCALE
1/98079719225760960512081171475328" = 1'-0"	SCALE
1/196159438451521921024162342950656" = 1'-0"	SCALE
1/39231887690304384204832468990112" = 1'-0"	SCALE

Flanagan
ARCHITECTS, INC.

410 S. BROADWAY, SUITE 207
HOUSTON, TEXAS 77002

TEL: 770-531-1111

PROJECT NO. 100-100-100

DATE: 10/10/10

SCALE: AS SHOWN

QUILLEN RESIDENCE

11 HEMLOCK STREET
HOUSTON, TEXAS 77002

PROJECT NO. 100-100-100

DATE: 10/10/10

SCALE: AS SHOWN

BASEMENT PLAN

PROJECT NO. 100-100-100

DATE: 10/10/10

SCALE: AS SHOWN

BY: [Signature]

CHECKED BY: [Signature]

APPROVED BY: [Signature]




KEYNOTES

1. ALL DIMENSIONS ARE TO FACE UNLESS OTHERWISE NOTED.
2. ALL WALLS ARE 12" THICK UNLESS OTHERWISE NOTED.
3. ALL DOORS ARE 36" WIDE BY 80" HIGH UNLESS OTHERWISE NOTED.
4. ALL WINDOWS ARE 48" WIDE BY 72" HIGH UNLESS OTHERWISE NOTED.
5. ALL FLOORS ARE 4" THICK CONCRETE UNLESS OTHERWISE NOTED.
6. ALL CEILING ARE 8" THICK CONCRETE UNLESS OTHERWISE NOTED.
7. ALL ROOF ARE 6" THICK CONCRETE UNLESS OTHERWISE NOTED.
8. ALL FOUNDATION ARE 18" THICK CONCRETE UNLESS OTHERWISE NOTED.
9. ALL EXTERIOR WALLS ARE 12" THICK CONCRETE UNLESS OTHERWISE NOTED.
10. ALL INTERIOR WALLS ARE 12" THICK CONCRETE UNLESS OTHERWISE NOTED.
11. ALL PARTITIONS ARE 12" THICK CONCRETE UNLESS OTHERWISE NOTED.
12. ALL STAIRS ARE 10" THICK CONCRETE UNLESS OTHERWISE NOTED.
13. ALL ELEVATIONS ARE TO FACE UNLESS OTHERWISE NOTED.
14. ALL FINISHES ARE TO FACE UNLESS OTHERWISE NOTED.
15. ALL MATERIALS ARE TO BE AS SHOWN UNLESS OTHERWISE NOTED.
16. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE BUILDING CODES AND SPECIFICATIONS.
17. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE MANUFACTURER'S INSTRUCTIONS.
18. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE NATIONAL ELECTRICAL CODE.
19. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE NATIONAL MECHANICAL CODE.
20. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE NATIONAL PLUMBING CODE.
21. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE NATIONAL FIRE PROTECTION ASSOCIATION (NFPA) CODES.
22. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL BUILDING CONVENTIONS (IBC).
23. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL RESIDENTIAL CODE CONVENTIONS (IRCC).
24. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL ENERGY CONSERVATION CODE (IECC).
25. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL GREENING CODE (IGCC).
26. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL SUSTAINABLE DESIGN AND CONSTRUCTION (ISDC) CODES.
27. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL WELL-BEING AND PRODUCTIVITY (IWP) CODES.
28. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL QUALITY MANAGEMENT (IQM) CODES.
29. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL RISK MANAGEMENT (IRM) CODES.
30. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL SAFETY AND HEALTH (ISH) CODES.
31. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL ENVIRONMENTAL MANAGEMENT (IEM) CODES.
32. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL SOCIAL RESPONSIBILITY (ISR) CODES.
33. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL GOVERNANCE (IG) CODES.
34. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL LEADERSHIP (IL) CODES.
35. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL INNOVATION (II) CODES.
36. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL KNOWLEDGE (IK) CODES.
37. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL SKILLS (IS) CODES.
38. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL MENTORSHIP (IM) CODES.
39. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL NETWORKING (IN) CODES.
40. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL COACHING (IC) CODES.
41. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL MENTORING (IM) CODES.
42. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL NETWORKING (IN) CODES.
43. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL COACHING (IC) CODES.
44. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL MENTORING (IM) CODES.
45. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL NETWORKING (IN) CODES.
46. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL COACHING (IC) CODES.
47. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL MENTORING (IM) CODES.
48. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL NETWORKING (IN) CODES.
49. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL COACHING (IC) CODES.
50. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL MENTORING (IM) CODES.

PLANNOTES

1. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE BUILDING CODES AND SPECIFICATIONS.
2. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE MANUFACTURER'S INSTRUCTIONS.
3. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE NATIONAL ELECTRICAL CODE.
4. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE NATIONAL MECHANICAL CODE.
5. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE NATIONAL PLUMBING CODE.
6. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE NATIONAL FIRE PROTECTION ASSOCIATION (NFPA) CODES.
7. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL BUILDING CONVENTIONS (IBC).
8. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL RESIDENTIAL CODE CONVENTIONS (IRCC).
9. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL ENERGY CONSERVATION CODE (IECC).
10. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL GREENING CODE (IGCC).
11. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL SUSTAINABLE DESIGN AND CONSTRUCTION (ISDC) CODES.
12. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL WELL-BEING AND PRODUCTIVITY (IWP) CODES.
13. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL QUALITY MANAGEMENT (IQM) CODES.
14. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL RISK MANAGEMENT (IRM) CODES.
15. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL SAFETY AND HEALTH (ISH) CODES.
16. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL ENVIRONMENTAL MANAGEMENT (IEM) CODES.
17. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL SOCIAL RESPONSIBILITY (ISR) CODES.
18. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL GOVERNANCE (IG) CODES.
19. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL LEADERSHIP (IL) CODES.
20. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL INNOVATION (II) CODES.
21. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL KNOWLEDGE (IK) CODES.
22. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL SKILLS (IS) CODES.
23. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL MENTORSHIP (IM) CODES.
24. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL NETWORKING (IN) CODES.
25. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL COACHING (IC) CODES.
26. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL MENTORING (IM) CODES.
27. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL NETWORKING (IN) CODES.
28. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL COACHING (IC) CODES.
29. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL MENTORING (IM) CODES.
30. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL NETWORKING (IN) CODES.
31. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL COACHING (IC) CODES.
32. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL MENTORING (IM) CODES.
33. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL NETWORKING (IN) CODES.
34. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL COACHING (IC) CODES.
35. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL MENTORING (IM) CODES.
36. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL NETWORKING (IN) CODES.
37. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL COACHING (IC) CODES.
38. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL MENTORING (IM) CODES.
39. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL NETWORKING (IN) CODES.
40. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL COACHING (IC) CODES.
41. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL MENTORING (IM) CODES.
42. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL NETWORKING (IN) CODES.
43. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL COACHING (IC) CODES.
44. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL MENTORING (IM) CODES.
45. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL NETWORKING (IN) CODES.
46. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL COACHING (IC) CODES.
47. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL MENTORING (IM) CODES.
48. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL NETWORKING (IN) CODES.
49. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL COACHING (IC) CODES.
50. ALL WORK IS TO BE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE INTERNATIONAL MENTORING (IM) CODES.



BASEMENT PLAN

SCALE: 1/8" = 1'-0"

DATE: 10/10/10

BY: [Signature]

CHECKED BY: [Signature]

APPROVED BY: [Signature]

Flanagan
ARCHITECTS, P.C.
1000 UNIVERSITY AVENUE, SUITE 100
ANN ARBOR, MI 48106
TEL: (313) 937-2441

FOR THE ARCHITECT'S INFORMATION:
THIS PLAN IS THE PROPERTY OF FLANAGAN ARCHITECTS, P.C. AND IS NOT TO BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM, WITHOUT THE WRITTEN PERMISSION OF FLANAGAN ARCHITECTS, P.C.

CULLEN RESIDENCE

13 KENNEDY STREET
ANN ARBOR, MI 48106

ROOF PLAN

DATE: 08/14/14

SCALE: AS SHOWN

NO.	DESCRIPTION
1	SEE KEYNOTES
2	SEE KEYNOTES
3	SEE KEYNOTES
4	SEE KEYNOTES
5	SEE KEYNOTES
6	SEE KEYNOTES
7	SEE KEYNOTES
8	SEE KEYNOTES
9	SEE KEYNOTES
10	SEE KEYNOTES
11	SEE KEYNOTES
12	SEE KEYNOTES
13	SEE KEYNOTES
14	SEE KEYNOTES
15	SEE KEYNOTES
16	SEE KEYNOTES
17	SEE KEYNOTES
18	SEE KEYNOTES
19	SEE KEYNOTES
20	SEE KEYNOTES
21	SEE KEYNOTES
22	SEE KEYNOTES
23	SEE KEYNOTES
24	SEE KEYNOTES
25	SEE KEYNOTES
26	SEE KEYNOTES
27	SEE KEYNOTES
28	SEE KEYNOTES
29	SEE KEYNOTES
30	SEE KEYNOTES
31	SEE KEYNOTES
32	SEE KEYNOTES
33	SEE KEYNOTES
34	SEE KEYNOTES
35	SEE KEYNOTES
36	SEE KEYNOTES
37	SEE KEYNOTES
38	SEE KEYNOTES
39	SEE KEYNOTES
40	SEE KEYNOTES
41	SEE KEYNOTES
42	SEE KEYNOTES
43	SEE KEYNOTES
44	SEE KEYNOTES
45	SEE KEYNOTES
46	SEE KEYNOTES
47	SEE KEYNOTES
48	SEE KEYNOTES
49	SEE KEYNOTES
50	SEE KEYNOTES
51	SEE KEYNOTES
52	SEE KEYNOTES
53	SEE KEYNOTES
54	SEE KEYNOTES
55	SEE KEYNOTES
56	SEE KEYNOTES
57	SEE KEYNOTES
58	SEE KEYNOTES
59	SEE KEYNOTES
60	SEE KEYNOTES
61	SEE KEYNOTES
62	SEE KEYNOTES
63	SEE KEYNOTES
64	SEE KEYNOTES
65	SEE KEYNOTES
66	SEE KEYNOTES
67	SEE KEYNOTES
68	SEE KEYNOTES
69	SEE KEYNOTES
70	SEE KEYNOTES
71	SEE KEYNOTES
72	SEE KEYNOTES
73	SEE KEYNOTES
74	SEE KEYNOTES
75	SEE KEYNOTES
76	SEE KEYNOTES
77	SEE KEYNOTES
78	SEE KEYNOTES
79	SEE KEYNOTES
80	SEE KEYNOTES
81	SEE KEYNOTES
82	SEE KEYNOTES
83	SEE KEYNOTES
84	SEE KEYNOTES
85	SEE KEYNOTES
86	SEE KEYNOTES
87	SEE KEYNOTES
88	SEE KEYNOTES
89	SEE KEYNOTES
90	SEE KEYNOTES
91	SEE KEYNOTES
92	SEE KEYNOTES
93	SEE KEYNOTES
94	SEE KEYNOTES
95	SEE KEYNOTES
96	SEE KEYNOTES
97	SEE KEYNOTES
98	SEE KEYNOTES
99	SEE KEYNOTES
100	SEE KEYNOTES



KEYNOTES

1. SEE KEYNOTES

2. SEE KEYNOTES

3. SEE KEYNOTES

4. SEE KEYNOTES

5. SEE KEYNOTES

6. SEE KEYNOTES

7. SEE KEYNOTES

8. SEE KEYNOTES

9. SEE KEYNOTES

10. SEE KEYNOTES

11. SEE KEYNOTES

12. SEE KEYNOTES

13. SEE KEYNOTES

14. SEE KEYNOTES

15. SEE KEYNOTES

16. SEE KEYNOTES

17. SEE KEYNOTES

18. SEE KEYNOTES

19. SEE KEYNOTES

20. SEE KEYNOTES

21. SEE KEYNOTES

22. SEE KEYNOTES

23. SEE KEYNOTES

24. SEE KEYNOTES

25. SEE KEYNOTES

26. SEE KEYNOTES

27. SEE KEYNOTES

28. SEE KEYNOTES

29. SEE KEYNOTES

30. SEE KEYNOTES

31. SEE KEYNOTES

32. SEE KEYNOTES

33. SEE KEYNOTES

34. SEE KEYNOTES

35. SEE KEYNOTES

36. SEE KEYNOTES

37. SEE KEYNOTES

38. SEE KEYNOTES

39. SEE KEYNOTES

40. SEE KEYNOTES

41. SEE KEYNOTES

42. SEE KEYNOTES

43. SEE KEYNOTES

44. SEE KEYNOTES

45. SEE KEYNOTES

46. SEE KEYNOTES

47. SEE KEYNOTES

48. SEE KEYNOTES

49. SEE KEYNOTES

50. SEE KEYNOTES

51. SEE KEYNOTES

52. SEE KEYNOTES

53. SEE KEYNOTES

54. SEE KEYNOTES

55. SEE KEYNOTES

56. SEE KEYNOTES

57. SEE KEYNOTES

58. SEE KEYNOTES

59. SEE KEYNOTES

60. SEE KEYNOTES

61. SEE KEYNOTES

62. SEE KEYNOTES

63. SEE KEYNOTES

64. SEE KEYNOTES

65. SEE KEYNOTES

66. SEE KEYNOTES

67. SEE KEYNOTES

68. SEE KEYNOTES

69. SEE KEYNOTES

70. SEE KEYNOTES

71. SEE KEYNOTES

72. SEE KEYNOTES

73. SEE KEYNOTES

74. SEE KEYNOTES

75. SEE KEYNOTES

76. SEE KEYNOTES

77. SEE KEYNOTES

78. SEE KEYNOTES

79. SEE KEYNOTES

80. SEE KEYNOTES

81. SEE KEYNOTES

82. SEE KEYNOTES

83. SEE KEYNOTES

84. SEE KEYNOTES

85. SEE KEYNOTES

86. SEE KEYNOTES

87. SEE KEYNOTES

88. SEE KEYNOTES

89. SEE KEYNOTES

90. SEE KEYNOTES

91. SEE KEYNOTES

92. SEE KEYNOTES

93. SEE KEYNOTES

94. SEE KEYNOTES

95. SEE KEYNOTES

96. SEE KEYNOTES

97. SEE KEYNOTES

98. SEE KEYNOTES

99. SEE KEYNOTES

100. SEE KEYNOTES

GENERAL ROOF NOTES

1. ROOF SHALL BE AS SHOWN UNLESS OTHERWISE NOTED.

2. ROOF SHALL BE 2" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

3. ROOF SHALL BE 1/2" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

4. ROOF SHALL BE 1/4" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

5. ROOF SHALL BE 1/8" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

6. ROOF SHALL BE 1/16" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

7. ROOF SHALL BE 1/32" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

8. ROOF SHALL BE 1/64" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

9. ROOF SHALL BE 1/128" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

10. ROOF SHALL BE 1/256" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

11. ROOF SHALL BE 1/512" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

12. ROOF SHALL BE 1/1024" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

13. ROOF SHALL BE 1/2048" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

14. ROOF SHALL BE 1/4096" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

15. ROOF SHALL BE 1/8192" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

16. ROOF SHALL BE 1/16384" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

17. ROOF SHALL BE 1/32768" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

18. ROOF SHALL BE 1/65536" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

19. ROOF SHALL BE 1/131072" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

20. ROOF SHALL BE 1/262144" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

21. ROOF SHALL BE 1/524288" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

22. ROOF SHALL BE 1/1048576" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

23. ROOF SHALL BE 1/2097152" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

24. ROOF SHALL BE 1/4194304" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

25. ROOF SHALL BE 1/8388608" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

26. ROOF SHALL BE 1/16777216" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

27. ROOF SHALL BE 1/33554432" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

28. ROOF SHALL BE 1/67108864" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

29. ROOF SHALL BE 1/134217728" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

30. ROOF SHALL BE 1/268435456" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

31. ROOF SHALL BE 1/536870912" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

32. ROOF SHALL BE 1/1073741824" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

33. ROOF SHALL BE 1/2147483648" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

34. ROOF SHALL BE 1/4294967296" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

35. ROOF SHALL BE 1/8589934592" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

36. ROOF SHALL BE 1/17179869184" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

37. ROOF SHALL BE 1/34359738368" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

38. ROOF SHALL BE 1/68719476736" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

39. ROOF SHALL BE 1/137438953472" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

40. ROOF SHALL BE 1/274877906944" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

41. ROOF SHALL BE 1/549755813888" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

42. ROOF SHALL BE 1/1099511627776" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

43. ROOF SHALL BE 1/2199023255552" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

44. ROOF SHALL BE 1/4398046511104" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

45. ROOF SHALL BE 1/8796093022208" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

46. ROOF SHALL BE 1/17592186044416" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

47. ROOF SHALL BE 1/35184372088832" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

48. ROOF SHALL BE 1/70368744177664" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

49. ROOF SHALL BE 1/140737488355328" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

50. ROOF SHALL BE 1/281474976710656" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

51. ROOF SHALL BE 1/562949953421312" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

52. ROOF SHALL BE 1/1125899906842624" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

53. ROOF SHALL BE 1/2251799813685248" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

54. ROOF SHALL BE 1/4503599627370496" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

55. ROOF SHALL BE 1/9007199254740992" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

56. ROOF SHALL BE 1/18014398509481984" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

57. ROOF SHALL BE 1/36028797018963968" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

58. ROOF SHALL BE 1/72057594037927936" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

59. ROOF SHALL BE 1/144115188075855872" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

60. ROOF SHALL BE 1/288230376151711744" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

61. ROOF SHALL BE 1/576460752303423488" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

62. ROOF SHALL BE 1/1152921504606846976" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

63. ROOF SHALL BE 1/2305843009213693952" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

64. ROOF SHALL BE 1/4611686018427387904" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

65. ROOF SHALL BE 1/9223372036854775808" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

66. ROOF SHALL BE 1/18446744073709551616" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

67. ROOF SHALL BE 1/36893488147419103232" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

68. ROOF SHALL BE 1/73786976294838206464" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

69. ROOF SHALL BE 1/147573952589676412928" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

70. ROOF SHALL BE 1/295147905179352825856" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

71. ROOF SHALL BE 1/590295810358705651712" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

72. ROOF SHALL BE 1/1180591620717411303424" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

73. ROOF SHALL BE 1/2361183241434822606848" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

74. ROOF SHALL BE 1/4722366482869645213696" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

75. ROOF SHALL BE 1/9444732965739290427392" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

76. ROOF SHALL BE 1/18889465931478580854784" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

77. ROOF SHALL BE 1/37778931862957161709568" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

78. ROOF SHALL BE 1/75557863725914323419136" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

79. ROOF SHALL BE 1/151115727451828646838272" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

80. ROOF SHALL BE 1/302231454903657293676544" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

81. ROOF SHALL BE 1/604462909807314587353088" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

82. ROOF SHALL BE 1/1208925819614629174706176" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

83. ROOF SHALL BE 1/2417851639229258349412352" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

84. ROOF SHALL BE 1/4835703278458516698824704" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

85. ROOF SHALL BE 1/9671406556917033397649408" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

86. ROOF SHALL BE 1/19342813113834066795298816" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

87. ROOF SHALL BE 1/38685626227668133590597632" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

88. ROOF SHALL BE 1/77371252455336267181195264" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

89. ROOF SHALL BE 1/154742504910672534362390528" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

90. ROOF SHALL BE 1/309485009821345068724781056" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

91. ROOF SHALL BE 1/618970019642690137449562112" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

92. ROOF SHALL BE 1/1237940039285380274899124224" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

93. ROOF SHALL BE 1/2475880078570760549798248448" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

94. ROOF SHALL BE 1/4951760157141521099596488896" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

95. ROOF SHALL BE 1/9903520314283042199193977792" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

96. ROOF SHALL BE 1/19807040628566084398387955584" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

97. ROOF SHALL BE 1/39614081257132168796775911168" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

98. ROOF SHALL BE 1/79228162514264337593551822336" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

99. ROOF SHALL BE 1/158456325028528675187103644672" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

100. ROOF SHALL BE 1/316912650057057350374207289344" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.

LEGEND

1. SEE KEYNOTES

2. SEE KEYNOTES

3. SEE KEYNOTES

4. SEE KEYNOTES

5. SEE KEYNOTES

6. SEE KEYNOTES

7. SEE KEYNOTES

8. SEE KEYNOTES

9. SEE KEYNOTES

10. SEE KEYNOTES

11. SEE KEYNOTES

12. SEE KEYNOTES

13. SEE KEYNOTES

14. SEE KEYNOTES

15. SEE KEYNOTES

16. SEE KEYNOTES

17. SEE KEYNOTES

18. SEE KEYNOTES

19. SEE KEYNOTES

20. SEE KEYNOTES

21. SEE KEYNOTES

22. SEE KEYNOTES

23. SEE KEYNOTES

24. SEE KEYNOTES

25. SEE KEYNOTES

26. SEE KEYNOTES

27. SEE KEYNOTES

28. SEE KEYNOTES

29. SEE KEYNOTES

30. SEE KEYNOTES

31. SEE KEYNOTES

32. SEE KEYNOTES

33. SEE KEYNOTES

34. SEE KEYNOTES

35. SEE KEYNOTES

36. SEE KEYNOTES

37. SEE KEYNOTES

38. SEE KEYNOTES

39. SEE KEYNOTES

40. SEE KEYNOTES

41. SEE KEYNOTES

42. SEE KEYNOTES

43. SEE KEYNOTES

44. SEE KEYNOTES

45. SEE KEYNOTES

46. SEE KEYNOTES

47. SEE KEYNOTES

48. SEE KEYNOTES

49. SEE KEYNOTES

50. SEE KEYNOTES

51. SEE KEYNOTES

52. SEE KEYNOTES

53. SEE KEYNOTES

54. SEE KEYNOTES

55. SEE KEYNOTES

56. SEE KEYNOTES

57. SEE KEYNOTES

58. SEE KEYNOTES

59. SEE KEYNOTES

60. SEE KEYNOTES

61. SEE KEYNOTES

62. SEE KEYNOTES

63. SEE KEYNOTES

64. SEE KEYNOTES

65. SEE KEYNOTES

66. SEE KEYNOTES

67. SEE KEYNOTES

68. SEE KEYNOTES

69. SEE KEYNOTES

70. SEE KEYNOTES

71. SEE KEYNOTES

72. SEE KEYNOTES

73. SEE KEYNOTES

74. SEE KEYNOTES

75. SEE KEYNOTES

76. SEE KEYNOTES

77. SEE KEYNOTES

78. SEE KEYNOTES

79. SEE KEYNOTES

80. SEE KEYNOTES

81. SEE KEYNOTES

82. SEE KEYNOTES

83. SEE KEYNOTES

84. SEE KEYNOTES

85. SEE KEYNOTES

86. SEE KEYNOTES

87. SEE KEYNOTES

88. SEE KEYNOTES

89. SEE KEYNOTES

90. SEE KEYNOTES

91. SEE KEYNOTES

92. SEE KEYNOTES

93. SEE KEYNOTES

94. SEE KEYNOTES

95. SEE KEYNOTES


96. SEE KEYNOTES

97. SEE KEYNOTES

98. SEE KEYNOTES

99. SEE KEYNOTES

100. SEE KEYNOTES




ROOF PLAN

DATE: 08/14/14

NORTH




12 HESBERT ST.



LEFT SIDE ELEV.

LOWER ROOF TO
PIPELINE-UP SCALE
OF ADDITION.


12 HESKETH ST.



RIGHT SIDE ELEV.



12 HESKETH ST.



REAR - ELEV.



1 THE MARYLAND-NATIONAL CAPITAL PARK AND PLANNING COMMISSION
 2
 3
 4 - - - - - X
 5 HISTORIC AREA WORK PERMIT - : HPC Case No. 35/14-007A-16A
 6 7272 Wisconsin Avenue :
 7 - - - - - X
 8 PRELIMINARY CONSULTATION - :
 9 3807 Bradley Lane :
 10 - - - - - :
 11 PRELIMINARY CONSULTATION - :
 12 12 Hesketh Street :
 13 - - - - - :
 14
 15

A meeting in the above-entitled matter was held on
 December 7, 2016, commencing at 7:36 p.m., in the MRO
 Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland
 20910, before:

COMMITTEE MEMBERS

- Bill Kirwan, Chair
- Sandra Heiler
- Brian Carroll
- Marsha Barnes
- Kenneth Firestone
- Kathleen Legg
- Richard Arkin
- Eliza Voigt

1 And I think that the, you know, it's subtle, but
2 I think the really high note for this, for me, is bringing
3 the corners of the building back on both sides. Keeping
4 that flair, I understand what they did with the addition
5 before, they tried to keep it going all the way down
6 because they thought that was picking up the queues of the
7 house, and I just think that was not right so thank you
8 for putting the corners back. I think that really is a
9 very nice touch. So, thank you. I'm really in support of
10 this. I'm looking forward to seeing it.

11 MR. KIRWAN: So, I think you've heard some
12 unanimous support for the project, so I think you're ready
13 to come back with a HAWP, and we look forward to seeing
14 you come back then.

15 MR. CUNNINGHAM: Thank you all, it's been a
16 pleasure.

17 MR. KIRWAN: Great. Thank you. All right, the
18 next preliminary consultation is Case II.B at 12 Hesketh
19 Street in Chevy Chase. Do we have a Staff Report?

20 MR. KYNE: Yes, we do. This is 12 Hesketh
21 Street in Chevy Chase. A contributing resource within the
22 Chevy Chase Village Historic District. Dutch Colonial
23 style, circa 1916 to 1927. The proposal on this case is
24 to remove an existing two-story rear addition, construct a
25 new two-story rear addition, replace the historic windows

1 with new windows, restore/extend the existing driveway to
2 the existing rear garage. And remove one 7 inch dbh
3 Sycamore tree.

4 Again, I'm going to walk you around the
5 property, starting at the left side. I do want to point
6 out that, if you look at the screen, this is part of an
7 existing addition which will be removed. This is the
8 existing rear addition, with a gambrel roof to reflect the
9 Dutch Colonial style of the main house.

10 MR. KIRWAN: That's a non-historic addition?

11 MR. KYNE: That's right. And also, it's an
12 extension of this addition that I showed you previously.
13 Looking at the house from the left side of the rear yard
14 as viewed from the street. And then this will be the rear
15 of the left side as viewed from the street. And this is
16 the existing garage at the rear right side, which the
17 driveway will be extended to. And just a couple photos of
18 the existing windows which appear to be historic. And I
19 have the plans if we need to refer to them.

20 The applicable guidelines in this case are the
21 Chevy Chase Village Historic District Guidelines, and the
22 Secretary of Interior Standards for Rehabilitation. And,
23 Staff asks the Commission's guidance regarding the
24 following: so for the addition, scale and massing. The
25 proposed rear addition is much larger than the existing

1 rear addition, appearing to double the size of the
2 historic house. Style. The existing elevation has a
3 gambrel roof, which is compatible with the Dutch Colonial
4 style of the historic house, while the proposed new
5 addition has a hipped roof, giving it a four square like
6 appearance when viewed from the rear. The ridge line of
7 the proposed new addition is slightly lower than the
8 historic house. However, in this case, Staff suggests
9 that the ridge line is not low enough to make the addition
10 differential to the historic house.

11 And fenestration. The fenestration of the
12 historic house is symmetrical and Staff thought while that
13 of the proposed addition is not. There are also paired
14 windows on all the elevations of the proposed addition,
15 but they are absent from the historic house. Chimney.
16 The proposed chimney on the left elevation appears to have
17 a cultured stone veneer, but I cannot confirm that's what
18 it appears to be. In the past, the Commission has found
19 that cultured stone veneer is generally incompatible for
20 features that are visible from the public right-of-way.

21 The porch. Staff asks for the Commission's
22 guidance regarding the proposed covered porch with
23 standing seam metal roof on the left elevation of the
24 proposed new addition. And brackets. The proposed
25 brackets on the rear/side elevations of the proposed

1 addition are incompatible with the historic house, as
2 decorative brackets are not a common features on Dutch
3 Colonial style houses.

4 And, on to window replacement. The proposed
5 replacement windows will be generally consistent with the
6 existing windows. With six-over-six and 4-lite casement
7 windows being replaced with the same. Where the existing
8 addition/wraparound will be removed from the right
9 elevation of the historic house, and that was the addition
10 I had pointed out earlier. The applicant proposes to
11 install or perhaps restore, you will have to ask them,
12 three new 4-lite casement windows to match the existing
13 window on the same elevation.

14 Staff visited the property and many, if not all
15 of the windows, appear to be original. As we saw in the
16 photographs. The Guidelines instruct the Commission to
17 review window replacement that is visible from the public
18 right-of-way with moderate scrutiny. And, Staff asks for
19 the Commission's guidance regarding the proposed window
20 replacement, and any specific requirements for approval.
21 And, as an example, in the past we had required that the
22 applicants matched the dimensions of the existing windows.

23 And driveway. The Guidelines instruct the
24 Commission to review driveways with lenient scrutiny,
25 except where trees will be impacted. And according to the

1 site plan, one 4 inch dbh tree will be removed to
2 accommodate the proposed driveway extension. The removal
3 of a 4 inch dbh tree is outside of your purview, and is
4 unlikely to impact the park-like character of the historic
5 district. Other tree removals to look at. The applicant
6 proposes to remove one 7 inch dbh Sycamore tree to
7 accommodate the proposed new addition. And the proposed
8 tree removal is unlikely to detract from the subject
9 property or surrounding district, but in accordance with
10 the Guidelines, the applicant should adhere to the Village
11 urban forest ordinance.

12 In this case, we did receive public comments
13 from the neighbors at 10 Hesketh Street. The comments
14 were in opposition, generally, and they were -- they
15 largely had a concern with the porch, and they also voiced
16 concern about two American Elm trees. One which is 42.2
17 inches in diameter, and the other which is 37.1 inches in
18 diameter that may be impacted by the proposed project.
19 And the trees in question, according to the neighbor, are
20 at Hesketh, or at 10 Hesketh, and/or straddle 10 Hesketh
21 and the subject property. At the HAWP stage, the
22 Commission might add a condition requiring that the
23 applicants have a tree protection plan in place prior to
24 beginning their project.

25 And then, finally, LAP comments. As summarized

1 by Staff, the LAP generally concurs with Staff, but is
2 somewhat less concerned with the fenestration pattern of
3 the rear addition. The LAP concurs with Staff that the
4 proposed addition is substantially larger than the
5 existing addition, but notes that it is at the rear of the
6 property. The LAP has stated that from the drawings, the
7 addition appears to be hidden when viewed from the street,
8 and therefore, it would seem to have no adverse impact on
9 streetscape or open park-like setting of the Village,
10 which has been an issue with other projects. The LAP
11 hopes the final design can be sensitive to adjacent
12 properties. The proposed tree removal must be handled
13 separately for the Village.

14 And, with that, I recommend that the applicants
15 make any revisions and return with a HAWP based upon the
16 recommendations. And I'll take any questions you have for
17 me.

18 MR. KRIWAN: Thank you. Michael, I have one
19 question. Is it clear in the Staff Report, what is the
20 material for the window replacements? Is it wood or is
21 it, or do we not yet know?

22 MR. KYNE: I believe that they are proposing
23 wood windows, wood SDL windows to replace the original
24 windows, or we can confirm that with the applicants.

25 MR. CARROLL: Michael, do you have an image that

1 shows the two trees in question, the 37 and 42 inch?

2 MR. KYNE: I do not. These comments were ones
3 that were received within the last day or two. I did
4 forward the comments to you as a Commission, but I did not
5 have a chance to go back out to the property and take
6 photographs of those trees.

7 MS. BARNES: Michael, do you know what the
8 square footage is of the existing house and what the
9 square footage of the proposed addition is, by chance?

10 MR. KYNE: I do not have the numbers. I do
11 believe the numbers were provided. But again, this might
12 be something --

13 MS. BARNES: For the applicant? And, the other
14 question, on the driveway, was there, did I miss it, was
15 there information about the material to be used for the
16 driveway?

17 MR. KYNE: I believe the material proposed is
18 gravel extending what is or was there previously. And
19 again, we can confirm that.

20 MS. BARNES: Thank you.

21 MS. HEILER: Michael, what's the material on the
22 house? In the information it says that it compliments,
23 the addition materials compliment the house. Are they the
24 same as the house, and is it wood?

25 MR. KYNE: That is something that we should,

1 again, address to the applicants, because they have it
2 written like proposed to remove the existing wooden siding
3 from the front of the house, along with the corner coins,
4 and I'm not sure if they revised their proposal consistent
5 with my recommendation to not propose that, because it's
6 unlikely to be approved. I know at one point they had one
7 iteration of the project, they were proposing Hardie
8 shingles on the second floor, and Hardie siding on the
9 first. And, I believe now in this iteration that it is
10 all Hardi on both floors. Does that answer your question?

11 MR. KIRWAN: Any other questions for Staff? If
12 not, we invite the applicant to please come forward. We
13 can give you seven minutes for your testimony, and anyone
14 who speaks should state their name for the record before
15 they do.

16 MR. FLANAGAN: Good evening, my name is Tom
17 Flanagan, I'm the architect of the project. And next to
18 me is Jason Gagen, who is the project architect. I think
19 the summary, real quick summary of this is, we're taking
20 the existing structure that has an addition to it, and
21 removing it a series of additions that have been done over
22 time. There's on the right hand side, then one to the
23 rear. So we've kind of taken it back to the basic house
24 that's already there. The addition that we're proposing,
25 we have seven -- it's all in the back, we're not doing

1 anything to the front with the exception of window
2 replacement -- and then we set in on both sides in the
3 rear, and our addition is completely to the rear of the
4 house but set in. And it's also lower in scale. The
5 ridgeline is matching the existing house. We're not going
6 higher in any way.

7 We worked with Staff. We did, we were trying to
8 do some work in the beginning to the front of the house.
9 We just talked briefly about some siding. About some ship
10 lap siding that is flush, kind of a water issue, it's like
11 no siding we've ever been seen before. It's not really
12 siding. I'm not sure what it is. The coins in the wood,
13 we're leaving all that. We're not doing anything with it
14 at this time, so it's a non-issue for the front of the
15 house. All the windows in the front will be wood, SDL
16 replacement windows with the same mutin patterns that are
17 present now there. And, we have worked with Staff, to go
18 through some comments. We kind of addressed a lot of
19 those. Take no exception with most of them. And looking
20 for a little bit of direction on a couple of items that
21 are identified.

22 MR. KIRWAN: Thank you. Any questions for the
23 applicant?

24 MS. BARNES: I would address to you the question
25 that I put to the Staff, could you let me know the square

1 footage of the original house, and then what is proposed
2 for the addition? And you just noted that the addition
3 will be inset from the original house, and how much of an
4 inset are we talking about? I'm curious about materials
5 for the drive, and I believe there is a sort of stone
6 veneer chimney proposed, and I wanted to check on that
7 because that's something that's --

8 MR. FLANAGAN: We were proposing a stone
9 chimney. I don't know where the stone veneer came from,
10 or the fake stone. We were never proposing that.

11 MS. BARNES: Maybe it was in the drawing. That
12 it conveyed that sense.

13 MR. FLANAGAN: Maybe the graphic looked like it,
14 but it is a real stone chimney.

15 MS. BARNES: It's real stone?

16 MR. FLANAGAN: Yes, it is.

17 MS. BARNES: Well, that's very good news to
18 hear.

19 MR. GAGEN: Jason Gagen with Flanagan
20 Architects. The existing square footage, would you like
21 the whole house or just the footprint?

22 MS. BARNES: Footprint.

23 MR. GAGEN: So the first floor footprint is 1179
24 square feet currently. That includes the addition. We
25 are proposing to add 439 square feet to that original

1 footprint, for a total of 1618 square feet. First floor.

2 MS. BARNES: Can you separate out the original
3 house from its additions so that chunk without the old
4 additions?

5 MR. GAGEN: I would need to do a little math for
6 you here. If you give me a couple of moments, I'll do
7 that for you.

8 MS. BARNES: Thank you. And the issue of inset
9 and materials perhaps can be -- while you're doing your
10 math, is somebody else able to do that one? Sure.

11 MR. GAGEN: The inset is two feet on either side
12 of the existing house.

13 MS. BARNES: Thank you.

14 MR. GAGEN: The driveway material, you asked
15 that. We were proposing a concrete driveway.

16 MR. ARKIN: Would you be replacing the asphalt
17 or would you have a change in material on the driveway?

18 MR. GAGEN: I'll defer to the owner for that
19 one. I assume we would probably do concrete the entire
20 length.

21 MR. CULLEN: Neil Cullen, Chevy Chase,
22 homeowner. I want it to be consistent with the house.

23 MR. FLANAGAN: So, no change in material.
24 Concrete the entire, from the front to the garage.

25 MR. ARKIN: Could you discuss the condition of

1 the windows and why it is you want to replace them?

2 MR. FLANAGAN: They're not insulated glass.
3 They're for energy efficiency. For ease of operation,
4 they've been painted for many, many years, and they don't
5 operate very well.

6 MR. ARKIN: Thank you.

7 MS. VOIGT: And, are you replacing the windows
8 in the front of the house as well, did you mention?

9 MR. FLANAGAN: We are planning to replace the
10 windows in the front with wood SDL, yes, to match
11 proportions.

12 MS. VOIGT: And, I just had another quick
13 question. Just looking at the elevation, No. 21, so talk
14 to me -- so looking at that roofline, so you have the
15 Dutch Colonial roof and then the addition roof is, it's
16 just coming right off the --

17 MR. FLANAGAN: There is a roofline in that set
18 of drawings, I believe, as well. So we had a hipped roof
19 that failed. So the lower portion of that is the existing
20 Dutch Colonial with a hipped roof that comes off the -- we
21 looked at several other forms to continue the Dutch
22 Colonial, and we thought that this was the most
23 appropriate, and being respectful to the existing
24 structure. To do a side elevation, that is sitting back
25 there.

1 And one option is to do the big brother, little
2 brother, which is very disruptive to the existing historic
3 structure. And then the other is to do identical twin
4 next to it, which seems like it was somewhat inappropriate
5 as well to try to match and have an old and new side-by-
6 side. It didn't feel like those were really compatible
7 solutions to the resources out there. By setting it in,
8 doing a hipped roof, we felt that the eaves would be the
9 main portion of the roof you would see from the ground,
10 and because the buildings on both sides go the same depth
11 or deeper on the property, there's really no place to even
12 understand the roof, honestly. We didn't want gables that
13 would compete with the Gambrel form. We thought that that
14 would be the lowest profile roof to provide the abutting
15 form to the historic structure.

16 MR. GAGEN: So, going back to your square
17 footage question. The historical house is 821 square
18 feet. Our proposed addition would be 801 square feet.

19 MS. BARNES: Thank you.

20 MS. HEILER: So, is it your view that none of
21 the addition, because it is directly behind the house,
22 will be visible in any way from the street?

23 MR. FLANAGAN: I don't know that I said none of
24 it. But very limited. We pushed it back in two feet on
25 each side. There's a very narrow side yard. I think we

1 had 12 feet on the side yard on the right hand side. Do
2 you know what is on the left? It's like seven.

3 MR. GAGEN: It's like seven, yes.

4 MR. FLANAGAN: It's like seven feet is the side
5 yard on the left hand side. So you're not seeing very --
6 from the street you're not seeing very far down the
7 driveway. There may be a photo in here. Yeah, there was
8 a photo showing the trees of all the driveway as well on
9 the right hand side, which would limit your view to the
10 rear on that side of the house. The left side of the
11 house has the one-story porch, and we are continuing that
12 porch in our addition which would also help to conceal the
13 body of the addition at the rear as well.

14 MR. KIRWAN: Any other questions for the
15 applicant? I guess not. I think we have testimony from a
16 speaker.

17 MR. GAGEN: If I may add? There was a question
18 about the trees. We have a graphic showing the location
19 of those trees, if that will be helpful to you guys. Do
20 you want to pass it around or show it to you.

21 MR. KIRWAN: That's fine. Yeah, why don't you
22 pass it around.

23 MR. GAGEN: This is the porch. And this is our
24 proposed addition. And this is the closer of the two Elms
25 that were in question. It's 29 feet from our porch, and

1 approximately 35 feet from the addition. And 44 feet
2 here.

3 MR. CARROLL: I'm sorry, could you point at
4 them, even approximately?

5 MR. GAGEN: So, these are the two Elms here.
6 Elm 1 and Elm 2. This Elm is approximately 29 feet from
7 the porch here. And this one, I believe, was 44 is what I
8 had. The Chevy Chase arborist had no concern with those
9 trees when he visited the site.

10 MR. KIRWAN: Any other questions? We have a Ms.
11 Michele Rosenfeld who's going to provide some testimony.
12 If you could make room for her up at the table. And just
13 make sure you state your name for the record before you
14 speak. And we can give you three minutes for your
15 testimony.

16 MS. ROSENFELD: Thank you. Michele Rosenfeld,
17 and I'm here on behalf of the owners of 10 Hesketh,
18 Stephen Sayre and Nancy Waters. And they apologize for
19 not being here tonight in person. They had a previous
20 conflict that they could not rechedule. And so they asked
21 me to appear tonight to represent them. And, you do have
22 copies of some written testimony that they have provided.
23 I just would like to highlight several points in here.
24 That are, I think, overriding concerns. First, the
25 representation that the -- a new addition is in keeping

1 with the scale and the massing of existing homes in the
2 neighborhood, it's their view, based on their
3 observations, that that in fact is not the case. That the
4 addition will result in a structure that's significantly
5 larger than the predominant characteristics within the
6 neighborhood. They also are concerned with the use of
7 stone on the chimney, that that is not characteristic of
8 the chimneys. Chimneys elsewhere on the block are brick,
9 and so this would introduce a new type of feature in the
10 neighborhood and not, again, characteristic with the
11 predominant historic features on the existing homes.

12 They also believe that the size of the addition
13 will have an adverse effect on the park-like
14 characteristics in Chevy Chase. That it will reduce the
15 open and park-like characteristics and views along the
16 street. And, there is the belief that the addition would
17 be visible from the street. And again, would have the
18 effect of reducing the open space and the park-like
19 characteristics. In addition, they do support the Staff
20 recommendations and the concerns regarding the roof style,
21 regarding the size and the massing, regarding the use of
22 stone on the chimney, and they do have concerns about
23 protection of the trees.

24 And, as you see in their letter, they have
25 consulted with their arborist, who has been maintaining

1 the Elms, who did recommend that there be some root
2 protection for the critical root zones during the period
3 of construction. And we would ask that you take that into
4 consideration as well. Thank you.

5 MR. KIRWAN: Thank you very much. Any questions
6 for the speaker? Thank you very much for your testimony.
7 Appreciate you coming out this evening and providing us
8 with some helpful considerations.

9 MS. BARNES: Michael, at the beginning of your
10 Staff presentation you had shown the street view and an
11 overhead. Thank you.

12 MR. FLANAGAN: I have a street view if that's
13 helpful.

14 MR. KIRWAN: Well, when we are ready, we should
15 give our thoughts on the case before us. Commissioner
16 Carroll, could I ask you to -- impose on you to kick
17 things off?

18 MR. CARROLL: Sure. So, I think, you know,
19 you've done what we typically ask by moving the sides of
20 the addition in. I think the narrow lot, you know, you
21 have, really a case with the porch on the left side, seven
22 feet to the lot line, 12 feet to the next house on the
23 right side. It's going to be difficult to see much of
24 what's going on behind the house. I don't have any
25 problem with the fenestration pattern on the rear

1 addition. I think whoever put that addition on the back
2 of the house made your task easy for you because there's
3 very little you could do to make it more, because it's,
4 you know, just add that overhang in the back.

5 Replacing windows. I would want to see some
6 details. You know, you're replacing the original windows
7 on the front facade of the house, and we've got to be
8 pretty clear that there's a real good reason to do that.
9 Once you move around to the sides and rear it becomes a
10 different issue for us. But, that's one of the things
11 that, if there's a compelling case for replacing those
12 windows, and then giving us a cut pattern so we can see
13 the molding profiles and so forth, so that we can make the
14 argument that they're going to maintain the same
15 proportions and look and so forth.

16 And then, with the trees, I think, you know, an
17 easy way to go about this if there's a debate about
18 whether the trees are in danger, is to put a tree
19 protection plan in there so it's, you know, the root zones
20 don't get compacted and so forth. And I think that's the,
21 you know, the reasonable way to go about that. You know,
22 there's, I'd like to know if there's any other stone
23 chimneys around. You know, if the streetscape is all brick
24 chimneys, it's going to be easier to get it through if
25 it's got brick.

1 MR. FLANAGAN: We'll be happy with brick.

2 MR. CARROLL: Okay. I'm just trying to get
3 through my list here. I think I'm going to leave it
4 there. Thank you.

5 MR. KIRWAN: And just to clarify, you're okay
6 with the scale and massing?

7 MR. CARROLL: I'm generally okay with it. I
8 think that the, you know, looking at the numbers, it looks
9 like it's about 50 percent increase. All things
10 considered there's, you know, between what you're taking
11 off and what you're adding, it's not a concern, it's
12 certainly within your rights to do that. And I'm looking
13 at a streetscape, you know, we're always, I would rather
14 see something smaller, but I don't think it's outrageous.
15 And it's not a huge house.

16 MS. LEGG: Thank for coming in for a prelim.
17 Sorry it's so late. I'll be brief. I actually think this
18 addition will improve the property because I think it'll
19 be less visible than the current addition. The massing
20 does not bother me if it's consistent with the Village. I
21 think especially in the chimney the brick will be an
22 improvement. That's it. Sorry. And also, I mean, I
23 would encourage you to work directly with the arborist and
24 protect the roots.

25 MS. HEILER: I would agree with the previous

1 Commissioners. Ordinarily, I would think that really
2 doubling the size of the historic house was a problem.
3 But, I do agree that it's likely to be hidden from the
4 street. Usually, we like the ridge to be lower, and the
5 roofline to be more compatible with the house. However,
6 again, I don't think it will be visible. I echo the
7 remarks about the chimney that, I think that really would
8 stand out. And overall, I think it does less damage than
9 the existing addition, and it will not be visible.

10 MS. BARNES: I appreciate your willingness to
11 switch your materials for your chimney, and also the fact
12 that you've chosen to inset your addition substantially.
13 There are some graphics that you have on Circle, I think
14 22, on the upper story, that seem to me a little odd. And
15 I'm not sure what that's all about. This is clearly what
16 we would describe as a major addition, so it does require
17 some attention from us.

18 And, the one thing that I find really remarkable
19 when I look at the drawings, is that I feel that I look at
20 the front of the house and I see one house, and I look at
21 the proposed rear elevation, and I see a totally different
22 style house. And, for me, that is somehow jarring. In
23 that it doesn't seem to provide for a kind of
24 compatibility.

25 I appreciate your comments earlier about the

1 challenges of how do you deal with this roofline, you
2 don't want to have, you know, a junior partner and
3 duplicate. And, I suppose this is what makes architecture
4 a very challenging profession, is coming up with the
5 appropriate solution. So, while it's a major addition, it
6 is at the rear. It is inset. That's all to the good.
7 But, I must say that I find myself struggling with the
8 compatibility question. Perhaps I shouldn't, since it's
9 the rear and not visible. But it is something that, for
10 me, is jarring.

11 MR. FIRESTONE: I don't have much to add to
12 what's been said before. My initial impression from some
13 of the drawings was that this is going to be something,
14 you know, massive and overpowering the original house.
15 But then when I realized that it is inset quite a bit,
16 it's to the rear, it's on a fairly narrow lot. I can see
17 that it, you know, could work. And while you'll be
18 increasing the size of the house, which is probably
19 desirable from the owner's standpoint, it looks like
20 you're not going to be really doing something that would be
21 obnoxious to the neighborhood.

22 I guess, thinking about it awhile, I'm not quite
23 as concerned about the different styles of the addition
24 and the front of the house, because it does at least
25 differentiate it, since the addition wasn't here when this

1 house was originally built. So, I can see that being a
2 good thing as well. That's all I have to say.

3 MS. VOIGT: Thanks for coming in. I agree with
4 Commissioner Barnes. I think that, and I do appreciate
5 you insetting it. I think this Dutch Colonial, I think
6 what's unique about the house is the roof, and I think
7 that although it is a rear addition, I think that it's a
8 large addition, and I think that whatever you can do to
9 make the addition more compatible in terms of proportions
10 and kind of relating to the uniqueness of the Dutch
11 Colonial style, I think would really help not only make it
12 a more compatible addition, but it would seem to lessen
13 the impact of the addition. And, I don't mean it to say
14 to copy the existing home, but I think that this addition
15 lacks a consistency in terms of kind of the proportions
16 with the Dutch Colonial. So, I think if you could look at
17 that, you know, and kind of figure that out in terms of
18 the roof, you know, the totally different, the two
19 different styles of roof and how they kind of interact up
20 there on the ridgeline.

21 MR. ARKIN: What first struck me about -- I
22 guess I should start off by thanking you for coming in for
23 the preliminary consultation, because generally they're
24 very helpful. And, though what struck me about this house
25 when I first looked at it, this proposal, proposed

1 addition, is its size. It is good that it's inset. And
2 it is good that the addition is entirely in the rear. I
3 think the historic house, the Dutch Colonial historic
4 house, really is a very charming house. And, I would
5 agree with the comments that were made that the back of
6 the house looks like a different house. I think that
7 nowhere more striking than if you look at the back
8 elevation of the house. But that will be invisible from
9 the public way. And because there are narrow -- we're
10 supposed to look at a building or a proposed building, as
11 if there is no landscaping, no foliage at all. But
12 because of the narrowness of the lot, and the narrow side
13 lot lines, I think most of the addition will be only
14 barely visible, if visible at all from the public way.

15 There is a simplicity to the Dutch Colonial that
16 I think you missed on your addition. But again, that's
17 more a matter of taste than the requirement, because we
18 are basically supposed to look only at what's visible. I
19 would be more comfortable if the ridgeline of the roof
20 were slightly lower. But, I would be much more
21 comfortable if you do end up replacing the stone chimney
22 with a brick chimney.

23 I would like to see you try to preserve the
24 front windows, the historic front windows to see if there
25 is an answer that might be workable perhaps inside

1 interior storm windows, something of that nature. At
2 least look into it. And also, the historic windows on the
3 two sides of the historic house, I think, would be worth
4 taking a look at whether those windows can be preserved
5 and retained.

6 The addition is certainly differentiated from
7 the original house. There's certainly no question about
8 that. And, I guess I would agree with the other comments
9 that have been made, and I don't really have much to add
10 beyond that. So, thank you very much.

11 MR. KIRWAN: And just to close, I would sort of
12 characterize my feeling on this case as very reluctant
13 approval. You know, one of the great characteristics of a
14 Gambrel roof is that you get the impression of a one-story
15 building with the second floor being in the attic. And,
16 your addition completely ignores that characteristic of
17 the house and just creates a two-story volume. A very
18 large two-story volume on the back of this house. I think
19 there are solutions where a Gambrel could come off the
20 back of the house and be broken us scale-wise on the rear
21 facade, and you would have dormers for your second floor
22 instead of a shield wall, and you would effectively get
23 the same second floor footprint that you would be after.

24 In the case of the siting of this house, the
25 siting of this house, there's very minimal impact that the

1 addition has on the front. So, you know, I don't think I
2 could be compelled to force you to a different design
3 solution because again, the levels of scrutiny we can
4 apply to this matter given its visibility to public space
5 is somewhat limited. But I do think there are better
6 solutions that are more sensitive to this house. And I
7 would encourage you to explore those. But I think we're
8 hearing a general consensus that what's been proposed is
9 likely acceptable.

10 But, again, in the spirit of, you know, being
11 good neighbors, I would encourage, you know, the neighbors
12 had very similar comments to the concerns that Staff
13 raised. I would encourage you to try to work with your
14 neighbors concerns, and try to modify the design to
15 address those. I think that would go a long way to making
16 this a much more easily approvable project when it came
17 back to us. And, I do want to reiterate the concerns that
18 Commissioner Carroll had about particularly the front
19 facade windows. I think we need to have, for you to
20 replace those, we would need to have some pretty clear
21 documentation that those are not repairable or could be
22 restored.

23 So, I think you got general approval on your
24 project with some concerns about the form of the massing
25 of the rear. But the footprint seems to be generally okay

1 and, you know, I would encourage you to continue to work
2 the design and try to make some improvements to it, and
3 then come back in with a HAWP.

4 MR. WHIPPLE: Mr. Chairman, can I just jump in
5 with two points about the windows?

6 MR. KIRWAN: Yes.

7 MR. WHIPPLE: It's generally the practice of the
8 Commission to require when you have paired or ganged
9 windows to have mulls, wide mulls.

10 MR. KIRWAN: And that's, I think, a comment
11 Commissioner Carroll wanted to make.

12 MR. WHIPPLE: Yeah. That the drawings don't
13 show. So, I think that that probably needs to get
14 revised. Another thing that the Commission generally
15 requires with window replacements is drawings that
16 establish that the new windows maintain the daylight
17 openings of the existing windows. And so, the applicant
18 will have to give, I think, pretty clear and extensive
19 documentation to that end.

20 MR. KIRWAN: Mutin sizes included. Great. All
21 right. Thank you for coming in tonight. And, I do -- it
22 was mentioned before, but I think, we do appreciate you
23 coming in for a preliminary. It gives us a chance to give
24 you some general feedback, and I think it'll make the
25 approval process go much smoother.

1 MR. FLANAGAN: Great. Thank you. Thanks for
2 staying late for us.

3 MR. KIRWAN: We're not done. I think Item No.
4 III, Tax Credit applications for Calendar Year 2015. This
5 is the final third group for tax credits.

6 MR. KYNE: Yes, that is correct. This is the
7 third and final group of tax credits for the year 2015.
8 And we are asking you to approve the transmittal of the
9 final 25 out of 98 tax credits to the Department of
10 Finance.

11 MR. KIRWAN: Yes. And I think we discussed that
12 upstairs in our worksession.

13 MR. BARNES: Mr. President, could I make a
14 motion that we recommend that these 25 tax credits be
15 transferred to the Finance Department for action.

16 MS. HEILER: I second the motion.

17 MR. KIRWAN: Any discussion? All in favor,
18 please raise your right hand.

19 VOTE.

20 MR. KIRWAN: The motion passes unanimously. Do
21 we have a volunteer for tonight's meeting minutes?

22 MS. VOIGT: I think I haven't done it in a
23 while. Okay.

24 MR. ARKIN: What about the Staff items, Mr.
25 Chairman?

1 MR. KIRWAN: Yes, we'll get to those. And do we
2 have any minutes to approve this evening?

3 MR. WHIPPLE: Are you ready to move the July
4 27th?

5 MS. VOIGT: Yes, I sent those in.

6 MR. WHIPPLE: So those are good?

7 MS. VOIGT: Yeah.

8 MR. WHIPPLE: And then also September 21.

9 MR. KIRWAN: So we need a motion for the July
10 27th and the September 21st meeting minutes.

11 MS. HEILER: I move that we approve the July
12 27th and September 21st minutes.

13 MR. CARROLL: I'll second that.

14 MR. KIRWAN: Any discussion? All in favor,
15 please raise your right hand.

16 VOTE.

17 MR. KIRWAN: The motion passes unanimously.
18 Those minutes are approved. And Commissioner Voigt is
19 taking the minutes for this evening. Any Commission
20 items? If not, then we have some Staff items.

21 MR. KYNE: Yes, that is correct. We have four
22 Staff items which were approved in the worksession. You
23 had revisions at 5923 Baltimore Street in Kensington; 4209
24 Bradley Lane, Chevy Chase; 36 Philadelphia Avenue, Takoma
25 Park; and 43 West Ninth Street in Chevy Chase.

1 MR. KIRWAN: We looked at those upstairs, and we
2 were fine with those revisions. And with that, we're
3 adjourned. Thank you.

4 (Whereupon, at 10:46 p.m., the meeting was
5 adjourned.)

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

% Digitally signed by Keena Lukacinsky

ELECTRONIC CERTIFICATE

DEPOSITION SERVICES, INC., hereby certifies that the foregoing pages represent an accurate transcript of the electronic sound recording of the proceedings before the Montgomery County Historic Preservation Commission.



Keena Lukacinsky

December 18, 2016