MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address: 3100 Brimstone Academy Dr., Olney Meeting Date: 8/14/2019

Resource: Master Plan Site #23/97 **Report Date:** 8/7/2019

Rockland

Applicant: Gary H. and Aimee A. Weiss **Public Notice:** 7/31/2019

Review: HAWP **Tax Credit:** n/a

Case No.: 23/97-19A Staff: Dan Bruechert

Proposal: Building Addition and Fenestration Alteration

RECOMMENDATION

Staff recommends the HPC approve the HAWP.

ARCHITECTURAL DESCRIPTION

SIGNIFICANCE: Individially Listed Master Plan Site #23/97 (*Rockland*)

STYLE: Federal

DATE: 1838 w/ 1850 alterations (Major renovation c.1986)

From Places from the Past:

"Rockland was the residence of Benjamin Hallowell, influential Quaker educator and agriculturalist. Hallowell was a founder of Swarthmore College, was first president and a founder of the college that became the Agricultural College of the University of Maryland, and established Brimstone Academy in Alexandria, Virginia. The main five-bay block with center passage was likely built around 1838, incorporating an earlier log structure. A significant interior feature is an elliptical arch between the two east rooms. The house was expanded about 1850 with dual service wings to create a large formal double residence. The west wing had been removed by c.1900 and was rebuilt in the late 1980s."



Figure 1: Rockland has had significant development around the historic resource.

BACKGROUND

On June 12, 2019 the HPC heard a first preliminary consultation of this same proposal. The applicant made some modifications to the proposal and a second preliminary consultation was held on July 10, 2019 with additional information regarding the historic development and alteration of the Rocklands Master Plan Site. The HPC was generally supportive of the proposal, but had some questions about construction of the roof on the addition. The applicant has provided a roof plan, with identified slopes in the supplied application materials.

The original house was constructed in 1838 as indicated in the application and in the information provided from *Places from the Past*. The house was expanded c.1850 with additional two-story wings. However, from 1850 until the 1986 renovation there were a series of additions and modifications to the house to fit the needs of the residents. The construction and removal of these additions created an appearance that is not representative of any one time period of the subject property's occupation. Over the first 150 years of the house's use it served primarily as a duplex and boarding school and it wasn't until the 1940s that the interior of the house was unified for single family occupation. The collection of

¹ The Staff Report from the June 12, 2019 HPC meeting can be found here: https://montgomeryplanning.org/wp-content/uploads/2019/06/II.A-3100-Brimstone-Academy-Drive-Olney.pdf with the audio from the meeting here: https://mncppc.granicus.com/MediaPlayer.php?publish_id=b43cef92-8e0e-11e9-848a-0050569183fa (discussion of this agenda item begins at 1:23:30).

² The Staff Report from the July 10, 2019 HPC meeting can be found here: https://montgomeryplanning.org/wp-content/uploads/2019/07/II.A-3100-Brimstone-Academy-Drive-Olney.pdf with audio of the meeting here: http://mncppc.granicus.com/MediaPlayer.php?publish id=fa469984-a3ef-11e9-b00b-0050569183fa (discussion of this agenda item begins at 32:35).

additions and modifications left an appearance that was vastly different from its current appearance, which Staff identifies as mostly conjecture of the appearance of a newly-constructed, c.1838 Federal building (with the 1850 wings).



Figure 2: An undated photo prior to 1900 with both wings intact, with a porch to the left and sunroom to the right.

At the time of this photograph in Figure 2, the house maintained both of its wings and included a substantial left side porch supported with Queen Anne columns and a room off of the right wing.

A 1936 HABS photo shows there were not many alterations on the front of the house from the early 20th century until 1986. A close examination of this photo shows the columns of a porch on the left elevation and an expanded, co-planer addition to the right wing.



Figure 3: 1936 Historic American Building Survey photo.



Figure 4: Rear of the house c.1975 showing rear, non-historic fenestration.

In 1986, just prior to the building's listing on the Master Plan for Historic Preservation, Rockland underwent a substantial renovation. Because this work occurred before HPC review, a full recounting of the work done is challenging, but at a minimum it included the following: the removal of the rear addition, reconstructed dormers, replacement cedar siding, new (enlarged) windows, new shutters, a cedar roof, reconstruction of the left wing, a replacement front door, new mechanical systems, and significant site work. In reviewing the historic context of Rockland, Staff reviewed the historic inventory form, which determined that the site was significant for its association with a prominent family, and for its significance as a historic school; the historic resource was not designated for its architectural significance or integrity.

The large one-story rear addition was constructed in 1992 after the building's 1986 Master Plan listing.



Figure 5: Existing rear elevation showing the regularized fenestration and 1992 rear addition.

PROPOSAL

The applicant proposes to construct a two-story addition in the northwest corner of the house and to make modifications to a second story bathroom that will alter the rear fenestration.

APPLICABLE GUIDELINES

Proposed alterations to individual Master Plan Sites are reviewed under Montgomery County Code Chapter 24A (Chapter 24A) and the Secretary of the Interior's Standards for Rehabilitation. Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features, which convey its historical, cultural, or architectural values.

Montgomery County Code, Chapter 24A Historic Resources Preservation

- (b) The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to insure conformity with the purposes and requirements of this chapter, if it finds that:
 - (1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or
 - (2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter;

Secretary of the Interior's Standards for Rehabilitation

2. The historic character of a property will be retained and preserved. The removal of distinctive

- materials or alteration of features, space and spatial relationships that characterize a property will be avoided.
- 5. Distinctive materials, features, finishes and construction techniques or examples of craftsmanship that characterize a property will be preserved.
- 9. New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportions, and massing to protect the integrity of the property and its environment.
- 10. New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

STAFF DISCUSSION

The applicant proposes two areas of modification. First, the applicant proposes to construct an addition to the rear of the left-wing addition. Second, the applicant proposes to reconfigure a second-story bathroom at the rear. This modification will require the removal of two non-historic windows. Staff finds that these alterations will not substantially alter historic features of the house and will not detract from the historic character. Staff recommends approval of this HAWP.

Building Addition

The applicant proposes constructing a rear addition off of the 1986 left side wing (which is based on a c.1850 addition) to provide a family room on the first floor, second floor closet and laundry space, and additional space to accommodate a lift in the future so the applicants may continue to occupy the house and age in place.

The applicant proposes constructing a two-story addition, measuring 21' × 16' (twenty-one by sixteen feet) in the northwest corner of the house. The western (left side) wall will be co-planer with the existing wall plane. The roof of the addition will introduce a new rear-facing gable. The application indicates that the finishes of the addition will match the historic house including painted cedar clapboards, a stone foundation and cedar shake roof. To differentiate this addition from the 1986 side addition, the applicant proposes adding a trim piece to mark the corner of addition. No windows are proposed for the west elevation. On the north (rear) elevation two existing, non-historic, windows will be removed from the house and relocated on the north wall of the addition if possible. These windows date from the 1986 renovation. If the windows cannot be re-located, the applicant proposes installing windows that match the existing.

On the west (side) of the new construction the applicant proposes to construct a simply detailed wood side porch with round columns, a hipped cedar shake roof, and a single door. The design details and materials for the proposed side porch are taken from the front porch.

Staff finds that a building addition in this location is acceptable. It is in the rear of the building connecting to a c.1980s addition. Historic photos show that the subject property has historically utilized co-planer additions to the side wing additions. No photographs of the rear of the west side exist to show if there is a precedent for this type of addition on this side of the house. Typically, additions are required to be inset from the existing construction to differentiate the historic from the new construction. Because the existing wing is a c.1980s construction, Staff supports a co-planer addition with the proposed corner board trim piece. Staff finds that the size, design, and materials are all consistent with the historic house and are compatible with 24A-8(b)(2).

Staff finds that additional consideration should given to the significant distance from the right-of-way where this addition would be visible. The right side of the front elevation is not visible from Brimstone

Academy Dr. due to a knoll running parallel to the road along Brimstone Academy. In fact, the only place the proposed addition will be visible from is over 300' (three hundred feet) away along Prince Philip Dr. (see Fig. 6, below).



Figure 6: Due to a knoll along Brimstone Academy Dr. the proposed addition will only be visible from more than 300' away.

Standard 9 is one of the main sources of guidance when evaluating new additions to historic buildings. Staff finds there is a challenge in applying Standard 9 in this instance, because the requirement is that the "new work shall be differentiated from the old." As demonstrated above, there is very little that is old except for the general form in the subject property. Staff finds that as the visible materials all date from 1986, the proper question is whether the proposal is compatible with the architectural features of the historic site (per 24A-8(b)(2)). Staff finds that the size and massing of the proposed addition is compatible with the house and its additions. Furthermore, the impact of the proposed work is reduced even more when it is evaluated from the nearest right-of-way.

Staff finds that the materials identified are compatible with the historic house as they will match the siding, trim, roof form and materials, and windows in the house (per 24A-8(b)(2)).

Staff finds that the proposal to construct a new porch on the west elevation is also appropriate. The hipped roof, wood railing and lattice are all drawn from the existing front porch. The front porch appears to be 1980s construction, though the historic photographs do show a hipped roof porch of approximately the same dimensions. Staff finds the proportions of the side porch to be appropriate and finds a precedent for a larger side porch shown in the historic photographs. Staff supports approval of the proposed addition.

2nd Floor Bathroom Reconfiguration

Adjacent to the bedroom in the left wing, there is an existing bathroom. The bathroom space runs from east to west and has two, rear facing windows. The applicant proposes to remove interior closet space and construct a larger bathroom along the rear wall. The HPC does not typically review interior work, however, in this instance the proposal will remove two window openings and cover them up. The question before the HPC is whether it is appropriate to cover this space at the rear of the house.

Based on the evidence shown in Figure 4, above, Staff finds there is no historical basis for the existing fenestration pattern. Additionally, all of the windows installed in the house date from 1986 and, at least on the front, required enlarging the second-floor openings. As the design, opening size, and materials are not historic, Staff finds that the evaluation of the proposal must rest on the visual impact this work will have on the overall character of the house.

Prior to the 1986 rehabilitation, the window in the bathroom was a pair of boarded up, four-over four sash windows (Fig. 11, below). In further analyzing this proposal, Staff considered the possibility of installing smaller windows in this space to maintain the ratio of solids to voids on the rear elevation. Staff's conclusion was that introducing a new window size would create more visual complexity that would detract from the regularly sized openings in the rear.




Figure 7: View of the window in the bathroom space prior to the 1986 renovation.

Based on Staff's finding and HPC feedback at the July 10, 2019 preliminary consultation, Staff supports the removal of these two windows and filling in the openings with cedar siding matching the existing in dimensions and finish. This proposal is not altering a historic feature of the house (per 24A-8(b)(1)).

Staff finds that this alteration to the rear will not substantially alter the historic character of the house nor will it impact the historic character. In fact, Staff finds that a full existing rear elevation needs to be submitted with the HAWP application to allow the HPC to make a final determination as to the window removal's appropriateness.

STAFF RECOMMENDATION

Staff recommends that the Commission <u>approve</u> the HAWP application under the Criteria for Issuance in Chapter 24A-8(b)(1) and (2), having found that the proposal will not substantially alter the exterior features of the historic resource and is compatible in character with the purposes of *Chapter 24A*;

and with the Secretary of the Interior's Standards for Rehabilitation #2, #5, #9, and #10,

and with the general condition that the applicant shall present the **3 permit sets of drawings**, **if applicable**, **to Historic Preservation Commission (HPC) staff for review and stamping** prior to submission for the Montgomery County Department of Permitting Services (DPS) building permits;

and with the general condition that final project design details, not specifically delineated by the Commission, shall be approved by HPC staff or brought back to the Commission as a revised HAWP application at staff's discretion;

and with the general condition that the applicant shall notify the Historic Preservation Staff if they propose to make **any alterations** to the approved plans. Once the work is completed the applicant will <u>contact the staff person</u> assigned to this application at 301-563-3400 or <u>dan.bruechert@montgomeryplanning.org</u> to schedule a follow-up site visit.



Edit 6/21/99

HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

1	MICHAEL SHAPP
Contact Basis MSharpark	Chiconst. com Contact Person: MICHAEL SHARP Deytime Phone No.: 443.472.2775
Tex Account No.: 02735607	
Name of Property Ovener: GARY H. & A	IMEEA. WEISS Dayline Phone No.: 3019109397
Address: 3100 BRIMSTONE A	CADEMY BRIVE OLNEY MD 20832
Contractor: KNI CONSTRUCT	110N LLC Proce No.: 443 472 2775
Contractor Registration No.: MHIC 904	23 MHBR (286
	ARP Daytime Phone No.: 443 472 2775
KOPORCI GLI HUDDISPADAS I PO	
	STORE BRIMSTONE ACADEMY DRIVE
Town/City: DLNEY	Nearest Cross Street PRINCE PHILL P DRIVE
.ot: 7 Block: N Subdi	
iber:Folio:	
ZAMOR Z MISTOLISCU MARKUMANIS	
A CHECK ALL APPLICABLE:	CHECK ALL APPLICABLE:
Construct X Extend X Alter/Renovae	■ □ A/C □ Slab ★ Room Addition ★ Porch □ Dack □ Shed
☐ Move ☐ Install ☐ Wireck/Raza	☐ Solar ☐ Fireplace ☐ Weodburning Stove ☐ Single Family
☐ Revision ☐ Repair ☐ Revocable	☐ Fence/Well (complete Section 4) ☐ Other:
B. Construction cost estimate: 8 90	
C. If this is a revision of a previously approved active p	Wmit, see Permit #
Date West Additional to the Management of the Control of the Contr	O. MARD PART ARRANGEMENTS
A. Type of sewage disposal: 01 WSSC	02 🗆 Septic 03 🗀 Other:
8. Type of water supply: 01 WSSC	02 🗍 Well 03 🗍 Other:
Alleniil (1944) geologia (1941) (1941) Barolle Alfa (1	ABIA WAL
A. Heightiestinches	
B. Indicate whether the fence or retaining wall is to be) constructed on one of the following locations:
13 On party line/property line Entirel	iy on lend of overser Do public right of way/easement
hereby certify that I have the authority to make the fore	rgoing application, that the application is correct, and that the construction will comply with plans
intraeo of the admicinal listed and ynamoly actinowleds	ye and accept this to be a condition for the issuance of this permit.
1 Identito Les	- MAN 544 2019
Signature of somer or suthorized egent	Deta
xproved:	Es Chalanna Harda B
sapproved: Signature:	For Chairperson, Historic Preservation Commission
plication/Permit No.:	Date Flied: Date Leaved:
ere ne	
it 6/21/99 SEE NE	VERSE SIDE FOR INSTRUCTIONS

10

THE FOLLOWING ITEMS MUST BE COMPLETED AND THE

Ţ	REQUIRED	<u>DOCUMENTS</u>	MUST	ACCOMP/	MY THIS	APPLICATION

٦.	WAIFTEN DESCRIPTION OF PROJECT				
	a. Description of existing structure(s) and environmental setting, including their historical features and significance: 2 STORY SINGLE FAMILY HOME PAINTED CEDAR SIDING STONE TO GRADE CEDAR SHINGLES				
	b. General description of project and its effect on the historic resource(a), the environmental setting, and, where applicable, the historic district 2 STORY 21'K 16' ADDITION ON CRAWL SPACE ALL EXTERIOR FINISHES TO MATCH EXISTING				
2.	SITE PLAN				
	Site and environmental setting, drawn to scale. You may use your plat. Your site plan must include:				
	a. the scale, north arrow, and date;				
	b. dimensions of all existing and proposed structures; and				
	c. site features such as walkways, driveways, fences, ponds, streems, trash dumpsters, mechanical equipment, and landscaping.				
3.	PLANS AND ELEVATIONS				
	You must submit 2 copies of plans and elevations in a format no larger than 11" x 17". Plans on 3 1/2" x 11" gaper are preferred.				

3. F

- a. Schematic construction plans, with marked dimensions, indicating location, size and general type of walls, window and door openings, and other fixed features of both the existing resource(s) and the proposed work.
- b. Elevations (facades), with marked dimensions, clearly indicating proposed work in relation to existing construction and, when appropriets, context. All materials and fixtures proposed for the exterior must be noted on the elevations drawings. An existing and a proposed elevation drawing of each facada affected by the proposed work is required.

4. MATERIALS SPECIFICATIONS

General description of materials and manufactured items proposed for incorporation in the work of the project. This information may be included on your design drawings.

5. PHOTOGRAPHS

- a. Clearly labeled photographic prints of each facade of existing resource, including details of the affected portions. All labels should be placed on the front of photographs.
- b. Clearly label photographic prints of the resource as viewed from the public right-of-way and of the adjoining properties. All labels should be placed on the front of photographs.

6. TREE SURVEY

If you are proposing construction adjacent to or within the dripline of any trace 6" or larger in diameter (at approximately 4 feet above the ground), you must file an accurate tree survey identifying the size, location, and species of each tree of at least that dimension.

7. ADDRESSES OF ADJACENT AND CONFRONTING PROPERTY OWNERS

For ALL projects, provide an accurate list of adjacent and confronting property owners (not tenants), including names, addresses, and zip codes. This list should include the owners of all lots or parcets which adjoin the parcel in question, as well as the owner(s) of lot(s) or parcel(s) which lie directly across the street/highway from the parcel in question.

PLEASE PRINT (IN BLUE OR BLACK INK) OR TYPE THIS IMPORMATION ON THE FOLLOWING PAGE. PLEASE STAY WITHIN THE GUIDES OF THE TEMPLATE, AS THIS WILL BE PHOTOCOPIED DIRECTLY ONTO MAILING LABELS.

HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFING [Owner, Owner's Agent, Adjacent and Confronting Property Owners]

Owner's mailing address 3100 BRIMSTONE ACABEMY DRIVE OLNEY, M.D. 20832 Adjacent and confronting Property Owners mailing addresses PROPERT IS SURROUNDED BY COMMON AREA OF HALLOWELL HOMEOWNERS ASSOCIATION, INC. LID COMMUNITY ASSOCIATION SERVICES, INC. 18401 WCCDFIELD ROAD, SUITE H GAITHERS BURG, M.D. 20879		, , , , , , , , , , , , , , , , , , , ,
Adjacent and confronting Property Owners mailing addresses PROPERT IS SURROUNDED BY COMMON AREA OF HALLOWELL HOMEOWNERS ASSOCIATION, INC. CO COMMUNITY ASSOCIATION S ERVICES, INC. 18401 WOODFIELD ROAD, SUITE H	Owner's mailing address	Owner's Agent's mailing address
Adjacent and confronting Property Owners mailing addresses PROPERT IS SURROUNDED BY COMMON AREA OF HALLOWELL HOMEOWNERS ASSOCIATION, INC. 40 COMMUNITY ASSOCIATION SERVICES, INC. 18401 WOODFIELD ROAD, SUITE H	3100 BRIMSTONE ACADEMY DRIVE	17005 HARDY ROAD
PROPERT IS SURROUNDED BY COMMON AREA OF HALLOWELL HOMEOWNERS ASSOCIATION, INC. C/O COMMUNITY ASSOCIATION SERVICES, INC. 18401 WOODFIELD ROAD, SUITE H	OLNEY, MD 20832	MOUNT AIRY, MB 21771
COMMON AREA OF HALLOWELL HOMEOWNERS ASSOCIATION, INC. 40 COMMUNITY ASSOCIATION SERVICES, INC. 18401 WOODFIELD ROAD, SUITE H	Adjacent and confronting	Property Owners mailing addresses
HALLOWELL HOMEOWNERS ASSOCIATION, INC. 40 COMMUNITY ASSOCIATION SERVICES, INC. 18401 WOODFIELD ROAD, SUITE H	PROPERT IS SURROUNDED BY	
40 COMMUNITY ASSOCIATION SERVICES, INC. 18401 WOODFIELD ROAD, SUITE H		
18401 WOODFIELD ROAD, SYITE H	HALLOWELL HOMEOWNERS ASSOCIA	TION, INC.
. '	40 COMMUNITY ASSOCIATIONS	ERVICES, INC.
GATHERS BURG, MID 20879	· '	
	GATHERS BURG, MD 208	379



Existing Property Condition Photographs



Details: Front elevation



Details: Right side elevation





Detail: Rear elevation



Detail: Rear elevation at proposed addition location





Detail: Left side elevation at proposed addition location



Site Plan:

