MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address: 2240 Brighton Dam Road, Brookeville Meeting Date: 10/26/2022

Resource: Master Plan Site #23/82 **Report Date:** 10/19/2022

Grafton Holland Farm

Public Notice: 10/12/2022

Applicant: Duanne Epperly

(Miche Booz, Architect) Tax Credit: Partial

Review: HAWP Staff: Rebeccah Ballo

Case Number: 1007629

Proposal: Comprehensive building rehabilitation, hardscape alterations, fenestration alterations,

installation of a new roof, and other alterations.

STAFF RECOMMENDATION:

Staff recommends that the HPC approve the subject application with five (5) conditions:

- 1. The final window schedule detailing each existing window and door, including its condition, details, and hardware components, and each window and door's proposed replacement shall be submitted to staff for final review and approval prior to issuance of the HAWP. The final window schedule shall show the comparative details between the existing and proposed fenestration.
- 2. The railing on the historic north porch shall be traditionally detailed with wood railings and balusters, with final review of compatibility and detailing delegated to staff.
- **3.** The original fenestration pattern on the south elevation will be retained and shown on the permit level drawings.
- **4.** Final specifications of the new metal roof and details on the installation methods shall be submitted to staff for final review and approval prior to issuance of the HAWP.
- **5.** Final approval of the mortar mix for all masonry repair, and a detailed drawing of the chimney proposed for reconstruction shall be submitted to staff for final review and approval prior to issuance of the HAWP.

ARCHITECTURAL DESCRIPTION:

SIGNIFICANCE: Master Plan Site #23/82, *Grafton Holland Farm*

DATE: c1800, c1835, mid-1800s

Excerpt from *Places from the Past* [updated information on construction dates and techniques are included in the narrative detailed in the staff report]:

The Grafton Holland House represents the evolution of a house owned by the same family for over a century. It is one of three Holland farms in the Hawlings River Valley. The first eastern (left) section of the house was probably built about 1800. The one-story log structure has an

internal end chimney noteworthy for its substantial stone construction. In 1834, Grafton Holland inherited 92 acres from his father James Holland. Grafton is thought to have built the western section c1835, soon after his inheritance. Facing north the three bay dwelling has a two-story rear gallery porch. Like the two other Holland houses in the valley (Prospect Hill and Landgate), there is a blank end wall (west) lit only by two attic windows. The two structures were probably joined in the mid-1800s, before Grafton's 1864 death. The farmstead includes a gambrel-roof bank barn and corncrib.



Fig. 1: Subject property, with historic house marked by the blue star.

PROPOSAL:

The applicant proposes comprehensive building rehabilitation, hardscape alterations, fenestration alteration, installation of a new roof, and other alterations.

APPLICABLE GUIDELINES:

In accordance with section 1.5 of the Historic Preservation Commission Rules, Guidelines, and Procedures (Regulation No. 27-97) ("Regulations"), in developing its decision when reviewing a Historic Area Work Permit application for an undertaking at a Master Plan site the Commission uses section 24A-8 of the Montgomery County Code ("Chapter 24A"), the Secretary of the Interior's Standards for Rehabilitation (Standards), and pertinent guidance in applicable master plans. The pertinent information in these documents, incorporated in their entirety by reference herein, is outlined below.

Montgomery County Code; Chapter 24A-8

(a) The commission shall instruct the director to deny a permit if it finds, based on the evidence and information presented to or before the commission that the alteration for which the permit is sought would be inappropriate, inconsistent with or detrimental to the preservation, enhancement or ultimate protection of the historic site or historic resource within an historic district, and to the purposes of this chapter.

- (b) The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to ensure conformity with the purposes and requirements of this chapter, if it finds that:
 - (1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or
 - (2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter; or
 - (3) The proposal would enhance or aid in the protection, preservation and public or private utilization of the historic site or historic resource located within an historic district in a manner compatible with the historical, archeological, architectural or cultural value of the historic site or historic district in which an historic resource is located; or
 - (4) The proposal is necessary in order that unsafe conditions or health hazards be remedied; or
 - (5) The proposal is necessary in order that the owner of the subject property not be deprived of reasonable use of the property or suffer undue hardship; or
 - (6) In balancing the interests of the public in preserving the historic site or historic resource located within an historic district, with the interests of the public from the use and benefit of the alternative proposal, the general public welfare is better served by granting the permit.
- (c) It is not the intent of this chapter to limit new construction, alteration or repairs to any 1 period or architectural style.

Secretary of the Interior's Standards for Rehabilitation

The Secretary of the Interior defines rehabilitation as "the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features, which convey its historical, cultural, or architectural values." Because the property is a Master Plan Site, the Commission's focus in reviewing the proposal should be the *Secretary of the Interior's Standards for Rehabilitation*. The *Standards* are as follows:

- 1. A property shall be used for its historic purpose or be placed in a new use that requires minimal change to the defining characteristics of the building and its site and environment.
- 2. The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.
- 3. Each property shall be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as adding conjectural features or architectural elements from other buildings, shall not be undertaken.
- 4. Most properties change over time; those changes that have acquired historic significance in their own right shall be retained and preserved.

- 5. Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a historic property shall be preserved.
- 6. Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary, physical, or pictorial evidence.
- 7. Chemical or physical treatments, such as sandblasting, that cause damage to historic materials shall not be used. The surface cleaning of structures, if appropriate, shall be undertaken using the gentlest means possible.
- 8. Significant archaeological resources affected by a project shall be protected and preserved. If such resources must be disturbed, mitigation measures shall be undertaken.
- 9. New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.
- 10. New additions and adjacent or related new construction shall be undertaken in such a manner that if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

STAFF DISCUSSION:

Background and 2021 Site Visits

The Grafton Holland House is an early-to-mid 19th century farmhouse, which was constructed in three phases. The designation states that the earliest part of the house, dating to c. 1800, is the 1½-story eastern section (left side, as viewed from the public right-of-way of Brighton Dam Road). The westernmost/rightmost section dates to c. 1835 and is two stories, with two-level gallery porch on the south side (rear). The eastern and western sections of the house were connected via the construction of the two-story center section in the mid-1800s. The subject property contains several extant outbuildings, including the hay barn, corn crib, dairy building, cottage, and tenant house; the tenant house was approved for demolition at the July 28, 2021 HPC meeting.¹

4

¹ Link to July 28, 2021 HAWP staff report for demolition of the tenant house: https://montgomeryplanning.org/wp-content/uploads/2021/07/I.F-2240-Brighton-Dam-Road-Brookeville-958637.pdf




Fig. 2: Sequence of construction.

Staff visited the subject property on December 2, 2021 and noted that all three sections of the house have a mix of materials and construction techniques, making it difficult to verify the sequence of construction via physical evidence.

On the eastern section, areas where siding has deteriorated and/or been removed reveals frame construction, not log as stated in the designation. Additionally, the roofing on the south/rear slope has been replaced with standing seam copper, while the north/front slope is covered with tin. From inside the attic, cedars shingles are present in some locations beneath the tin roofing. Notable alterations include two areas of the rear porch that have been enclosed to accommodate separate bathrooms, as well as the addition of a second-floor rooftop bathroom, which is accessed from an altered window in the center section.



Fig. 3: Rear of the eastern section of the historic house, with previous alterations/bathroom additions tinted red.

All three sections of the house share common features throughout, including a mix of cut nails and wire nails (the cut nails are not exposed enough to determine if they are Type A or B), hand-hewn joists in the basements and root cellar, locally found quartz and fieldstone foundations, a mix of circular saw marks and machine operated pit saw marks on the attic rafters and purlins, and pegged mortise and tenon joints.

Staff also noted that the attic/roof construction in the eastern section (believed to be the earliest) and center (the latest, connecting section) share similar atypical ridge boards with centered lap joints and notched rafters at the wall plates. However, the rafters in the attic of the western section exhibit a different method of construction. In the western section, staff also observed hand carved numbers on the rafters, which were likely used during construction, as well as the year 1855 hand painted with plaster on one rafter.

Based upon observations in the field, staff finds that the original log structure (eastern section) may have been altered and/or replaced with frame construction at some point, perhaps when the center section was constructed. This is supported by the matching atypical roof/attic construction techniques and materials, which at least indicate that the roof of the eastern section was replaced when the center section was constructed.

Previous HPC Hearings and Recommendations

The HPC heard the preliminary consultation for this proposal at its December 15, 2021 public hearing.²

² The link to the staff report is available here: https://montgomeryplanning.org/wp-content/uploads/2021/12/II.A-2240-Brighton-Dam-Road-Brookeville-Preliminary-Consultation.pdf

To summarize, the Commission was supportive of the applicant's proposal and indicated that they could approve a HAWP with revisions. Recommendations and comments included:

- o Reduce the size of the proposed hyphen and addition.
 - Specific suggestions include: narrowing the hyphen, lowering roof lines, and reducing the size of the Media/Family Room and Bedroom 3 in the proposed addition.
- o Consider more traditional or porch-like designs for the proposed hyphen.
- Explore converting existing outbuildings to living spaces, which may allow a reduction in the size of the proposed addition.
- o Consider a carport in lieu of the patio at the west end of the house for proximity parking.

Current Proposal

Since that hearing in December 2021, the applicants have scaled back the proposal substantially. All work items related to the bank barn have been removed and may be considered as part of a future HAWP. The new two-story addition with connecting hyphen has been removed from the proposal as well. The applicant has instead proposed a comprehensive and thorough rehabilitation of the historic house with limited alterations to the building and site.

This HAWP is now for consideration of the following items:

- Demolition of non-historic features including the west concrete garage and its associated elevated patio, demolition of concrete slabs around the main house, demolition of the first floor bathroom addition and 2nd floor bathroom dormer:
- Replacement of all deteriorated wood windows, doors, trim, and siding where rehabilitation is not possible;
- Fenestration alterations:
- Installation of new standing seam metal roof;
- Construction of new stone patio at grade with associated retaining walls;
- Construction of new wood deck with exterior access stairs and new railing;
- Construction of new 2nd story dormer on the east elevation;
- Construction of new stone patio and screened in porch on east elevation;
- Rebuilding one chimney and repairing other chimneys;
- Restored basement windows and cellar access;
- Rehabilitation of structural members, foundations, and other repointing and exterior repair as needed:
- Installation of half-round metal gutters throughout; and,
- Expanded driveway and turnarounds to be provided on site for enhanced access to accessory buildings.

Demolition

The applicant proposes to remove the rear porch bathroom enclosures and rooftop bathroom from the eastern section of the historic house. The demolition was proposed and favorably reviewed by the HPC. The applicant is also proposing to demolish the non-historic garage and patio on the west elevation.

General Items: Siding, Windows, Doors

The house has a mix of wood frame siding including several layers of clapboard and German lap siding. The predominant siding is 1"x6" German lap on the majority of the elevations. The applicant will save all exterior framing that is not rotted or deteriorated and replace all damaged siding with new 1"x6" wood German lap siding.

All windows that can be repaired or restored shall be as part of this proposal. Some windows are missing entirely. Other locations such as on the new dormer and egress openings will require all new wood windows. The applicant has not yet submitted a complete window survey and it is unclear from the notations on the floor plans which windows will be ultimately replaced. The window schedule proposes Marvin wood windows with detailing that the HPC has accepted for replacing historic windows. Staff will add a condition that the final window scheduling detailing each window, its condition, and showing the comparative details between the existing window and its proposed replacement be provided. This information should be submitted to staff for final review and approval prior to issuance of the permit. Similar comments apply to all the existing and proposed doors.

New Construction - West Elevation: Patio, Deck, Railing, Hardscape

The applicant is proposing a new stone patio to replace the garage slab on the west elevation. This work will be the same size as the existing concrete slab and will include stone-clad masonry retaining walls on both the north and south sides to retain the grade in substantially the same location as it currently exists. A new flagstone landing, constructed of concrete faced with stone, and stairs will traverse the southern portion of the patio leading to the wood deck which will be constructed directly above the patio. This new wood deck will have wood porch floorboards and will be supported by wooden posts set in concrete footings. The deck will tie into the existing porch on the north elevation. The applicant is proposing new metal cable railings at the northern porch, around the perimeter of the deck, and on the new stairs adjacent to the retaining walls and patio. The portion of the railing on the stairs will be painted black metal.

The demolition of the existing concrete slab garage and patio would remove a non-historic feature and should be approved as a matter of course. The proposed design for the new patio and elevated deck will be built in this already disturbed area. The potential in this area for archaeological features is low given the degree and depth of ground disturbance and no archaeological investigations are recommended. The design of the hardscape will use cut stone and stone facing on concrete block for all visible portions of the work. This will help to tie the new and clearly modern construction both visually and materially to the historic building. This is the most visible portion of the house as it sits on a plateau above the adjacent stream valley and is approached from the gravel road below at Brighton Dam Road. Utilizing the previously disturbed below grade area for this new construction will not have a detrimental visual or physical effect on the historic architecture of the house, and could be easily removed in the future with no impact to the historic house, thereby satisfying SOI #9 and #10. Similarly, the deck about the patio will be constructed from all wood materials and will not have any adverse impact to the site. Staff has no issues with the modern metal railings and cables for the new deck itself, as this is a clearly acceptable method to differentiate modern from historic construction. The railings will have a very light visual 'weight'. However, staff finds that the extension of this clearly modern railing design on to the historic north porch to be an inappropriate alteration. While the existing wood railings are not original to the house, and it is most likely there were no railings when this block was constructed c. 1835, staff finds that a traditionally detailed wood railing is the only appropriate choice for this location on the historic building itself. There is no need to provide a visual or material differentiation in this historic porch, and staff finds that the addition of this design feature is not-compatible with the historic building. Staff has added a condition that the railing on this portion of the porch be traditionally detailed wood, with final review of compatibility and detailing delegated to staff.

New Construction – East Elevation: Dormer, Screened Porch, Hardscape, Basement Access
On the east elevation, the new construction will be directly connected to the oldest/first period of construction. Information detailing in the staff report above and in the early survey forms do note that this part of the house has been altered several times already.³ The removal of the non-historic bathroom dormer on the southern facing roof of the east elevation would remove this modern addition. The

8

³ The MIHP form is available here: https://mcatlas.org/hp2/hpdocs/M %2023-082.pdf

applicant is proposing the addition of a new dormer to be centered on this portion of the roof; the new dormer would be constructed with a shed roof, triple-ganged wood windows, and faced with 1x6 German lap siding (the same siding proposed to be used throughout). The dormer would engage the historic roof at its ridgeline. The removal of the non-historic additions on this portion of the building (and as shown in *Figure 3* above in red) should be approved as a matter of course. The newly proposed dormer is sized appropriately for this diminutive roof and portion of the house. The configuration of the windows and the size of the dormers distinguish this addition from the historic building, satisfying *SOI #9*.

The infill bathroom additions on the first floor of the southeast elevation will be removed. The applicant is proposing to expose the exterior stone wall of the existing fireplace and construct a new screened in porch on this addition. The screened in porch will measure approximately 7.75' wide by 17' long. The screened in porch will be accessed by a new wood screen door, with associated wooden steps and handrail on the south elevation. HP Office documentation from the 1970s and 1980s show there was a small lean-to covered 'porch' in this area. The newly proposed screened in porch is appropriately detailed, constructed of all wood framing and metal mesh for the screens. Much like its predecessor, this screened in porch could be removed without any impact to the historic building, and its compatible size, scale, and design make it an attractive addition to this side of the house.

The applicant is proposing to restore and reconstruct a stone patio at grade along the south and east elevations per the submitted plans. A restored access hatch to the basement will be located within the patio area adjacent to the door to the screened in porch. The restoration of the basement hatch is an appropriate rehabilitation proposal and should be approved. The old concrete slab will be removed and a stone patio installed in this area per the proposed plans. This hardscape addition will have no adverse effect on the historic building and should be approved.

Fenestration Alteration – South Elevation

The applicant is proposing an alteration to the fenestration pattern on the first floor of the central bay. This portion of the building of the building is the most recent, dating to the mid-1800s, however it is an integral part of this historic building composition. It is constructed with a balanced and symmetrical pairing of windows on the south and north elevations. To accommodate sink heights in the kitchen, the applicant is proposing to replace the two original window openings with a ganged triple window opening on the first floor of the south elevation.

While understandable from an interior design perspective, this alteration contravenes the *SOI* #2, specifically, "The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided." This middle addition to the house, constructed c. 1850s retains its Greek Revival-style elements, most notably the absolute symmetry of fenestration on both the north and south elevations. The HPC has been consistent in finding that when it comes to exterior alterations that are put forward in response to interior design or kitchen placement, that interior solutions must be found so as not to disrupt significant window patterns or other solid to void ratios. This fenestration pattern is a character defining feature of the building, indeed there are few to begin with for this spare and lightly detailed central portion, and therefore these openings should be retained. Staff has added a condition that the original fenestration pattern on this elevation will be retained and this change should be shown on the permit level drawings.



Figure 4: South elevation c.2020. The windows in question are outlined in red.



Figure 5: Proposed south elevation. The windows in question are outlined in red.

Roof Replacement

The applicant is proposing to replace the deteriorated standing seam metal roof and install a new standing seam metal roof throughout. Close investigations in the roof of the various attic spaces in 2021 uncovered evidence of a previous wood shake roof installed beneath the extant metal roof. However, the rehabilitation standards do not require restoration of the first period roof, and the replacement in kind of the standing seam metal roof is an appropriate preservation option that meets the intent of the *SOI #2*, #4, #5, and #6. The metal roof should have seams no greater than 1" and corner seams hand turned in the field. No ridge caps should be permitted. Final review of the roof specifications and installation methods should be submitted to staff with the permit level drawings for review and approval.

Chimney Rebuild and Repointing

The applicant is proposing to remove the centermost brick chimney and reconstruct it with new interior supports. The interior portion of this non-functional chimney will be demolished to accommodate interior alterations. The HPC does not have purview over the interior changes. Rebuilding the chimney to the same height, reusing the existing bricks and matching new bricks exactly where old bricks cannot be reused, using only compatible Type O Mortar, will rehabilitate this character defining feature and will

also meet SOI #2, #4, #5, and #6. Final approval of the mortar mix and a detailed drawing of the chimney will be submitted to staff with the permit level drawings for review and approval.

Gutters

The applicant will remove all deteriorated gutters and replace them with new half round metal gutters throughout. Portions of the building that did not have gutters will have them installed along the drip edge of the roofs. This alteration will have no material effect on the historic character of the resource and should be approved.

Driveway Turnaround

The final alteration will expand the driveway in the southern farmyard to provide better access to the remaining accessory buildings. This alteration will not remove or destroy any mature trees or extant outbuildings. Aerial photographs show there are no former outbuildings located in this area. Archaeological investigations should not be required since this change merely involves adding gravel to the area at grade and will not require excavation.




Figure 7: Excerpt from Sheet G01 showing the existing gravel driveway.




Figure 8: Excerpt from Sheet A01 showing the expanded gravel turnaround within the red circle.

STAFF RECOMMENDATION:

After full and fair consideration of the applicant's submission, staff finds the proposal consistent with the Criteria for Issuance in Chapter 24A-(b)(1) and (2), and having found it consistent with the Secretary of the Interior's Standards for Rehabilitation #2, #3, #5, #6, #9, and #10 as outlined above.

STAFF RECOMMENDATION

Staff recommends that the Commission <u>approve</u> the HAWP application with five (5) conditions as noted on page 1, and under the Criteria for Issuance in Chapter 24A-(b)(1) and (2), and having found that the proposal will not substantially alter the exterior features of the historic resource and is compatible in character with the purposes of Chapter 24A;

and with the Secretary of the Interior's Standards for Rehabilitation #2, #3, #5, #6, #9 and #10;

and with the general condition that the applicant shall present an electronic set of drawings, if applicable, to Historic Preservation Commission (HPC) staff for review and stamping prior to submission for the Montgomery County Department of Permitting Services (DPS) building permits;

and with the general condition that final project design details, not specifically delineated by the Commission, shall be approved by HPC staff or brought back to the Commission as a revised HAWP application at staff's discretion;

and with the general condition that the applicant shall notify the Historic Preservation Staff if they propose to make **any alterations** to the approved plans. Once the work is completed the applicant will contact the staff person assigned to this application at 301-563-3404 or rebeccah.ballo@montgomeryplanning.org to schedule a follow-up site visit.

THU, MAY 29, 1986,

ATLAS #: 23/082-000

HIST. NAME:

GRAFTON HOLLAND FARM

ADDRESS: 2240 BRIGHTON DAM ROAD OWNER: INGRID SOLEM

LOCATION:

LAYTONSVILLE

PHONE 703-356-1989 1130 BASIL ROAD CITY: MCLEAN ST: VA Z 22101

TAX ACCT. #: 00719470

TAX MAP #: JU122

227W02

LOT/BL/PARCEL: P311

MAP COORD.

ACREAGE

AREA MASTER PLAN:

OLNEY - 1980

CIVIC ASSOC: 357 358

EX. ZONING: RC

EX. USE:

RURAL/RESIDENTIAL

***** DESCRIPTION/SIGNIFICANCE *****

ORDINANCE CRITERIA 1A: X 1B:

10: X 1D:

2A: 2B: 2D:

20:

SE:

YEAR: C 1830

COND GOOD

STYLE: RURAL VERNACULAR

ENVIR. SETTING & APPURT .: HPC REC .= ENTIRE 74 ACRES AND ALL OUTBUILDINGS

10.2710 acres

**** STATUS ****

SITE: X DISTRICT: RESOURCE:

LATLAS: X

MPLAN:

REMOVE LA

HISTORIC PRES. COMM. EVAL DATE: 09/19/85 HPC TRANS DATE: 10/29/85 HPC REC: POS

PLAN. BD. PUBLIC HEARING DATE: 04/21/86

PB ACTION DATE:

COUNTY COUNCIL PH DATE:

CC ACTION DATE:

PB RES. DATE:

CC RESOLUTION NO. : FULL COMM. RES. NO .:

PB RES. NO.: FC RES. DATE:

ENTRY DATE: 05/28/86

CRITERIA

- (1) Historical and cultural significance. The historic resource:
- a. Has character, interest or value as part of the development, heritage or cultural characteristics of the county, state or nation:
 - b. Is the site of a significant historic event;
- c. Is identified with a person or a group of persons who influenced society; or
- d. Exemplifies the cultural economic, social, political or historic heritage of the county and its communities.
- (2) Architectural and design significance. The historic resource:
- a. Embodies the distinctive characteristics of a type, period or method of construction;
 - b. Represents the work of a master;
 - c. Possesses high artistic values;
- d. Represents a significant and distinguishable entity whose components may lack individual distinction; or
- e. Represents an established and familiar visual feature of the neighborhood, community or county due to its singular physical characteristic or landscape. (Ord. No. 9-4, § 1.)


6/25/02 OWNER: INGRID SOLEM 1130 BASIL MCLEAN 7210

23/82 GRAFTON HOLLAND FARM

Atlas #	<u>Site</u>	Location	Associated <u>Acreage</u>
23/82	Grafton Holland Farm (Sunnymeade Farm)	2240 Brighton Dam Road	
•		nd log farmhouse built in thre e evolution of rural architectur	
•	Associated with the Brookeville/Brighton	Holland family, influential lan	d-owners and farmers in the
•		nvironmental setting includes associated with the site."	the entire 11.36-acre parcel


23/82








GRAFTON HOLLAND #23/82







	" Crofton Wallen Boum	23/82
1.	Name: Grafton Hollanu Farm	yes 9/85
2.	Planning Area/Site Number: 23/82	
4.	Address: Brighton Dam Road Brookeville, Maryland	Coordinate J-15
5.	Classification Summary	
	Category building Ownership private Public Acquisition N/A Status occupied	Previous Survey Recording MNCPPC Title and Date: Historic Sites Invento
	Accessible no Present use agriculture/private r	FederalState_x_County_x_Localesidence
6.	Date: c. 1830 7. Orig	inal Owner:
8.	Apparent Condition	
•	whhar end conditional	
•	a. good b. altered	c. original site
	a. good b. altered Description: The present "farmhous deceptive, as the house was built i section faces north and has three A one-story porch crosses the first on both levels at the west wall, an trim here.	e" appearance of this structure is n three parts. The main northwest bays with a door in the northeast bay. story. There are interior fireplaces d there are chair-rails and other early
	a. good b. altered Description: The present "farmhous deceptive, as the house was built i section faces north and has three A one-story porch crosses the first on both levels at the west wall, an trim here. Built onto the east end is a t south (perpendicular to the horizon on its north end, and there are cha sections are all six-over-six.	e" appearance of this structure is n three parts. The main northwest bays with a door in the northeast bay. story. There are interior fireplaces

gable end, and a two-story porch extends to the rear of the house.

10. Significance: This farm house overlooking the lovely Hawlings River Valle between Brookeville and Brighton is associated with the Holland family, wh

first bought land in the area from Richard Simmons in 1742.

In 1834 the children of James Holland divided the estate of their lat father according to his will. Grafton Holland received 92 acres of land from the tract "Bordley's Choice" with buildings and improvements. He probably built or improved the house at this time which approximately coin cided with the time of his marriage. His first child, Thomas Jr. was born a year later. Grafton added to his holdings, between 1840 and 1854 he accummulated an additional 544 acres of land, two servants, two slaves an \$10,000 in personal property.

The property remained in the Holland family until 1929. The current

owner purchased the property in 1953.

Michael Dwyer - Arch. Description 11. Researcher and date researched: Roberta Hahn July 1979

12. Compiler: Margaret Coleman 13. Date Compiled: Sept. 1979 14. Designation Approval

15. Acreage: 74.48 acres

The first site to be evaluated by the Commission was the Grafton Holland Farm (#23/82). Mrs. Hahn made the staff presentation for this historic site. The Grafcon Holland Farm is one of three Holland farms in the Hawlings River valley between Brookeville and Brighton. The first section of this house is believed to have been built sometime around 1800 and was of log construction. This farm was passed on to Grafton Holland as his share of the estate of his father James Holland in 1834 at about which time the western-most block of the house is believed to have been built. The two sections are believed to have been joined sometime soon thereafter, certainly before the death of Grafton Holland in 1864. Although the original log section of the house has been altered in shape, the two later, more massive sections are little changed from their The Hollands were major original architectural form. landowners and farmers in the area and as such were of local importance. Ingrid Solem, the owner, spoke in favor of designation. Mr. Cantelon spoke about the clean lines of the house. Ms. McGuckian noted the fine collection of out-buildings on the property and said that she found the additions to the house interesting.

MOTION: Ms. McGuckian moved that the Grafton Holland Farm be recommended for placement on the Master Plan with the entire 74 acres as the environmental setting and all out-buildings based on criteria lc and la for its association with the Holland family and as a representative of the evolution of rural vernacular architecture in the area. Mrs. Kuklewicz seconded the motion which passed unanimously.

* HPC Recommendation - 10/29/85

The Commission recommends the Grafton Holland Farm (#23/82) for placement on the Master Plan for Historic Preservation based on criteria la, ("has character, interest, or value as part of the development, heritage, or cultural characteristics of the County, State or Nation"); and 1c. ("is identified with a person or group of persons who has influenced society"). recommended environmental setting is the entire 74 acre parcel including all outbuildings. The first section of this house. located between Brookeville and Brighton in the Hawlings River Valley, is believed to have been built around 1800 and is of log construction. The farm was passed on to Grafton Holland as his share of the estate of his father, James Holland, in 1834 at which time the western-most block of the house was believed to have been built. The sections were joined soon thereafter. Although the original log section of the house has been altered the two later, more massive sections are little changed from their original architectural form. The Hollands were major landowners and farmers in the area and because of their expensive holdings exerted considerable influence in the Brookeville/Brighton area. The house itself is representative of the evolution of rural vernacular architecture in the area.

DESCRIPTION

CONDITION

CHECK ONE

CHECK ONE

__EXCELLENT

__DETERIORATED

X_ORIGINAL SITE

∭GOOD __FAIR __RUINS

X_ALTERED

__MOVED DATE____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The present "farmhouse" appearance of this structure is deceptive, as the house was built in three parts. The main northwest section faces north and has three bays with a door in the northeast bay. A one-story porch crosses the first story. There are interior fireplaces on both levels at the west wall, and there are chair-rails and other early trim here.

Built onto the east end is a two-story section that extends north to south (perpendicular to the horizontal section). This part has two bays on its north end, and there are chair-rails here, also. Windows in both sections are all six-over-six.

The third part is probably earlier yet since it is a low, one-story section with a massive stone fireplace chimney embedded in the east wall. The house is now sheathed in German siding, but old clapboards and nails can be seen on the rear of the west part. Like the two other Holland houses in the valley, there is a blank end wall with two small windows high in the gable end, and a two-story porch extends to the rear of the house.

tache" was in it.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

I NAME		
	rafton Holland Farm	
AND/OR COMMON	"Sunnymeade Farm"	
2 LOCATION	V	
STREET & NUMBER	2222 Brighton Dam Road	in the swift of the state of th
	Brookeville vicinity of	CONGRESSIONAL DISTRICT
STATE	Maryland	COUNTY Montgomery
3 CLASSIFIC		TIOTOG OMET Y
CATEGORY	OWNERSHIP STATUS	. PRESENT USE
A BUILDING(S)	TPUBLIC XOCCUPIED TPUBLIC XOCCUPIED UNOCCUPIED	X_AGRICULTUREMUSEUM COMMERCIALPARK
STRUCTURE	BOTHWORK IN PROGRESS	_EDUCATIONAL X_PRIVATE RESIDEN
SITE	PUBLIC ACQUISITION ACCESSIBLE	ENTERTAINMENTRELIGIOUS
OBJECT	IN PROCESSYES: RESTRICTED	GOVERNMENTSCIENTIFIC
	BEING CONSIDEREDYES: UNRESTRICTED ★NO	INDUSTRIALTRANSPORTATIO MILITARYOTHER:
OWNER O	Ingrid Solem	Telephone #: 356-1989
STREET & NUMBER	1130 Basil Road	
CITY, TOWN	McLean vicinity of	STATE, zip code Virginia 22101
LOCATION	OF LEGAL DESCRIPTION	7.21
COURTHOUSE		Liber #: 1782
REGISTRY OF DEEDS,	ETC Montgomery County Courthouse	Folio #: 511
STREET & NUMBER		17
CITY, TOWN	Rockville	STATE Monistration 3
6 REPRESEN	TATION IN EXISTING SURVEYS	Maryland
TITLE	M-NCPPC Inventory of Historic S	
DATE		
DEPOSITORY FOR	1976FEDERALX	_STATE X.COUNTY _LOCAL
SURVEY RECORDS	Park Historian's Office	
CITY, TOWN		STATE
	Rockville	Maryland 20855

CONDITION

__EXCELLENT

XG00D

__DETERIORATED

__RUINS

__UNALTERED X_ALTERED

CHECK ONE

CHECK ONE

X ORIGINAL SITE _MOVED

__FAIR __UNEXPOSED

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The present "farmhouse" appearance of this structure is deceptive, as the house was built in three parts. The main northwest section faces north and has three bays with a door in the northeast bay. A one-story porch crosses the first story. There are interior fireplaces on both levels at the west wall, and there are chair-rails and other early trim here.

Built onto the east end is a two-story section that extends north to south (perpendicular to the horizontal section). This part has two bays on its north end, and there are chair-rails here, also. Windows in both sections are all six-over-six.

The third part is probably earlier yet since it is a low, one-story section with a massive stone fireplace chimney embedded in the east wall. The house is now sheathed in German siding, but old clapboards and nails can be seen on the rear of the west part. Like the two other Holland houses in the valley, there is a blank end wall with two small windows high in the gable end, and a two-story porch extends to the rear of the house.

MAJOR BIBLIOGRAPHICAL REFERENCES

Land Records of Montgomery County, Maryland.
Montgomery County Tax Assessment Records.
U.S. Census Records.

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY 74.48 acres

VERBAL BOUNDARY DESCRIPTION

1. 3 17.5

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

energy of the gar over the secret, and

II FORM PREPARED BY

NAME/TITLE Roberta Hahn

Michael Dwyer Architectural Description

ORGANIZATION

Sugarloaf Regional Trails

July 1979

STREET & NUMBER

TELEPHONE

Box 87

926-4510

CITY OR TOWN

STATE

Dickerson

Maryland 20753

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust

The Shaw House, 21 State Circle

Annapolis, Maryland 21401

(301) 267-1438

P8- 110

AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW

__PREHISTORIC __ARCHEULUGY-PREHISTORIC __COMMUNITY PLANNING **LANDSCAPE ARCHITECTURE** -RELIGION __1400-1499 __ARCHEOLOGY-HISTORIC __CONSERVATION ...LAW __SCIENCE __1500-1599 XAGRICULTURE __ECONOMICS __LITERATURE __SCULPTURE _1600-1699 _ARCHITECTURE __EDUCATION __MILITARY _SOCIAL/HUMANITARIAN _1700-1799 ...ART __ENGINEERING _MUSIC : __THEATER X 1800-1899 __COMMERCE __EXPLORATION/SETTLEMENT __PHILOSOPHY __TRANSPORTATION1900-**__COMMUNICATIONS** _INDUSTRY __POLITICS/GOVERNMENT _OTHER (SPECIFY)

SPECIFIC DATES

PERIOD

c. 1830

BUILDER/ARCHITECT

Grafton Holland

STATEMENT OF SIGNIFICANCE

This farm house overlooking the lovely Hawlings River Valley between Brookeville and Brighton is associated with the Holland family, who first

bought land in the area from Richard Simmons in 1742.1

_INVENTION

Grafton Holland, who is traditionally considered the builder of this home, was born in 1800, the son of James Holland. In 1834 Grafton and his brothers and sisters, Charles, Lemuel, Philip, Sarah, Ann, and Mercy Ann, divided the estate of their late father according to his oral will.2 The three girls were to get the mansion house of James Holland and 369 acres, and the boys were to get their own farms. At that time Grafton received 92 acres of "Bordley's Choice" with buildings and improvements.

It is probable that Grafton Holland built or expanded his home at about the time of his inheritance which was also shortly after his marria to his wife, Ellen, and shortly before the birth of his first child, Thomas J., in 1835. He seems to have been an industrious and successful farmer: by 1840 he had two servants and two slaves in his household; 3 by 1841 he had an additional 100 acres of farm land; by 1850 his worth was given as \$10,000 in the Census Record, and by the 1854 tax assessment his property includes 100 acres of "Bordley's Choice" and 344 acres of part of "Rum Punch" and part of Dublin.6

Following Grafton's death in 1863, his son Thomas J. inherited 99 acres of Bordley's Choice with the home and 49 acres of the Gittings HaHa property. 7 He and his wife Charlotte apparently had no children, and the sold his land to his nephew, James C. Holland, in 1900 for \$5,863.37. His son Willie Grafton Holland inherited the property in 1929 and immediately sold it to Gertrude Doyle, who retained ownership until 1953. The old Grafton Holland farm is now owned by Joseph Solem, a Washington, D.C.

attorney.

FOOTNOTES:

1. Mentioned, Land Records of Montgomery County, Md., JA 33/83 (April 189: 2. Ibid., BS 6/560 - 570 (October 1834).

3. U.S. Census Records (1840).
4. Montgomery County Tax Assessment Records (1841).

5. U.S. Census Records (1850).

- 6. Tax Assessment Records, Op. Cit., (1854).
 7. Ibid., (1879). Note: 1857 road part refers to widow Holland (?).
 8. Land Records, Op. Cit., TD 114/139 (Feb. 1900).
 9. Ibid., 482/214 (April 27, 1929).

MAJOR BIBLIOGRAPHICAL REFERENCES

Land Records of Montgomery County, Maryland. Montgomery County Tax Assessment Records. U.S. Census Records.

CONTINUE ON SEPARATE SHEET IF NECESSARY

MIGEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY

74.48 acres

VERBAL BOUNDARY DESCRIPTION

7. 3. 12. 1.

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

COUNTY

FORM	PREPARED	BY
ENTER OFFICE	T YAND TITLE	

NAME / TITLE

Roberta Hahn

Michael Dwyer

Architectural Description

ORGANIZATION

Sugarloaf Regional Trails

STREET & NUMBER

TELEPHONE

...Box 87

926-4510

CITY OR TOWN

STATE

Dickerson

Maryland 20753

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA,

what are he has not been be brought to

1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.


RETURN TO:


Maryland Historical Trust

The Shaw House, 21 State Circle

Annapolis, Maryland 21401

(301) 267-1438





Resolution No. 10-2179

Introduced:

1986 September 23.

Adopted:

September 23, 1986

COUNTY COUNCIL FOR MONTGOMERY COUNTY, MARYLAND SITTING AS THE DISTRICT COUNCIL FOR THAT PORTION OF THE MARYLAND-WASHINGTON REGIONAL DISTRICT WITHIN MONTGOMERY COUNTY, HARYLAND

By: District Council

Amendment to the Approved and Adopted Master Plan for Historic Preservation in Montgomery County, Maryland re: Six Historic Resources in Northern and Eastern Montgomery County

Background

- On June 12, 1986, the Montgomery County Planning Board transmitted to the Montgomery County Council a Final Draft Amendment to the Historic Preservation Master Plan proposing the designation of three sites in the Bethesda Central Business District.
- 2. On September 16, 1986, the Planning, Housing and Economic Development Committee reviewed the Final Draft Master Plan Amendment and the testimony given at the public hearing with the Montgomery County Planning Board, staff, and interested parties.
- 3. The Montgomery County Council reviewed the Final Draft Amendment and the recommendations of the Planning, Housing and Economic Development Committee at a worksession held on September 23, 1986.

Action

For these reasons, the County Council for Montgomery County, Maryland, sitting as the District Council for that portion of the Maryland-Washington Regional District in Montgomery County, Maryland, approves the following resolution:

The Final Draft Amendment to the Historic Preservation Master Plan, for the designation of six historic resources in Northern and Eastern Montgomery County, dated June 1986, is approved as amended:

Resolution No. 10-2179

-2-

<u>Site</u>	Name	Location	Associated Acreage
#15/67	Maiden's Fancy - * * * - * * *	15701 Aitcheson Lane	18.97
#23/19	Retirement _ * * * _ * * * _ * * * _ * * *	5501 Griffith Road	3.5
#23/33	Bleakwood - * * * - * * *	3730 Damascus Road	1.87
#23/82	Grafton Holland Farm - * * * - * * * - * * *	2240 Brighton Dam Ros	id 11.36
#23/103	John D. Berry House - * * * - * * *	17201 Palomino Court	4.52
•	Jacob Allnutt Farm _ * * * _ * * * _ * * * _ * * *	23601 Route 108	2.5

This is a correct copy of Council Action.

Donna Brand, Assistant Secretary
County Council

JA:mc 0026b



VIEW FROM SOUTHWEST SHOWING GARAGE ELEVATED PATIO, RAILING & HIGH AWNING, c. 1979 Provided by Ingrid Solem (apparently included in ACHS Summary Form, Sept 1979)



VIEW FROM SOUTHEAST SHOWING EAST SHED ROOF WITH LOW EAVE & WEST PATIO, c. 1985 Provided by Ingrid Solem (apparently included in HPC Recommendation, Oct 1985)

MICHE	BOOZ
ARCH	TECT
15 High St, Brook	l keville, MD 20833

Duane & Rachel Epperly **Grafton Holland Farm**

2240 Brighton Dam Road, Brookeville, MD 20833

"Sunnymeade Farm" MHT Inventory M:23/82

FARMHOUSE SCHEMATIC DESIGN September 21, 2022

HAWP Review

HISTORIC CONDITIONS

EXTERIOR PHOTOS

G83



FOR STAFF ONLY: HAWP# 1007629 DATE ASSIGNED___

APPLICATION FOR HISTORIC AREA WORK PERMIT HISTORIC PRESERVATION COMMISSION 301.563.3400

APPLICANT:

Name: Duane Epperly	E-mail: duane@epperly.me
Address: 22600 Fitzgerald Drive	City: Gaithersburg Zip: 20882
Daytime Phone:	Tax Account No.: 00719470
AGENT/CONTACT (if applicable):	
Name: Miche Booz Architect	E-mail: mbooz@michebooz.com
Address: 15 High Street	City: Brookeville Zip: 20833
Daytime Phone: 3017746911	Contractor Registration No.:
LOCATION OF BUILDING/PREMISE: MIHP # of Hi	istoric Property M: 23-82
map of the easement, and documentation from th	ovals / Reviews Required as part of this Application?
Building Number: 2240 Street: E	Brighton Dam Road
Town/City: Brookeville Nearest	Cross Street: Golden Valley Lane
Lot: - Subdivis	ion: <u>0501</u> Parcel: <u>P311</u>
	plication. Incomplete Applications will not Shed/Garage/Accessory Structu Solar Tree removal/planting andscape Window/Door Other: Pool the foregoing application, that the application is correly with plans reviewed and approved by all necessary

HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFING

[Owner, Owner's Agent, Adjacent and Confronting Property Owners]

Owner's mailing address	Owner's Agent's mailing address
Duane Epperly 22600 Fitzgerald Drive Gaithersburg, MD 20882	Miche Booz 208 Market Street Brookeville, MD 20833
Adjacent and confronting	Property Owners mailing addresses
Prakash, John & Elizabeth Liv Trust 19737 Golden Valley Lane Brookeville, MD 20833	Sunnymeade Homeowners Assn 19727 Golden Valley Lane Brookeville, MD 20833
Gaskill William H 3RD & K T 19709 Golden Valley Lane Brookeville, MD 20833	

Description of Property: Please describe the building and surrounding environment. Include information on significant structures landscape features, or other significant features of the property:
Description of Work Proposed: Please give an overview of the work to be undertaken: Stabilization + renovation of historic farm house and outbuildings. The 2- story frame house will have the exterior siding and finishes restored and interior renovated with preservation of original woodwork detailing.
Farmhouse in significant disrepair. Structural work necessary foundation to roof. Many elements have non-original repairs, need replacement for structure/energy. Renovation for accessibility requires adding/modifying +/- 6 windows, improving doors, site access. New to match historic as is possible.

Work Item 1:	
Description of Current Condition:	Proposed Work:
Work Item 2:	
Description of Current Condition:	Proposed Work:
Work Item 3:	
Description of Current Condition:	Proposed Work:

HISTORIC AREA WORK PERMIT CHECKLIST OF APPLICATION REQUIREMENTS

	Required Attachments						
Proposed Work	I. Written Description	2. Site Plan	3. Plans/ Elevations	4. Material Specifications	5. Photographs	6. Tree Survey	7. Property Owner Addresses
New Construction	*	*	*	*	*	*	*
Additions/ Alterations	*	*	*	*	*	*	*
Demolition	*	*	*		*		*
Deck/Porch	*	*	*	*	*	*	*
Fence/Wall	*	*	*	*	*	*	*
Driveway/ Parking Area	*	*		*	*	*	*
Grading/Exc avation/Land scaing	*	*		*	*	*	*
Tree Removal	*	*		*	*	*	*
Siding/ Roof Changes	*	*	*	*	*		*
Window/ Door Changes	*	*	*	*	*		*
Masonry Repair/ Repoint	*	*	*	*	*		*
Signs	*	*	*	*	*		*

TAX MAP: #JU12 TAX ACCOUNT#: 00719470

PARCEL: P311 LIBER: 64760 FOLIO: 00062

TRACT AREA: 11.36 ACRES

PROPERTY INFO

WATERSHED:

HAWLINGS RIVER-REDDY BRANCH

SPA: NO

STREAM BUFFER: 100'

PROJECT TEAM

OWNER DUANE AND RACHEL EPPERLY

ARCHITECT MICHE BOOZ ARCHITECT, INC. MICHE BOOZ, AIA

CIVIL ENGINEER LANDMARK ENGINEERING, INC. CHARLES T. GRIMSLEY, P.E.

LOT DESCRIPTION ZONE: RC

SEE TITLEBLOCK FOR

REQUIRED SETBACKS FRONT YARD: 80' SIDE YARD: 15' EACH REAR YARD: 35'

BUILDING HEIGHT ALLOWABLE: 50'

AVG. FRONT GRADE

PROPERTY INFORMATION

PROPOSED STRUCTURE: 25'-0" FROM

LOT COVERAGE (STANDARD DEVEL.) LOT SIZE: 11.36 ac = 494,841 SF

PROJECT DESCRIPTION

DOORS + OTHER ELEMENTS.

THE PROJECT SHALL REPAIR AND RENOVATE THE HISTORIC

FARM) AT 2240 BRIGHTON DAM ROAD, BROOKEVILLE (NOT

REVEALED SEVERE DEGRADATION OF THE STRUCTURE AND

ENVELOPE AS WELL AS EXTENSIVE DAMAGE TO WINDOWS,

THE WORK SHALL INCLUDE DEMOLITION OF NON-HISTORIC

ELEVATED SLAB PATIO, 1ST FLR BATHROOM ADDITONS +

2ND FLR BATHROOM DORMER. THE SIDING, ROOF, TRIM,

INSULATED EXTERIOR SHEATHING WILL BE USED TO STABILIZE

REPLACED WITH STONE CLAD PATIO ON GRADE (+ RETAINING

WALLS); ELEVATED SLAB PATIO/ROOF TO BE REPLACED WITH

SMALLER WOOD DECK + SITE STAIRS. BASEMENT ACCESS

THE WEST ATTACHED GARAGE SHALL BE DEMOLISHED +

FARMHOUSE AT "SUNNYMEADE", (THE GRAFTON HOLLAND

IN HISTORIC DISTRICT). THE EXISTING HOUSE IS IN A

DANGEROUS AND DERELICT STATE BUT RETAINS IT'S

FEATURES NAMELY THE WEST CONCRETE GARAGE +

AND MAJORITY OF WINDOWS AND DOORS SHALL BE REPLACED WITH NEW ELEMENTS TO MATCH EXISTING (AS POSSIBLE). EXTENSIVE REPAIR AND REPLACEMENT OF

TIMBER STRUCTURE IS REQUIRED DUE TO ROT; NEW

TO BE MAINTAINED AND DOOR REPLACED.

HISTORIC CHARACTER, HOWEVER INVESTIGATION HAS

"Sunnvmeade Farm'

AIO

ALI

G80

A50

A60

FARMHOUSE SCHEMATIC DESIGN

AT THE EAST SECTION THREE NON-HISTORIC BATHROOMS DEMOLISHED AND MAIN STRUCTURE RESTORED TO EARLIER HISTORIC PROFILE. SECOND FLR BATHROOM REPLACED WITH

AT THE EAST ELEVATION THERE WAS ONCE A WIDE PORCH ROOF THAT WAS APPROX. 2/3 ENCLOSED AND WHICH INCLUDED STEPS TO A STONE PATIO (AS REVEALED THROUGH INVESTIGATION). A NEW ROOF, SCREENED PORCH, AND STONE PATIO WILL BE CONSTRUCTED IN THE APPROXIMATE LOCATION

WIDER DORMER CENTERED IN SOUTH FACING ROOF.

REPLACEMENT WINDOWS WILL BE WOOD EXTERIOR + INTERIOR WITH DIVISIONS AND DETAILS TO MATCH THOSE REPLACED.

THE CENTER CHIMNEY IS NON-FUNCTIONAL AND SHALL BE REMOVED AT THE SECOND FLOOR AND ABOVE. THE LARGE STONE FIREPLACE ON 1ST FLR WILL BE RETAINED AS ORNAMENT AND A NON-FUNCTIONING CHIMNEY ELEMENT CONSTRUCTED AT THE ROOF TO SIMULATE THE ORIGINAL.

THE GRAVEL DRIVEWAY WILL BE REGRADED FOR ALIGNMENT AS NEEDED AND THE FARMYARD TURN AROUND SHALL BE EXPANDED FOR BETTER ACCESS TO THE CORN CRIB + HAY BARN.

ZONING PROPOSED VIEW

ENCLOSURE.

RENDERING FROM DRIVEWAY LOOKING SOUTHEAST



continued,



DRAWING LIST

MNCPPC

INCLUDING ACCESSORY

PRELIMINARY HAWP: DATED | 2/15/2021 NUMBER: 975256

COI PROJECT INFORMATION PROPERTY SITE PLAN GO I GO3 EXISTING HOUSE SITE PLAN GIO EXISTING BASEMENT PLAN G20 EXISTING NORTH ELEVATION G2 I EXISTING EAST ELEVATION G22 EXISTING SOUTH ELEVATION G23 EXISTING WEST ELEVATION

G81 EXISTING CONDITIONS PHOTOS G82 EXISTING CONDITIONS PHOTOS G83 EXISTING CONDITIONS PHOTOS AO I A04

ARCHITECTURAL SITE PLAN FARMHOUSE AREA SITE PLAN BASEMENT PLAN FIRST FLOOR PLAN

EXISTING CONDITIONS PHOTOS AI2 SECOND FLOOR PLAN A14 ROOF PLAN A20 NORTH ELEVATION A21 EAST ELEVATION A22 SOUTH ELEVATION A23

A92 A93 A94 A95 WEST ELEVATION WINDOW DETAILS A96 **SCHEDULES** A97

A90

A91

HISTORIC COMPARISON FROM SE HISTORIC COMPARISON FROM N AERIAL VIEWS FROM NE + NW AERIAL VIEW FROM SOUTHWEST GROUND LEVEL VIEW GROUND LEVEL VIEW GROUND LEVEL VIEW GROUND LEVEL VIEW

RENDERED VIEWS

MICHE BOOZ ARCHITECT

l 5 High St, Brookeville, MD 20833

Grafton Holland Farm 2240 Brighton Dam Road, Brookeville, MD 20833

Duane & Rachel Epperly


MHT Inventory M:23/82


HAWP Review


September 28, 2022

PROJECT INFORMATION

C01







MICHE BOOZ

ARCHITECT

15 High St, Brookeville, MD 20833
301 774 6911

Duane & Rachel Epperly

Grafton Holland Farm

2240 Brighton Dam Road, Brookeville, MD 20833

"Sunnymeade Farm"

MHT Inventory M:23/82

FARMHOUSE SCHEMATIC DESIGN


HAWP Review


September 21, 2022



1/8" = 1'

EXISTING BASEMENT FLOOR PLAN





MICHE	BOOZ
ARCH	TECT
15 High St, Broo 301 774 6911	keville, MD 20833

Duane & Rachel Epperly

Grafton Holland Farm "Sunny
2240 Brighton Dam Road, Brookeville, MD 20833 MHT

"Sunnymeade Farm"

MHT Inventory M:23/82

FARMHOUSE
SCHEMATIC DESIGN


HAWP Review September 21, 2022



EXISTING SECOND FLOOR PLAN

1/8" = 1'

G12



MICHE	BOOZ
ARCH	TECT
15 High St, Broo 301 774 6911	keville, MD 20833

Duane & Rachel Epperly

Grafton Holland Farm "Sunnymeade Farm"

2240 Brighton Dam Road, Brookeville, MD 20833 MHT Inventory M:23/82

FARMHOUSE
SCHEMATIC DESIGN


HAWP Review September 21, 2022



EXISTING THIRD FLOOR PLAN

1/8" = 1'

G13





4 VIEW FROM SOUTHEAST



2 VIEW FROM SOUTHWEST



3 VIEW FROM SOUTH



VIEW FROM NORTHWEST

MICHE	BOOZ
ARCH	ТЕСТ
15 High St, Broo 301 774 6911	keville, MD 20833

2240 Brighton Dam Road, Brookeville, MD 20833

"Sunnymeade Farm"

MHT Inventory M:23/82

FARMHOUSE SCHEMATIC DESIGN

HAWP Review

September 21, 2022

EXISTING CONDITIONS

EXTERIOR PHOTOS

G80



4 NORTH FOUNDATION WALL AT PORCH



2 NORTH PORCH + ELEVATED SLAB



3 VIEW IN GARAGE LOOKING NORTHEAST



1 VIEW OF GARAGE FROM WEST

MICHE	BOOZ
ARCH	TECT
15 High St, Broo 301 774 6911	keville, MD 20833

"Sunnymeade Farm"

FARMHOUSE SCHEMATIC DESIGN

EXISTING CONDITIONS

G81

HAWP Review September 21, 2022

2240 Brighton Dam Road, Brookeville, MD 20833 MHT Inventory M:23/82

22 EXTERIOR PHOTOS




DEGRADED ORIGINAL FNDTN + STRUCTURE AT SE



HISTORIC SIDING AT 2ND FLR BATHROOM DORMER



ROTTED STRUCTURE AT COLLAPSED SHED ROOF AT BATHRMS



ROTTED SILL + RESTORED FNDTN AT NW



EVIDENCE OF STONE PATIO FOUNDATION



VIEW OF EAST SECTION DURING STRUCTURAL STABILIZATION

MICHE	BOOZ
ARCH	TECT
15 High St, Broo 301 774 6911	eville, MD 20833

2240 Brighton Dam Road, Brookeville, MD 20833

"Sunnymeade Farm"


FARMHOUSE SCHEMATIC DESIGN


EXISTING CONDITIONS


EXTERIOR PHOTOS


G82


MHT Inventory M:23/82 **HAWP Review** September 21, 2022











MICHE	BOOZ
ARCH	TECT
15 High St, Broo 301 774 6911	keville, MD 20833

Duane & Rachel Epperly

Grafton Holland Farm

2240 Brighton Dam Road, Brookeville, MD 20833

"Sunnymeade Farm"

MHT Inventory M:23/82

FARMHOUSE SCHEMATIC DESIGN


HAWP Review


September 28, 2022




1/8" = 1'

PROPOSED SECOND FLOOR PLAN







MICHE | BOOZ

A R C H | T E C T

15 High St, Brookeville, MD 20833
301 774 6911

Duane & Rachel Epperly

Grafton Holland Farm

"Sunnymeade Farm"

FARMHOUSE SCHEMATIC DESIGN



1/8" = 1'

SOUTH ELEVATION


A22

September 28, 2022




MICHE	BOOZ
ARCH	ТЕСТ
15 High St, Brook	keville, MD 20833

3/16" = 1'



EXISTING WINDOW SCHEDULE									
SYMBOL	TYPE	MANUF.	DESCRIPTION	DIM. (W x H)	STYLE	GLAZING	HARDWARE	QTY	NOTES
1	DOUBLE HUNG	EXISTING	1ST FLR TYP (CENTER, WEST)	RO: 2'-8" x 5'-0" (VIF) FS: 2'-7 1/2" x 4'-11 1/2" (VIF)	9/6 DL	SINGLE PANE, CLR, REPLACEMENT	THUMB LATCH	8	
2>	DOUBLE HUNG	EXISTING	2ND FLR TYP (CENTER, WEST)	RO: 2'-8" x 4'-3" (VIF) FS: 2'-7 1/2" x 4'-2" (VIF)	6/6 DL	SINGLE PANE, CLEAR, REPLACEMENT	THUMB LATCH	9	
3>	DOUBLE HUNG	EXISTING	IST FLR EAST, TRIPLE MULLED	RO: 2'-6" x 4'-0" (VIF) FS: 2'-5 1/2" x 3-11 1/2" (VIF)	4/4 DL	SINGLE PANE, CLEAR, REPLACEMENT	THUMB LATCH	3	
4	CASEMENT INSWING	EXISTING	IST FLR EAST, HINGED	RO: 1'-10" x 2'-8" (VIF) FS: 1'-9 1/2" x 2'-7 1/2" (VIF)	2/2 DL	SINGLE PANE, CLEAR, REPLACEMENT	THUMB LATCH	1	
(5)	FIXED TRANSOM	EXISTING	IST FLR EAST, POWDER RMS	RO: 2'-9" x 1'-3" (VIF) FS: 2'-8" x 1-2" (VIF)	3/1 DL	SINGLE PANE, CLEAR, REPLACEMENT	-	2	
6	CASEMENT INSWING	EXISTING	2ND FLR EAST, HINGED	RO: 2'-8" x 3'-6" (VIF) FS: 2'-7 1/2" x 3-5 1/2" (VIF)	SNGLE PANE	SINGLE PANE, CLEAR, REPLACEMENT	THUMB LATCH	1	
7	DOUBLE HUNG	EXISTING	2ND FLR, BATHROOM	RO: 2'-8" x 4'-0" (VIF) FS: 2'-7 1/2" x 3'-11 1/2" (VIF)	6/6 DL	SINGLE PANE, FROSTED, REPLACEMENT	THUMB LATCH	1	
8	DOUBLE HUNG	EXISTING	ATTIC CENTER	RO: 2'-8" x 3'-6" (VIF) FS: 2'-7 1/2" x 3-5 1/2" (VIF)	6/3 DL	SINGLE PANE, CLEAR, REPLACEMENT	THUMB LATCH	2	
9>	CASEMENT INSWING	EXISTING	ATTIC WEST, HINGED	RO: 1'-8" x 2'-0" (VIF) FS: 1'-7" x 1-11 1/2" (VIF)	2/2 DL	SINGLE PANE, CLEAR, REPLACEMENT	THUMB LATCH	2	
10>	AWNING INSWING	EXISTING	BASEMENT WEST, HINGED	RO: 2'-0" x 1'-6" (VIF) FS: 1'-8" x 1-2" (VIF)	3/1 DL	SINGLE PANE, CLEAR, REPLACEMENT	THUMB LATCH	4	

PROP	PROPOSED WINDOW SCHEDULE											
SYMBOL	TYPE	MANUF.	DESCRIPTION [BASIS OF DESIGN]	DIM. (W x H)	STYLE	GLAZING	U - VALUE	SHGC	VT	HARDWARE	QTY	NOTES
1	DOUBLE HUNG 1ST FLR TYP	MARVIN	SIGNATURE ULTIMATE WOOD INSERT [UWDH2626]	RO: 2'-8 3/8" x 5'-1 1/2" (VIF) FS: 2'-7 3/8" x 5'-1"	9/6 SDL	INSULATED, LOW E2, ARGON	0.29	0.29	0.51	THUMB LATCH	6	
2	DOUBLE HUNG 2ND FLR TYP	MARVIN	SIGNATURE ULTIMATE WOOD INSERT [UWDH26custom]	RO: 2'-8 3/8" x 4'-3" (VIF) FS: 2'-7 3/8" x 4'-2" (VIF)	6/6 DL	INSULATED, LOW E2, ARGON	0.29	0.29	0.51	THUMB LATCH	4	
Æ.	CASEMENT 2ND FLR EGRESS	MARVIN	ULTIMATE WOOD CASEMENT PUSH OUT [UWCPO3254]	RO: 2'-8 3/8" x 4'-6 5/8" (VIF) FS: 2'-8 1/8" x 4'-6 1/8" (VIF)	3X4 DL	INSULATED, LOW E2, ARGON	0.29	0.29	0.51	HANDLE LATCH	5	7.5 SF CLEAR EGRESS (5.7 MIN REQ.)
3	DOUBLE HUNG 1ST FLR EAST TRIPLE	MARVIN	SIGNATURE ULTIMATE WOOD INSERT [UWDH2622]	RO: 2'-8 3/8" x 4'-5 1/2" (VIF) FS: 2'-7 3/8" x 4'-5"	4/4 DL	INSULATED, LOW E2, ARGON	0.29	0.29	0.51	THUMB LATCH	6	
4	DOUBLE HUNG IST FLR EAST	MARVIN	SIGNATURE ULTIMATE WOOD INSERT [UWDH1612]	RO: 1'-10 3/8" x 2'- 9 1/2"(VIF) FS: 1'-9 3/8" x 2'-9"	2/2 SDL	INSULATED, LOW E2, ARGON	0.29	0.29	0.51	THUMB LATCH	3	
5	DOUBLE HUNG IST FLR EAST	MARVIN	SIGNATURE ULTIMATE WOOD INSERT [UWDH2014]	RO: 2'-2 3/8" x 3'- 1 1/2" (VIF) FS: 2'-1 3/8" x 3'-1"	2/2 SDL	INSULATED, LOW E2, ARGON	0.29	0.29	0.51	-	1	
6	DOUBLE HUNG 2ND FLR EAST	MARVIN	SIGNATURE ULTIMATE WOOD INSERT [UWDH2416]	RO: 2'-6 3/8" x 3'-5 1/2" (VIF) FS: 2'-5 3/8" x 3-5" (VIF)	2/2 SDL	INSULATED, LOW E2, ARGON	0.29	0.29	0.51	THUMB LATCH	1	
7	DOUBLE HUNG 2ND FLR SE TRIPLE	MARVIN	SIGNATURE ULTIMATE WOOD INSERT [UWDH2416]	RO: 2'-6 3/8" x 3'-5 1/2" (VIF) FS: 2'-5 3/8" x 3-5" (VIF)	2/2 SDL	INSULATED, LOW E2, ARGON	0.29	0.29	0.51	THUMB LATCH	3	
8	DOUBLE HUNG ATTIC CENTER	MARVIN	SIGNATURE ULTIMATE WOOD INSERT [UWDH2418]	RO: 2'-6 3/8" x 3'-9 1/2" (VIF) FS: 2'-5 3/8" x 3-9"	2/2 SDL	INSULATED, LOW E2, ARGON	0.29	0.29	0.51	THUMB LATCH	2	
9	CASEMENT INSWING	EXISTING	ATTIC WEST, HINGED	RO: 1'-8" x 2'-0" (VIF) FS: 1'-7" x 1-11 1/2" (VIF)	2/2 DL	SINGLE PANE, CLEAR, REPLACEMENT	-	-	•	THUMB LATCH	2	
10>	AWNING INSWING	EXISTING	BASEMENT WEST, HINGED	RO: 2'-0" x 1'-6" (VIF) FS: 1'-8" x 1-2" (VIF)	3X1 DL	SINGLE PANE, CLEAR, REPLACEMENT	-	-	-	THUMB LATCH	4	



MICHE BOOZ

A R C H | T E C T

15 High St, Brookeville, MD 20833
301 774 6911

Duane & Rachel Epperly

Grafton Holland Farm "Sunnym

2240 Brighton Dam Road, Brookeville, MD 20833

"Sunnymeade Farm"

MHT Inventory M:23/82

FARMHOUSE
SCHEMATIC DESIGN

HAWP Review September 21, 2022

EXISTING + PROPOSED SCHEDULES

1/4" = 1'

DEMOLISH NON-ORIGINAL BATHROOM DORMER; SEVERLY DEGRADED + STRUCTURALLY UNSOUND COLLAPSED/ DEMOLISHED SHED PORCH ROOF, LOW EAVE AT +/- 7' ABOVE PATIO


> DEMOLISHED SCREENED PORCH AT DECK SITTING ON PATIO

REPLACEMENT BATHROOM DORMER CENTERED ON ROOF

FLAGSTONE PATIOS + STEPS,
INTEGRATING STONES FROM
ORIGINAL PATIO/FOUNDATION

HIP PORCH ROOF, STANDING
SEAM METAL, EAVE TO BE
7'-6" MIN ABOVE FLOOR

SCREENED PORCH ON
WOOD DECK ON STONE
FOUNDATION







AERIAL VIEW FROM EAST-SOUTHEAST, PROPOSED

MICHE	BOOZ
ARCH	TECT
15 High St, Brool	keville, MD 20833

Duane & Rachel Epperly
Grafton Holland Farm

2240 Brighton Dam Road, Brookeville, MD 20833

"Sunnymeade Farm"

MHT Inventory M:23/82

FARMHOUSE SCHEMATIC DESIGN

HAWP Review

September 21, 2022

COMPARISON VIEWS



REFERENCE AERIAL VIEW FROM NORTH, 1974

AERIAL VIEW FROM NORTH, PROPOSED

MICHE	BOOZ
ARCH	ТЕСТ
15 High St, Broo 301 774 6911	keville, MD 20833

Duane & Rachel Epperly

Grafton Holland Farm

2240 Brighton Dam Road, Brookeville, MD 20833

"Sunnymeade Farm"

MHT Inventory M:23/82

FARMHOUSE SCHEMATIC DESIGN

HAWP Review

September 21, 2022

HISTORIC COMPARISON VIEWS





AERIAL VIEW FROM NORTHEAST

HAWP Review

AERIAL VIEW FROM NORTHWEST

MICHE	BOOZ
ARCH	ТЕСТ
15 High St, Broo	l keville, MD 20833 I

2240 Brighton Dam Road, Brookeville, MD 20833

September 21, 2022



MICHE	BOOZ
ARCH	TECT
15 High St, Brool 301 774 6911	keville, MD 20833

"Sunnymeade Farm" 2240 Brighton Dam Road, Brookeville, MD 20833 MHT Inventory M:23/82

FARMHOUSE SCHEMATIC DESIGN September 21, 2022

HAWP Review

RENDERED VIEWS OF PROPOSED WORK



AERIAL VIEW FROM SOUTHEAST

MICHE	BOOZ
ARCH	ТЕСТ
15 High St, Brool	l keville, MD 20833

2240 Brighton Dam Road, Brookeville, MD 20833

"Sunnymeade Farm"

MHT Inventory M:23/82

FARMHOUSE SCHEMATIC DESIGN

HAWP Review

September 21, 2022

RENDERED VIEWS OF PROPOSED WORK



GROUND LEVEL VIEW LOOKING NORTH



GROUND LEVEL VIEW LOOKING NORTHWEST

MICHE	BOOZ
ARCH	TECT
15 High St, Broo	keville, MD 20833

2240 Brighton Dam Road, Brookeville, MD 20833

"Sunnymeade Farm"

MHT Inventory M:23/82

FARMHOUSE SCHEMATIC DESIGN

HAWP Review

September 21, 2022

RENDERED VIEWS OF PROPOSED WORK



GROUND LEVEL VIEW LOOKING SOUTH

MICHE BOOZ

A R C H T E C T

15 High St, Brookeville, MD 20833
301 774 6911

Duane & Rachel Epperly

Grafton Holland Farm

2240 Brighton Dam Road, Brookeville, MD 20833

"Sunnymeade Farm"

MHT Inventory M:23/82

FARMHOUSE SCHEMATIC DESIGN

HAWP Review

September 21, 2022

RENDERED VIEWS OF PROPOSED WORK