EXPEDITED MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION STAFF REPORT				
Address:	15215 Barnesville Road, Boyds	Meeting Date:	10/26/2022	
Resource:	Boyd-Maughlin House/Primary Resource Boyds Historic District	Report Date:	10/19/2022	
Applicant:	Montgomery County Dept. of Parks/M-NCPPC (Jamie Ferguson, Agent)	Public Notice:	10/12/2022	
<b>Review:</b>	HAWP	Tax Credit:	n/a	
Case No.:	1008756	Staff:	Rebeccah Ballo	
Proposal:	Installation of interpretive signage.			

## **STAFF RECOMMENDATION**

Approve Approve with conditions

## **ARCHITECTURAL DESCRIPTION**

SIGNIFICANCE:	Primary Resource
STYLE:	Gothic Revival
DATE:	1866



Figure 1: The subject property is the northernmost parcel in the Boyds Historic District.

### **BACKGROUND**

The c. 1866 Boyd-Maughlin House and adjacent parcels are owned by the M-NCPPC Parks Department. The property is leased out by Parks as a residence and Parks owns all adjacent parcels.

## **PROPOSAL**

The applicant proposes to install five (5) interpretive markers to the rear of the Boyd-Maughlin House near the walking trail in Black Hill Regional Park. The signs will be manufactured from fiberglass panels set at a 45-degree angle on brown aluminim posts. The signs will be set at an ADA compliant waist height of 28"-32". The posts will be anchored in poured concrete bases. The design and layout of the signs comply with the M-NCPPC Parks approved standards. Images and text are provided for review in the HAWP application. Several photos of the property and grounds are also provided for review. The Parks Department has worked closely with the Boyds Historical Society on the design, layout, and placement of these signs. The signs are located far from any extant historic structures. They will not be placed within the root zone of any mature trees. There will be no impact to the resource or the District from this alteration.

#### **APPLICABLE GUIDELINES**

#### Policy On Use of Expedited Staff Reports for Simple HAWP Cases

IV. The Expedited Staff Report format may be used on the following type of cases:

- 2. Modifications to a property, which do not significantly alter its visual character;
- 6. Signs that are in conformance with all other County sign regulations.

#### Montgomery County Code; Chapter 24A-8

- (b) The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to ensure conformity with the purposes and requirements of this chapter, if it finds that:
  - (1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or
  - (2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter; or
- (d) In the case of an application for work on an historic resource located within an historic district, the commission shall be lenient in its judgment of plans for structures of little historical or design significance or for plans involving new construction, unless such plans would seriously impair the historic or architectural value of surrounding historic resources or would impair the character of the historic district. (Ord. No. 9-4, § 1; Ord. No. 11-59.)

#### Secretary of Interior's Standards for Rehabilitation

The Secretary of the Interior defines rehabilitation as "the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features, which convey its historical, cultural, or architectural values." The relevant *Standards* are as follows:

2. The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.

- 9. New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportions, and massing to protect the integrity of the property and its environment.
- 10. New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

#### **STAFF RECOMMENDATION**

Staff recommends that the Commission <u>approve</u> the HAWP application under the Criteria for Issuance in Chapter 24A-8(b)(1), (2) and (d), having found that the proposal will not substantially alter the exterior features of the historic resource and is compatible in character with the district and the purposes of Chapter 24A;

and with the Secretary of the Interior's Standards for Rehabilitation #2, #9, and #10;

and with the general condition that the applicant will obtain all other applicable Montgomery County or local government agency permits. After the issuance of these permits, the applicant must contact this Historic Preservation Office if any changes to the approved plan are made;

and with the general condition that final project design details, not specifically delineated by the Commission, shall be approved by HPC staff or brought back to the Commission as a revised HAWP application at staff's discretion;

and with the general condition that the applicant shall notify the Historic Preservation Staff if they propose to make **any alterations** to the approved plans. Once the work is completed the applicant will <u>contact the staff person</u> assigned to this application at 301-563-3404 or <u>rebeccah.ballo@montgomeryplanning.org</u> to schedule a follow-up site visit.

OMERYC			OR STAFF ONLY: AWP#
ALL	APPLICATION	FOR <sup>D</sup>	ATE ASSIGNED
	RIC AREA WO	'	TIM
H	STORIC PRESERVATION CO 301.563.3400	OMMISSION	
APPLICANT:			
Name:	E-	mail:	
Address:	Ci	ty:	Zip:
Daytime Phone:	Та	ax Account No.:	
AGENT/CONTACT (if applica	ble):		
Name:	E-	mail:	
Address:	Ci	ty:	Zip:
Daytime Phone:	Co	ontractor Regist	tration No.:
LOCATION OF BUILDING/PR	EMISE: MIHP # of Historic P	roperty	
Is the Property Located within			
	/		Name
Is there an Historic Preservation map of the easement, and do			the Property? If YES, include a porting this application.
Are other Planning and/or Heat (Conditional Use, Variance, Resupplemental information.	• • • • •	•	
Building Number:	Street:		
Town/City:	Nearest Cross S	treet:	
Lot: Block:	Subdivision:	Parcel:	
TYPE OF WORK PROPOSED: for proposed work are sub	-	-	
be accepted for review. Che		-	ed/Garage/Accessory Structure
- New Construction	Deck/Porch	Sol	
Addition	Fence	Tre	e removal/planting
Demolition	Hardscape/Landscap	be Wi	ndow/Door
Grading/Excavation	Roof	Oth	ner:
			n, that the application is correct
			and approved by all necessary
agencies and hereby acknow	ledge and accept this to be a	a condition for t	he issuance of this permit.

# HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFING

[Owner, Owner's Agent, Adjacent and Confronting Property Owners]

Owner's mailing address	Owner's Agent's mailing address			
Adjacent and confronting	Property Owners mailing addresses			

Description of Property: Please describe the building and surrounding environment. Include information on significant structures, landscape features, or other significant features of the property:

Description of Work Proposed: Please give an overview of the work to be undertaken:

Work Item 1:			
Description of Current Condition:	Proposed Work:		
Work Item 2:			
Description of Current Condition:	Proposed Work:		

Work Item 3:		
Description of Current Condition:	Proposed Work:	

## HISTORIC AREA WORK PERMIT CHECKLIST OF APPLICATION REQUIREMENTS

	Required Attachments						
Proposed Work	I. Written Description	2. Site Plan	3. Plans/ Elevations	4. Material Specifications	5. Photographs	6. Tree Survey	7. Property Owner Addresses
New Construction	*	*	*	*	*	*	*
Additions/ Alterations	*	*	*	*	*	*	*
Demolition	*	*	*		*		*
Deck/Porch	*	*	*	*	*	*	*
Fence/Wall	*	*	*	*	*	*	*
Driveway/ Parking Area	*	*		*	*	*	*
Grading/Exc avation/Land scaing	*	*		*	*	*	*
Tree Removal	*	*		*	*	*	*
Siding/ Roof Changes	*	*	*	*	*		*
Window/ Door Changes	*	*	*	*	*		*
Masonry Repair/ Repoint	*	*	*	*	*		*
Signs	*	*	*	*	*		*

#### **1. WRITTEN DESCRIPTION OF PROJECT:**

a. Description of existing structural and environmental setting, including historic features and significance. The Boyd-Maughlin House, located at 15215 Barnesville Road, is listed as a primary resource in the Boyd's Historic District (18/8-1). The district is comprised mostly of frame, vernacular Gothic Revival commercial and residential structures initially erected to house laborers laying the Metropolitan line of the B&O. The Boyd-Maughlin house, constructed in 1866 for James Boyd and eventually occupied by David Maughlin, is among the eldest and predates the 1873 establishment of the village.

The house sits on a 2.0 -acre parcel surrounded by parkland on a gentle rise overlooking Barnesville Road. The only historic structure on the site is the house. The site is leased for residential use.

#### b. General description of project and its effect on the historic resources and environmental setting.

The project seeks to install interpretive signage along an existing paved trail.

The project will not have an Adverse Effect on the historic integrity of the contributing resource or the historic district. Cultural Resources worked extensively with the Boyds Historical Society throughout this project. They will have a positive impact by providing historic information to Park visitors and are an asset the community sought for the park.

#### 2. SITE PLAN: see attached

#### 3. PLANS AND ELEVATIONS: N/A

#### 4. MATERIAL SPECIFICATIONS:

The signs are composed of 36" x 24" embedded fiberglass panels set at a 45-degree angle on brown aluminum posts. The cantilevered exhibit base is set into the ground at an ADA compliant waist height of 28"-32". Cement will be used to anchor the sign posts in the ground to prevent easy removal by vandals and heaving in the winter. The sign will be fabricated by Pannier, a National Park Service approved vendor. The design of the interpretive material follows a standard being set for all historic markers being placed within the county's Parks system.

#### 5. PHOTOGRAPHS: see attached

6. **TREE SURVEY:** N/A - The signs will not be placed next to any mature trees.

#### 7. ADDRESS OF ADJACENT AND CONFRONTING PROPERTY OWNERS

<u>Adjacent</u>: the adjacent, separate legal parcels are owned by MNCPPC. There are no adjacent private property owners.

#### Confronting:

- 15203 Barnesville Road (US Post Office)
- 15189 Barnesville Road (private residence)



## Site Plan



Proposed Location for the Interpretive Signage




Photo 1: Boyd-Maughlin House



Photo 2: Location for the five interpretive signs, with the house and town of Boyds in the background

#### Signage Proofs:





James and Sarah Boyd had one adopted son, their nephew James Boyd Maughlin. In 1866, Boyd built this two-story, frame, clapboard house in the rural Gothic-style. Today, it is among the oldest houses in Boyds, predating the 1873 establishment of the village. Known as the "Dairyman's House," this dwelling served as the residence for the farm manager, the most prestigious position on the property, who followed Boyd's philosophy: "Whatever is worth doing is worth doing well."

When it came to dairy farming, Boyd was extremely progressive. Between 1871 and 1880 Boyd outfitted his property with several outbuildings including a dairy barn that could hold 50 cows, "25 on a side, with broad pathway for feeding, and water-troughs and feed-troughs for each animals...the floor is concrete, kept

scrupulously clean..." His innovations were years ahead of



accepted agricultural practices in northern Montgomery County. His cows, a hybrid of Alderney and Durham, produced 180 gallons/day which Boyd shipped chilled by train to Washington, D.C. Boyd also grew wheat and corn in fields irrigated by a wind-mill pump; managed an orchard; and constructed and maintained 8 barns, a dairy, a washhouse, and an ice house.

IMES MAUGHLIN SR. WA'S MARRIED TO BOYD'S SISTER IN LAW, INE RINEHART. THE COUPLE NAMED JAMES JR. AFTER HIS UNCLE. IMES JR. BECAME THE HEIR OF THE BOYD ESTATE. Ca. 1890.



As one admirer noted: "His farm is a card inviting strangers to examine and purchase in the neighborhood."





HistoryInTheParks.org

An agricultural operation of this magnitude required hired labor. Boyd employed men from the local African American community to farm his extensive acreage, including John (Henry) Duffin and his son Addison. John built his first home in the White Ground area. His wife, Maria, was also employed by the Boyds, working as a domestic at Bonnie Brae.









white appearance of the soil in some places

### **Development of** e Seneca La IIII ke

Probably the most noticeable feature in Boyds is Little Seneca Lake. Did you know it was manmade? As early as 1960, the county planned this lake partly as a means  $% \left( {{{\rm{A}}_{\rm{B}}}} \right)$ of flood control, but the goals shifted in the late 1970s when its function evolved to providing an emergency water supply for Washington metro area. The 505-acre reservoir required the acquisition of four dairy farms, two mills and more than 20 households. Today, Washington Suburban Sanitary Commission (WSSC) manages the dam and its outflow, while the Maryland-National Capital Park & Planning Commission maintains this 4.25-billion-gallon lake. The one consistent objective was to create a recreational outlet as part of the larger Black Hill Regional Park which officially opened on



THE NEW LAKE AT BLACK HILL REGI OR THE JUNE 14, 1987 EDITION OF T


PLAN

M · N · C · P · P DEPARTMENT OF PA

#### Diabase Stone

8 6 BOYDS MASTER PLAN Diabase Deposit Map

HistoryInTheParks.org



(Rockville Crush Stone Quarry)

Perhaps the

least visible natural feature of Boyds is the diabase bedrock. Also called dolerite, this fine-to-medium grained intrusive igneous rock is extremely hard and tough. Once crushed, diabase is used as a construction aggregate for paved road beds, buildings, and within dams. After 40 years, the county finally succumbed to the wishes of the citizens and rejected the proposal to establish a quarry

in the center of the Boyds community. Much of the land that would have been a quarry is now the Hoyles Mill Conservation Park.

GOLD! After the Civil War, prospectors dug pits to look for gold on land that became part of this regional park. Commercial gold mining in Montgomery County ended in the 1950s. Remember! Parks Rules & Regulations state: "Using metal detectors and/or digging into the surface of Park Property is prohibited."