MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address: 7307 Baltimore Ave., Takoma Park Meeting Date: 7/26/2023

Resource: Contributing Resource **Report Date:** 7/19/2023

Takoma Park Historic District

Applicant: Catherine Bernard **Public Notice:** 7/12/2023

Review: HAWP **Tax Credit:** n/a

Permit No.: 1035500 Staff: Dan Bruechert

Proposal: Fenestration Alteration

STAFF RECOMMENDATION

Staff recommends the HPC **approve** the HAWP application.

ARCHITECTURAL DESCRIPTION

SIGNIFICANCE: Contributing Resource to the Takoma Park Historic District

STYLE: Colonial Revival

DATE: c.1906



Figure 1: The subject property is near the intersection of Baltimore Ave. and Takoma Ave.

PROPOSAL

The applicant proposes to remove two attic windows and install two new windows in the existing openings.

APPLICABLE GUIDELINES

When reviewing applications for alterations within the Takoma Park Historic District, several documents are to be utilized as guidelines to assist the Commission in developing their decision. These documents include the historic preservation review guidelines in the approved and adopted amendment for the *Takoma Park Historic District (Guidelines)*, *Montgomery County Code Chapter 24A (Chapter 24A)*, and the Secretary of the Interior's Standards for Rehabilitation (Standards).

Takoma Park Historic District Guidelines

There are two very general, broad planning and design concepts which apply to all categories. These are:

- The design review emphasis will be restricted to changes that are all visible from the public rightof-way, irrespective of landscaping or vegetation (it is expected that the majority of new additions will be reviewed for their impact on the overall district), and
- The importance of assuring that additions and other changes to existing structures act to reinforce and continue existing streetscape, landscape, and building patterns rather than to impair the character of the historic district.

Contributing Resources should receive a more lenient review than those structures that have been classified as Outstanding. This design review should emphasize the importance of the resource to the overall streetscape and its compatibility with existing patterns rather than focusing on a close scrutiny of architectural detailing. In general, however, changes to Contributing Resources should respect the predominant architectural style of the resource. As stated above, the design review emphasis will be restricted to changes that are *at all visible from the public right-of-way*, irrespective of landscaping or vegetation.

All exterior alterations, including those to architectural features and details, should be generally consistent with the predominant architectural style and period of the resource and should preserve the predominant architectural features of the resource; exact replication of existing details and features is, however, not required,

Minor alterations to areas that do not directly front on a public right-of-way such as vents, metal stovepipes, air conditioners, fences, skylights, etc. – should be allowed as a matter of course; alterations to areas that do not directly front on a public way-of-way which involve the replacement of or damaged to original ornamental or architectural features are discouraged, but may be considered and approved on a case-by-case basis,

Original size and shape of window and door openings should be maintained, where feasible

Some non-original building materials may be acceptable on a case-by-case basis; artificial siding on areas visible to the public right-of-way is discouraged where such materials would replace or damage original building materials that are in good condition

Alterations to features that are not visible from the public right-of-way should be allowed as a matter of course

All changes and additions should respect existing environmental settings, landscaping, and patterns of open space.

Montgomery County Code; Chapter 24A-8

- (1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or
- (2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter; or
- (d) In the case of an application for work on an historic resource located within an historic district, the commission shall be lenient in its judgment of plans for structures of little historical or design significance or for plans involving new construction, unless such plans would seriously impair the historic or architectural value of surrounding historic resources or would impair the character of the historic district. (Ord. No. 9-4, § 1; Ord. No. 11-59.)

Secretary of the Interior's Standards for Rehabilitation

The Secretary of the Interior defines rehabilitation as "the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features, which convey its historical, cultural, or architectural values." The applicable *Standards* are as follows:

- 2. The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.
- 9. New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.
- 10. New additions and adjacent or related new construction shall be undertaken in such a manner that if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

STAFF DISCUSSION

The subject property is a two-story clapboard-sided Colonial Revival house with a wrap-around front porch (the front porch had been removed and was reinstalled sometime after 1994). There are two gable dormers on the roof; one on the front-facing roof slope, the other on the right-facing roof slope. The front-facing dormer window is an 8/8 vinyl-clad sash window. The window on the right-facing roof slope has a window air conditioner with a fixed light window in the upper sash. Bother windows are vinyl clad and, according to the application, were installed c.1985. The applicant proposes to remove both windows and install 8-light SDL vinyl-clad wood windows in the existing openings. While Staff is reluctant to recommend the HPC approve vinyl-clad windows on Contributing Resource, Staff recommends they do so for the reasons outlined below.

Were the applicant proposing to replace only the front-facing window, Staff would determine that the replacement window is an in-kind replacement that does not require a HAWP. However, the window in the right-facing dormer will not match the configuration of the existing one and does require an approved HAWP. Staff finds the current configuration of the right-facing dormer window, with a fixed single-light upper sash and a window air conditioner, is not the historic configuration and its removal should be approved as a matter of course.

The remaining question is, what is the appropriate window to go in the existing opening? Staff was able to find a photo from an earlier application (before the designation of the Master Plan District) that shows a pair of multi-light casement windows on the front-facing dormer. Based on the details in the photo, Staff cannot determine if that window is the original attic window, however, there is a documentary basis for a pair of multi-light casement windows. Staff also finds that matching the configuration of the other attic window opening is a reasonable justification, provided that window is consistent with the character and time period of the historic resource, per the *Design Guidelines*. Staff finds that the proposed 8/8 sash configuration is compatible with the character of the house and surrounding district.



Figure 2: Photo submitted with 1988 application. Note the front porch had not been reconstructed. Source: Montgomery Planning.

The preferred window materials for a replacement window in the Takoma Park Historic District are wood or aluminum clad wood because those materials best replicate the profile of a historic wood window. Vinyl windows are generally disfavored because they tend to have a flatter profile and a shinier appearance that does not dull over time. In this instance, the applicant proposes to install a vinyl-clad SDL window. Staff finds the 7/8" (seven-eighths inch) exterior and interior grids will help to add some depth to the window and create a more compatible profile. Without examining a sample window, Staff cannot provide feedback on the character of the exterior finish, but Staff finds the finish is less important in this instance. First, Staff finds the proposed replacement window is on a side-facing dormer, that is much less visible from the public right-of-way than the front-facing dormer. Second, Staff finds there is a benefit to having the attic windows match, even though the right-side dormer is not as visible as the front-facing one. An incongruent window appearance in the attic may stand out and attract attention, rather than reinforcing the existing patterns, per the *Design Guidelines* and 24A-8(d). But for the front window replacement in-kind, Staff would not recommend the HPC approve the proposed vinyl clad attic window.



Figure 3: Photo of the subject property with the right-facing dormer circled in yellow.

STAFF RECOMMENDATION

Staff recommends that the Commission <u>approve</u> the HAWP application under the Criteria for Issuance in Chapter 24A-8(d), having found that the proposal will not substantially alter the exterior features of the historic resource and is compatible in character with the district and the purposes of Chapter 24A;

the Secretary of the Interior's Standards for Rehabilitation #2;

and with the general condition that the applicant shall present an electronic set of drawings, if applicable, to Historic Preservation Commission (HPC) staff for review and stamping prior to submission for the Montgomery County Department of Permitting Services (DPS) building permits;

and with the general condition that final project design details, not specifically delineated by the Commission, shall be approved by HPC staff or brought back to the Commission as a revised HAWP application at staff's discretion;

and with the general condition that the applicant shall notify the Historic Preservation Staff if they propose to make **any alterations** to the approved plans. Once the work is completed the applicant will contact the staff person assigned to this application at 301-563-3400 or dan.bruechert@montgomeryplanning.org to schedule a follow-up site visit.



APPLICATION FOR DATE ASSIGNED HISTORIC AREA WORK PERMIT

RIC PRESERVATION COMMISSION 301.563.3400

FOR STAFF ONLY:

1111	
APPLICANT:	1G. 81 11
Name: Catherine Bernard	E-mail: Catherine bernard 63630 gi
Address: 7307 Baltmore Au	City: Takona Park zip: 209/2
Daytime Phone: 301 615 7196	Tax Account No.:
AGENT/CONTACT (if applicable):	
Name: \(\frac{1}{2} \) \(\frac{1} \) \(\frac{1}{2} \) \(\frac{1}{2} \) \(\frac{1}{2} \) \(\frac{1}{2} \) \(\frac{1}{2	E-mail:
Address:	City: Zip:
Daytime Phone:	Contractor Registration No.:
LOCATION OF BUILDING/PREMISE: MIHP # of Hist	toric Property
Is the Property Located within an Historic District?	✓Yes/District Name <u>Ta Kome Park</u> No/Individual Site Name
Is there an Historic Preservation/Land Trust/Environ map of the easement, and documentation from the	mental Easement on the Property? If YES, include a
Are other Planning and/or Hearing Examiner Approv (Conditional Use, Variance, Record Plat, etc.?) If YES supplemental information.	
Building Number: $\phantom{aaaaaaaaaaaaaaaaaaaaaaaaaaaaaaaaaaa$	altimore Avenue
Talzama Darlz	ross Street:
Lot: Block: Subdivisio	n: Parcel:
	Shed/Garage/Accessory Structure Solar Irec removal/planting Window/Door Other: foregoing application, that the application is correct
and accurate and that the construction will comply agencies and hereby acknowledge and accept this to	
	V4-01-70L

Adjacent and Confronting Properties:

Takoma Park, MD 20912

7305 Baltimore Avenue

7311 Baltimore Avenue

7306 Baltimore Avenue

7308 Baltimore Avenue

7310 Baltimore Avenue

7316 Piney Branch Road

7314 Piney Branch Road

7312 Piney Branch Road

Description of Property: Please describe the building and surrounding environment. Include information on significant structures, landscape features, or other significant features of the property:

le Sidestrol property

Description of Work Proposed: Please give an overview of the work to be undertaken:

contact two dorner windows (work item 1)
on third floor.

partition to the country of the parties of a regard partition of the country of t

Description of Current Condition: window #1 - cracked & convot be bited window# 2 built in air Conditiona needs to be removed + bull widow replaced.

Proposed Work; 2 historically gorrect windows & replace the existing domaged wirdreds which were installed in about 1985.

existing windows are not historic.

See attached proposal from Shanco Winlows are oak wood covering viny! Wood-clad viny! windows

City of Takoma Park

Housing and Community Development Department

Main Office 301-891-7119 Fax 301-270-4568 www.takomaparkmd.gov



7500 Maple Avenue Takoma Park, MD 20912

MUNICIPALITY LETTER

June 23, 2023

To: Catherine Bernard

7307 Baltimore Avenue

catherinebernard6363@gmail.com

301-675-7196

To: Department of Permitting Services

2425 Reedie Drive, 7th floor Wheaton, Maryland 20902

From: Planning and Development Services Division

THIS IS NOT A PERMIT - For Informational Purposes Only

VALID FOR ONE YEAR FROM DATE OF ISSUE

The property owner is responsible for obtaining all required permits from Montgomery County and the City of Takoma Park. If this property is in the **Takoma Park Historic District**, it is subject to Montgomery County Historic Preservation requirements.

Representative Name: Catherine Bernard Location of Project: 7307 Baltimore av

catherinebernard6363@gmai ____ 301-675-7196

Proposed Scope of Work: 2 dormer windows - broken. need to be replaced.

The purpose of this municipality letter is to inform you that the City of Takoma Park has regulations and city permit requirements that may apply to your project. This municipality letter serves as notification that, in addition to all Montgomery County requirements, you are required to comply with all City permitting requirements, including:

- Tree Impact Assessment/Tree Protection Plan
- Stormwater management
- City Right of Way

Failure to comply with these requirements could result in the issuance of a Stop Work Order and other administrative actions within the provisions of the law. Details of Takoma Park's permit requirements are attached on page 2.

The issuance of this letter does not indicate approval of the project nor does it authorize the property owner to proceed with the project. The City retains the right to review and comment on project plans during the Montgomery County review process.

11

City Of Takoma Park

The City of Takoma Park permits for the following issues:

Tree Impact Assessment/Tree Protection Plan/Tree Removal Application:

Construction activities that occur within 50 feet of any urban forest tree (7 and 5/8" in trunk diameter or greater), located on the project property or on an adjacent property, may require a Tree Impact Assessment and possibly a Tree Protection Plan Permit. Make sure to submit a request for a Tree Impact Assessment and schedule a site visit with the City's Urban Forest Manager if any urban forest tree is in the vicinity of proposed construction activities. See the Tree Permits section of the City website for the specific conditions in which a Tree Impact Assessment is required. Depending on the Urban Forest Manager's conclusion following the Tree Impact Assessment, you may need to prepare a full Tree Protection Plan and apply for a Tree Protection Plan Permit as well. Separately, the removal of any urban forest tree will require a Tree Removal Permit application. The tree ordinance is detailed in the City Code, section 12.12. For permit information check: https://takounaparkind.gov/services/permits/tree-301-891-7612 reached he Forest Manager can Urban permits The City's urbanforestmanager@takomaparkind.gov.

Stormwater Management:

If you plan to develop or redevelop property, you may be required to provide appropriate stormwater management measures to control or manage runoff, as detailed in City Code section 16.04. All commercial or institutional development in the city must apply for a Stormwater Management Permit regardless of the size of the land disturbance. Additions or modifications to existing detached single-family residential properties do not require a Stormwater Management permit if the project does not disturb more than 5,000 square feet of land area. For more information visit: https://takomaparkund.gov/government/public-works/stormwater-management-program/. The City Engineer should be contacted to determine if a City permit is required. The City Engineer can be reached at 301-891-7620.

City Right of Way:

- To place a construction dumpster or storage container temporarily on a City right of way (usually an adjacent road), you will need to obtain a permit. A permit is not required if the dumpster is placed in a privately-owned driveway or parking lot.
- If you plan to install a new **driveway apron**, or enlarge or replace an existing driveway apron, you need a Driveway Apron Permit.
- If you plan to construct a fence in the City right of way, you need to request a Fence Agreement. If approved, the Agreement will be recorded in the Land Records of Montgomery County.

For more information and applications for City permits, see: https://takomaparkind.gov/services/permits/ or contact the Department of Public Works at 301-891-7633.

Failure to comply with the City's permitting requirements could result in the issuance of a Stop Work Order and other administrative actions within the provisions of the law.





Window #2



Window

#1 Window is cracked and cannot be repaired.





Shanco Companies Agreement

Prepared for: Catherine Bernard

7307 Baltimore Avenue Takoma Park, Maryland 20912

Prepared by: Derrick Sieber





Date 06/13/2023

Agreement
Partial Window Replace

Sales Rep

Derrick Sieber
Phone: 2023021990
Email: dsieber@goshanco.com

Agreement

Catherine Bernard 7307 Baltimore Avenue Takoma Park, Maryland 20912

Partial Window Replace


Product


WOOD-CLAD VINYL WINDOW REPLACEMENTS [2]

- Shall provide professional measuring of existing openings for best fit and finish. (Measure to be scheduled separately).
- Shall remove existing 2 windows on the 3rd floor of the home and haul away all job related debris.
- Shall replace any rotted wood as needed to complete installation (refer to your contract for additional pricing details).
- Shall furnish and install 1 new ProVia ™ Aeris Series double-hung vinyl window into the existing openings.
- Shall install 2 new windows into existing jams, sills, and headers.
- Shall caulk and seal windows and capping as needed to complete installation.
- All windows come with Manufacturer's Lifetime Warranty and Shanco 5-year workmanship warranty.
- **SEE WINDOW SPEC SHEET ATTACHED FOR ALL WINDOW SPECIFICATIONS**

YOUR **PROFESSIONAL-CLASS** PRODUCT

Aeris Aeris 1000 Series 1001 - Double Hung





OUTSIDE VIEW

SIZING

Opening Width Range: 36 3/4" to 37" Opening Height Range: 40 3/4" to 41" Window Size: 36 1/2" x 40 1/2"

United Inches: 78

Egress Size: 29 1/2" x 13 11/16"

Egress Square Foot: 2.8040 Egress Meets Criteria: No

Top Sash Size: 32 5/16" x 19"

Top Glass Size: 30 3/8" x 17" x 1"

Top Glass Viewable Size: 29 1/4" x 15 15/16"

Bottom Sash Size: 33 5/16" x 19"

Bottom Glass Size: 31 3/8" x 17" x 1" Bottom Glass Viewable Size: 30 1/4" x 15 15/16"

Bottom Screen: 32 3/16" x 19 7/16"

Structural

Cert #: 462-H-020.01

R-PG55

Size Tested: 40" x 63" DP: +55/-55

AAMA/WDMA/CSA 101/1.5.2/A440-08/-011/-17

Hallmark Certification

ENERGY

ENERGY PERFORMANCE RATINGS

U-Factor (U.S/I-P)

Solar Heat Gain Coefficient

0.27

0.19

ADDITIONAL PERFORMANCE RATINGS Condensation Resistance

Visible Transmittance

0.41

59.00

Air Infiltration (cfm/ft2)

<= 0.30



ENERGY STAR* Certified In All 50 States.



Sugarcreek, OH 44681

OUOTE INFORMATION

DETAILS

Aeris Window

1001 - Double Hung

Oak Interior Material

Honey Wheat Inside / White Outside

Sandstone Jamb Pocket

Opening Size: 37" x 41"

Unit Size: 36 1/2" x 40 1/2"

Compound Tension Balance System

Double Profile DA Locks

Flat Bronze Hardware

Extruded Bottom Screen (White) with BetterVue Screen

Graphite Foam Insulation

ComforTech DLA-UV

Double Strength Glass

1" IG Thickness

Colonial (Standard) Flat Grid - 2V x 1H

Honey Wheat Inside / White Outside Grids

Installation Instructions



Customer Information

Catherine Bernard		301-675-7196	Date: 06/13/2023
7307 Baltimore Avenue	ca	therinebernard6363@gmail.com	Rep: Derrick Sieber
Takoma Park, Maryland 20912			
Total Order			
Total Contract Amount			\$3,300.00
Payment Schedule			
Down Payment (1/3rd)			\$1,100.00
Remaining Balance			\$2,200.00
	This price in	cludes any and all applicable discounts.	
Homeowner Signature	Date	Homeowner Signature	Date
Shanco Companies Representative			Date