

Description of Property: Please describe the building and surrounding environment. Include information on significant structures, landscape features, or other significant features of the property:

Description of Work Proposed: Please give an overview of the work to be undertaken:

Repair front porch rotting railings

Repair and expand rear porch

Replace rotting deck and railings

Work Item 1: Front Porch

Description of Current Condition:

Some rotting wood on railings

Proposed Work:

Replace rotting wood with in-kind wood material for spindles, top and bottom railing. All spindles will be duplicated to match existing spindle.

Work Item 2: Rear Porch (back)

Description of Current Condition:

Wood is rotting in both railing and deck surface.

Very restricted use area due to fact that it was build around a tree that no longer exists

Proposed Work:

Proposed change is to make the porch rectangle over rotted tree stump (drawing attached). All material used will be in-kind for spindles, posts, top and bottom rail. All spindles will be duplicated to match existing spindle.


Work Item 3: _____

Description of Current Condition:


Proposed Work:

DRAWING

CURRENT PORCH



PROPOSED PORCH



SCALE EACH BLOCK = 1 FT



PRIVATE
RESIDENCE

9601
Cedar Drive





9601
Dewitt Drive















